LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building

51 Ubi Ave 1 #01-25 78 Shenton Way #08-16 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Md Ishak, Mohd Imran Date: 23 Jul 2019

Preliminary Advice

Vehicle No : SKW1333G **Accident Date** : 23/03/2019 Make : AUDI A5 Policy No. : 1900012908 **Assignment Date** : 26/03/2019 **Excess** : S\$0.00 Date of Inspection : 25/03/2019 Est. Duration of Repair : 21 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s, front portion, n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	71,119.00 (Inclusive supp)
Revised Amount	:S\$	34,409.70 (Inclusive supp)
Check Items (Estimated)	:S\$	19,431.30 (Inclusive supp)

Total :S\$ 53,841.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 175,000.00 COE / PARF Rebate :S\$ 67.548.00

Salvage Value :S\$

Margin for Repair :S\$ 107,452.00

Remarks

(X)	The vehicle is repa	airable at our adjusted amo	ount. We have als	so confirmed exces	s and policy coverage
	Kindly let us have	your authorisation.			

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Suppplementary amount is \$1,128.00, inclusive check items \$880.30.