

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50594
Date Estimated : 26/03/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Vipin Kumar Rastogi
Blk 9 Bukit Batok Central Link
#23-02

Singapore 658074

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME4050Z	VD11347	28/09/2018	216i AT	0

DESCRIPTION

Disassembly and assembly works for front bumper panel and to replace damage parts

Spray front bumper

To check electrical wiring systems at the front section for proper function including adjustments of headlights

Sundries

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VALUE

850 1,278.00

934 1,038.00

150 177.00

? 80.00

40

Total Labour 1: 2,570.00

DESCRIPTION

LH FINISHER

LH GRID LATERAL (LINES/PDC)

DECOUPING RING PDC TORQUE CONVERTER

QTY

PRIC

VALUE

1 49.70

1 103.65

4 5.05

Total Parts : 173.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No.

Claim No.

Date & Time

Excess S\$

Surveyor's Name

Sign

Surveyor's Tel

Authorised Yes / No

Authorised Date

Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes No PVL Yes / No

Surveyor's E-mail

No. of Working Days Recommend

Labour 1 : 2,570.00

Parts : 173.55

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 192.05

Grand Total : 2,935.60



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 50594**
Date Estimated : **26/03/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Vipin Kumar Rastogi
Blk 9 Bukit Batok Central Link
#23-02

Singapore 658074

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME4050Z	VD11347	28/09/2018	216i AT	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT
To make good front bumper and replace left finisher, to remove and install body parts in order to carry out painting job.	850.00	0	850.00 ✓
To respray front bumper	934.00	0	934.00 ✓
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00 ✓
Sundries	40.00	0	40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
LH FINISHER	49.70	1	0	49.70 ✓

	OD	3RD PARTY	DATE	REMARKS
PAY TO		Rahul	10/9/19	3
PAY TO		LKK		
TO				
CONFIRMED DATE				
PLEASE FINALISE BY				

Total Labour :	1,974.00
Total Parts :	49.70
Total Repair Costs less Excess:	2,023.70
GST @7%:	141.66
Grand Total :	2,165.36

LOSS OF USE = \$60 X 3 DAYS
GIA SEARCH FEE - \$2.00