

REF: CS/C11 19005254/ Dtd 3n2

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): chong Boon Sen

of

C11

Date/Time: 26/3/19 @ 10:10am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MYICS

To Inspect Vehicle No:

SHB 4391C

Insured:

SJW 7394C

at Workshop m/n:

Chenni Motor

Tel:

65425119

of

Blk 10 Amk #01-05/06

Policy No:

Claim No:

SNM17D01613C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:41pm @ 26/3/19

Person Contacted:

Jym

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (☒) Estimate

SHB 4391C - X

SJW 7394C - X

REF


ALCO, NMI, NY

COB June 2024

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Work Shop no: _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)

Remark: The vch had commenced its
 repair at the time of inspection.



Bal or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 9 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP: / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Vch No: SHB 4391 P Date: 2016 June
 Type: M Car / M Cycle / Bus / Van / Lorry / Car / Prime Mover /
 Truck / Trailer or
 Make: Hyundai I40 C: 1685
 Colour: Blue AC Insured / Std / NI / NA
 Sp Reading: 407374 T/Air/o: Insured / Std / NI / NA
 Eng No: D4FDGU614110
 C/A No: KMHLB41UMGU091319
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Mod: Std / S/Rim / STD A/Rim or
 Tyre Size: F: 205 / 60 R 16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 24/03/2019 D.O.I: 26/03/2019
 Survey held at Churni AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Front & Rev
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: China Teiping SSW 7394C

24/04/19 Jinnu 2/8 16000/- with 9 days 2/19
 Cred: 10339.68, 3970

RECEIVED 25 APR 2019

Date/Time, File Pass to?

24/4 Typist

Date/Time, File Return to?

☐ : Prelim. Report
☒ : Final Report

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

Transportation

1. S + P.S. 50

2. Other

3. Other

4. Other

T-119

Report Format:

Lump Sum / L.B.T. (\$)

Tp
16,000/-Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. fees (\$)☐ Weekend (\$)

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 26 March 2019 10:10 AM
To: Chunni Motor
Cc: assignments
Subject: RE: Accident involving Veh no: SHB 4391P & SJW 7394C on 24.03.19 (SNM17D01613)

Without Prejudice

Dear Sir,

We pri.

Dear LKK,

Pls pri.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Tuesday, 26 March, 2019 10:07 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: Accident involving Veh no: SHB 4391P & SJW 7394C on 24.03.19 (SNM17D01613)

Dear Sir,

We appoint Henry Ng

Thank you

Regards,
Chunni Motor Work P/L

On Tue, Mar 26, 2019 at 9:59 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Claims Dept of CTI
Sent: Tuesday, 26 March, 2019 9:08 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: FW: Accident involving Veh no: SHB 4391P & SJW 7394C on 24.03.19 (SNM17D01613)

From: Chunni Motor [<mailto:chunnimotor@gmail.com>]
Sent: Tuesday, 26 March 2019 9:01 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Accident involving Veh no: SHB 4391P & SJW 7394C on 24.03.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

MCD619038098 / ComfortDelGro Engineering Pte Ltd - Laying
 ENTRY DATE & TIME: 25/03/2019 16:21
 SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/03/2019 16:21
 Date Of Accident 24/03/2019 13:40
 Exact Location Of Accident SLE TWDS CTE AFTER MANDAI EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB4391P
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI
 Model I40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

Driver

Name of Driver GOH POH HUAT
 NRIC No S1777528F
 Date Of Birth 13/04/1966
 Occupation OUTDOOR
 Date Of Driving Pass 27/08/1984
 Driving Experience 34 YEARS AND 6 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98217577

Fax Number

Contact Number

Email Address WINSTON.GOHPH@GMAIL.COM

Address BLK 136 RIVERVALE STREET #10-734
 Postcode 540136
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY
 Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (Including own vehicle) involved in the accident 4
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJW7394C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver CHEN TIN KONG
 NRIC/Passport Number S7175524Z
 Contact Number 96185580
 Address
 Postcode
 Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Nature Of Damage REAR AND FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJJ1878G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO TEONG ANN
NRIC/Passport Number	S7717263G
Contact Number	98489336
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJW1290H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25.03.2019@1100HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24.03.2019 @ 1340HRS I was travelling along SLE twds CTE after Mandai Exit with one female passenger onboard.

As I was travelling straight suddenly veh(C) SJJ 1878G stopped and I followed however I could I felt an impact from the back and caused my vehicle to surge forward.

As the accident took place too fast I could not take evasive action to prevent the accident.

I have company video and photos at scene to support my claims.

No injury in this accident.

Veh (B) SJW 7394C MR Chen Tin Kong S 7175524Z HP:9618 5580

Veh(C) SJJ 1878G MR Teo Teong Ann S 7717263G

Veh(D) SJW 1290H Male Driver

DECLARATION

I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25.03.2019@1100HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 4391P

DATE : 25.03.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

ChinaTaiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>Dented</i>			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) <i>WH</i>	\$	41.00	\$ 82.00	X
	Bonnet Lock <i>st</i>			\$ 36.90	✓
	Bonnet Absorber <i>WH</i>	\$	58.10	\$ 116.20	X
	Bonnet Insulator <i>WH</i>			\$ 196.50	X
	Bonnet Insulator Clips <i>WH</i>			\$ 8.40	X
	Radiator Grille <i>broken</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>broken</i>			\$ 120.30	✓
	Front Bumper Cover <i>distorted</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>torn</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>st</i>			\$ 402.10	✓
	Front Bumper Bracket Top (LH/RH) <i>WH</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>WH</i>	\$	24.60	\$ 49.20	X
	Headlamp Support Top Cover <i>crack</i>			\$ 222.60	✓
	Headlamp Support Panel Assy <i>st</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>mostly broken</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>2 punctured</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>WH</i>			\$ 792.95	X
	Radiator Bracket (RH/LH) <i>WH</i>	\$	6.50	\$ 13.00	X
	Radiator Hose Upper <i>WH</i>			\$ 105.80	X
	Radiator Hose Lower <i>WH</i>			\$ 52.70	X
	Radiator Guard <i>st</i>	\$	20.00	\$ 40.00	X
	Horn Unit (LH/RH) <i>broken</i>	\$	73.80	\$ 147.60	✓
	Front Fender (LH) <i>Dented</i>			\$ 663.00	✓
	Aircon Condenser <i>st</i>			\$ 927.50	✓
	Inter Cooler <i>2 punctured</i>			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) <i>WH</i>			\$ 25.90	X
	Hose B To Inter Cooler <i>WH</i>			\$ 229.70	X
	Hose C To Inter Cooler Inlet <i>WH</i>			\$ 294.50	X
	Pipe To Inter Cooler <i>WH</i>			\$ 167.05	X
	Pipe To Inter Cooler Outlet <i>WH</i>			\$ 244.55	X
			12461.60		
			9969.28		
	SUB TOTAL			\$ 14,924.85	
	LESS 20%			\$ 2,984.97	
	DISCOUNTED TOTAL			\$ 11,939.88	
	Front Number Plate <i>st</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>WH</i>			\$ 30.00	Nett X
	Front Fender Advertisement Logo (LH) <i>WH</i>		125.00	\$ 100.00	Nett ✓
				\$ 155.00	

SHB 4391P

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Labour Charge				
	Panel Beating			S 1,000.00	600/-
	Spray Painting Charge			S 750.00	600/-
	Wiring Charge			S 50.00	30/-
	Tuff Kote			S 50.00	40/-
	Towing Charge			S 50.00	40/-
	Remove/Refix Aircon & Refill Gas		1350.00	S 150.00	80/-
	Diagnostic & Resetting To Erase Fault Code			S 480.00	40/-
	TOTAL LABOUR			S 2,530.00	
	Boot Lid 1/4			S 2,174.90	✓
	Boot Lid Rubber damaged / torn			S 96.50	✓
	Boot Lid Lock Upper 1/4			S 102.60	✓
	Boot Lid Lock Lower 1/4			S 31.70	X
	Boot Lid 'H' Emblem 1/4			S 28.70	✓
	Boot Lid CRDI Plate 1/4			S 27.90	✓
	Boot Lid Lamp (LH/RH) 1/4 S work o/s 1/4	S	565.60	S 1,131.20	✓
	Boot Lid Trimboard 1/4			S 116.40	✓
	Boot Lid Trimboard Clips (10pcs) 1/4			S 11.00	✓
	Bootlid Moulding 1/4			S 85.00	X
	Bootlid i40 Emblem 1/4			S 27.90	X
	Bootlid Lower Garnish 1/4			S 227.90	X
	Rear Bumper distorted / 1/4 crack			S 553.00	✓
	Rear Bumper Reinforcement 1/4			S 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) 1/4	S	80.30	S 160.60	X
	Rear Bumper Clip 10 pcs 1/4			S 22.00	✓
	Rear Bumper Bracket 1/4	S	35.60	S 71.20	X
	Rear Bumper Sponge 1/4			S 118.40	X
	Rear Bumper Under Cover distorted			S 228.00	✓
	Tail Lamp (LH/RH) 1/4	S	697.80	S 1,395.60	✓
	Rear Panel 2 Distorted			S 526.70	2 ✓
	Rear Panel Garnish 1/4			S 57.70	X
	Rear Panel Lower Panel 2 Distorted			S 495.50	2 ✓
	Exhaust Pipe Insulator 1/4	S	58.55	S 117.10	X
	Exhaust Silencer 1/4 1/4	S	967.70	S 1,935.40	X ✓
	Exhaust Pipe Hanger 1/4	S	58.55	S 117.10	X
	Exhaust Pipe Centre 1/4			S 730.10	X
	SUB TOTAL		8708.20	S 11,018.50	
	LESS 20%			S 2,203.70	
	DISCOUNTED TOTAL		6966.56	S 8,814.80	

SHB 4391P

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker <i>h/c</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>h/c</i>			\$ 100.00	Nett ✓
	Rear Bumper Advertisement Logo <i>h/c</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>h/c</i>		\$ 100.00	\$ 200.00	Nett ✓
			380.00	\$ 380.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	600/-
	Spray Painting Charge			\$ 1,000.00	600/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	40/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Exhaust Pipe		1370.00	\$ 300.00	60/-
	TOTAL LABOUR			\$ 2,520.00	
	ESTIMATE TOTAL			\$ 26,339.68	
	26/03/2019 @ 1430hrs		20160-84		
	him Antman		1/516000/-		
	L/Smm				
	<i>[Signature]</i>				
	LKK Auto				
	9 days.				
	<i>[Signature]</i>				
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19005354/DTD3N2

Date: 02/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN10135916066	
Claimant Vehicle No :	SHB4391P	Insured Vehicle No :	SJW7394C	
Date of Loss:	24/03/2019	Nature of Claim:	TP	Claim No: SNM17D01613C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB4391P	Engine No:	D4FDGU614110
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMGU091319
Reg. Date:	09/06/2016 (Man. Year: 2016)	Odometer:	407374 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	21,289.68	17,440.84	3,848.84	18.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,050.00	2,720.00	2,330.00	46.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,339.68	20,160.84	6,178.84	23.46
Approved Total (Overridden) (\$\$)		16,000.00		
(\$\$)	26,339.68	16,000.00	10,339.68	39.26
+ GST 7.00/7.00% (\$\$)	1,843.78	1,120.00	723.78	39.26
Nett Amount (\$\$)	28,183.46	17,120.00	11,063.46	39.26

INSPECTION

Date of Assignment:	26/03/2019
Date Inspected:	26/03/2019 Inspected At:

CHUNNI MOTOR WORK PTE LTD
BLK 10 ANG MO KIO IND. PARK 2A,
#03-19 AMK AUTOPOINT
SINGAPORE 568047

Estimated Period of Repair: 9.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2019)
Parts:	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB4391P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Not Necessary	82.00 FL	*- FL
3	1		*BONNET LOCK	Bent	36.90 FL	*36.90 FL
4	2		*BONNET ABSORBER	Not Necessary	116.20 FL	*- FL
5	1		*BONNET INSULATOR	Not Necessary	196.50 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*- FL
7	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
8	1		*RADIATOR GRILLE H EMBLEM	Broken	120.30 FL	*120.30 FL
9	1		*FRONT BUMPER COVER	Distorted	1,052.20 FL	*1,052.20 FL
10	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
12	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
13	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
14	1		*HEADLAMP SUPPORT TOP COVER	Cracked	222.60 FL	*222.60 FL
15	1		*HEADLAMP SUPPORT PANEL ASSY	Bent	907.40 FL	*907.40 FL
16	2		*HEADLAMP (LH/RH)	Mounting Broken	2,776.00 FL	*2,776.00 FL
17	1		*RADIATOR	Punctured	698.30 FL	*698.30 FL
18	1		*RADIATOR FAN	Not Necessary	792.95 FL	*- FL
			BLADE,COWLING,MOTOR ASSY			
19	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
20	1		*RADIATOR HOSE UPPER	Not Necessary	105.80 FL	*- FL
21	1		*RADIATOR HOSE LOWER	Not Necessary	52.70 FL	*- FL
22	2		*RADIATOR GUARD	Serviceable	40.00 FL	*- FL
23	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
24	1		*FRONT FENDER (LH)	Dented	663.00 FL	*663.00 FL
25	1		*AIRCON CONDENSER	Bent	927.50 FL	*927.50 FL
26	1		*INTER COOLER	Punctured	1,032.50 FL	*1,032.50 FL
27	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
28	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
29	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*- FL
30	1		*PIPE TO INTER COOLER	Not Necessary	167.05 FL	*- FL
31	1		*PIPE TO INTER COOLER OUTLET	Not Necessary	244.55 FL	*- FL
32	1		*BOOTLID	Bent	2,174.90 FL	*2,174.90 FL
33	1		*BOOTLID RUBBER	Deformed/Torn	96.50 FL	*96.50 FL
34	1		*BOOTLID LOCK UPPER	Bent	102.60 FL	*102.60 FL
35	1		*BOOTLID LOCK LOWER	Not Necessary	31.70 FL	*- FL
36	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
37	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
38	1		*BOOT LID LAMP (LH/RH)	N/s Cracked/O/s Not Necessary	1,131.20 FL	*565.60 FL
39	1		*BOOTLID TRIMBOARD	Torn	116.40 FL	*116.40 FL
40	10		*BOOTLID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
41	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*BOOTLID I40 EMBLEM	Not Necessary	27.90 FL	*- FL
43	1		*BOOTLID LOWER GARNISH	Not Necessary	227.90 FL	*- FL
44	1		*REAR BUMPER	Distorted/Mounting Cracked	553.00 FL	*553.00 FL
45	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
46	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	160.60 FL	*- FL
47	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
48	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
49	1		*REAR BUMPER SPONGE	Serviceable	118.40 FL	*- FL
50	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
51	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL
52	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
53	1		*REAR PANEL GARNISH	Not Necessary	57.70 FL	*- FL
54	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
55	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
56	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
57	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
58	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
59	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
60	1		*FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
61	1		*FRONT FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 FS	*100.00 FS
62	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
63	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
64	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
65	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	26,478.35	21,674.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,188.67	4,233.96	
	Total Parts (\$\$)	21,289.68	17,440.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,750.00	1,200.00
3	WIRING CHARGE	New	100.00	60.00
4	TUFF KOTE	New	100.00	80.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
7	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX EXHAUST PIPE	New	300.00	60.00
Gross Labour Cost (S\$)			5,050.00	2,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >