

ASS. REC. BY:

REF: CS/FCI 19005357/Ksd3

n2

Special Instruction:

SA/VEYOR

Kenneth

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

11.56am @ 26/3/19

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLH 7043X

Insured:

SHD 7107P

at Workshop m/s:

Estern Performance

Tel:

8799 0066

of

388 Sir Ming Drive

Policy No:

Claim No:

D19002042MF8H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1:02pm @ 26/3/19

Person Contacted:

Carmen

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLH 7043X - X

SHD 7107P - CS/FCI 18020806/Dtd 302

D.O.A - 14/11/2018

03/04/19

@ 17:27 p.m.

revised RA to Joanne Yong via email

815

@ 2382.12 Confirmed.

(\$2,115.11 Red - 47%)

ASS. REC. BY:

REF: 1-021

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 77k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH 7043X Yr Regn: 11, 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prit c.c. 1798Colour: M. P. White A/C: Insured / Std / NI / NASp. Reading: 192236 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD KB 3FU 403 537489

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Yoko 195/65R15R: PavaniBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 22/1/19

Survey held at

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 1/4/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 06 MAY 2019

Date/Time, File Pass to?

08/05/19☐ : Prell. Report☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - FS, SI

Fixups

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

2,382.12 P/P
2,382.12

135
50
50
15
250



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002042MFSH

Date: 03 April 2019

Our Ref: CS/FCI19005357/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 7043X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/04/2019 at the premises of M/s Esteem Performance Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 4,497.23 .
Revised Estimate Amount	: S\$ 2,932.12 .
"Check" Items Amount	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the o/s rear body.



Comments/ Present Status:

Damages Consistent.

Repair days: 4 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-03-2019	Our Ref No. D19002042MFSH
Accident Date	22-01-2019	Claim Type. Third Party
Insured Vehicle	SHD7107P	Third Party Vehicle. SLH7043X
Survey Location	385, SIN MING DRIVE (INSIDE VICOM)	
Contact Person.	CARMEN LIM	
Contact No.	87990066/ 0	Fax No. 62593326
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 3 April 2019 5:27 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002042MFSH/1
Attachments: SLH 7043X - Preli Advise -.pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SLH 7043X.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 26 March 2019 1:04 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002042MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 26 March 2019 11:56 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong

<Joannehoyong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19002042MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLH 7043 X

Parts	(a) Cost / List Price Items	\$	3,302.97
	Plus/Less 25%	\$	825.74
	Total of Cost / List	\$	2,477.23
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	2,020.00
Total		\$	4,497.23

The above total will be subjected to 7% G.S.T.

Not Authorized
Resurvey Repair



Name of Surveyor

Kenneth

Company

CLKC

Survey conducted on

11/4/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$

(e) Signature of surveyor

Le

Date:

11/4/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLH 7043 X
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU403537449

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH rear door <i>R</i>	1	\$1,017.40		✓
2	RH rear door hinge top <i>R</i>	1	\$78.30		✓
3	RH rear door hinge bottom <i>R</i>	1	\$78.30		X
4	RH rear door checker <i>SL</i>	1	\$155.15		X
5	RH rear door weatherstrip <i>SL</i>	1	\$206.79		X
6	RH rear door trim <i>SL</i>	1	\$811.77		✓
7	RH side skirt <i>R</i>	1	\$721.50		✓
8	RH side skirt clip <i>vv</i>	10	\$35.00		X
9	RH hub cap <i>Not In Stock</i>	1	\$198.76		✓
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19005357/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7107P	Veh. Inspected	SLH 7043X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002042MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	26/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKB3FU403537449	Colour	METALLIC PEARL WHITE	
Odometer	192236	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	6 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/01/2019	Inspection Date	01/04/2019	
Survey held at	385 SIN MING DRIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 7043X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH REAR DOOR	BENT	1,017.40	1,017.40
1	RH REAR DOOR HINGE TOP	TO REPAIR SEE LABOUR	78.30	-
1	RH REAR DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	78.30	-
1	RH REAR DOOR CHECKER	SERVICEABLE	155.15	-
1	RH REAR DOOR WEATHERSTRIP	SERVICEABLE	206.79	-
1	RH REAR DOOR TRIM	SERVICEABLE	811.77	-
1	RH SIDE SKIRT	TO REPAIR SEE LABOUR	721.50	-
10	RH SIDE SKIRT CLIP	NOT NECESSARY	35.00	-
1	RH HUB CAP	DENTED / SCRATCHED	198.76	198.76
	LESS 25% DISCOUNT		-825.74	-304.04
			2,477.23	912.12
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(RHR FENDER,RHR DOOR,RH SIDE SKIRT).INCLUSIVE OF THE REPAIR OF RH REAR DOOR HINGE TOP,RH REAR DOOR HINGE BOTTOM AND RH SIDE SKIRT.		800.00	500.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(RHR FENDER,RHR DOOR,RH SIDE SKIRT).		800.00	800.00
	TO CHECK WIRING.		50.00	20.00
	TO TUFF COAT.		100.00	30.00
	TO DO WHEEL ALIGNMENT.		120.00	60.00
	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD.		150.00	60.00
			2,020.00	1,470.00
GRAND TOTAL			4,497.23	2,382.12
RECOMMENDED COST OF REPAIRS				2,382.12

Report Ref No. CS/FCI19005357/Ksd3n2



Report Ref No. CS/FCI19005357/Ksd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.