

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 27 Mar 2019

Preliminary Advice

Vehicle No	: SJM8954H	Accident Date	: 20/03/2019
Make	: SUZUKI SX4	Policy No.	: PNPV2018-00016867
Assignment Date	: 25/03/2019	Excess	: S\$0.00
Date of Inspection	: 26/03/2019	Est. Duration of Repair	: -
Inspection At	: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages caught fire. Cause of fire pending investigations.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	21,000.00
COE / PARF Rebate	:S\$	13,163.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,837.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :