

ASS. REC. BY:

REF: CS/INC 19005362/TND302

Special Instruction:

Surveyor:

Taufiqh

ASSIGNMENT (Office)

From (Person):

Annie Koh

of

INC

Date/Time:

26/3/19 @ 9:29am

Estimated Cost:

Bill to:

OD (TP) WS/TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJE 2308E

Insured:

SME 6531P

at Workshop n/s

Autowheel Motor

Tel:

9192 8963

of

1 Bkt Batok Crescent # 02-40

Policy No:

Claim No:

MT/10363/S-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/03/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:11am 26/3/19

Person Contacted:

Louis

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SJE 2308E - NS/INC 1500765/ H/663

D.O.A - 02/04/2015

SME 6531P - X

1/4/19

LS \$1500 confirmed by email (Ref 4969.40, 7715)

Taufik

REF: INC

ASSIGNMENT

LoE 2027 Nov.

From: _____ Date: 26/3/19

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJE 2308E

at Workshop m/s: Auto wheel

of: 1 Bukit Batok Crescent #02-40

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SJE 2308E Yr Regn: 2008, Apr 1

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Allion 1.5 c.c. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 217870 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NET 260302870

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15 R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 843K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT _{LMS}

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Fallen

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm

D.O.A. _____ D.O.I. 21/3/191730

Survey held at: Auto wheels BB

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair cost 96K, inform LMS
	Taufik, pls check parts prices.

RECEIVED 01 APR 2019.

29/3

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

Date/Time, File Return to? 2) 1/4 - typist

Report Format: TP

Lump Sum / I.B.I: (\$) 1500p

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee:	290
Transportation:	
Photos	
Others	
TOTAL	290

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 26 March 2019 9:29 AM
To: 'assignments@lkkauto.com'
Subject: RE: TP CASES FARMED OUT TO LKK ON 26/03/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 26 March 2019 9:10 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Toh Choon Hin <choonhin.toh@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 26/03/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Toh's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA
1	Eric Tang	MT/1036315-002	SJE2308E	AUTO WHEELS MOTOR WORKS	No.1 BUKIT BATOK CRESCENT #02-40	Louis Ong / 91928963	SME6531P	17/3/19

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh

Senior Admin Assistant, Motor Insurance

T +65 6430 7899

www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4024J

Vehicle Details

Vehicle No.: SJE2308E
Vehicle to be Exported: No
Intended Deregistration Date: 27 Mar 2019
Vehicle Make: TOYOTA
Vehicle Model: ALLION 1.5 A
Primary Colour: Black
Manufacturing Year: 2008
Engine No.: 1NZC997160
Chassis No.: NZT2603022870
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$15,268.00
Original Registration Date: 17 Apr 2008
First Registration Date: 17 Apr 2008
Transfer Count: 2
Actual ARF Paid: \$16,795.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Nov 2027
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
PQP Paid: \$41,994.00
COE Rebate Amount: \$36,429.00
Total Rebate Amount: \$36,429.00

The information contained herein is correct as at 27 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 09:42
Date Of Accident	17/03/2019 10:30
Exact Location Of Accident	BT BATOK EAST AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE2308E
Insured/Policyholder	
Name Of Registered Owner	FO WAI CHENG
NRIC No	S6924024J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96742023
Alternative Phone No	OFFICE-96742023
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALLION
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095909340-01(CLASSIC)
Cover Note Number	
Driver	
Name of Driver	FO WAI CHENG
NRIC No	S6924024J
Date Of Birth	27/07/1969
Occupation	INDOOR
Date Of Driving Pass	19/07/1988
Driving Experience	30 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96742023
Fax Number	
Contact Number	OFFICE-96742023
EEmail Address	NOEMAIL

Address 26 BT BATOK EAST AVE 2 #18-10
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WILL EMAIL IF REQUIRED
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SME6531P
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

18/3/19

10 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

CONFIDENTIAL

Annex E

NOTICE OF REPORTING

This is to confirm that A1) Fo Wai Cheng NRIC/FIN S6924024J, has reported to the Police a non-injury traffic accident which occurred T-Junction of Bukit Batok East Ave 2 and Bukit Batok East Ave 2 on 17/03/2019 at 1030hrs involving the following vehicles:

V1. SJE2308E – belongs to A1

V2. SME6531P – belongs to A2) Jenkins Tan Geik Koon S1381141E, HP: 86088584

2. If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Facts:

On 17/30/2019 at 1030hrs, A1 was driving her vehicle bearing plate number of SJE2308E and wanting to turn right into Bukit Batok East Ave 2 at the T-Junction of Bukit Batok East Ave 2 and Bukit Batok East Ave 2/Hillview Ave. A1 proceeded and stopped before the pedestrian traffic light as she saw a man cycling across the pedestrian traffic light. When he cycled onto the road, the pedestrian traffic turns red and he continued to cycle. After A1 stopped, A2's vehicle came and collided onto the rear of A1's vehicle. No one was injured. No ambulance and traffic police at scene. Both driver exchanged particulars. A1's vehicle sustained dent and scratches on its left rear bumper. A1 has in-car video camera in her car. No government property damaged.

Rank/Name of Issuing Officer: SSSgt Danny Ang

Date: 17/03/2019 Time: 2317hrs

S/D Ref: 148

Police Post/Unit: Bukit Batok NPC

BUKIT BATOK NPC
BUKIT BATOK EAST AVE 2
SINGAPORE 659820
Tel: 65984025

FO WAI CHENG

S 6924024J

[Signature]

Original - to be issued to informant
Duplicate - to be submitted to Traffic Police

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 28/3/2019
 VEHICLE NO: SJE2308E
 MODEL: TOYOTA ALLION
 YEAR: 2008-2027
 ACCIDENT DATE: 17/3/2019
 TYPE OF CLAIM: TP CLAIM
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	\$ 979.20 X
BOOTLID LOCK		\$ 214.30 X
REAR EMBLEM	1	\$ 65.70 X
REAR LOGO - ALLION	1	\$ 61.30 X
LH TAILLAMP	1	\$ 497.80 <i>cut</i> ✓
LH TAILLAMP PANEL R	1	RESTORE
REAR BUMPER	1	\$ 857.30 <i>de</i> ✓
REAR BUMPER CLIPS	10	\$ 30.00 <i>ner</i> ✓
REAR BUMPER RETAINER	2	\$ 49.30 98.60 <i>LH ner, RH →</i>
LH REAR BUMPER REFLECTOR	1	\$ 113 396.80 <i>ner</i> ✓
END PANEL	1	\$ 564.20 <i>R.20</i>
SPARE TYRE PANEL R	1	RESTORE
REAR WEATHER STRIP	1	\$ 299.70 X <i>hn</i>
END PANEL TOP GARNISH	1	\$ 214.30 X <i>uh</i>
LH REAR FENDER R	1	RESTORE
TOTAL:		\$ 4,279.20
DISCOUNT 25%:		\$ 1,069.80
		<u>\$ 3,209.40</u>

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 28/3/2019
 VEHICLE NO: SJE2308E
 MODEL: TOYOTA ALLION
 YEAR: 2008-2027
 ACCIDENT DATE: 17/3/2019
 TYPE OF CLAIM: TP CLAIM
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

S/NET		PRICE
END PANEL SEALANT	1	\$ 80.00 $\times m$
REVERSE SENSOR	1	\$ 250.00 $200? \times m$
		\$ 330.00

LABOUR		PRICE
LABOUR FOR FACILITATE REPAIR - REAR		\$ 1,300.00 300
TO RESPRAY AFFECTED AREAS - REAR BUMPER		\$ 300.00 200
TO RESPRAY AFFECTED AREAS - LH REAR FENDER AND LH TAILLAMP PANEL ✓		\$ 300.00 100
TO RESPRAY AFFECTED AREAS - END PANEL		\$ 300.00 $200? photo$
TO RESPRAY AFFECTED AREAS - SPARE TYRE PANEL		\$ 300.00 $\times m$
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR		\$ 250.00 40
RUST PROOFING		\$ 80.00 $\times m$
SUNDARIES		\$ 50.00 $20 \times$
TO CHECK AND RECONNECT ALL NECESSARY WIRING		\$ 50.00 30
		TOTAL: \$ 2,930.00

TOTAL: \$ 6,469.40
 7% GST: \$ 452.86
\$ 6,922.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
29/3/19

Tanglin 97495749

haupin @ lkhantow.com

2 delays 26/3/19 @ 1730

Resurvey after repair

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 28/3/2019
 VEHICLE NO: SJE2308E
 MODEL: TOYOTA ALLION
 YEAR: 2008-2027
 ACCIDENT DATE: 17/3/2019
 TYPE OF CLAIM: TP CLAIM
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	\$ X 979.20 X
BOOTLID LOCK		\$ X 214.30 Y
REAR EMBLEM	1	\$ X 65.70 X
REAR LOGO - ALLION	1	\$ X 61.30 X
LH TAILLAMP	1	\$ ✓ 497.80 cut ✓
LH TAILLAMP PANEL	1	RESTORE
REAR BUMPER	1	\$ ✓ 857.30 dl ✓
REAR BUMPER CLIPS	10	\$ ✓ 30.00 us ✓
REAR BUMPER RETAINER	2	(49.30) \$ ✓ 98.60 LH-wei, RH- ✓
LH REAR BUMPER REFLECTOR	1	\$ - 398.80 arc ✓ 198.40
END PANEL	1	\$ R 564.20 P.w
SPARE TYRE PANEL	1	RESTORE
REAR WEATHER STRIP	1	\$ X 299.70 X
END PANEL TOP GARNISH	1	\$ X 214.30 X
LH REAR FENDER	1	RESTORE
TOTAL:	\$	4,279.20
DISCOUNT 25%:	\$	1,069.80
	\$	<u>3,209.40</u>
		1,632.80
		25%
		<u>1,224.60</u>

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: NTUC INCOME INSURANCE

DATE: 28/3/2019
 VEHICLE NO: SJE2308E
 MODEL: TOYOTA ALLION
 YEAR: 2008-2027
 ACCIDENT DATE: 17/3/2019
 TYPE OF CLAIM: TP CLAIM
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

S/NET

		PRICE
END PANEL SEALANT	1	\$ X 80.00 X
REVERSE SENSOR	1	\$ 250.00 200? X
		<u>\$ 330.00</u>

LABOUR

	PRICE
LABOUR FOR FACILITATE REPAIR - REAR	\$ 1,300.00 300
TO RESPRAY AFFECTED AREAS - REAR BUMPER	\$ 300.00 200
TO RESPRAY AFFECTED AREAS - LH REAR FENDER AND LH TAILLAMP PANEL ✓	\$ 300.00 100
TO RESPRAY AFFECTED AREAS - END PANEL	\$ 300.00 200? photo (100) repair.
TO RESPRAY AFFECTED AREAS - SPARE TYRE PANEL	\$ 300.00 X
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$ 250.00 40
RUST PROOFING	\$ 80.00 X
SUNDARIES	\$ 50.00 20 790
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$ 50.00 30

TOTAL: \$ 2,930.00

TOTAL: \$ 6,469.40

7% GST: \$ 452.86

\$ 6,922.26

2,014.60

LS: 1,600

③ days.

Tanjit 97495149

fanfian @ hhandan.com

03 days 26/3/19 1730

Resny offer wip4b

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 1 April 2019 4:11 PM
To: 'louisongautowheels@yahoo.com'; Taufikh (LKKAuto); SUR
Subject: RE: Finalize for vehicle SJE2308E lumpsum \$1,600 with 3 repair days.

Dear Louis,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Monday, 1 April 2019 4:08 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Finalize for vehicle SJE2308E lumpsum \$1,600 with 3 repair days.

Hi,

We agreed with the amount.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

On Mon, 1 Apr 2019 at 16:05, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Louis,

WITHOUT PREJUDICE

Offer Lump Sum \$1500/- @ 3 working days.

LH rear bumper reflector-price revised to \$113

Parts -\$1547.40 (less 25%)=\$1160.55

Labour-\$770.00

Total -\$1930.55 (less 20%)=\$ 1544.44

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Saturday, 30 March 2019 12:52 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Finalize for vehicle SJE2308E lumpsum \$1,600 with 3 repair days.

Hi,

The above attachment is the finalize and after paint photo.

Can help to finalize for vehicle SJE2308E lumpsum \$1,600 with 3 repair days.

No Supplementary.

Thanks

Auto Wheels Motorworks PTE LTD

Louis Ong

91928963



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19005362/T1vd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 10-04-2019



ATTN: ERIC TANG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SME 6531P	Veh. Inspected	SJE 2308E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1036315-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	26/03/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALLION 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZT2603022870	Colour	BLACK
Odometer	217870 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/03/2019	Inspect Date / Time	26/03/2019 (05:30 PM)
Survey held at	AUTO WHEELS MOTORWORKS PTE LTD NO 1 BUKIT BATOK CRESCENT #02-40 WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 2308E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	NOT NECESSARY	979.20	-
1	BOOTLID LOCK	NOT NECESSARY	214.30	-
1	REAR EMBLEM	NOT NECESSARY	65.70	-
1	REAR LOGO - ALLION	NOT NECESSARY	61.30	-
1	LH TAILLAMP	CUT	497.80	497.80
1	LH TAILLAMP PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER	DEFORMED	857.30	857.30
10	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER RETAINER	N/S NECESSARY / O/S NOT NECESSARY	98.60	49.30
1	LH REAR BUMPER REFLECTOR	CRACKED	396.80	113.00
1	END PANEL	TO REPAIR SEE LABOUR	564.20	-
1	SPARE TYRE PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR WEATHER STRIP	NOT NECESSARY	299.70	-
1	END PANEL TOP GARNISH	NOT NECESSARY	214.30	-
1	LH REAR FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-1,069.80	-386.85
			3,209.40	1,160.55
<u>SPECIAL NETT ITEMS</u>				
1	END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			380.00	-
<u>LABOUR</u>				
	LABOUR FOR FACILITATE REPAIR - REAR. INCLUSIVE OF THE REPAIR OF LH TAILLAMP PANEL, END PANEL, SPARE TYRE PANEL AND LH REAR FENDER.		1,300.00	300.00
	TO RESPRAY AFFECTED AREAS - REAR BUMPER.		300.00	200.00

Report Ref No. CS/INC19005362/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY AFFECTED AREAS - LH REAR FENDER AND LH TAILLAMP PANEL.		300.00	100.00
	TO RESPRAY AFFECTED AREAS - END PANEL.		300.00	100.00
	TO RESPRAY AFFECTED AREAS - SPARE TYRE PANEL.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR.		250.00	40.00
	RUST PROOFING.	NOT NECESSARY	80.00	-
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		50.00	30.00
			2,880.00	770.00
GRAND TOTAL			6,469.40	1,930.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,500.00

Report Ref No. CS/INC19005362/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.