

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2019 Edit Reg		26 Mar 2019 00:00 Edit Adj Rpt	S\$23,000.00 Edit Estimates	S\$23,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Main Claimant: SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K									
Vehicle Reg. No.: SHC4127G		Date of Loss: 23/03/2019 05:00 - :59 [38 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MCT19030583		Policy/Cover Note No.: MCOM0015							
Vehicle Reg. No. (Insured): SHC2575J		Policy No. (Claimant): D-18090213MFSH							
		Excess:							
Repairer: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]									
Claimant's Insurer: MS First Capital Insurance Ltd (HQ) - Tel: 62222311									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 04/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (15/09/2020): Alert - Adj Mandate Approved (S\$35102.40) - SHC4127G - Claim Handler: Priya - III_SG (04/09/2020): Alert - Adj Mandate Maintained - SHC4127G - Claim Handler: Priya - III_SG (05/12/2019): Alert - Adj Mandate Maintained - SHC4127G - Claim Handler: Priya - III_SG (18/06/2019): Alert - Adj Mandate Approved (S\$0.00) - SHC4127G - Claim Handler: Priya - III_SG (01/04/2019): Alert - Adj Mandate Maintained - SHC4127G - Claim Handler: Priya									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC4127G (MCT19030583)**
[SHC2575J]
TP
SMRT TAXIS PTE LTD
Mar 23 2019 5:00AM
[COMFORT TRANSPORTATION PTE LTD]
SMRT Automotive Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	18/06/19 09:35	Video - Accident	 Load MP4	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/03/19 08:47	General View	 Load JPG	☒
2	29/03/19 08:47	General View	 Load JPG	☒
3	29/03/19 08:47	General View	 Load JPG	☒
4	29/03/19 08:47	General View	 Load JPG	☒
5	29/03/19 08:47	General View	 Load JPG	☒
6	29/03/19 08:47	General View	 Load JPG	☒
7	29/03/19 08:47	General View	 Load JPG	☒
8	29/03/19 08:47	General View	 Load JPG	☒
9	29/03/19 08:47	General View	 Load JPG	☒
10	29/03/19 08:47	General View	 Load JPG	☒
11	29/03/19 08:47	General View	 Load JPG	☒
12	29/03/19 08:47	General View	 Load JPG	☒
13	29/03/19 08:47	General View	 Load JPG	☒
14	29/03/19 08:47	General View	 Load JPG	☒
15	29/03/19 08:47	General View	 Load JPG	☒
16	29/03/19 08:47	General View	 Load JPG	☒
17	29/03/19 08:47	General View	 Load JPG	☒
18	29/03/19 08:47	General View	 Load JPG	☒
19	29/03/19 08:47	General View	 Load JPG	☒
20	29/03/19 08:47	General View	 Load JPG	☒
21	29/03/19 08:47	General View	 Load JPG	☒
22	29/03/19 08:47	General View	 Load JPG	☒
23	29/03/19 08:47	General View	 Load JPG	☒
24	29/03/19 08:47	General View	 Load JPG	☒
25	29/03/19 08:47	General View	 Load JPG	☒
26	29/03/19 08:47	General View	 Load JPG	☒
27	29/03/19 08:47	General View	 Load JPG	☒
28	29/03/19 08:47	General View	 Load JPG	☒
29	29/03/19 08:47	General View	 Load JPG	☒
30	29/03/19 08:47	General View	 Load JPG	☒
31	29/03/19 08:47	General View	 Load JPG	☒
32	29/03/19 08:47	General View	 Load JPG	☒
33	29/03/19 08:47	General View	 Load JPG	☒
34	29/03/19 08:47	General View	 Load JPG	☒
35	29/03/19 08:47	General View	 Load JPG	☒
36	29/03/19 08:47	General View	 Load JPG	☒
37	29/03/19 08:47	General View	 Load JPG	☒

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
38	29/03/19 08:47	General View		Load JPG	☒
39	29/03/19 08:47	General View		Load JPG	☒
40	29/03/19 08:47	General View		Load JPG	☒
41	29/03/19 08:47	General View		Load JPG	☒
42	29/03/19 08:47	General View		Load JPG	☒
43	29/03/19 08:47	General View		Load JPG	☒
44	29/03/19 08:47	General View		Load JPG	☒
45	29/03/19 08:47	General View		Load JPG	☒
46	29/03/19 08:47	General View		Load JPG	☒
47	29/03/19 08:47	General View		Load JPG	☒
48	29/03/19 08:47	General View		Load JPG	☒
49	29/03/19 08:47	General View		Load JPG	☒
50	29/03/19 08:47	General View		Load JPG	☒
51	29/03/19 08:47	General View		Load JPG	☒
52	29/03/19 08:47	General View		Load JPG	☒
53	29/03/19 08:47	General View		Load JPG	☒
54	29/03/19 08:47	General View		Load JPG	☒
55	29/03/19 08:47	General View		Load JPG	☒
56	29/03/19 08:47	General View		Load JPG	☒
57	29/03/19 08:47	General View		Load JPG	☒
58	29/03/19 08:47	General View		Load JPG	☒
59	29/03/19 08:47	General View		Load JPG	☒
60	29/03/19 08:47	General View		Load JPG	☒
61	29/03/19 08:47	General View		Load JPG	☒
62	29/03/19 08:47	General View		Load JPG	☒
63	29/03/19 08:47	General View		Load JPG	☒
64	29/03/19 08:47	General View		Load JPG	☒
65	29/03/19 08:47	General View		Load JPG	☒
66	29/03/19 08:47	General View		Load JPG	☒
67	29/03/19 08:47	General View		Load JPG	☒
68	29/03/19 08:47	General View		Load JPG	☒
69	29/03/19 08:47	General View		Load JPG	☒
70	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
71	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
72	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
73	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
74	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
75	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
76	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
77	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
78	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
79	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
80	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
81	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
82	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
83	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
84	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
85	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
86	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
87	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
88	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
89	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
90	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
91	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
92	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
93	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
94	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
95	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
96	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
97	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
98	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
99	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
100	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
101	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
102	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
103	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
104	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
105	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
106	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
107	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
108	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
109	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
110	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
111	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
112	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
113	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
114	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
115	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
116	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
117	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
118	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
119	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
120	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
121	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
122	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
123	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
124	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
125	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
126	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
127	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
128	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
129	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
130	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
131	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
132	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
133	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
134	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
135	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
136	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
137	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
138	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
139	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
140	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
141	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
142	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
143	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
144	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
145	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
146	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
147	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
148	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
149	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
150	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
151	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
152	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
153	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
154	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
155	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
156	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
157	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
158	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
159	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
160	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
161	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
162	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
163	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
164	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
165	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
166	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
167	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
168	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
169	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
170	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
171	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
172	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
173	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
174	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
175	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
176	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
177	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
178	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
179	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
180	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
181	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
182	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
183	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
184	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
185	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
186	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
187	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
188	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
189	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
190	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
191	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
192	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
193	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
194	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
195	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒
196	19/09/19 10:53	Photographs of Damaged Items	 Load JPG	☒

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
197	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
198	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
199	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
200	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
201	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
202	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
203	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
204	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
205	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
206	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
207	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
208	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
209	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
210	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
211	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
212	19/09/19 10:53	Photographs of Damaged Items		Load JPG	☒
213	19/09/19 10:54	After Repair Photo		Load JPG	☒
214	19/09/19 10:54	After Repair Photo		Load JPG	☒
215	19/09/19 10:54	After Repair Photo		Load JPG	☒
216	19/09/19 10:54	After Repair Photo		Load JPG	☒
217	19/09/19 10:54	After Repair Photo		Load JPG	☒
218	19/09/19 10:54	After Repair Photo		Load JPG	☒
219	19/09/19 10:54	After Repair Photo		Load JPG	☒
220	19/09/19 10:54	After Repair Photo		Load JPG	☒
221	19/09/19 10:54	After Repair Photo		Load JPG	☒
222	19/09/19 10:54	After Repair Photo		Load JPG	☒
223	19/09/19 10:54	After Repair Photo		Load JPG	☒
224	19/09/19 10:54	After Repair Photo		Load JPG	☒
225	19/09/19 10:54	After Repair Photo		Load JPG	☒
226	19/09/19 10:54	After Repair Photo		Load JPG	☒
227	19/09/19 10:54	After Repair Photo		Load JPG	☒
228	19/09/19 10:54	After Repair Photo		Load JPG	☒
229	19/09/19 10:54	After Repair Photo		Load JPG	☒
230	19/09/19 10:54	After Repair Photo		Load JPG	☒
231	19/09/19 10:54	After Repair Photo		Load JPG	☒
232	19/09/19 10:54	After Repair Photo		Load JPG	☒
233	19/09/19 10:54	After Repair Photo		Load JPG	☒
234	19/09/19 10:54	After Repair Photo		Load JPG	☒
235	19/09/19 10:54	After Repair Photo		Load JPG	☒
236	19/09/19 10:54	After Repair Photo		Load JPG	☒
237	19/09/19 10:54	After Repair Photo		Load JPG	☒
238	19/09/19 10:54	After Repair Photo		Load JPG	☒
239	19/09/19 10:54	After Repair Photo		Load JPG	☒
240	19/09/19 10:54	After Repair Photo		Load JPG	☒
241	19/09/19 10:54	After Repair Photo		Load JPG	☒
242	19/09/19 10:54	After Repair Photo		Load JPG	☒
243	19/09/19 10:54	After Repair Photo		Load JPG	☒
244	19/09/19 10:54	After Repair Photo		Load JPG	☒
245	19/09/19 10:54	After Repair Photo		Load JPG	☒
246	19/09/19 10:54	After Repair Photo		Load JPG	☒
247	19/09/19 10:54	After Repair Photo		Load JPG	☒
248	19/09/19 10:54	After Repair Photo		Load JPG	☒
249	19/09/19 10:54	After Repair Photo		Load JPG	☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
250	19/09/19 10:54	After Repair Photo		Load JPG ☒
251	19/09/19 10:54	After Repair Photo		Load JPG ☒
252	19/09/19 10:54	After Repair Photo		Load JPG ☒
253	19/09/19 10:54	After Repair Photo		Load JPG ☒
254	19/09/19 10:54	After Repair Photo		Load JPG ☒
255	19/09/19 10:54	After Repair Photo		Load JPG ☒
256	19/09/19 10:54	After Repair Photo		Load JPG ☒
257	19/09/19 10:54	After Repair Photo		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	26/03/19 14:39	EMAIL FROM III DD 26032019		Load PDF
2	26/03/19 14:39	TP GIA REPORT		Load PDF
3	28/03/19 17:54	TP ESTIMATE- MARKED		Load PDF
4	28/11/19 09:08	Workshop Invoice		Load PDF
5	28/11/19 09:08	Rental Rate & Mileage		Load PDF
6	28/11/19 09:08	Letter From Borneo Motors (For parts)		Load PDF
7	28/11/19 09:11	PARF_COE REBATE		Load PDF
8	27/08/20 12:14	DO INVOICE (for parts)		Load PDF
9	24/09/20 10:06	Authorisation to Act		Load PDF
10	24/09/20 10:06	DISCHARGE VOUCHER		Load PDF
11	24/09/20 10:06	LOD		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	27/03/19 08:59	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19005370/EPS3S2**Date:** 24/09/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHC4127G	Insured Vehicle No :	SHC2575J
Date of Loss:	23/03/2019	Nature of Claim:	TP
		Claim No:	MCT19030583

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4127G		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR6574894
Reg. Date:	22/01/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U005767288
Colour:	Maroon	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	84,474.72	41,726.91	42,747.81	50.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,896.00	4,290.00	5,606.00	56.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	94,370.72	46,016.91	48,353.81	51.24
Approved Total (Overridden) (S\$)		23,000.00		
Nett Amount (S\$)	94,370.72	23,000.00	71,370.72	75.63
+ Loss of Use (70.0 x S\$40.00/day) (S\$)		2,800.00		
+ Car Rental (70.0 x S\$111.28/day) (S\$)		7,789.60		
Nett Liability (S\$)		33,589.60		
Global Sum Settlement (S\$)		33,500.00		

INSPECTION

Date of Assignment:	26/03/2019	
Date Inspected:	26/03/2019	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	17.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Book Value: \$55,000.00(est) less LTA Rebate: \$31,031.00(est) = Nett Book Value :\$23,969.00(est)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2020)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4127G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HORN ASSY, HIGH (DISC 25%)	Bent	110.40 F	*82.80 F
2	1		*HORN ASSY, LOW (DISC 25%)	Bent	110.40 F	*82.80 F
3	1		*DEFLECTOR, RADIATOR LH (DISC 25%)	Crushed	77.00 F	*57.75 F
4	1		*DEFLECTOR, RADIATOR RH (DISC 25%)	Crushed	83.50 F	*62.63 F
5	1		*A/C CONDENSER (DISC 25%)	Dented	1,181.90 F	*886.43 F
6	1		*TUBE & ACCESSORY (DISC 25%)	Bent	631.90 F	*473.93 F
7	1		*COVER, CYLINDER (DISC 25%)	Broken	165.20 F	*123.90 F
8	1		*AIR CLEANER ASSY (DISC 25%)	Broken	929.90 F	*697.43 F
9	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
10	1		*FENDER LINER FRT/LH (DISC 25%)	Torn	171.70 F	*128.78 F
11	1		*FENDER FRT/RH (DISC 25%)	Dented	723.40 F	*542.55 F
12	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
13	1		*FENDER LINER FRT/RH (DISC 25%)	Missing	171.70 F	*128.78 F
14	1		*FENDER LINER PAD, FR WHEEL, RH (DISC 25%)	Missing	49.30 F	*36.98 F
15	1		*BUMPER FRT (DISC 25%)	Broken	482.00 F	*361.50 F
16	1		*BUMPER CLIPS (DISC 25%) 10pcs	Necessary	16.10 F	*12.08 F
17	1		*BUMPER ENERGY ABSORBER FRT (DISC 25%)	Broken	78.80 F	*59.10 F
18	1		*BUMPER REINFORCEMENT FRT (DISC 25%)	Dented	498.40 F	*373.80 F
19	1		*ARM SUB-ASSY, FR BUMPER LH (DISC 25%)	Dented	250.40 F	*187.80 F
20	1		*ARM SUB-ASSY, FR BUMPER RH (DISC 25%)	Dented	250.40 F	*187.80 F
21	1		*BRACKET, FR BUMPER (DISC 25%)	Dented	110.40 F	*82.80 F
22	1		*BUMPER SUPPORT F/LH (DISC 25%)	Broken	76.40 F	*57.30 F
23	1		*COVER, FR BUMPER HOLE LH (DISC 25%)	Missing	18.50 F	*13.88 F
24	1		*COVER, FR BUMPER HOLE RH (DISC 25%)	Missing	18.50 F	*13.88 F
25	1		*BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	Cut	311.10 F	*233.33 F
26	1		*EMBLEM FRONT (DISC 25%)	Necessary	86.50 F	*64.88 F
27	1		*BUMPER LIP FRT (DISC 25%)	Cut	139.60 F	*104.70 F
28	1		*BUMPER FRT ABSORBER LOWER (DISC 25%)	Broken	127.70 F	*95.78 F
29	1		*HOOD PANEL (DISC 25%)	Dented	748.10 F	*561.08 F
30	1		*HOOD HINGE LH (DISC 25%)	Bent	55.90 F	*41.93 F
31	1		*HOOD HINGE RH (DISC 25%)	Bent	55.90 F	*41.93 F
32	1		*WINDSCREEN MOULDING FRT (DISC 25%)	Necessary	57.60 F	*43.20 F
33	1		*WINDSCREEN FRT (DISC 25%)	Broken	1,543.80 F	*1,157.85 F
34	1		*SUPPORT SUB-ASSY (DISC 25%)	Dented	1,460.40 F	*1,095.30 F
35	1		*SEAT BELT FRT/LH (DISC 25%)	Jammed	822.60 F	*616.95 F
36	1		*SEAT BELT FRT/RH (DISC 25%)	Jammed	822.60 F	*616.95 F
37	1		*HOSE. INVETER NO.1 (DISC 25%)	Crushed	80.00 F	*60.00 F
38	1		*HOSE SUB-ASSY, DISCHARGE (DISC 25%)	Crushed	386.90 F	*290.18 F
39	1		*HOSE SUB-ASSY, SUCTION (DISC 25%)	Crushed	405.40 F	*304.05 F
40	1		*RADIATOR ASSY (DISC 25%)	Dented	1,496.90 F	*1,122.68 F
41	1		*RADIATOR ASSY, UPPER (DISC 25%)	Dented	679.60 F	*509.70 F
42	1		*RADIATOR LOWER SUPPORT (DISC 25%)	Crushed	876.30 F	*657.23 F
43	1		*RADIATOR HOSE BYPASS NO.2 (DISC 25%)	Crushed	29.00 F	*21.75 F
44	1		*COOLANT RESERVE TANK (DISC 25%)	Necessary	395.30 F	*296.48 F
45	1		*FAN BLADE (DISC 25%)	Cut	158.60 F	*118.95 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*FAN BLADE NO.2 (DISC 25%)	Cut	204.20 F	*153.15 F
47	1		*FAN SHROUD (DISC 25%)	Broken	244.50 F	*183.38 F
48	1		*FAN SHROUD TOP (DISC 25%)	Broken	99.60 F	*74.70 F
49	1		*SIDE CHASSIC FRT/RH (DISC 25%)	Dented	173.50 F	*130.13 F
50	1		*UNDER COVER CENTER (DISC 25%)	Broken	448.30 F	*336.23 F
51	1		*MEMBER SUB-ASSY, FR RH (DISC 25%)	Dented	810.70 F	*608.03 F
52	1		*INLET ASSY, AIR (DISC 25%)	Broken	232.50 F	*174.38 F
53	1		*WIPER WASHER INLET (DISC 25%)	Broken	36.90 F	*27.68 F
54	1		*WIPER WASHER JAR (DISC 25%)	Broken	180.10 F	*135.08 F
55	1		*FENDER APRON SUB FRT/RH (DISC 25%)	Dented	637.80 F	*478.35 F
56	1		*DASH BOARD (DISC 25%)	Broken	906.10 F	*679.58 F
57	1		*COVER STEERING, LOWER (DISC 25%)	Broken	116.30 F	*87.23 F
58	1		*BUMPER SUPPORT F/RH (DISC 25%)	Broken	76.40 F	*57.30 F
59	1		*BRACKET, FR TURN LOWER RH (DISC 25%)	Broken	26.00 F	*19.50 F
60	1		*GRILLE RADIATOR LOWER NO.2 (DISC 25%)	Broken	94.60 F	*70.95 F
61	1		*GRILLE RADIATOR (DISC 25%)	Broken	310.60 F	*232.95 F
62	1		*HOOD LOCK (DISC 25%)	Bent	128.90 F	*96.68 F
63	1		*HOOD PANEL INSULATOR (DISC 25%)	Torn	390.50 F	*292.88 F
64	1		*CABLE ASSY, HOOD (DISC 25%)	Torn	52.20 F	*39.15 F
65	1		*WIPER GARNISH (DISC 25%)	Broken	614.00 F	*460.50 F
66	1		*WIPER GARNISH COVER, LH (DISC 25%)	Cut	23.80 F	*17.85 F
67	1		*WIPER GARNISH COVER, RH (DISC 25%)	Cut	23.80 F	*17.85 F
68	1		*INVERTER BRACKET TRAY (DISC 25%)	Bent	251.60 F	*188.70 F
69	1		*BOX ASSY, CONSOLE, REAR (DISC 25%)	Broken	1,734.60 F	*1,300.95 F
70	1		*BODY ASSY, THROTTLE (DISC 25%)	Broken	1,925.30 F	*1,443.98 F
71	1		*ENGINE MOUNTING FRT (DISC 25%)	Bent	198.00 F	*148.50 F
72	1		*AIR BAG ASSY, INSTR DRIVER (DISC 10%)	Broken	1,555.80 F	*1,400.22 F
73	1		*AIR BAG COMPUTER (DISC 10%)	Necessary	815.20 F	*733.68 F
74	1		*AIR BAG SPIRAL CABLE (DISC 10%)	Necessary	953.70 F	*858.33 F
75	1		*AIR BAG STEERING DRIVER (DISC 10%)	Broken	2,360.40 F	*2,124.36 F
76	1		*AIR BAG ASSY, INSTR / PASSENGER (DISC 10%)	Broken	3,177.00 F	*2,859.30 F
77	1		*WIRE ASSY, AIR BAG (DISC 10%)	Necessary	23.60 F	*21.24 F
78	2		*SENSOR, AIR BAG FRT/RH/LH (DISC 10%)	Necessary	546.60 F	*491.94 F
79	1		*SWITCH ASSY, HEAD LAMP (DISC 10%)	Broken	318.40 F	*286.56 F
80	1		*SWITCH ASSY, WINDSHIELD WIPER (DISC 10%)	Broken	350.50 F	*315.45 F
81	1		*HEAD LAMP LH (DISC 10%)	Missing	945.20 F	*850.68 F
82	1		*HEAD LAMP RH (DISC 10%)	Broken	945.20 F	*850.68 F
83	1		*FAN MOTOR NO.1 (DISC 10%)	Dented	538.30 F	*484.47 F
84	1		*FAN MOTOR NO.2 (DISC 10%)	Dented	538.30 F	*484.47 F
85	1		*FOG LAMP LH (DISC 10%)	Broken	280.10 F	*252.09 F
86	1		*FOG LAMP RH (DISC 10%)	Broken	295.20 F	*265.68 F
87	1		*LENS & BODY, FR TURN RH (DISC 10%)	Broken	511.80 F	*460.62 F
88	1		*LENS & BODY, FR TURN LH (DISC 10%)	Broken	511.80 F	*460.62 F
89	1		*WIRE, ENGINE ROOM, NO.3 (DISC 10%)	Broken / Torn	242.00 F	*217.80 F
90	1		*INVERTER W CONVERTER (DISC 10%)	Bent	5,390.20 F	*4,851.18 F
91	1		*WIRE, ENGINE (DISC 10%)	Broken / Torn	1,889.50 F	*1,700.55 F
92	1		*PUMP ASSY WATER, ELECTRIC (DISC 10%)	Broken	989.50 F	*890.55 F
93	1		*COOLANT (SN)	Necessary	12.32 F	*12.32 F
94	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
95	1		*NUMBER PLATE (SN)	Missing	15.00 F	*15.00 F
96	1		*NUMBER PLATE FRAME (SN)	Missing	12.00 F	*12.00 F
97	2		*SEALANT W/SCREEN (SN)	Necessary	74.00 F	*74.00 F
98	1		*HOSE, INVERTER COOLING NO.2	Not Necessary	90.10 F	*- F
99	1		*HOSE, INVERTER COOLING NO.5	Not Necessary	125.30 F	*- F
100	1		*HOSE, INVERTER COOLING NO.6	Not Necessary	37.40 F	*- F
101	1		*HOSE, INVERTER NO.1	Not Necessary	80.00 F	*- F
102	1		*PUMP ASSY, WATER	Not Necessary	454.00 F	*- F
103	1		*HOSE SUB-ASSY, DISCHARGE	Not Necessary	386.90 F	*- F
104	1		*HOSE SUB-ASSY, SUCTION	Not Necessary	405.40 F	*- F
105	1		*TUBE SUB-ASSY, SUCTION	Not Necessary	371.40 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
106	1		*RADIATOR ASSY	Not Necessary	1,496.90 F	*- F
107	1		*RADIATOR ASSY, UPPER	Not Necessary	679.60 F	*- F
108	1		*RADIATOR LOWER SUPPORT	Not Necessary	876.30 F	*- F
109	1		*SUPPORT, RADIATOR	Not Necessary	18.50 F	*- F
110	1		*SUPPORT, RADIATOR, LH	Not Necessary	17.70 F	*- F
111	1		*SUPPORT, RADIATOR, RH	Not Necessary	54.50 F	*- F
112	1		*CUSHION, RADIATOR	Not Necessary	11.30 F	*- F
113	1		*RADIATOR TOP HOSE NO.1	Not Necessary	42.40 F	*- F
114	1		*RADIATOR HOSE LOWER	Not Necessary	42.40 F	*- F
115	1		*RADIATOR HOSE, BYPASS NO.1	Not Necessary	37.20 F	*- F
116	1		*RADIATOR HOSE, BYPASS NO.2	Not Necessary	29.00 F	*- F
117	1		*RADIATOR HOSE, BYPASS NO.3	Not Necessary	37.20 F	*- F
118	1		*RADIATOR HOSE, BYPASS NO.4	Not Necessary	37.20 F	*- F
119	1		*COOLANT RESERVE TANK	Not Necessary	395.30 F	*- F
120	1		*FAN BLADE	Not Necessary	158.60 F	*- F
121	1		*FAN BLADE NO.2	Not Necessary	204.20 F	*- F
122	1		*FAN MOTOR NO.1	Not Necessary	538.30 F	*- F
123	1		*FAN MOTOR NO.2	Not Necessary	538.30 F	*- F
124	1		*FAN SHROUD	Not Necessary	244.50 F	*- F
125	1		*FAN SHROUD TOP	Not Necessary	99.60 F	*- F
126	1		*MEMBER FRT, SUB CENTRE	Not Necessary	65.00 F	*- F
127	1		*SIDE CHASSIC FRT/LH	Not Necessary	172.90 F	*- F
128	1		*SIDE CHASSIC FRT/RH	Not Necessary	173.50 F	*- F
129	1		*UNDER COVER CENTER	Not Necessary	448.30 F	*- F
130	1		*MEMBER SUB-ASSY, FR LH	Not Necessary	810.70 F	*- F
131	1		*MEMBER SUB-ASSY, FR RH	Not Necessary	810.70 F	*- F
132	1		*INLET ASSY, AIR	Not Necessary	232.50 F	*- F
133	1		*RESONATOR, INTAKE	Not Necessary	57.20 F	*- F
134	1		*WIPER WASHER INLET	Not Necessary	36.90 F	*- F
135	1		*WIPER WASHER JAR	Not Necessary	180.10 F	*- F
136	1		*FENDER INNER PAD, FR WHEEL LH	Not Necessary	49.30 F	*- F
137	1		*PROTECTOR, FRONT FENDER SIDE PANEL LH	Not Necessary	114.50 F	*- F
138	1		*FENDER PROTECTOR FRT/RH SIDE	Not Necessary	113.90 F	*- F
139	1		*FENDER APRON SUB FRT/RH	Not Necessary	637.80 F	*- F
140	1		*QUARTER GLASS FRT/RH	Not Necessary	234.90 F	*- F
141	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
142	1		*FENDER APRON SUB FRT/LH	Not Necessary	637.80 F	*- F
143	1		*DASH BOARD	Not Necessary	906.10 F	*- F
144	1		*COVER, STEERING LOWER	Not Necessary	116.30 F	*- F
145	1		*COVER, STEERING UPPER	Not Necessary	77.00 F	*- F
146	1		*BUMPER SUPPORT F/RH	Not Necessary	76.40 F	*- F
147	1		*FOG LAMP LH	Not Necessary	280.10 F	*- F
148	1		*FOG LAMP RH	Not Necessary	295.20 F	*- F
149	1		*BRACKET, FR TURN LOWER RH	Not Necessary	26.00 F	*- F
150	1		*BRACKET, FR TURN UPPER RH	Not Necessary	24.40 F	*- F
151	1		*LENS & BODY, FR TURN RH	Not Necessary	511.80 F	*- F
152	1		*BRACKET, FR TURN CENTER LH	Not Necessary	58.20 F	*- F
153	1		*BRACKET, FR TURN LOWER LH	Not Necessary	26.00 F	*- F
154	1		*BRACKET, FR TURN UPPER LH	Not Necessary	24.40 F	*- F
155	1		*LENS & BODY, FR TURN LH	Not Necessary	511.80 F	*- F
156	1		*GRILLE RADIATOR LOWER NO.2	Not Necessary	94.60 F	*- F
157	1		*GRILLE RADIATOR	Not Necessary	310.60 F	*- F
158	1		*WIRE, ENGINE ROOM, NO.3	Not Necessary	242.00 F	*- F
159	1		*THERMISTOR ASSY	Not Necessary	107.00 F	*- F
160	1		*HOOD END PANEL SEAL	Not Necessary	35.50 F	*- F
161	1		*HOOD LOCK	Not Necessary	128.90 F	*- F
162	1		*HOOD PANEL INSULATOR	Not Necessary	390.50 F	*- F
163	1		*CABLE ASSY, HOOD	Not Necessary	52.20 F	*- F
164	1		*CLAMP, HOOD LOCK	Not Necessary	5.90 F	*- F
165	1		*HOSE WINDSHIELD WASHER (FROM JOINT TO)	Not Necessary	13.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
166	1		*HOSE WINDSHIELD WASHER (FROM JOINT TO)	Not Necessary	13.60 F	*- F
167	1		*HOSE WINDSHIELD WASHER (FROM JOINT TO)	Not Necessary	13.60 F	*- F
168	1		*WIPER GARNISH	Not Necessary	614.00 F	*- F
169	1		*WIPER GARNISH COVER, LH	Not Necessary	23.80 F	*- F
170	1		*WIPER GARNISH COVER, RH	Not Necessary	23.80 F	*- F
171	1		*PILLAR, FR BODY, LH	Not Necessary	363.10 F	*- F
172	1		*COVER, RADIATOR	Not Necessary	122.80 F	*- F
173	1		*WIRE, ENGINE ROOM	Not Necessary	5,567.10 F	*- F
174	1		*FUSE BLOCK, COVER LOWER	Not Necessary	18.50 F	*- F
175	1		*FUSE BLOCK, TOP COVER	Not Necessary	82.30 F	*- F
176	1		*INVERTER BRACKET TRAY	Not Necessary	251.60 F	*- F
177	1		*INVERTER COVER SUB ASSY	Not Necessary	39.60 F	*- F
178	1		*INVERTER W CONVERTER	Not Necessary	5,390.20 F	*- F
179	1		*BRACKET, INVERTER NO.1	Not Necessary	31.40 F	*- F
180	1		*COVER ASSY, INVERTER LH	Not Necessary	54.50 F	*- F
181	1		*TANK ASSY, INVERTER	Not Necessary	364.30 F	*- F
182	1		*BOX ASSY, CONSOLE REAR	Not Necessary	1,734.60 F	*- F
183	1		*HOLDER, REAR CONSOLE BOX, CUP	Not Necessary	230.80 F	*- F
184	1		*FENDER FRT/LH	Repair	723.40 F	*- F
185	1		*DOOR FRT/RH	Repair	894.40 F	*- F
186	1		*PILLAR, FR BODY	Repair	363.10 F	*- F
187	1		*SOLAR FILM (SN)	Necessary	575.00 F	*450.00 F

F=Franchise part.

Total Parts (\$\$)	84,474.72	41,726.91
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	2,704.00	1,800.00
2	SPRAY PAINT.	New	3,870.00	1,400.00
3	TOWING CHARGE.	New	182.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	200.00	40.00
6	TO TOP UP A/C GAS.	New	120.00	50.00
7	TO REMOVE / REFIT WINDSCREEN.	New	120.00	100.00
8	TO ALIGN CHASSIS.	New	350.00	0.00
9	TO CHECK & RESET SYSTEM FUNCTION.	New	350.00	0.00
10	TO REMOVE & REFIX FRONT LHS/RHS QUARTER GLASS.	New	120.00	0.00
11	REMOVE AND REFIT WIRE HARDESS.	New	250.00	0.00
12	TO REMOVE AND REFIX AIR BAG SYSTEM.	New	120.00	100.00
13	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.	New	120.00	80.00
14	TO REMOVE AND REFIX DASHBOARD.	New	120.00	80.00
15	TO REMOVE AND REFIT FRONT SEAT BELT.	New	120.00	80.00
16	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
17	TO WASH AND VACUUM.	New	60.00	0.00
18	TO ALIGN CHASSIS.	New	350.00	200.00
19	TO REMOVE AND REFIT WIRE HARDESS.	New	120.00	80.00
20	TO REMOVE AND REFIT ENGINE MOUNTING.	New	120.00	80.00
21	TO REMOVE AND REFIT INVERTER CONVERTER.	New	200.00	120.00
22	TO REMOVE AND REFIX CENTER CONSOLE.	New	120.00	50.00
Gross Labour Cost (\$\$)			9,896.00	4,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >