

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER ASSY, INVERTER, LH	1	54.50	54.50	25.00	40.88	Replace	0	0	Check ▼	
One Time Key In	Main			TANK ASSY, INVERTER	1	364.30	364.30	25.00	273.23	Replace	0	0	Check ▼	
One Time Key In	Main			BOX ASSY, CONSOLE, REAR	1	1,734.60	1,734.60	25.00	1,300.95	Replace	0	0	Check ▼	
One Time Key In	Main			HOLDER, REAR CONSOLE BOX, CUP	1	230.80	230.80	25.00	173.10	Replace	0	0	Check ▼	
One Time Key In	Main			SEAT BELT FRT/LH	1	822.60	822.60	25.00	616.95	Replace	1	616.95	Replace ▼	
One Time Key In	Main			SEAT BELT FRT/RH	1	822.60	822.60	25.00	616.95	Replace	1	616.95	Replace ▼	
Total Spare Part Cost									47,507.67		Surveyor Total		20,372.11	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20	
Final Spare Part Cost									38,006.14		Final Sur Total		16,297.69	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,859.00	1,200	
Total:			1,859.00	1,200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
3	Main	TO REPSRAY FRONT HOOD	378.00	200	
4	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	100	
5	Main	TO RESPRAY RADIATOR SUPPORT LOWER	180.00	0	

Total:			3,510.00	1,200.00	
--------	--	--	----------	----------	--

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
7	Main	TO RESPRAY APRON PANEL RH	180.00	0	
8	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
9	Main	TO RESPRAY APRON PANEL LH	180.00	0	
10	Main	TO RESPRAY FRONT PILLAR LH	180.00	0	
11	Main	TO RESPRAY FRONT PILLAR RH	180.00	100	
12	Main	TO RESPRAY FRT MEMBER,RH	180.00	0	
13	Main	TO RESPRAY FRT MEMBER,LH	180.00	0	
14	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
Total:			3,510.00	1,200.00	


Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	182.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
4	Main	TO TOP UP A/C GAS	120.00	50	
5	Main	TO REMOVE / REFIT WINDSCREEN	120.00	100	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	575.00	450	
7	Main	TO ALIGN CHASSIS	350.00	0	
8	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
9	Main	TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	0	
10	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0	

Total:	2,987.00	1,010.00	
---------------	-----------------	-----------------	--

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
11	Main	TO REMOVE AND REFIX AIR BAG SYSTEM	120.00	100	
12	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	80	
13	Main	TO REMOVE AND REFIX DASHBOARD	120.00	80	
14	Main	TO REMOVE AND REFIT FRONT SEAT BELT	120.00	80	
15	Main	TO REPLACE SUNDRY PARTS	100.00	0	
16	Main	TO WASH AND VACUUM	60.00	0	
Total:			2,987.00	1,010.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	38,006.14	16,297.69
Total Labour Cost	1,859.00	1,200.00
Total Spray Painting	3,510.00	1,200.00
Other	2,987.00	1,010.00
Overall Total	46,362.14	19,707.69
Lump Sum Repair Option	☒	☒
Lump Sum Total	46,350.00	19,700.00
Surveyor Approved Amount		19,700.00
No of Repair Days*	14	10
Remarks	-	Surveyor Remarks
Surveyor Name		Hwee jie
Signature		
Survey Date	27/03/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: