



Section A - Accident Details

|                                    |                             |
|------------------------------------|-----------------------------|
| Registration Number                | SHC4127G                    |
| Case Reference Number              | TAX/03/19/2110              |
| Registration Date                  | 22/1/2016                   |
| Company Type                       | SMRT Taxis Pte Ltd          |
| Make                               | TOYOTA                      |
| Model                              | PRIUS                       |
| Name of Driver                     | PANG SOON LEE (PENG SHUNLI) |
| Type of Accident                   | Head To Side                |
| Accident Date and Time             | 23/3/2019 5:00 AM           |
| Accident Reported Date and Time    | 23/3/2019 8:44 AM           |
| Is Surveyor Required?              | Yes                         |
| Survey by                          |                             |
| Vehicle is Towed Back?             | Yes                         |
| Towed Back Date and Time           | 23/3/2019 5:41 AM           |
| Replacement Vehicle issued?        | No                          |
| Job Card Number                    | 24100721                    |
| Special Instruction to ARC, if any | TOWED \$90 + \$40 / III     |
| Prepared Date and Time             | 25/3/2019 11:10 AM          |
| Chassis Number                     |                             |
| Mileage                            |                             |
| Work Shop                          |                             |
| Repair Completion Date and Time    |                             |



Section B - Summary of Repair Estimates

| Summary of Repair Estimates: |                                                                                     |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost            | \$2,704.00                                                                          | \$1,800.00                                                                          |
| Total Spray Cost             | \$3,870.00                                                                          | \$1,400.00                                                                          |
| Total Spare Part Cost        | \$68,412.32                                                                         | \$33,021.53                                                                         |
| Total Other Cost             | \$3,897.00                                                                          | \$1,540.00                                                                          |
| TOTAL COST                   | \$78,883.32                                                                         | \$37,761.53                                                                         |
| Lump Sum Total               | \$78,900.00                                                                         | \$37,750.00 (L/S)                                                                   |
| Number of Repair Days        | 21.0                                                                                | 17.0                                                                                |
| Prepared / Adjusted By       | Kim Ming Chin                                                                       | Hwee Jie (LKK) / III                                                                |
| ARC / Surveyor Sign Off Date | 04/04/2019 2:17 PM                                                                  | 04/04/2019 10:55 AM                                                                 |
| Signature                    |  |  |
| Remarks                      | SUP = 7 DAYS                                                                        |                                                                                     |

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1909-0207 | Invoice Number |  |
| Quotation Date   | 13.09.2019   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope               | Quotation from AR | Adjusted by Surveyor, if applicable |
|-------------------------|-------------------|-------------------------------------|
| TO REPAIR FRONT PORTION | \$1,859.00        | \$1,200.00                          |
| TO REPAIR FRONT PORTION | \$845.00          | \$600.00                            |
| <b>Total Labour</b>     | <b>\$2,704.00</b> | <b>\$1,800.00</b>                   |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY FRONT BUMPER                         | \$378.00           | \$200.00                            |
| TO SPRAY FRONT BUMPER LOWER SUB GRILLE          | \$180.00           | \$0.00                              |
| TO REPSRAY FRONT HOOD                           | \$378.00           | \$200.00                            |
| TO RESPRAY FRONT SUPPORT PANEL                  | \$180.00           | \$100.00                            |
| TO RESPRAY RADIATOR SUPPORT LOWER               | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT FENDER RH                      | \$378.00           | \$200.00                            |
| TO RESPRAY APRON PANEL RH                       | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT FENDER LH                      | \$378.00           | \$200.00                            |
| TO RESPRAY APRON PANEL LH                       | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT PILLAR LH                      | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT PILLAR RH                      | \$180.00           | \$100.00                            |
| TO RESPRAY FRT MEMBER,RH                        | \$180.00           | \$0.00                              |
| TO RESPRAY FRT MEMBER,LH                        | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT DOOR RH                        | \$378.00           | \$200.00                            |
| TO RESPRAY APRON PANEL RH                       | \$180.00           | \$100.00                            |
| TO RESPRAY FRT MEMBER,RH                        | \$180.00           | \$100.00                            |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$3,870.00</b>  | <b>\$1,400.00</b>                   |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                                         | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------------------------------|--------------------|-------------------------------------|
| TOWING CHARGE                                     | \$182.00           | \$0.00                              |
| TO CHECK WIRING AND SYSTEM FUNCTION               | \$80.00            | \$30.00 <i>ARC</i>                  |
| TO APPLY RUST-PROOFING ON AFFECTED AREA           | \$200.00           | \$40.00 <i>ARC</i>                  |
| TO TOP UP A/C GAS                                 | \$120.00           | \$50.00 <i>ARC</i>                  |
| TO REMOVE / REFIT WINDSCREEN                      | \$120.00           | \$100.00 <i>ARC</i>                 |
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) | \$575.00           | \$450.00 <i>ARC</i>                 |
| TO ALIGN CHASSIS                                  | \$350.00           | \$0.00                              |
| TO CHECK & RESET SYSTEM FUNCTION                  | \$350.00           | \$0.00                              |
| TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS      | \$120.00           | \$0.00                              |



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 60 Woodlands Industrial Park E4 Singapore 757705  
 FAX Number: 83685592  
 Estimator Telephone Number: 86662623  
 Accident Reporting Number: 86662872

Date Generated: 13/09/2019  
 User ID: PohSuan

|                                                                                 |            |            |     |
|---------------------------------------------------------------------------------|------------|------------|-----|
| TO REMOVE AND REFIT WIRE HARDESS                                                | \$250.00   | \$0.00     |     |
| TO REMOVE AND REFIT AIR BAG SYSTEM                                              | \$120.00   | \$100.00   | N/C |
| TO REMOVE & REFIT FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER | \$120.00   | \$80.00    | N/C |
| TO REMOVE AND REFIT DASHBOARD                                                   | \$120.00   | \$80.00    | N/C |
| TO REMOVE AND REFIT FRONT SEAT BELT                                             | \$120.00   | \$80.00    | N/C |
| TO REPLACE SUNDRY PARTS                                                         | \$100.00   | \$0.00     |     |
| TO WASH AND VACUUM                                                              | \$60.00    | \$0.00     |     |
| TO ALIGN CHASSIS                                                                | \$350.00   | \$200.00   | N/C |
| TO REMOVE AND REFIT WIRE HARDESS                                                | \$120.00   | \$80.00    | N/C |
| TO REMOVE AND REFIT ENGINE MOUNTING                                             | \$120.00   | \$80.00    | N/C |
| TO REMOVE AND REFIT INVERTER CONVERTER                                          | \$200.00   | \$120.00   | N/C |
| TO REMOVE AND REFIT CENTER CONSOLE                                              | \$120.00   | \$50.00    | N/C |
| Total Other Costs                                                               | \$3,897.00 | \$1,540.00 |     |

## Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name                   | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |       |
|-------------|---------|--------------|-----------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|-------|
|             |         | G9226-47020  | HOSE, INVERTER COOLING NO 2 | 0.00     | \$90.10         | 0.00         | \$0.00           | Replace            | Check             | X NAI |
|             |         | G9229-47020  | HOSE, INVERTER COOLING NO 5 | 0.00     | \$125.30        | 0.00         | \$0.00           | Replace            | Check             | X NAI |
|             |         | G9236-47031  | HOSE, INVERTER COOLING NO 6 | 0.00     | \$37.40         | 0.00         | \$0.00           | Replace            | Check             | X NAI |
|             |         | G9225-47021  | HOSE, INVERTER NO.1         | 0.00     | \$80.00         | 0.00         | \$0.00           | Replace            | Check             | X NAI |
|             |         | G9040-47090  | PUMP ASSY WATER             | 0.00     | \$454.00        | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | 86510-28130  | HORN ASSY, HIGH             | 1.00     | \$110.40        | 25.00        | \$82.80          | Replace            | Replace           | / BT  |
|             |         | 86520-28180  | HORN ASSY, LOW              | 1.00     | \$110.40        | 25.00        | \$82.80          | Replace            | Replace           | / BT  |
|             |         | 53294-47030  | DEFLECTOR, RADIATOR LH      | 1.00     | \$77.00         | 25.00        | \$57.75          | Replace            | Replace           | / CRU |
|             |         | 53293-47040  | DEFLECTOR, RADIATOR RH      | 1.00     | \$83.50         | 25.00        | \$62.63          | Replace            | Replace           | / CRU |
|             |         | 88460-47150  | A/C CONDENSER               | 1.00     | \$1,181.90      | 25.00        | \$886.43         | Replace            | Replace           | / DD  |
|             |         | 88703-47040  | HOSE SUB-ASSY DISCHARGE     | 0.00     | \$386.90        | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | 88710-47150  | TUBE & ACCESSORY            | 1.00     | \$631.90        | 25.00        | \$473.93         | Replace            | Replace           | / BT  |
|             |         | 88704-47090  | HOSE SUB-ASSY SUCTION       | 0.00     | \$405.40        | 0.00         | \$0.00           | Replace            | Check             | X NAI |
|             |         | 88707-47041  | TUBE SUB-ASSY SUCTION       | 0.00     | \$371.40        | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         |              | COOLANT                     | 1.00     | \$12.32         | 0.00         | \$12.32          | Replace            | Replace           | / N/C |
|             |         | 16400-37230  | RADIATOR ASSY               | 0.00     | \$1,496.90      | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | G9010-47031  | RADIATOR ASSY, UPPER        | 0.00     | \$679.60        | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | 57104-47020  | RADIATOR LOWER SUPPORT      | 0.00     | \$876.30        | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | 16535-20030  | SUPPORT, RADIATOR           | 0.00     | \$18.50         | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | 16534-37010  | SUPPORT, RADIATOR LH        | 0.00     | \$17.70         | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | 16533-28051  | SUPPORT, RADIATOR RH        | 0.00     | \$54.50         | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | 16523-21050  | CUSHION, RADIATOR           | 0.00     | \$11.30         | 0.00         | \$0.00           | Replace            | Check             | / NN  |
|             |         | 16571-37140  | RADIATOR TOP HOSE NO 1      | 0.00     | \$42.40         | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | 16572-37120  | RADIATOR HOSE LOWER         | 0.00     | \$42.40         | 0.00         | \$0.00           | Replace            | Check             | X NN  |
|             |         | 16261-37070  | RADIATOR HOSE BYPASS NO 1   | 0.00     | \$37.20         | 0.00         | \$0.00           | Replace            | Check             | X NN  |

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
Fax Number: 63085592  
Estimator Telephone Number: 68662623  
Accident Reporting Number: 68662672

Date Generated: 13/08/2019  
User ID: PohSuan

|             |                                       |      |            |        |            |         |         |   |         |
|-------------|---------------------------------------|------|------------|--------|------------|---------|---------|---|---------|
| 16264-37080 | RADIATOR HOSE, BYPASS NO.2            | 0.00 | \$29.00    | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 16267-37030 | RADIATOR HOSE, BYPASS NO.3            | 0.00 | \$37.20    | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 16281-37030 | RADIATOR HOSE, BYPASS NO.4            | 0.00 | \$37.20    | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 15480-28080 | COOLANT RESERVE TANK                  | 0.00 | \$395.30   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 16361-37010 | FAN BLADE                             | 0.00 | \$158.60   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 15361-28360 | FAN BLADE NO 2                        | 0.00 | \$204.20   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 16363-37010 | FAN MOTOR NO 1                        | 0.00 | \$538.30   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 16363-37020 | FAN MOTOR NO 2                        | 0.00 | \$538.30   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 16711-37040 | FAN SHROUD                            | 0.00 | \$244.50   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 16712-37030 | FAN SHROUD TOP                        | 0.00 | \$99.60    | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 51425-12060 | MEMBER FRT. SUB CENTRE                | 0.00 | \$65.00    | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 51108-47020 | SIDE CHASSIC FRT/LH                   | 0.00 | \$172.90   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 51107-12010 | SIDE CHASSIC FRT/RH                   | 0.00 | \$173.50   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 51410-12105 | UNDER COVER CENTER                    | 0.00 | \$448.30   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 5702812020  | MEMBER SUB-ASSY, FR LH                | 0.00 | \$810.70   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 5702712010  | MEMBER SUB-ASSY, FR RH                | 0.00 | \$810.70   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 11212-37090 | COVER, CYLINDER                       | 1.00 | \$165.20   | 25.00  | \$123.90   | Replace | Replace | X | DR      |
| 17700-38252 | AIR CLEANER ASSY                      | 1.00 | \$929.90   | 25.00  | \$697.43   | Replace | Replace | X | DR      |
| 17750-37010 | INLET ASSY, AIR                       | 0.00 | \$232.50   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 17894-37010 | RESONATOR, INTAKE                     | 0.00 | \$57.20    | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 65319-47120 | WIPER WASHER INLET                    | 0.00 | \$36.90    | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 85315-47140 | WIPER WASHER JAR                      | 0.00 | \$180.10   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 53802-47050 | FENDER FRT/LH                         | 1.00 | \$723.40   | 100.00 | \$0.00     | Replace | Repair  | X | X R     |
| 75374-47051 | NAME PLATE (HYBRID)                   | 1.00 | \$51.90    | 25.00  | \$38.93    | Replace | Replace | X | N/C     |
| 53876-47030 | FENDER LINER FRT/LH                   | 1.00 | \$171.70   | 25.00  | \$128.78   | Replace | Replace | X | TN      |
| 53852-47020 | FENDER LINER PAD, FR WHEEL LH         | 0.00 | \$49.30    | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 53828-47060 | PROTECTOR, FRONT FENDER SIDE PANEL LH | 0.00 | \$114.50   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 53801-47050 | FENDER FRT/RH                         | 1.00 | \$723.40   | 25.00  | \$542.55   | Replace | Replace | X | OO      |
| 75374-47051 | NAME PLATE (HYBRID)                   | 1.00 | \$51.90    | 25.00  | \$38.93    | Replace | Replace | X | N/C     |
| 53875-47030 | FENDER LINER FRT/RH                   | 1.00 | \$171.70   | 25.00  | \$128.78   | Replace | Replace | X | FAT MIS |
| 53851-47040 | FENDER LINER PAD, FR WHEEL RH         | 1.00 | \$49.30    | 25.00  | \$36.98    | Replace | Replace | X | CHF MIS |
| 53827-47030 | FENDER PROTECTOR FRT/RH SIDE          | 0.00 | \$113.90   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 53701-47050 | FENDER APRON SUB FRT/RH               | 0.00 | \$637.80   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 67001-47070 | DOOR FRT/RH                           | 1.00 | \$894.40   | 100.00 | \$0.00     | Replace | Repair  | X | X R     |
| 62110-47021 | STICKER DECAL SMRT (DOOR)             | 1.00 | \$60.00    | 0.00   | \$60.00    | Replace | Replace | X | N/C     |
|             | QUARTER GLASS FRT/RH                  | 0.00 | \$234.90   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
|             | SEALANT W/SCREEN                      | 0.00 | \$37.00    | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 53702-47050 | FENDER APRON SUB FRT/LH               | 0.00 | \$637.80   | 0.00   | \$0.00     | Replace | Check   | X | N/A     |
| 73900-47020 | AIR BAG ASSY, INSTR DRIVER            | 1.00 | \$1,555.80 | 10.00  | \$1,400.22 | Replace | Replace | X | DR      |
| 89170-47111 | AIR BAG COMPUTER                      | 1.00 | \$815.20   | 10.00  | \$733.68   | Replace | Replace | X | N/C     |
| 84307-74020 | AIR BAG SPIRAL CABLE                  | 1.00 | \$953.70   | 10.00  | \$858.33   | Replace | Replace | X | N/C     |



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
Fax Number: 63585592  
Estimator Telephone Number: 68662623  
Accident Reporting Number: 68662672

Date Generated: 13/09/2019  
User ID: PohSuan

|               |                               |       |            |       |            |         |           |   |     |
|---------------|-------------------------------|-------|------------|-------|------------|---------|-----------|---|-----|
| 45130-47100C0 | AIR BAG STEERING DRIVER       | 1.00  | \$2,360.40 | 10.00 | \$2,124.36 | Replace | Replace   | ✓ | BR  |
| 73960-47050   | AIR BAG ASSY. INSTR/PASSENGER | 1.00  | \$3,177.00 | 10.00 | \$2,859.30 | Replace | Replace   | ✓ | BR  |
| 82140-47060   | WIRE ASSY. AIR BAG            | 1.00  | \$23.60    | 10.00 | \$21.24    | Replace | Replace   | ✓ | REC |
| 89173-79025   | SENSOR AIR BAG FRT/RH/LH      | 2.00  | \$273.30   | 10.00 | \$491.94   | Replace | Replace   | ✓ | REC |
| 55300-47190C0 | DASH BOARD                    | 0.00  | \$906.10   | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 84140-42060   | SWITCH ASSY. HEAD LAMP        | 1.00  | \$318.40   | 10.00 | \$286.56   | Replace | Replace   | ✓ | BR  |
| 84652-42141   | SWITCH ASSY. WINDSHIELD WIPER | 1.00  | \$350.50   | 10.00 | \$315.45   | Replace | Replace   | ✓ | BR  |
| 45287-47090   | COVER. STEERING LOWER         | 0.00  | \$116.30   | 0.00  | \$0.00     | Replace | Check     | ✓ | NAI |
| 45286-47040   | COVER. STEERING UPPER         | 0.00  | \$77.00    | 0.00  | \$0.00     | Replace | Check     | ✓ | NAI |
| 52119-47930   | BUMPER FRT                    | 1.00  | \$482.00   | 25.00 | \$361.50   | Replace | Replace   | ✓ | BR  |
| 52161-16010   | BUMPER CLIPS                  | 10.00 | \$1.61     | 25.00 | \$12.08    | Replace | Replace   | ✓ | REC |
| 52611-47080   | BUMPER ENERGY ABSORBER FRT    | 1.00  | \$78.80    | 25.00 | \$59.10    | Replace | Replace   | ✓ | BR  |
| 52021-47023   | BUMPER REINFORCEMENT FRT      | 1.00  | \$498.40   | 25.00 | \$373.80   | Replace | Replace   | ✓ | DO  |
| 57014-47030   | ARM SUB-ASSY. FR BUMPER LH    | 1.00  | \$250.40   | 25.00 | \$187.80   | Replace | Replace   | ✓ | DO  |
| 57013-47030   | ARM SUB-ASSY. FR BUMPER RH    | 1.00  | \$250.40   | 25.00 | \$187.80   | Replace | Replace   | ✓ | DO  |
| 52114-47140   | BRACKET. FR BUMPER            | 1.00  | \$110.40   | 25.00 | \$82.80    | Replace | Replace   | ✓ | DO  |
|               | NUMBER PLATE                  | 1.00  | \$15.00    | 0.00  | \$15.00    | Replace | Replace   | ✓ | MIS |
|               | NUMBER PLATE FRAME            | 1.00  | \$12.00    | 0.00  | \$12.00    | Replace | Replace   | ✓ | MIS |
| 52116-47040   | BUMPER SUPPORT F/LH           | 1.00  | \$76.40    | 25.00 | \$57.30    | Replace | Replace   | ✓ | BR  |
| 52115-47040   | BUMPER SUPPORT F/RH           | 0.00  | \$76.40    | 0.00  | \$0.00     | Replace | Not Given | X | NAI |
| 52128-47903   | COVER. FR BUMPER HOLE LH      | 1.00  | \$18.50    | 25.00 | \$13.88    | Replace | Replace   | ✓ | MIS |
| 52127-47903   | COVER. FR BUMPER HOLE RH      | 1.00  | \$18.50    | 25.00 | \$13.88    | Replace | Replace   | ✓ | MIS |
| 53102-47020   | BUMPER GRILLE SUB-ASSY. LOWER | 1.00  | \$311.10   | 25.00 | \$233.33   | Replace | Replace   | ✓ | CUT |
| 01220-12230   | FOG LAMP LH                   | 0.00  | \$280.10   | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 81210-12230   | FOG LAMP RH                   | 0.00  | \$295.20   | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 81519-47050   | BRACKET. FR TURN LOWER RH     | 0.00  | \$26.00    | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 81519-47060   | BRACKET. FR TURN UPPER RH     | 0.00  | \$24.40    | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 81511-47050   | LENS & BODY. FR TURN RH       | 0.00  | \$511.80   | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 81529-47060   | BRACKET. FR TURN CENTER LH    | 0.00  | \$58.20    | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 81529-47050   | BRACKET. FR TURN LOWER LH     | 0.00  | \$26.00    | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 81529-47040   | BRACKET. FR TURN UPPER LH     | 0.00  | \$24.40    | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 81521-47050   | LENS & BODY. FR TURN LH       | 0.00  | \$511.80   | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 53113-47040   | GRILLE RADIATOR LOWER NO 2    | 0.00  | \$94.60    | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 53111-47040   | GRILLE. RADIATOR              | 0.00  | \$310.60   | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 75310-47010   | EMBLEM FRONT                  | 1.00  | \$86.50    | 25.00 | \$64.88    | Replace | Replace   | ✓ | REC |
| 76851-47020   | BUMPER LIP FRT                | 1.00  | \$139.60   | 25.00 | \$104.70   | Replace | Replace   | ✓ | CUT |
| 52618-47050   | BUMPER FRT ABSORBER LOWER     | 1.00  | \$127.70   | 25.00 | \$95.78    | Replace | Replace   | ✓ | BR  |
| 82113-47180   | WIRE. ENGINE ROOM NO 3        | 0.00  | \$242.00   | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 88790-22131   | THERMISTOR ASSY               | 0.00  | \$107.00   | 0.00  | \$0.00     | Replace | Check     | X | NAI |
| 53301-47060   | HOOD PANEL                    | 1.00  | \$748.10   | 25.00 | \$561.08   | Replace | Replace   | ✓ | DO  |
| 53395-47020   | HOOD END PANEL SEAL           | 0.00  | \$35.50    | 0.00  | \$0.00     | Replace | Not Given | X | NAI |

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
Fax Number: 63855592  
Estimator Telephone Number: 68662823  
Accident Reporting Number: 68662072

Date Generated: 13/09/2019  
User ID: PohSuan

|                 |                                        |      |             |        |             |         |           |        |
|-----------------|----------------------------------------|------|-------------|--------|-------------|---------|-----------|--------|
| 53420-47070     | HOOD HINGE LH                          | 1.00 | \$55.90     | 25.00  | \$41.93     | Replace | Replace   | BT     |
| 53410-47070     | HOOD HINGE RH                          | 1.00 | \$55.90     | 25.00  | \$41.93     | Replace | Replace   | BT     |
| 53510-47102     | HOOD LOCK                              | 0.00 | \$128.90    | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 53341-47020     | HOOD PANEL INSULATOR                   | 0.00 | \$390.50    | 0.00   | \$0.00      | Replace | Not Given | X NAI  |
| 53630-47050     | CABLE ASSY. HOOD                       | 0.00 | \$52.20     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 53614-47030     | CLAMP. HOOD LOCK                       | 0.00 | \$5.90      | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 85372 / 90099-  | HOSE, WINDSHIELD WASHER (FROM JOINT TO | 0.00 | \$13.60     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 85372B / 90099- | HOSE, WINDSHIELD WASHER (FROM JOINT TO | 0.00 | \$13.60     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 85372H / 90099- | HOSE, WINDSHIELD WASHER (FROM JOINT TO | 0.00 | \$13.60     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 55708-47101     | WIPER GARNISH                          | 0.00 | \$614.00    | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 55084-47011     | WIPER GARNISH COVER, LH                | 0.00 | \$23.80     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 55083-47011     | WIPER GARNISH COVER, RH                | 0.00 | \$23.80     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 61132-47030     | PILLAR, FR BODY, LH                    | 0.00 | \$363.10    | 0.00   | \$0.00      | Replace | Not Given | X NAI  |
| 61131-47030     | PILLAR, FR BODY                        | 1.00 | \$363.10    | 100.00 | \$0.00      | Replace | Repair    | X R    |
| 75533-47050     | WINDSCREEN MOULDING FRT                | 1.00 | \$57.60     | 25.00  | \$43.20     | Replace | Replace   | REC    |
| 561014E 909     | WINDSCREEN FRT                         | 1.00 | \$1,543.80  | 25.00  | \$1,157.85  | Replace | Replace   | DR     |
|                 | SEALANT W/SCREEN                       | 2.00 | \$37.00     | 0.00   | \$74.00     | Replace | Replace   | REC    |
| 53201-47902     | SUPPORT SUB-ASSY                       | 1.00 | \$1,460.40  | 25.00  | \$1,095.30  | Replace | Replace   | DO     |
| 53289-47032     | COVER, RADIATOR                        | 0.00 | \$122.80    | 0.00   | \$0.00      | Replace | Not Given | X NAI  |
| 81170-47500     | HEAD LAMP LH                           | 1.00 | \$945.20    | 10.00  | \$850.68    | Replace | Replace   | DR MII |
| 81130-47500     | HEAD LAMP RH                           | 1.00 | \$945.20    | 10.00  | \$850.68    | Replace | Replace   | DR     |
| 82111-47772     | WIRE, ENGINE ROOM                      | 0.00 | \$5,567.10  | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 82663-47060     | FUSE BLOCK, COVER LOWER                | 0.00 | \$18.50     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 82662-47110     | FUSE BLOCK, TOP COVER                  | 0.00 | \$82.30     | 0.00   | \$0.00      | Replace | Check     | X NN   |
| G9110-47011     | INVERTER BRACKET TRAY                  | 0.00 | \$251.60    | 0.00   | \$0.00      | Replace | Check     | X NN   |
| G9022-47041     | INVERTER COVER SUB ASSY                | 0.00 | \$39.60     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| G9200-49025     | INVERTER W CONVERTER                   | 0.00 | \$5,390.20  | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| G9214-47060     | BRACKET, INVERTER, NO.1                | 0.00 | \$31.40     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| G9140-47010     | COVER ASSY, INVERTER, LH               | 0.00 | \$54.50     | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| G92A0-47010     | TANK ASSY, INVERTER                    | 0.00 | \$364.30    | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 58901-47191-B3  | BOX ASSY, CONSOLE, REAR                | 0.00 | \$1,734.60  | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 55630-47030     | HOLDER, REAR CONSOLE BOX, CUP          | 0.00 | \$230.80    | 0.00   | \$0.00      | Replace | Check     | X NAI  |
| 73320-47113     | SEAT BELT FRT/LH                       | 1.00 | \$822.60    | 25.00  | \$616.95    | Replace | Replace   | Jamil  |
| 73210-47144     | SEAT BELT FRT/RH                       | 1.00 | \$822.60    | 25.00  | \$616.95    | Replace | Replace   | Jamil  |
| Total           |                                        |      | \$57,939.43 |        | \$20,372.20 |         |           |        |

## Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name               | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-------------------------|----------|---------------|--------------|------------------|-----------|----------------|
|             |         | G9225-47021  | HOSE, INVERTER NO 1     | 1.00     | \$80.00       | 25.00        | \$60.00          | Replace   | Replace        |
|             |         | 88703-47040  | HOSE SUB-ASSY DISCHARGE | 1.00     | \$386.90      | 25.00        | \$290.18         | Replace   | Replace        |
|             |         | 88704-47090  | HOSE SUB-ASSY, SUCTION  | 1.00     | \$405.40      | 25.00        | \$304.05         | Replace   | Replace        |





## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
80 Woodlands Industrial Park E4, Singapore 757708  
Fax Number: 63655592  
Estimator Telephone Number: 68662623  
Accident Reporting Number: 68662672

Date Generated: 13/09/2019

User ID: PohSuan

|                |                            |      |            |       |            |         |         |       |
|----------------|----------------------------|------|------------|-------|------------|---------|---------|-------|
| 16400-37230    | RADIATOR ASSY              | 1.00 | \$1,496.90 | 25.00 | \$1,122.68 | Replace | Replace | DD    |
| G9010-47031    | RADIATOR ASSY, UPPER       | 1.00 | \$679.60   | 25.00 | \$509.70   | Replace | Replace | DD    |
| 57104-47020    | RADIATOR LOWER SUPPORT     | 1.00 | \$875.30   | 25.00 | \$657.23   | Replace | Replace | CR4   |
| 16264-37080    | RADIATOR HOSE BYPASS NO 2  | 1.00 | \$29.00    | 25.00 | \$21.75    | Replace | Replace | CR4   |
| 16480-28080    | COOLANT RESERVE TANK       | 1.00 | \$395.30   | 25.00 | \$296.48   | Replace | Replace | ACC   |
| 16361-37010    | FAN BLADE                  | 1.00 | \$158.60   | 25.00 | \$118.95   | Replace | Replace | CNT   |
| 16361-28360    | FAN BLADE NO 2             | 1.00 | \$204.20   | 25.00 | \$153.15   | Replace | Replace | CNT   |
| 16363-37010    | FAN MOTOR NO 1             | 1.00 | \$538.30   | 10.00 | \$484.47   | Replace | Replace | DD    |
| 16363-37020    | FAN MOTOR NO 2             | 1.00 | \$538.30   | 10.00 | \$484.47   | Replace | Replace | DD    |
| 16711-37040    | FAN SHROUD                 | 1.00 | \$244.50   | 25.00 | \$183.38   | Replace | Replace | DR    |
| 16712-37030    | FAN SHROUD TOP             | 1.00 | \$99.60    | 25.00 | \$74.70    | Replace | Replace | DR    |
| 51107-12010    | SIDE CHASSIS FRT/RH        | 1.00 | \$173.50   | 25.00 | \$130.13   | Replace | Replace | DD    |
| 51410-12105    | UNDER COVER CENTER         | 1.00 | \$448.30   | 25.00 | \$336.23   | Replace | Replace | DR    |
| 5702712010     | MEMBER SUB-ASSY, FR RH     | 1.00 | \$810.70   | 25.00 | \$608.03   | Replace | Replace | DD    |
| 17750-37010    | INLET ASSY, AIR            | 1.00 | \$232.50   | 25.00 | \$174.38   | Replace | Replace | DR    |
| 65319-47120    | WIPER WASHER INLET         | 1.00 | \$36.90    | 25.00 | \$27.68    | Replace | Replace | DR    |
| 85315-47140    | WIPER WASHER JAR           | 1.00 | \$180.10   | 25.00 | \$135.08   | Replace | Replace | DR    |
| 53701-47050    | FENDER APRON SUB FRT/RH    | 1.00 | \$637.80   | 25.00 | \$478.35   | Replace | Replace | DD    |
| 55300-47190-C0 | DASH BOARD                 | 1.00 | \$906.10   | 25.00 | \$679.58   | Replace | Replace | DR    |
| 45287-47090    | COVER, STEERING LOWER      | 1.00 | \$116.30   | 25.00 | \$87.23    | Replace | Replace | DR    |
| 52115-47040    | BUMPER SUPPORT F/RH        | 1.00 | \$76.40    | 25.00 | \$57.30    | Replace | Replace | DR    |
| 81220-12230    | FOG LAMP LH                | 1.00 | \$280.10   | 10.00 | \$252.09   | Replace | Replace | DR    |
| 81210-12230    | FOG LAMP RH                | 1.00 | \$295.20   | 10.00 | \$265.68   | Replace | Replace | DR    |
| 81519-47050    | BRACKET, FR TURN LOWER RH  | 1.00 | \$26.00    | 25.00 | \$19.50    | Replace | Replace | DR    |
| 81511-47050    | LENS & BODY, FR TURN RH    | 1.00 | \$511.80   | 10.00 | \$460.62   | Replace | Replace | DR    |
| 81521-47050    | LENS & BODY, FR TURN LH    | 1.00 | \$511.80   | 10.00 | \$460.62   | Replace | Replace | DR    |
| 53113-47040    | GRILLE RADIATOR LOWER NO 2 | 1.00 | \$94.60    | 25.00 | \$70.95    | Replace | Replace | DR    |
| 53111-47040    | GRILLE RADIATOR            | 1.00 | \$310.60   | 25.00 | \$232.95   | Replace | Replace | DR    |
| 82113-47180    | WIRE, ENGINE ROOM, NO 3    | 1.00 | \$242.00   | 10.00 | \$217.80   | Replace | Replace | DR/TN |
| 53510-47102    | HOOD LOCK                  | 1.00 | \$128.90   | 25.00 | \$96.68    | Replace | Replace | DT    |
| 53341-47020    | HOOD PANEL INSULATOR       | 1.00 | \$390.50   | 25.00 | \$292.88   | Replace | Replace | TN    |
| 53630-47050    | CABLE ASSY HOOD            | 1.00 | \$52.20    | 25.00 | \$39.15    | Replace | Replace | TN    |
| 55708-47101    | WIPER GARNISH              | 1.00 | \$614.00   | 25.00 | \$460.50   | Replace | Replace | DR    |
| 55084-47011    | WIPER GARNISH COVER, LH    | 1.00 | \$23.80    | 25.00 | \$17.85    | Replace | Replace | CNT   |
| 55083-47011    | WIPER GARNISH COVER, RH    | 1.00 | \$23.80    | 25.00 | \$17.85    | Replace | Replace | CNT   |
| G9110-47011    | INVERTER BRACKET TRAY      | 1.00 | \$251.60   | 25.00 | \$188.70   | Replace | Replace | DT    |
| G9200-49025    | INVERTER W CONVERTER       | 1.00 | \$5,390.20 | 10.00 | \$4,851.18 | Replace | Replace | DT    |
| 58901-47191-B3 | BOX ASSY, CONSOLE, REAR    | 1.00 | \$1,734.60 | 25.00 | \$1,300.95 | Replace | Replace | DR    |
| 82121-47103    | WIRE, ENGINE               | 1.00 | \$1,889.50 | 10.00 | \$1,700.55 | Replace | Replace | DR/TN |
| 161A0-29015    | PUMP ASSY WATER, ELECTRIC  | 1.00 | \$989.50   | 10.00 | \$890.55   | Replace | Replace | DR    |
| 22030-37060    | BODY ASSY THROTTLE         | 1.00 | \$1,925.30 | 25.00 | \$1,443.98 | Replace | Replace | DR    |

|       |  |             |                     |      |           |       |           |         |         |    |
|-------|--|-------------|---------------------|------|-----------|-------|-----------|---------|---------|----|
|       |  | 12361-37090 | ENGINE MOUNTING FRT | 1.00 | \$198.00  | 25.00 | \$148.50  | Replace | Replace | BT |
| Total |  |             |                     |      | 25,835.50 |       | 20,904.71 |         |         |    |

41,276.91

- 20%

33,021.53

+ 1,800.00

+ 2,940.00

37,761.53

- 14,761.53 (Repair cost exceed repair limit beared by smrt Taxi)

23,000.00

4/s \$23,000/-