

23/03/2002

ASS. REC. BY:

Surveyor

REF

CS3/AWA19000440/R1-1031

Special Instruction

ASSIGNMENT (Office)

From (Person):

Wong Kin

of

AWAC

Date/Time

25/03/2019

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 9521R

Insured:

YP 3404T

at Workshop m/s

Toy Carz Auto

Tel:

9876 8299

of

210 Turfclub Road #01-V70/V71, 287995

Policy No:

AVCP8B 0082091802

Claim No:

NSV 1900011/KW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/01/2019

CA / REV / REP. / REV 24 HRS

(up)

9/11/2019

H.O.D. Endorsement:

Date/Time:

25/03/2019

Person Contacted

Mr. chong

Vehicle (IN) OUT

Date/Time


Action/Instruction (X) Estimate

Repairer agreed on 09/01/2019

SJR 9521R - X

YP 3404T - X

Pending Insured G/A Report.



5/4/2019

lump sum \$3600/- , 7 days (red: 4000/- ! 52%)

5/4- File pass to typist

RECEIVED 05 APR 2019



200-100=100

Person

REF: AWAC

1206K.
CofA 11/11/2019 / July

ASSIGNMENT

From Date: 09/01/2019

Veh No: SJR 9521R Yr Regn: 2008 / July

Estimated Cost:

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To Inspect Vehicle No: SJR 9521R

Make: HONDA CITY 1.5L C.C. 1497

at Workshop m/s: Toy Carz Auto

Colour: R60 A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

of 210 Turfclub Rd #01-V70/71,

Sp Reading: 228184 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Insured: 287995

Eng/No:

Policy No:

C/Nr: MRHGM26509P020358

Claims No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Mr. chong @ 9876 8299


Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

(Policy Condition)

Tyre Size: F: 175/65R15

R: 2

Remark: The veh had commenced its repair at the time of inspection.



BS: ☒ DUM / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or

Bal. or Market Value:

13K 14K

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal. 65 mm

R/Bal. 5 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal. 5 mm

L/Bal. 5 mm

Est. Repairs:

5 days Res: Yes or No

D.O.A. 04/01/19

D.O.I. 09/01/19 @ 0348PM

Lum Sum:

% 3 Val: Yes or No

Survey held at

TOY CARZ AUTO

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Frt / Rear / ☒ D/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

N/S FR

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- Estimated repair range \$3,500 - \$4,500

14/1/2019

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

Survey Fee:

100

Report Format :

PRE

Lump Sum / I.B.I: (\$

☐ Interview (\$

Transportation

S + RS

Photos

Others

☐ Tech Invs (\$

☐ Weekend (\$

TOTAL

100

Nivitha (LKK Auto)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Monday, 25 March 2019 1:07 PM
To: kin.wong@awac.com; assignments
Subject: FW: AW REF: NSV1900011 _ Your Ref: CS3/AWA19000440/R1cd3e _ SJR 9521R
Attachments: 25032019111940-0002.pdf

Dear Kin,

Thank you for the assignment.

Dear Assignment Team,

FYNA.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Kin <Kin.Wong@awac.com>
Sent: Monday, 25 March 2019 1:01 PM
To: SUR <sur@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: AW REF: NSV1900011 _ Your Ref: CS3/AWA19000440/R1cd3e _ SJR 9521R

Dear Shiau Chan

Please conduct a paper-re accordingly.

Thank you.

Regards,

Kin Wong (Mr.)

Asia-Pacific Claims Group

Allied World Assurance Company, Ltd.

60 Anson Road #08-01

Singapore 079914

T: +65 6423 0894

F: +65 6423 0864

E: kin.wong@awac.com

W: www.awac.com

From: Koh, Ivy <Ivy.Koh@awac.com>
Sent: Monday, 25 March 2019 12:58 PM
To: Wong, Kin <Kin.Wong@awac.com>
Subject: scan docs

Kindly refer attached.

Best Regards

Ivy Koh

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Company
Owner ID:	1206K
Vehicle Details	
Vehicle No.:	SJR9521R
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5L I-VTEC AUTO
Primary Colour:	Maroon
Manufacturing Year:	2009
Engine No.:	L15A71809047
Chassis No.:	MRHGM26509P020358
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,628.00
Original Registration Date:	23 Jul 2009
First Registration Date:	23 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$18,628.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2019
PARF Rebate Amount:	\$9,314.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,310.00
COE Rebate Amount:	\$761.00
Total Rebate Amount:	\$10,075.00

The information contained herein is correct as at 10 Jan 2019

OK

~~13,000~~ 14,000
 10,075
~~2925~~ 3,925

PERFECT AUTOMOBILE APPRAISAL SERVICES

10 Hougang Street 11 #14-29 The Minton Singapore 534080
Hand phone No. 96683949 Fax No. 63880908
Company Registration No. 53103119E

THIRD PARTY CLAIM

To : Leisure Leasing Pte Ltd
c/o : 180 Woodlands Industrial Park E5
#01-17 Woodlands Autohub
Singapore 757512

Date : 21st January 2019

Our Ref : PA/TR/19/1001/1

REFERENCE :

ASSIGNED BY : Owner
ASSIGNED ON : 8th January 2019

WORKSHOP : Toy Carz Auto Roaming
180 Woodlands Industrial Park E5
#01-17 Woodlands Autohub
Singapore 757512

ACCIDENT DATE : 4th January 2019
SURVEY DATE : 8th January 2019

VEHICLE DETAILS :

REGN PLATE	: SJR 9521 R	COLOUR	: Maroon
MAKE & MODEL	: Honda City 1.5	GEN BODY WORK	: Good
YEAR REGN	: 2009	AUDIO PLAYER	: Yes
ENG CAPACITY	: 1497cc	AIR CONDITIONER	: Yes
ENGINE NO.	: L15A71809047	STEERING	: Serviceable
CHASSIS NO	: MRHGM26509P020358	HAND BRAKE	: Serviceable
MILEAGE	: 228189Km	FOOT BRAKE	: Serviceable

TYRES SIZE & CONDITION :

FRONT O/S : Dunlop 175/65 R 15 approximately 80%
FRONT N/S : Dunlop 175/65 R 15 approximately 80%
REAR O/S : Dunlop 175/65 R 15 approximately 80%
REAR N/S : Lead 185/65 R 15 approximately 80%

Note : The above percentage represent the remaining estimated life of the tyre treads.

Our Ref : PA/TR/19/1001/1

Veh. No. : SJR 9521 R

GENERAL DESCRIPTION OF DAMAGES :

At the time of inspection, we noted that this vehicle sustained damages at the n/s body portion.

For more details of the damages, please see schedule and photographs attached.

Attached thirty-five (35) photographs taken during our inspections.

CONCLUSIONS & RECOMMENDATIONS :

ORIGINAL QUOTATION : \$ 16,868.72

REVISED QUOTATION : \$ 7,600.00 (Lump Sum)

We have thoroughly inspected each and every item on the estimate against the physical damages found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment attached.

In normal circumstances, the repairs would take approximately eight (8) days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** repair to the vehicle and the survey was conducted strictly on a '**WITHOUT PREJUDICE**' basis. We hope that this report will be of assistance to you in dealing with this matter.

Should you discover any discrepancy in this report, please kindly notify us within two (2) weeks or this report will be treated as valid.

The information contained in these documents is privileged and confidential and is for the exclusive use of the addressee's designation. If you are not the addressee, any enclosure, reproduction, distributions or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for its return.

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Toy Carz Auto Roaming
180 Woodlands Industrial Park E5
#01-17 Woodlands Autohub
Singapore 757512

Our Ref : PA/TR/19/1001/1

Veh. No. : SJR 9521 R

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

LIST PARTS

1 pc	Front bumper	grazed/ deformed	\$ 5,109.00	\$ 5,109.00 523
1 pc	Front bumper o/s side retainer	serviceable	\$ 28.60	\$ -
1 pc	Front bumper n/s side retainer	necessary	\$ 28.60	\$ 28.60 X succ
10 pcs	Front bumper clip @\$4.50	necessary	\$ 45.00	\$ 45.00
1 pc	Bonnet	repairable	\$ 610.20	\$ - R
2 pcs	Bonnet side seal @\$48.60	not necessary	\$ 97.20	\$ -
1 pc	Bonnet insulator	serviceable	\$ 89.90	\$ -
5 pcs	Bonnet insulator clip @\$4.50	necessary	\$ 22.50	\$ 22.50
1 pc	Bonnet air vent	serviceable	\$ 106.50	\$ -
5 pcs	Bonnet air vent clip @\$4.50	not necessary	\$ 22.50	\$ -
2 pcs	Bonnet hinge @\$45.50	repairable	\$ 91.00	\$ -
1 pc	Front n/s fender	dented	\$ 441.50	\$ 441.50 326
1 pc	Front n/s fender top quarter garnish	dislodged	\$ 84.60	\$ 84.60
1 pc	Front n/s fender signal lamp	broken	\$ 42.20	\$ 42.20 X succ
10 pcs	Front n/s fender inner shield clip @\$4.50	necessary	\$ 45.00	\$ 45.00
1 pc	Front n/s door	dented	\$ 781.60	\$ 781.60 704
1 pc	N/s door mirror	ripped off	\$ 485.90	\$ 485.90 } 426.50
1 pc	N/s door mirror cover	ripped off	\$ 123.60	\$ 123.60
1 pc	Front n/s door protector	bent	\$ 142.80	\$ 142.80 X succ
1 pc	Front n/s door glass	smashed	\$ 481.60	\$ 481.60 161
1 pc	Front n/s door glass outer moulding	bent	\$ 126.20	\$ 126.20 55
1 pc	Front n/s door glass run channel	dented	\$ 151.40	\$ 151.40 55
1 pc	Front n/s door outer handle	repairable	\$ 128.60	\$ -
1 pc	Front n/s door weatherstrip	necessary	\$ 132.60	\$ 132.60 100
1 pc	Front n/s door opening weatherstrip	necessary	\$ 189.90	\$ 189.90
1 pc	Front n/s door inner trim board	cracked	\$ 681.60	\$ 681.60 350
1 pc	Front n/s door insulation	necessary	\$ 120.30	\$ 120.30 X succ
1 pc	Front n/s door pillar outer	repairable	\$ 689.50	\$ -
1 pc	Front n/s door pillar inner trim	serviceable	\$ 189.60	\$ -
1 pc	Front n/s door checker	bent	\$ 89.60	\$ 89.60 X succ
list parts c/f			\$ 11,379.10	\$ 9,325.50

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Toy Carz Auto Roaming
180 Woodlands Industrial Park E5
#01-17 Woodlands Autohub
Singapore 757512

Our Ref : PA/TR/19/1001/1

Veh. No. : SJR 9521 R

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

list parts b/f

\$ 11,379.10 \$ 9,325.50

2 pcs	Front n/s door hinge @\$85.50	bent	\$ 171.00	\$ 171.00 X ⁵⁰⁰
1 pc	Front n/s shock absorber	serviceable	\$ 381.90	\$ -
1 pc	Front n/s shock absorber top mount	serviceable	\$ 120.60	\$ -
1 pc	Front n/s lower arm	serviceable	\$ 360.60	\$ -
1 pc	Front n/s knuckle arm	serviceable	\$ 415.20	\$ -
1 pc	Front n/s wheel hub	serviceable	\$ 341.60	\$ -
1 pc	Front n/s wheel bearing	necessary	\$ 199.60	\$ 199.60
1 pc	Front windscreen moulding	necessary	\$ 112.60	\$ 112.60 X ⁵⁰⁰
1 pc	Dashboard	repairable	\$ 1,362.50	\$ -
1 pc	Dashboard n/s side air vent	serviceable	\$ 116.20	\$ -
			\$ 14,960.90	\$ 9,808.70
Less 20%			\$ 2,992.18	\$ 1,961.74
			\$ 11,968.72	\$ 7,846.96

3097.20
20%
2477.76

S/NETT PARTS

1 pc	Front n/s sport wheel	dented	\$ 550.00	\$ 250.00 ✓
1 pc	Front n/s tyre	serviceable	\$ 300.00	\$ -
1 set	Front windscreen sealant	not necessary	\$ 80.00	\$ -
1 set	Front n/s door black tape	necessary	\$ 120.00	\$ 45.00 ✓
			\$ 1,050.00	\$ 295.00

295

LABOUR CHARGES

Towing charges.	\$ 100.00	\$ 50.00 ✓
-----------------	-----------	------------

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Toy Carz Auto Roaming
180 Woodlands Industrial Park E5
#01-17 Woodlands Autohub
Singapore 757512

Our Ref : PA/TR/19/1001/1

Veh. No. : SJR 9521 R

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

LABOUR CHARGES

To remove and refix front windscreen glass
to facilitate repairs and perform water test.

(not necessary) \$ 180.00 \$ -

To remove, repair & refix dashboard, meter
instruments, disconnect wiring, ducting and
connectors to facilitate repairs.

\$ 300.00 \$ 100.00 X 14

To remove and refix inner trims, garnishes,
linings and upholstery to facilitate repairs.

\$ 180.00 \$ 50.00 ✓

To remove and refix front undercarriage
parts and components including to carry
out balancing of wheel rim.

\$ 300.00 \$ 30.00 ✓

To check and re-adjust computerised wheel
alignment.

\$ 120.00 \$ 100.00 60

To disconnect and check front electrical
wiring, harness, wire sockets, etc.
To remove and reinstall damaged parts, test
and rectify for proper functioning.

\$ 50.00 \$ 30.00 ✓

To apply rustproofing, reseal tuff-coating
treatment to front replaced/ repaired parts
and panels.

\$ 120.00 \$ 50.00 ✓

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Toy Carz Auto Roaming
180 Woodlands Industrial Park E5
#01-17 Woodlands Autohub
Singapore 757512

Our Ref : PA/TR/19/1001/1

Veh. No. : SJR 9521 R

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

LABOUR CHARGES

To putty and spray painting on front damaged portion including touch up paint on accident affected areas.


\$ 1,200.00 \$ ~~1,000.00~~ 800

To remove and replace frontal damaged parts as listed above including reinstatement of the necessary attachments and fittings to facilitate repairs. Jack up, straighten, panel beat and reshape the affected parts and components. To correct and realign the necessary parts.

1770

\$ 1,300.00 \$ ~~900.00~~ 700
\$ 16,868.72 \$ 9,551.96

The repairer has agreed to undertake repairs on a contractual basis at **Lump Sum \$ 7,600.00** corresponding to supply of parts, labour and spray painting charges.


CHUAH POH SIONG GARY
CAE, MIMI, AMSOE,
AMIRTE, AMSAE-AUS, MSAAA

2477.76

295.00

1770.00

4542.76

20%

3634.20

L/S - 3,600

Repair limit - 2900

SINGAPORE ACCIDENT STATEMENT

old
already revise

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/01/2019 12:50
Date Of Accident 04/01/2019 10:10
Exact Location Of Accident HOLLAND RD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJR9521R

Insured/Policyholder

Name Of Registered Owner LEISURE LEASING PTE LTD
Co Reg No 201511206K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-86995178

Vehicle Particulars

Manufacturer HONDA
Model CITY
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5085977185-02(CLASSIC)
Cover Note Number

Driver

Name of Driver WONG KUM LOY
NRIC No S1279185B
Date Of Birth 25/10/1957
Occupation OUTDOOR
Date Of Driving Pass 16/03/2011
Driving Experience 7 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-86995178
Fax Number
Contact Number
Email Address NOEMAIL

X

Address	BLK 634 YISHUN ST 61 #05-50
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : --
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	JACELYN
Phone Number	92972219
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP3404T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ZHANG JIFENG
NRIC/Passport Number	G2635566X
Contact Number	85350726
Address	

X

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS3/AWA19000440/R1td3e2-1		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 08-04-2019		
		Code : AWA		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 3404T	Veh. Inspected	SJR 9521R	
Policy No.	AVCPSB0082091802	Coverage (\$)	0.00	
Claim No.	NSV1900011/KW	Excess (\$)	0.00	
Assign From	WONG KIN	Assign Date	25/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY 1.5L	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MRHGM26509P020358	Colour	RED	
Odometer	228189	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	DUNLOP	5 mm	
L/H Front Tyre	175/65 R15	DUNLOP	5 mm	
R/H Rear Tyre	175/65 R15	DUNLOP	5 mm	
L/H Rear Tyre	175/65 R15	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/01/2019	Inspection Date	09/01/2019	
Survey held at	TOY CARZ-210 TURFCLUB RD#01-V70/71			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 9521R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	GRAZED / DEFORMED	5,109.00	523.00
1	FRONT BUMPER O/S SIDE RETAINER	SERVICEABLE	28.60	-
1	FRONT BUMPER N/S SIDE RETAINER	SERVICEABLE	28.60	-
10	FRONT BUMPER CLIP @\$4.50	NECESSARY	45.00	45.00
1	BONNET	TO REPAIR SEE LABOUR	610.20	-
2	BONNET SIDE SEAL @\$48.60	NOT NECESSARY	97.20	-
1	BONNET INSULATOR	SERVICEABLE	89.90	-
5	BONNET INSULATOR CLIP @\$4.50	NECESSARY	22.50	22.50
1	BONNET AIR VENT	SERVICEABLE	106.50	-
5	BONNET AIR VENT CLIP @\$4.50	NOT NECESSARY	22.50	-
2	BONNET HINGE @\$45.50	TO REPAIR SEE LABOUR	91.00	-
1	FRONT N/S FENDER	DENTED	441.50	326.00
1	FRONT N/S FENDER TOP QUARTER GARNISH	DISLODGE	84.60	84.60
1	FRONT N/S FENDER SIGNAL LAMP	SERVICEABLE	42.20	-
10	FRONT N/S FENDER INNER SHIELD CLIP @\$4.50	NECESSARY	45.00	45.00
1	FRONT N/S DOOR	DENTED	781.60	704.00
1	N/S DOOR MIRROR }	RIPPED OFF	485.90	426.50
1	N/S DOOR MIRROR COVER }		123.60	-
1	FRONT N/S DOOR PROTECTOR	SERVICEABLE	142.80	-
1	FRONT N/S DOOR GLASS	SMASHED	481.60	161.00
1	FRONT N/S DOOR GLASS OUTER MOULDING	BENT	126.20	55.00
1	FRONT N/S DOOR GLASS RUN CHANNEL	DENTED	151.40	55.00
1	FRONT N/S DOOR OUTER HANDLE	TO REPAIR SEE LABOUR	128.60	-
1	FRONT N/S DOOR WEATHERSTRIP }	NECESSARY	132.60	100.00
1	FRONT N/S DOOR OPENING WEATHERSTRIP }		189.90	-
1	FRONT N/S DOOR INNER TRIM BOARD	CRACKED	681.60	350.00
1	FRONT N/S DOOR INSULATION	NOT NECESSARY	120.30	-
1	FRONT N/S DOOR PILLAR OUTER	TO REPAIR SEE LABOUR	689.50	-
1	FRONT N/S DOOR PILLAR INNER TRIM	SERVICEABLE	189.60	-
1	FRONT N/S DOOR CHECKER	SERVICEABLE	89.60	-

Report Ref No. CS3/AWA19000440/R1td3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT N/S DOOR HINGE @\$85.50	SERVICEABLE	171.00	-
1	FRONT N/S SHOCK ABSORBER	SERVICEABLE	381.90	-
1	FRONT N/S SHOCK ABSORBER TOP MOUNT	SERVICEABLE	120.60	-
1	FRONT N/S LOWER ARM	SERVICEABLE	360.60	-
1	FRONT N/S KNUCKLE ARM	SERVICEABLE	415.20	-
1	FRONT N/S WHEEL HUB	SERVICEABLE	341.60	-
1	FRONT N/S WHEEL BEARING	NECESSARY	199.60	199.60
1	FRONT WINDSCREEN MOULDING	SERVICEABLE	112.60	-
1	DASHBOARD	TO REPAIR SEE LABOUR	1,362.50	-
1	DASHBOARD N/S SIDE AIR VENT	SERVICEABLE	116.20	-
	LESS 20% DISCOUNT		-2,992.18	-619.44
			11,968.72	2,477.76
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT N/S SPORT WHEEL (SN)	DENTED	550.00	250.00
1	FRONT N/S TYRE (SN)	SERVICEABLE	300.00	-
1	SET FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET FRONT N/S DOOR BLACK TAPE (SN)	NECESSARY	120.00	45.00
			1,050.00	295.00
	<u>LABOUR</u>			
	TOWING CHARGES.		100.00	50.00
	TO REMOVE AND REFIX FRONT WINDSCREEN GLASS TO FACILITATE REPAIRS AND PERFORM WATER TEST.	NOT NECESSARY	180.00	-
	TO REMOVE, REPAIR & REFIX DASHBOARD, METER INSTRUMENTS, DISCONNECT WIRING, DUCTING AND CONNECTORS TO FACILITATE REPAIRS.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIX INNER TRIMS, GARNISHES, LININGS AND UPHOLSTERY TO FACILITATE REPAIRS.		180.00	50.00
	TO REMOVE AND REFIX FRONT UNDERCARRIAGE PARTS AND COMPONENTS INCLUDING TO CARRY OUT BALANCING OF WHEEL RIM.		300.00	30.00
	TO CHECK AND RE-ADJUST COMPUTERISED WHEEL ALIGNMENT.		120.00	60.00
	TO DISCONNECT AND CHECK FRONT ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC. TO REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		50.00	30.00
	TO APPLY RUSTPROOFING, RESEAL TUFF-COATING TREATMENT TO FRONT REPLACED / REPAIRED PARTS AND PANELS.		120.00	50.00

Report Ref No. CS3/AWA19000440/R1td3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON FRONT DAMAGED PORTION INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		1,200.00	800.00
	TO REMOVE AND REPLACE FRONTAL DAMAGED PARTS AS LISTED ABOVE INCLUDING REINSTATEMENT OF THE NECESSARY ATTACHMENTS AND FITTINGS TO FACILITATE REPAIRS. JACK UP, STRAIGHTEN, PANEL BEAT AND RESHAPE THE AFFECTED PARTS AND COMPONENTS. TO CORRECT AND REALIGN THE NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF BONNET, BONNET HINGE, FRONT N/S DOOR OUTER HANDLE, FRONT N/S DOOR PILLAR OUTER AND DASHBOARD.		1,300.00	700.00
			3,850.00	1,770.00
GRAND TOTAL			16,868.72	4,542.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CS3/AWA19000440/R1td3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.