

Continued

REC BY:

REF

CS3 / MSG19001763 / JSD3

of Instruction

Surveyor

From Person

Kony Ony

ASSIGNMENT (Office)

of MS1

Date/Time 25/03/2019

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No

XD 8115U

Insured

WC 2430R

at Workshop n/a

SW motor

Tel

8181 9694 9863 1300

of

No. 211 Kramji Road

Policy No

B24088496MKT

Claim No

583339

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

18012019

CA / REV / REP. / REV 24 HRS 'Up'

29012019 @ 2pm

H.O.D, Endorsement

Date/Time

28012019 1052am

Person Contacted

Win

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	XD 8115U - (5/15/17007133 / Kiganda)
	WC 2430 R - (5/15/17007133 / Kiganda)
	Submit H/S R \$ 150/- @ 5 days
	(\$ 6,450/- Red - 61%)

[Signature]

27/3/2019

RECEIVED 28 MAR 2019

RCF: MSIG

Hwee Jie
PRS (Mechanics)

STANDARD

Form Date 29/1/19

Estimated Cost

(ID) TP WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No

XD 81154

at Workshop no

3W Motor

V4

No. 211 Kranji Road

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh:

2pm

Win@ 81829694

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs

days Res: Yes or No

Lump Sum

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS^{1up}

Vehicle: IN / OUT

Date

Person Contacted

Sub No: XD 81154

Page 9 Jan 2014

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

(Truc) / Trailer or

Make: Mercedes MB Actros

Colour

white

AC: Insured / Std / NI / NA

Sp. Reading

574667

T/Radio: Insured / Std / NI / NA

Engine

C.No

W0B9321612L783119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Std / STD A/Rim or

Tyre Size

F: 315/80 R22.5

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal

8

mm

R/Bal

8

mm

L/Bal

8

mm

L/Bal

8

mm

D.O.A.

18/1/19

D.O.I.

29/1/19

Survey held at

SW motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Range: \$2,500 - \$3,000
3 days.

13/2/2019

Date/Time: For Pass to:

☐ : Preli. Report☐ : Final Report

H:

Date/Time: For Return to:

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

Transportation

1. Sub. Fee

1. Other

1. Other

1. Other

1. Other

Report Format:

PRS

Lump Sum / LB 1: 130

Add Fee:

☐ Site Trip \$☐ Interview \$☐ Tech. Ins. \$☐ Weekend \$

120

10

130

Nivitha (LKK Auto)

From: Keny Ong <Keny_Ong@sg.msig-asia.com>
Sent: Monday, 25 March 2019 1:39 PM
To: Admin-D (LKKAuto); SUR
Subject: Your ref: to be advised Our ref: 583339 Paper reinspection for TP motor vehicle XD8115U

Dear Catherine

We had appointed your firm to carry out a third party pre-repair inspection of XD8115U for an accident involving WC2430R and XD8115U on 18 Jan 2019 recently.

Please carry out a third party paper re-inspection of XD8115U and let us have the report by 8 Apr 2019.

Have a great day !

Keny Ong
Senior Executive, Claims Services (Motor)
Direct line +65 6643 1309 | Direct fax +65 6225 7402 | keny_ong@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CARLINK CONSULTANCY


60 Hillside Drive
Singapore 549009

Tel : 62856178

Fax : 62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CL 12011 XD 8115 U

1 REFERENCE					
Date of request	:	29th January 2019			
Requested by	:	M/S RLS Transport & Engineering Pte Ltd C/o No. 211 Kranji Road, Singapore 739461			
Type of claim	:	Third party			
Workshop	:	M/S SW Motor Trading No. 211 Kranji Road, Singapore 739461			
Date of survey	:	29th January 2019			
Accident date	:	18th January 2019			
2 DETAILS OF VEHICLE					
Registration No.	:	XD 8115 U			
Make & Model	:	MB Actros 3336K 6X4 3300 (Auto, ABS)			
Date of registration	:	9th January 2014			
Engine No.	:	541972C0903564			
Chassis No.	:	WDB9321612L783119			
Speedometer reading	:	574887.2 Km			
Transmission	:	Automatic			
Colour	:	White			
3 STATIC CHECK					
Steering	:	see annex(es)	Paintwork	:	Good
Footbrake	:	see annex(es)	Modification	:	Nil
Handbrake	:	see annex(es)	General condition	:	Good
4 TYRE CONDITION					
		<u>Nearside/Make</u>	<u>Offside/Make</u>	<u>Size</u>	
Front axle	:	9mm/Triangle	9mm/Triangle	:	315/80 R22.50
Centre axle	:	9mm/Sunfull	9mm/Sunfull	:	315/80 R22.50
Rear axle	:	9mm/Triangle	9mm/Triangle	:	315/80 R22.50
5 POINT OF IMPACT					
See Annex(es) and Motor Accident Reports					
6 REMARK					
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.					

Annex A : Assesement / Adjustment on Spare Parts

XD 8115 U

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
List Items						
1	Front windscreen glass	Cracked CRA /	1	1000 \$2,280.00	10%	\$2,052.00 900
2	Front windscreen glass moulding	Necessary NEL /	1	150 \$454.00	10%	\$408.60 135
3	Front door pillar outer garnish LH	Grazed/distorted CRA /	1	\$320.00	10%	\$288.00
4	Front LH mirror assy (motorized 24v)	Cracked/faulty CRA /	1	1200 \$2,850.00	10%	\$2,565.00 1800
5	Front LH top mirror (front view) (motorized 24v)	Cracked/torn MIS /	1	850 \$1,520.00	10%	\$1,368.00 765
6	Front LH door glass power window motor	Distorted/faulty AL X	1	\$950.00	10%	\$855.00
7	Cabin hydraulic jack	Bent/leaked AL X	1	\$3,240.00	10%	\$2,916.00
S/Nett Items						
8	ERP unit bracket	Necessary NEL /	1	\$20.00		\$20.00
9	Front windscreen glass sealant	Necessary NEL /	1	\$80.00		\$80.00
Total for Spare Parts :				\$11,714.00		\$10,552.60

Annex B : Adjustment on Labour and Spray Painting

XD 8115 U

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	To check wiring system	\$100.00	\$80.00 50
2	To remove/replace front LH door glass power window motor	\$120.00	\$90.00 X
3	To remove/replace front windscreen glass	\$180.00	\$150.00 ✓
4	To spray painting on affected areas	\$900.00	\$750.00 500
5	Labour to renew damaged parts/repair front LH door, front LH door pillar outer panel & roof top panel	\$1,500.00	\$900.00 500

TOTAL FOR LABOUR & SPRAY PAINTING : \$2,800.00 \$1,970.00

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$11,714.00	\$10,552.60
TOTAL FOR LABOUR & SPRAY PAINTING :	\$2,800.00	\$1,970.00
TOTAL REPAIR COSTS :	<u>\$14,514.00</u>	<u>\$12,522.60</u>

L/s \$4150/- 5days

CARLINK CONSULTANCY

XD 8115 U

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S SW Motor Trading estimated repair cost is **S\$14,514.00** and we have adjusted it to **S\$12,522.60** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

The repairer have agreed to undertake the repairs on a contract lump sum of **S\$10,600.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of **7** working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,
CARLINK CONSULTANCY

A handwritten signature in black ink, appearing to be 'Patrick Ng', is written over a circular stamp. The stamp contains the text 'CARLINK CONSULTANCY' around the top edge and 'PATRICK NG' in the center.

Automotive Engineer Assessor
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/01/2019 15:32
Date Of Accident 18/01/2019 09:00
Exact Location Of Accident 211 KRANJI ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number XD8115U
Insured/Policyholder
Name Of Registered Owner RLS TRANSPORT & ENGINEERING PTE LTD
Co Reg No 201327760D
Email Address RLS201327@GMAIL.COM
Mobile Phone No
Alternative Phone No Office-66101971

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model MB ACTROS-11.9 3336K 6X4 3300 ABS (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMCVSN1840651800
Cover Note Number

Driver

Name of Driver RAJ ANBUSELVAN
NRIC No S7369029C
Date Of Birth 24/08/1973
Occupation OUTDOOR
Date Of Driving Pass 09/06/2008
Driving Experience 10 YEARS AND 7 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-82831736

Fax Number	
Contact Number	
EMail Address	RLS201327@GMAIL.COM
Address	BLK 24 BENDEMEER RD #11-531
Postcode	330024

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

ON 11/01/2019 I SENT MY COMPANY VEHICLE XD8115U TO THE WORKSHOP WHICH LOCATED AT 211 KRANJI ROAD TO REPAIR. ON 18/01/2019 I RECEIVED A CALL FROM THE WORKSHOP SAID THAT MY VEHICLE HAS BEEN HIT BY WC2430R WHILE THE SAID VEHICLE DOING REVERSE. MY VEHICLE WAS DAMAGE AT THE FRONT PORTION. THE COMPANY OF THE VEHICLE WC2430R THEN ASK ME TO SEND MY VEHICLE TO THEIR WORKSHOP & THEY WILL PAY FOR THE REPAIR COST. UP TILL TODAY (22/01/2019) MY VEHICLE DID NOT DO ANY REPAIR AT THE WORKSHOP & THE SAID COMPANY PERSON IN CHARGE THEN ASK TO LODGE INSURANCE CLAIM. THIS CAUSING ME LATE REPORT. THAT'S ALL.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

Details of Witness 1

Name SELVAM ALEXPANDI

Phone Number 83033815

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number WC2430R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

LOH KHOON HOCK

NRIC/Passport Number

S1335830C

Contact Number

90626653

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN

211 Kranji Road



vehicle @: XD 8115U

vehicle @: WC 2430R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/01/2019 @ abt 0900hrs.

Refer to circumstances of accident.

- ☐ Claim own policy
- ☐ Claim third party
- ☒ Claim OD / CP at other works hop
- ☐ For record purpose

Policy No. DMCVSN1840651800
Insurer: Chirel (C) Veh. No. XD8115U

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

IC,DL,CI

10

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DNCVSH1840631800	Engine No : 941972C0903564	Chassis No: WDB9321612L783119
1. Index Mark and Registration Number of Vehicle	XD8115U		
2. Name of Policy Holder	RLS TRANSPORT & ENGINEERING PTE LTD		
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	18 DECEMBER 2018 (10:53 HOURS)	EXCESS SECT 1	\$91,500.00
		EK ON WINDSCREEN	\$5100.00
4. Date of Expiry of Insurance	17 DECEMBER 2019		
5. Persons or Classes of Persons entitled to drive *			

ANY PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH THEIR PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

5. Limitations as to use: *

- (1) USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
 - (2) USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
 - (3) USE FOR SOCIAL, DOMESTIC OR PLEASURE PURPOSES.
- THE POLICY DOES NOT COVER:
- (1) USE FOR HIRE OR REWARD OR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED TESTING.
 - (2) USE WHILE DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

HIRE PURCHASE CO. : SWEET SENG CREDIT PTE LTD AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse



Authorized Officer

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Authorized Signatory

Countersigned By:


3 Anson Road #16-00 Springleaf Tower Singapore 079909 Tel: 6389 8111 Fax: 6225 3592 Website: www.sg.cntaiping.com

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7369029C



REPUBLIC OF SINGAPORE DRIVING LICENCE
Licence Number S7369029C

RAJ ANBUSELVAN



Race
INDIAN
 Date of birth
24-08-1973 Sex
M
 Country of birth
INDIA

10P22

RAJ ANBUSELVAN



Date of birth
24 Aug 1973
 Date of issue
11 Jun 2008

004751961C

9034772



MRCHA **57369029C**
 NATIONALITY
INDIAN
 Date of issue
04-06-2008

APT BLK 34 BENDOMEER ROAD #11-531
 SINGAPORE 370074
 NPIC No: **57369029C** Date: **01/03/2011** No: **6770635**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

CLASS	VEHICLE CLASS	PASS DATE
Class 2B	Motorcycles < 200 cc	14 Mar 2008
Class 3	Motor Cars < 3500kg with < 7 passengers, exclusive of the driver, and other motor vehicles < 3500kg	14 Mar 2008
Class 4	Motor vehicles which are constructed to carry load or passengers and the unladen weight > 3500kg	09 Jun 2008
	Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg	

NP 4204

Licence No: **57369029C**



Accident Photo



Accident Photo



Accident Photo



45
3

60

Accident Photo



Driving License



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 19/01/2019 09:27
Date Of Accident 18/01/2019 09:00
Exact Location Of Accident 211 KRANJI ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number WC2430R
Insured/Policyholder
Name Of Registered Owner LOH KHOON HOCK
NRIC No S1335830C
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-90626653
Alternative Phone No Office-90626653

Vehicle Particulars

Manufacturer ISUZU
Model CEMENT MIXER TRUCK

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number B 29088496 MKF
Cover Note Number

Driver

Name of Driver LOH KHOON HOCK
NRIC No S1335830C
Date Of Birth 16/09/1958
Occupation OUTDOOR
Date Of Driving Pass 29/04/1998
Driving Experience 20 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90626653

Fax Number	
Contact Number	OFFICE-90626653
EMail Address	NOEMAIL
Address	517 JELAPANG ROAD #06-185
Postcode	S670517
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS REVERSING MY VEHICLE TO PARK ALONG THE SERVICE ROAD OF UNIT NO 211 KRANJI ROAD. THERE WAS A TRUCK THAT WAS PARKED WITHIN THE UNIT OF 211 WITH THE FRONT PRUDING OUT, AS I REVERSE, THE LEFT REAR PORTION OF MY VEHICLE ACCIDENTALLY HIT ONTO THE FRONT LEFT WINDSCREEN AND THE LEF WING MIRROR OF THE SAID VEHICLE. THE SAID DRIVER WAS NOT PRESENT AND I DID INFORMED THE SHOP OWNER TO INFORM THE SAID DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD8115U
Vehicle Make/Model/Colour	MERCEDES TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUKIT BATON (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg




Policyholder's Signature
Date & Time:

JAN 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



XD8154

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

19 JAN 2019

Policyholder's Signature
Date & Time:

Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

(If driver is not the policyholder)

Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

511 Bukit Batok Street 23

Singapore 659545

Tel: 6560 3312 Fax: 6569 0722

Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2019		28 Jan 2019 10:04 Edit Adj Rpt	S\$4,150.00 Edit Estimates	S\$4,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ALLIANCE CONCRETE SINGAPORE PTE LTD , Co. Reg. No.: 200516266D								
Main Claimant:	RLS TRANSPORT & ENGINEERING PTE LTD , Co. Reg. No.: 201327760D								
Vehicle Reg. No.:	XD8115U	Date of Loss:	18/01/2019 09:00 - :59 [60 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 583339	Policy/Cover Note No.:	B29088496MKF (Comprehensive) Coverage: 01/07/2018 - 30/06/2019						
Vehicle Reg. No. (Insured):	WC2430R	Policy No. (Claimant):	DMCV5N1840651800						
		Excess:	S\$1,500.00						
Repairer:	Sw Motor Trading (HQ) No.211 Kranji Road, 739461 Kranji - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Keny Ong Thiam Beng - 6643 1309]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 27/03/2019]								
Adj Asg. Remarks:	liability 100 % on OI appoint surveyor LKK Auto Consultants Pte Ltd contact Mr Tan @ 8182 9694								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (25/03/2019): Report Send Back Alerts - XD8115U (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD8115U (583339)
 [WC2430R]
 TP
 RLS TRANSPORT & ENGINEERING PTE LTD
 Jan 18 2019 9:00AM
 [ALLIANCE CONCRETE SINGAPORE PTE LTD]
 Sw Motor Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	25/01/19 16:09	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: SC - Reg. No: WC2430R, Claimant: LOH KHOON HOCK</small>	 Load HTM	
1	22/01/19 17:18	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	30/01/19 10:15	LKK Auto Consultants Pte Ltd (HQ) General View	 Load JPG	<input checked="" type="checkbox"/>
2	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
3	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
4	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
5	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
6	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
7	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
8	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
9	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
10	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
11	30/01/19 10:15	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	25/01/19 16:11	MSIG Insurance (Singapore) Pte. Ltd. (HQ) PRI-XD8115U	 Load PDF	
2	25/01/19 16:18	PRI NOA EMAIL	 Load PDF	
3	25/01/19 16:18	TP REJECT SJE APPT LKK AUTO CONSULTANT	 Load PDF	
4	25/03/19 13:33	XD8115U survey report	 Load PDF	
1	29/03/19 11:39	LKK Auto Consultants Pte Ltd (HQ) Colour Photo	 Load PDF	
2	29/03/19 11:39	PRS Invoice	 Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	22/01/19 17:18	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	22/01/19 17:18	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/01/19 17:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/01/19 17:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
4	22/01/19 17:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/01/19 17:18	Driving License	 Load JPG	<input checked="" type="checkbox"/>
6	22/01/19 17:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	22/01/19 17:17	Sketch Plan	 Load TIF	
2	22/01/19 17:18	IC,DL,CI	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19001763/JSD3E2-1

Date: 29/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B29088496MKF

Claimant Vehicle No: XD8115U

Insured Vehicle No:

WC2430R

Date of Loss: 18/01/2019

Nature of Claim:

TP

Claim No: 583339

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD8115U

Make & Model: MERCEDES-BENZ MB ACTROS, 11.9 3336K 6X4
3300 ABS (A)

Engine No: 541972C0903564

Reg. Date: 09/01/2014 (Man. Year: 2013)

Chassis No: WDB9321612L783119

Colour: White

Odometer: 574667 km

Engine Capacity: 11946 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5

Rear Tyre Size:

315/80 R22.5

Front Left Side: Triangle 8 mm

Rear Left Side:

Triangle 8 mm

Front Right Side: Triangle 8 mm

Rear Right Side:

Triangle 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,714.00	3,988.00	7,726.00	65.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,200.00	1,600.00	57.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,514.00	5,188.00	9,326.00	64.26
Approved Total (Overridden) (S\$)		4,150.00		
Nett Amount (S\$)	14,514.00	4,150.00	10,364.00	71.41

INSPECTION

Date of Assignment: 28/01/2019

Date Inspected: 29/01/2019

Inspected At:

Sw Motor Trading (HQ)
No.211 Kranji Road
Singapore 739461

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Mar 2019)	
Parts:	N/A	MERCEDES-BENZ MB ACTROS 11.9 3336K 6X4 3300 ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD8115U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	2,280.00 F	*1,000.00 FL
2	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	454.00 F	*150.00 FL
3	1		*FRONT DOOR PILLAR OUTER GARNISH LH	Cracked	320.00 F	*320.00 FL
4	1		*FRONT LH MIRROR ASSY (MOTORIZED 24V)	Cracked	2,850.00 F	*2,000.00 FL
5	1		*FRONT LH TOP MIRROR (FRONT VIEW) (MOTORIZED 24V)	Missing	1,520.00 F	*850.00 FL
6	1		*FRONT LH DOOR GLASS POWER WINDOW MOTOR (DISTORTED / FAULTY)	Not Consistent With The Impact	950.00 F	*- FL
7	1		*CABIN HYDRAULIC JACK (BENT/LEAKED)	Not Consistent With The Impact	3,240.00 F	*- FL
8	1		*ERP UNIT BRACKET	Necessary	20.00 FS	*20.00 FS
9	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,714.00	4,420.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	432.00
Total Parts (\$\$)	11,714.00	3,988.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING SYSTEM	New	100.00	50.00
2	TO REMOVE / REPLACE FRONT LH DOOR GLASS POWER WINDOW MOTOR	New	120.00	0.00
3	TO REMOVE / REPLACE FRONT WINDSCREEN GLASS	New	180.00	150.00
4	TO SPRAY PAINTING ON AFFECTED AREAS	New	900.00	500.00
5	LABOUR TO RENEW DAMAGED PARTS / REPAIR FRONT LH DOOR, FRONT LH DOOR PILLAR OUTER PANEL & ROOF TOP PANEL	New	1,500.00	500.00
Gross Labour Cost (\$\$)			2,800.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >