

LEE SHENG AUTO PTE LTD

Page 1 / 2

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. SIM SIEW HUAY
67 CHOACHU KANG LOOP
#10-01 S 689671

Attention : Motor Claim Department
Contact : 90018600

Estimate : ES000875

Date : 26/03/2019

Vehicle Num. : SLK 5233L

Make/Model : HONDA JAZZ 1.4A

Chassis/Eng# :

Accident Date : 15/03/2019

Claim No. :

Reference :

Policy No. :

TP A/G.
Ashes.

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	REAR WINDSCREEN MOULDING <i>new</i>		87.20 ✓
2.	1 PC	REAR BUMPER <i>new</i>		502.50 ✓
3.	2 PCS	REAR BUMPER SIDE RETAINER <i>new</i>		36.80 ✓
4.	10 PCS	REAR BUMPER CLIPS <i>new</i>	18.40	35.00 ✓
5.	1 PC	REAR BUMPER CORNER LH <i>new</i>	3.50	20.70 ✓
6.	2 PCS	REAR NUMBER PLATE LAMP <i>new</i>		70.20 X
7.	1 PC	REAR LAMP LOWER BRACKET <i>new</i>	35.10	18.40 X
8.	1 PC	REAR LAMP CLIP LH <i>new</i>		6.20 ✓
9.	1 PC	REAR END PANEL <i>new</i>		320.10 ✓
10.	1 PC	REAR TRUNKLID <i>new</i>		730.60 ✓
11.	1 PC	REAR TRUNKLID LOCK <i>new</i>		78.90 ✓
12.	1 PC	REAR TRUNKLID EMBLEM <i>new</i>		24.20 ✓
13.	1 PC	REAR TRUNKLID LOGO <i>new</i>		25.70 X
14.	1 PC	REAR TRUNKLID DAMPER <i>new</i>		106.80 X
15.	1 PC	REAR TRUNKLID WEATHERSTRIP <i>new</i>		92.30 ✓
16.	1 PC	REAR TRUNKLID TRIM BOARD <i>new</i>		71.20 ✓
17.	1 PC	WIPER MOTOR <i>new</i>		235.70 X
18.	1 PC	WIPER ARM <i>new</i>		42.60 X
19.	1 PC	REAR LAMP LH <i>new</i>		233.90 ✓
20.	1 PC	REAR END PANEL TOP GARNISH <i>new</i>		103.60 ✓
21.	1 PC	REAR FENDER INNER SIDE TRIM RH <i>new</i>		169.00 X
22.	1 PC	REAR FENDER INNER SIDE TRIM LH <i>new</i>		169.00 X
23.	1 PC	SPARE TYRE PANEL <i>new</i>		710.90 X
24.	1 PC	SPARE TYRE BOARD <i>new</i>		189.80 X

CONTINUE / ...

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. SIM SIEW HUAY
67 CHOA CHU KANG LOOP
#10-01 S 689671

Attention : Motor Claim Department

Contact : 90018600

Estimate : ES000875

Date : 26/03/2019

Vehicle Num. : SLK 5233L

Make/Model : HONDA JAZZ 1.4A

Chassis/Eng# :

Accident Date : 15/03/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1 PC	SPARE TYRE BRACKET		22.80 X
26.	1 PC	REAR CAMERA	234320	1,061.90 X
27.	1 PC	REAR TUNKLID REFLECTOR LH	1874.56	86.40 X
List TotalS\$:				5,252.40
20.00% Discount S\$:				1,050.48
				4,201.92
SPECIAL NETT ITEMS :				
1.	1 PC	REAR NUMBER PLATE	200	25.00 X
2.	1 PC	REAR NUMBER PLATE CASING		35.00 X
3.	1 PC	REAR BUMPER SENSOR		200.00 200
Special Nett Total S\$:				310.00
LABOUR :				
KNOCKING, CUTTING, JACKING WELDING ETC				900.00 800
SPRAY PAINTING				900.00 800
TO CHECK WIRING AND SYSTEM FUNCTION				100.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA				200.00 60
REMOVE & REFIX REAR WINDSCREEN				150.00 120
TO TRANSFER REAR TAILGATE MECHANISM				120.00 80
TO SUPPLY WINDSCREEN SEALANT				60.00 ✓
Labour Total S\$:				2,430.00

Total S\$: 6,941.92

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4024.56

1/5 : 3.2k.
06Days