

Date: 25.03.2019
Vehicle: SLA7246P
Model: HONDA VEZEL 1.5X
Chassis: RU11110148 - 2015
Reg.Year: 2016

Third Party Insurer: **AIG ASIA PACIFIC
INSURANCE PTE. LTD.**
Third Party Veh No: SFQ3939L
Date of Accident: 21.03.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT ALLY RIM LH 17"	1		<i>Per</i> \$650.00
2	FRONT KNUCKLE ARM LH	1		\$669.90
3	FRONT KNUCKLE ARM BEARING LH	1		\$357.30
4	FRONT FENDER LH	1		REPAIR
SUB TOTAL				\$1,677.20
LESS 20%				-\$335.44
PARTS TOTAL				\$1,341.76

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT TYRE LH 17"	1		<i>Per</i> \$200.00
2	FRONT TYRE VALVE TUBE LH	1		<i>Per</i> \$15.00
S/N TOTAL				\$215.00

LABOUR CHARGES:

LABOUR CHARGES TO REPAIRS ON ACCIDENT DAMAGED AREAS & ETC

na \$100.00 X

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS

na \$200.00 X

TO REMOVE & REFIX/REPLACE FRONT SUSPENSION ARM LH & ETC

\$200.00 ?

TO WHEEL ALIGNMENT & BALANCING

\$60.00 *2 of*

LABOUR TOTAL \$560.00

ONG TOTAL \$2,116.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Date:

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

999 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

