

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

THAM SOUK FUN  
BLK 505 WOODLANDS DRIVE 14  
#06-68  
S 730505

TPALG.  
X100 Tony.

Date :15.04.2019  
Vehicle no :SLT 3449 Y  
Make/Model :HYUNDAI ELANTRA  
Accident date :17.03.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<b>List Items</b>			
1	Front bumper <i>torn</i>	1	\$ 487.6 ✓
2	Front bumper side holder @ \$41.80 <i>LH side</i>	2	\$ 83.6 <i>41.80</i>
3	Front bumper fog lamp garnish <i>7/8 in</i>	1	\$ 105.4 +
4	Front bumper clips (1set) <i>new</i>	1	\$ 70.30
5	Front LH fender <i>Repair</i>	1	\$ 573.9 +
6	Front LH fender inner shield <i>see in</i>	1	\$ 83.4 +
7	Front LH head lamp <i>cracked</i>	1	\$ 1317.8 ✓
			\$ 2721.7
		Less 20% Disc	\$ 544.34
		<b>Total</b>	<b>\$ 2177.36</b>

### Labour Cost

- 1 Remove, replace & repair consistent to the accident
- 2 Respray painting
- 3 Tuff kote

4 Wiring

	\$ 1000 <i>300</i>
	\$ 900 <i>450</i>
	\$ 150 +
<b>Total</b>	<b>\$ 2050</b>

Grand Total

\$ 4227.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 2237.76.  
4/5 = 1.8K.  
03 Days

1.8K