

**BCC AUTOMOTIVE PTE LTD**

BLK 1 SIN MING IND. ESTATE
SECTOR C #101/103/105/107/109
SINGAPORE 575636
Tel: +65 6552 5588 Fax: +65 6552 7750
Email: enquiry@bcc.sg Website: www.bcc.sg

QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : **SMQ8680**Quotation Date : **2019-03-19**

Vehicle Reg No : SJY5958D
Name : WANG PU

Make & Model : MAZDA - MAZDA3 1.6L SDN LUX
Chassis No : JM6BL10Z1A0160048
Mileage : 228407 KM
Officer-In-Charge : KAHKHEE
Page : 1 of 1

No	Description	Unit Price	Qty	Amount
1	FRONT RH DOOR <i>1119-30</i>	1205.40	1.00 <i>BT/way</i>	1,205.40 ✓
2	REAR RH DOOR	1033.00	1.00 <i>R</i>	1,033.00 ✓
3	REAR RH FENDER <i>208</i>	1050.00	1.00 <i>R</i>	1,050.00 X
4	PANEL BEAT AFFECTED AREA	800.00	1.00 <i>75cl</i>	800.00
5	RESPRAY PAINT AFFECTED AREA	900.00	1.00 <i>80cl</i>	900.00

*Not not hatched
1/100 82600h*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

5 days

Sub-Total : 4,988.40
Add GST 7% : 349.19
Estimated Total Amt (SGD) : 5,337.59

NOTE:

1. This quotation is only the estimated cost of repair. Any additional works and parts be required during the course of repair, a supplementary quote will be submitted.
2. If you decide to terminate the repair after our diagnosis, a diagnostic fee will apply according to the job performed

CUSTOMER'S AUTHORISATION
I agree to this quotation and hereby authorize to proceed with the above listed repairs.

CUSTOMER'S SIGNATURE _____
(& Co's Stamp, WHERE NECESSARY)