

15/5/2010

INS. CASE OWNER:

CC 4, 561 1900 5384, 71K03 g.

LKK:

IDAC:

ASSIGNMENT

DOE

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 17/3/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP: motor/image

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 04/04/19

Sent By: ab

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 24,567.96 (12 days) Reduction: 36 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 3/3/2020 Confirm with Dennis

Email ☒ Call ☐

Final Liability:

% 100 % (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS 26,287.72

ER40: L: 100 % (Email 27/3/19)

Loss of Rental (LOR):

SS (- days)

Loss of Use (LOU):

SS 960 (580 x 12 days)

Loss of Income (LOI):

SS (3 x - days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

Legal Cost

SS -

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 27,249.72

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 27,249.72

Name 1:

MOTOR IMAGE ENTERPRISES PTELTD

Payee 2 (Strike if N.A.)

SS -

Name 2:

Payee 3 (Strike if N.A.)

SS -

Name 3:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CDMCG19000492/SL/JC
Our ref: CC4/EG119005384/T1ha3

Date: 04/04/2019

The Motor Claims Department
M/s ERGO INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJN 7666R

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/03/2019 at the premises of M/s Motor Image Enterprises Pte Ltd - Toa Payoh and have the following to report:-

Workshop Estimate Amount	: S\$	34,556.70
Revised Estimate Amount	: S\$	27,990.12
"Check" Items Amount	: S\$	5,351.70
Total (Including Check Items)	: S\$	33,341.82
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/016/2019
DATE : 25-MAR-2019

AIG ASIA PACIFIC INSURANCE PTE LTD
7B SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : LOW WEI CHEONG (LUO WEICHANG)
ADDRESS : 985 BUKIT TIMAH ROAD
#08-06
S(589627)
TELEPHONE NO : 8488 7666

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700031584-01
VEHICLE NO : SJN7666R
MODEL CODE : SJ5GK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YA52B41
CHASSIS NO : JF1SJ5KC5HG093125
MILEAGE : 1 KM
DATE IN : 25/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 25/03/2019

Print Date : 25/03/2019
Print Time : 21:00:42

Tanpin 97495749/67418434
'WP'
27/3/19 @ 1130
Resurvey before paint
10 days
surellkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJN7666R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE FRONT BUMPER,BUMPER BEAM,BRKT LHS,BRKT RHS ,BONNECT,FRT GRILL,HEADLAMP AND ETC	2900.00 560	2800 ✓
2	ZZ/002	REMOVE AND REFIX EXHAUST	150.00	2 photo.
3	ZZ/003	REMOVE & REFIX A/CON CONDENSER & RADIATOR TO FACILITATE REPAIR	220.00	✓✓
4	ZZ/004	REMOVE AND REFIX WIRE HARNESS	300.00	✓✓
5	ZZ/005	REMOVE AND REFIX DASHBOARD	400.00	✓✓
6	ZZ/006	REMOVE AND REFIX SEAT BEALT,MODULE & RESET	430.00	✓✓
7	ZZ/007	REMOVE AND REPLACE DRIVER & PASSENGER AIRBAG & RESET	500.00	✓✓
8	ZZ/008	COOLING SYSTEM PRESSURE TEST	100.00	✓✓
9	ZZ/009	TO CONDUCT ANTI RUST COATING	580.00	250 ✓
10	ZZ/011	NUMBER PLATE	55.00	61 ✓✓
11	ZZ/012	SUNDRIES	150.00	80 ✓
12	ZZ/013	RESPRAY FRT BUMPER,BONNECT,FENDER LH,FENDER RH AND BUMPER BEAM	2400.00 440	1760 ✓
13	ZZ/10	TO CONDUCT FRONT LIGHTING TEST	150.00	✓✓
TOTAL LABOUR CHARGES			8335.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	BOOT CP-AIR INT	14456AA440	162.00	? x		
2	METER AY-AIR FLOW	22680AA380	432.00	? x		
3	RADIATOR ASSY (SUPP)	45111SG000	792.00	?/BT		
4	BRKT ASSY OIL CLR	45124SG000	14.40	?/BT		
5	TANK RESERVE (SUPP)	45150SG001	61.20	?/OR		
6	HOSE-RADIATOR INLET (SUPP)	45161SC010	36.00	?/OR		
7	HOSE-RADIATOR OUTLET	45161SC020	36.00	? NH		
8	COOLER ATF	45512SG000	396.00	? NH		
9	HOSE ATF	45520AG100	27.00	? }		
10	HOSE ATF	45520AG110	36.00	? }		
11	HOSE ATF AIR IN	45520SG000	36.00	? }		
12	HOSE ATF AIR OUT	45520SG010	36.00	? }		
13	PIPE ATF COMPL	45522SG001	82.80	? }		
14	CLAMP HOSE	45527SG000	3.60	? }		
15	DUCT AIR INTAKE	46012SG000	36.00	?/OR		
16	RESONATOR	46043FG000	43.20	? }		
17	CASE-AIR CLNR UPR	46052AG070	108.00	? }		
18	CASE-AIR CLNR LWR	46052SG000	36.00	? }		
19	RAD PNL COMPL RPR	53029SG0019P	720.00	?/BT 360		
20	UNDER COVER COM FNA (SUPP)	56410SG050	158.40	?/BT		
21	BRKT FENDER R CP RH	57150SG0009P	28.80	? }		
22	BRKT FENDER R CP LH	57150SG0109P	28.80	? }		
23	EXT FENDER F CP RH	57160SG0009P	50.40	? }		
24	EXT FENDER F CP LH	57160SG0109P	25.20	? }		
25	STAY ASSY F HOOD	57251SG001	187.20	? }		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	COVER FENDER UPR RH	57256SG020	36.00	<i>2</i>		
27	COVER FENDER UPR RH (SUPP)	57256SG030	36.00	<i>2</i>		
28	HINGE COMPL F HD RH	57260SG0009P	86.40	<i>bt</i>	<i>43.20</i>	
29	HINGE COMPL F HD LH	57260SG0109P	86.40	<i>bt</i>	<i>43.20</i>	
30	STOPPER	57275SG000	10.80	<i>2</i>		
31	LOCK ASSY F HOOD ISR	57310SG020	144.00	<i>bt</i>	<i>72.00</i>	
32	CABLE ASSY HD	57330SG060	72.00	<i>2</i>		
33	CLIP LEL CABLE	57371GA070	3.28	<i>2</i>		
34	BRKT CORNER F RH	57707SG000	36.00	<i>2</i>		
35	BRKT CORNER F LH	57707SG010	36.00	<i>2</i>		
36	BRKT SD F RH	57707SG020	12.60	<i>2</i>		
37	BRKT SD F LH	57707SG030	12.60	<i>2</i>		
38	MOLDING BMRP F	57708SG020	43.20	<i>aut</i>		
39	MOLDING BMRP F	57708SG030	43.20	<i>aut</i>		
40	BUMPER FACE F NA (FOR H/L WSH)	57709SG030	594.00	<i>de</i>		
41	BACK BEAM CPL F	57711SG0009P	288.00	<i>2</i>	<i>photo</i>	
42	ENERGY ABSOR F	57722SG020	126.00	<i>2</i>	<i>photo</i>	
43	COVER HOOK F STD	57731SG220	4.40	<i>mis</i>	<i>X</i>	
44	MUD GUARD ASSY F RH	USE SG020 59110SG021	86.40	<i>2</i>	<i>mis</i>	
45	MUD GUARD ASSY F LH	SEE SG030 59110SG031	86.40	<i>de</i>		
46	CLIP	59122FA010	1.40	<i>aut</i>		
47	HINGE ASSY DR F FA	60079AG003	46.80	<i>X</i>		
48	HINGE ASSY DR F FB	60079AG013	46.80	<i>X</i>		
49	BELT ASSY F OUT RH	64622SG021VH	1376.00	<i>aut</i>	<i>688</i>	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

			DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
50	BELT ASSY F OUT LH	64622SG031VH	1376.00	aut	688	
51	ADJUSTER SHD ANC	64703FG000ME	144.00	3.44		
52	O RING	73039TA030	3.60	2		
53	O RING	73039TA040	3.60	2		
54	CONDENSER ASSY (SUPP)	73210SG011	532.80	2	519.35	
55	FAN&MOTOR ASSY	73310SG000	468.00	2		
56	BOOT TERMINAL	81611YC000	7.20	2		
57	TRAY BATT	82122AG001	8.00	2		
58	COVER BATT	82123SA003	28.80	2		
59	ROD BATT FIX	82161AG001	4.32	2	4.35	
60	ROD	82161SG000	4.32	2	4.35	
61	HOLDER ASSY	82184SG000	13.60	2		
62	LAMP ASSY HEAD EOF RH	84002SG220	2380.00	60		
63	LAMP ASSY HEAD EOF LH	84002SG230	2380.00	61		
64	HORN ASSY LOW	86012SG000	57.80	2		
65	HORN ASSY HIGH	86029FG000	57.80	2		
66	BRKT HORN	86041FG000	10.80	2		
67	MOTOR & PUMP ASSYFR	86611SG000	61.20	2		
68	MOTOR & PUMP ASSYRR	86611SG010	64.80	2		
69	MOTOR & PUMP ASSYHL	86611VA000	170.00	2		
70	CAP	86615FJ000	7.20	2		
71	TANK (SUPP) HLS	86631SG030	93.60	2		
72	NOZZLE F	86636SG000	28.80	2		
73	NOZZLE H L WASHERRH	86636SG361	79.20	2		
74	NOZZLE H L WASHERLH	86636SG371	79.20	dis	photo	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

			DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS

75 NOZZLE COVER ASSYRH	86636SG380TQ	54.00	3 no.		
76 NOZZLE COVER ASSYLH	86636SG390TQ	54.00	ms /		
77 HOSE ASSY F STD	USE SG000 86655SG001	39.60	3 } no.		
78 HOSE ASSY F SUB	86655SG010	7.20	3 } no.		
79 HOSE ASSY H/L WAS	86655SG150	64.80	2 no.		
80 GRILLE ASSY F UPRHG	91121SG210	140.40	as / 150.85		
81 GRILLE ASSY F CTRHG	91121SG240	180.00	as /		
82 GRILLE ASSY F LWRHG	91121SG280	316.80	as /		
83 BRKT GRILLE LWR NA	91165SG000	21.60	as /		
84 COWL PANEL ASSY RHD	91419SG001	144.00	2 no.		
85 COWL PANEL SD RH	91423SG000	7.20	2 no.		
86 COWL PANEL SD LH (SUPP)	91423SG010	7.20	2 no.		
87 AIR B MOD ASSY D	98211SG100VH	4800.00	3 act / 2400		
88 CONT UNIT AB	98221SG190	4760.00	act / 2380		
89 SENSOR ASSY F SUBSUB	98231SG010	340.00	act /		
90 AIR B SATL SEN SS	98237SG030	288.00	act / HH		
91 AIR B MOD ASSY P	98271SG030	4800.00	act X HH		
92 AIR B MOD ASSY K	98301SG000VH	1800.00	act / 900		
SUB TOTAL		32777.12	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		6555.42	0.00	0.00	0.00
GRAND TOTAL		26221.70	0.00	0.00	0.00
OVERALL TOTAL		26221.70			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJN7666R

TOTAL LABOUR CHARGES	8335.00
TOTAL SPARE PARTS CHARGES	26221.70
GRAND TOTAL	34556.70 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TORIMAGE ENTERPRISES PTE. LTD.
LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
INVOICE NO :
REFERENCE : INS/IC/JHI/016/2019
DATE : 25-MAR-2019

IG ASIA PACIFIC INSURANCE PTE LTD
3 SHENTON WAY
07-16 AIG BUILDING
(079120)
TEL : 91007211
FAX :
OTOR CLAIM DEPT

OWNER'S NAME : LOW WEI CHEONG (LUO WEICHANG)
ADDRESS : 985 BUKIT TIMAH ROAD
#08-06
S(589627)
TELEPHONE NO : 8488 7666

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700031584-01
VEHICLE NO : SJN7666R
MODEL CODE : SJ5GK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YA52841
CHASSIS NO : JF1SJ5KCSHG093125
MILEAGE : 1 KM
DATE IN : 25/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 25/03/2019

Print Date : 25/03/2019
Print Time : 21:00:42

Tanpin 97495749/67418434
WP
27/3/19 @ 1130
Resurvey before paint
12 days
save lkk auto. com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

16/10 Email to Dennis
WR # 24,567.96, 12 days

STORIMAGE ENTERPRISES PTE. LTD.
5 LENG KEE ROAD
SINGAPORE 159097

QUOTATION NO. 001

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJN7666R

ESTAL LABOUR CHARGES	8335.00
ESTAL SPARE PARTS CHARGES	26221.70

RAND TOTAL	34556.70 *

All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
ACCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

DISCLAIMER : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/016/2019
DATE : 25-MAR-2019

AIG ASIA PACIFIC INSURANCE PTE LTD
7B SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : LOW WEI CHEONG (LUO WEICHANG)
ADDRESS : 985 BUKIT TIMAH ROAD
#08-06
S(589627)
TELEPHONE NO : 8488 7666

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700031584-01
VEHICLE NO : SJN7666R
MODEL CODE : SJ5GK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YA52841
CHASSIS NO : JF1SJ5KCSHG093125
MILEAGE : 1 KM
DATE IN : 25/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 25/03/2019

Print Date : 05/06/2019
Print Time : 20:14:48

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJN7666R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE FRONT BUMPER, BUMPER BEAM, BRKT LHS, BRKT RHS, BONNET, FRT GRILL, HEADLAMP AND ETC	2900.00	2800.00 ✓
2	ZZ/002	REMOVE AND REFIX EXHAUST	150.00	.00 X 111
3	ZZ/003	REMOVE & REFIX A/CON CONDENSER & RADIATOR TO FACILITATE REPAIR	220.00	220.00 ✓
4	ZZ/004	REMOVE AND REFIX WIRE HARNESS	300.00	300.00 ✓
5	ZZ/005	REMOVE AND REFIX DASHBOARD	400.00	400.00 ✓
6	ZZ/006	REMOVE AND REFIX SEAT BELT, MODULE & RESET	430.00	430.00 ✓
7	ZZ/007	REMOVE AND REPLACE DRIVER & PASSENGER AIRBAG & RESET	500.00	500.00 ✓
8	ZZ/008	COOLING SYSTEM PRESSURE TEST	100.00	100.00 ✓
9	ZZ/009	TO CONDUCT ANTI RUST COATING	580.00	250.00 ✓
10	ZZ/011	NUMBER PLATE	55.00	55.00 ✓
11	ZZ/012	SUNDRIES	150.00	80.00 ✓
12	ZZ/013	RESPRAY FRT BUMPER, BONNET, FENDER LH, FENDER RH AND BUMPER BEAM	2400.00	1760.00 ✓
13	ZZ/10	TO CONDUCT FRONT LIGHTING TEST	150.00	150.00 ✓
TOTAL LABOUR CHARGES			8335.00	7045.00 ✗

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

S/NO	PARTS DESCRIPTION	(B) PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST	REMARKS
			NETT	LIST	S/NETT		
1	GAUGE AY-OIL LVL EG	✓ (SUPP) 11139AA050	25.20				OK de ✓
2	BRACKET ASSY-COLLECTOR COVER	✓ (SUPP) 14032AA120	25.20				OK de ✓
3	GROM-COLL COVER	✓ (SUPP) 14096AA020	14.40				OK de ✓
4	BOOT CP-AIR INT ✓	14456AA440	162.00				X n n
5	ELEM CP-OIL FILTER XV	✓ (SUPP) 15208AA160	14.40	✓			OK de ✓
6	METER AY-AIR FLOW ✓	22680AA380	432.00				X n n
7	COVER BELT-ALTERNATOR	✓ (SUPP) 23774AA050	65.55				OK de ✓
8	RELAY ASSY	✓ (SUPP) 25230AA190	11.20				OK de ✓
9	SEN REPAIR S/A	✓ (SUPP) 27549AL000	544.00				OK de ✓
10	RADIATOR ASSY (SUPP) ✓	45111SG000	792.00	✓			OK bt ✓
11	FAN	✓ (SUPP) 45121FJ000	54.00				OK crg ✓
12	SHROUD	✓ (SUPP) 45122SG000	86.40				OK crg ✓
13	BRKT RAD LWR	✓ (SUPP) 45124AG010	14.40				OK de ✓
14	BRKT RAD UPR	✓ (SUPP) 45124SC000	14.40				OK de ✓
15	BRKT ASSY OIL CLR ✓	45124SG000	14.40				OK de ✓
16	MOTOR	✓ (SUPP) 45131FG003	272.00				OK ju ✓
17	CUSHION	✓ (SUPP) 45135AE030	4.00				OK ne ✓
18	CUSHION	✓ (SUPP) 45135FE000	2.40				OK ne ✓
19	CAP AY-RAD	✓ (SUPP) 45137AE003	28.80				OK de ✓
20	TANK RESERVE (SUPP) ✓	45150SG001	61.20	✓			OK de ✓
21	HOSE-RADIATOR INLET (SUPP) ✓	45161SC010	36.00	✓			OK de ✓
22	HOSE-RADIATOR OUTLET ✓	45161SC020	36.00				X n n
23	PACKING RAD SD	✓ (SUPP) 45167SG000	8.65				OK ne ✓
24	PACKING RAD PNL	✓ (SUPP) 45167SG010	18.00				OK ne ✓
25	COOLER ATF ✓	45512SG000	396.00	✓			OK ne ✓

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	HOSE ATF ✓	45520AG100	27.00			X
27	HOSE ATF ✓	45520AG110	36.00			X
28	HOSE ATF AIR IN ✓	45520SG000	36.00			X
29	HOSE ATF AIR OUT ✓	45520SG010	36.00			X
30	PIPE ATF COMPL ✓	45522SG001	82.80			X
31	CLAMP HOSE ✓	45527SG000	3.60			X
32	DUCT AIR INTAKE ✓	46012SG000	36.00	✓		OK de ✓
33	RESONATOR ✓	46043FG000	43.20			X nq
34	CASE-AIR CLNR UPR ✓	46052AG070	108.00			X nq
35	CASE-AIR CLNR LWR ✓	46052SG000	36.00			X nq
36	FRAME LWR B CP ✓	(SUPP) 51231AG0009P	112.00			OK bt ✓
37	RAD PNL COMPL RPR ✓	53029SG0019P	360.00	✓		OK bt ✓
38	UNDER COVER COM FNA (SUPP) ✓	56410SG050	158.40	✓		OK bt ✓
39	FRT FENDER RH ✓	(SUPP) 57120SG0209P	270.00			OK bt ✓
40	FRT FENDER LH ✓	(SUPP) 57120SG0309P	270.00			OK bt ✓
41	BRKT FENDER R CP RH ✓	57150SG0009P	14.40			X
42	BRKT FENDER R CP LH ✓	57150SG0109P	14.40			X
43	EXT FENDER F CP RH ✓	57160SG0009P	25.20			X
44	EXT FENDER F CP LH ✓	57160SG0109P	25.20			X
45	HOOD F CPL ✓	(SUPP) 57229SG0009P	882.00			OK bt ✓
46	STAY ASSY F HOOD ✓	57251SG001	93.60			X nq
47	BUFFER A F HOOD ✓	(SUPP) 57254AA011	4.00			OK de ✓
48	COVER FENDER UPR RH ✓	57256SG020	18.00			X nq
49	COVER FENDER UPR RH (SUPP) ✓	57256SG030	18.00			X nq

NOTORIMAGE ENTERPRISES PTE. LTD.
15 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
50	HINGE COMPL F HD RH ✓	57260SG0009P	43.20	✓		OK <i>ht</i> ✓
51	HINGE COMPL F HD LH ✓	57260SG0109P	43.20	✓		OK <i>ht</i> ✓
52	STOPPER ✓	57275SG000	10.80	✓		OK <i>ht</i> ✓
53	LOCK ASSY F HOOD ISR ✓	57310SG020	72.00	✓		OK <i>ht</i> ✓
54	CABLE ASSY HD ✓	57330SG060	36.00			X <i>un</i>
55	CLIP LEL CABLE ✓	57371GA070	1.64			X <i>un</i>
56	BRKT CORNER F RH ✓	57707SG000	36.00	✓		OK <i>dis</i> ✓
57	BRKT CORNER F LH ✓	57707SG010	36.00	✓		OK <i>dis</i> ✓
58	BRKT SD F RH ✓	57707SG020	12.60			X <i>un</i>
59	BRKT SD F LH ✓	57707SG030	12.60			X <i>un</i>
60	MOLDING BMR F ✓	57708SG020	43.20	✓		OK <i>dis</i> ✓
61	MOLDING BMR F ✓	57708SG030	43.20	✓		OK <i>dis</i> ✓
62	BUMPER FACE F NA (FOR H/L WSH) ✓	57709SG030	594.00	✓		OK <i>dis</i> ✓
63	BACK BEAM CPL F ✓	57711SG0009P	288.00	✓		OK <i>ht</i> ✓
64	ENERGY ABSOR F ✓	57722SG020	126.00	✓		OK <i>dis</i> ✓
65	COVER HOOK F STD ✓	57731SG220	4.40			X <i>un</i>
66	PACKING RAD ✓	(SUPP) 57780SG010	9.00			OK <i>dis</i> ✓
67	MUD GUARD ASSY F RH ✓	USE SG020 59110SG021	86.40			X <i>un</i>
68	MUD GUARD ASSY F LH ✓	SEE SG030 59110SG031	86.40	✓		OK <i>dis</i> ✓
69	CLIP ✓	59122FA010	1.40	✓		OK <i>dis</i> ✓
70	HINGE ASSY DR F FA ✓	60079AG003	46.80			X <i>un</i>
71	HINGE ASSY DR F FB ✓	60079AG013	46.80			X <i>un</i>
72	BELT ASSY F OUT RH ✓	64622SG021VH	688.00	✓		OK <i>aut</i> ✓
73	BELT ASSY F OUT LH ✓	64622SG031VH	688.00	✓		OK <i>aut</i> ✓
74	ADJUSTER SHO ANC ✓	64703FG000ME	144.00			X <i>un</i>

IOTORIMAGE ENTERPRISES PTE. LTD.
 5 LENG KEE ROAD
 SINGAPORE 159097

ATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
------	-------------------	--------------	------	------	--------	----------------

75 PAD & FRAME ASSY RHD	(SUPP) 66040FJ021	720.00	OK des ✓
76 O RING	73039TA030	3.60	X n4
77 O RING	73039TA040	3.60	X n4
78 CONDENSER ASSY (SUPP)	73210SG011	579.35	OK b1 ✓
79 FAN&MOTOR ASSY	73310SG000	468.00	OK des ✓
80 O RING	(SUPP) 806908080	1.10	OK va ✓
81 BOOT TERMINAL	81611YC000	7.20	OK des ✓
82 TRAY BATT	82122AG001	8.00	OK ca ✓
83 COVER BATT	82123SA003	28.80	OK de ✓
84 ROD BATT FIX	82161AG001	4.35	OK des ✓
85 ROD	82161SG000	4.35	OK des ✓
86 HOLDER ASSY	82184SG000	13.60	OK de ✓
87 FUSE BOX COVER	(SUPP) 82243AG010	34.00	OK ca ✓
88 FUSE BOX COVER	(SUPP) 82243SG020	14.40	OK ca ✓
89 STRGROLL CONNECT SET	(SUPP) 83196FJ020	438.60	OK des ✓
90 LAMP ASSY HEAD EOF RH	84002SG220	2380.00	OK ca ✓
91 LAMP ASSY HEAD EOF LH	84002SG230	2380.00	OK ca ✓
92 HORN ASSY LOW	86012SG000	57.80	OK b1 ✓
93 HORN ASSY HIGH	86029FG000	57.80	OK b1 ✓
94 BRKT HORN	86041FG000	10.80	X n4
95 MOTOR & PUMP ASSYFR	86611SG000	61.20	OK des ✓
96 MOTOR & PUMP ASSYRR	86611SG010	64.80	OK des ✓
97 MOTOR & PUMP ASSYHL	86611VA000	170.00	X n4
98 CAP	86615FJ000	7.20	OK des ✓

MOTORIMAGE ENTERPRISES PTE. LTD.
 5 LENG KEE ROAD
 SINGAPORE 159097

ATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

/NO PARTS DESCRIPTION		DAMAGED PARTS & PRICES				S/LIST REMARKS
		PARTS NUMBER	NETT	LIST	S/NETT	
99 TANK (SUPP)	HLS	86631SG030	93.60	✓		OK
100 NOZZLE F		86636SG000	28.80			X

101 NOZZLE H L WASHERRH /		86636SG361	79.20	X
102 NOZZLE H L WASHERLH /		86636SG371	79.20	OK
103 NOZZLE COVER ASSYRH /		86636SG380TQ	54.00	X
104 NOZZLE COVER ASSYLH /		86636SG390TQ	54.00	OK
105 HOSE ASSY F STD /	USE SG000	86655SG001	39.60	X
106 HOSE ASSY F SUB /		86655SG010	7.20	X
107 HOSE ASSY H/L WAS /		86655SG150	64.80	OK
108 CLIP BMR	✓ (SUPP)	909140007	9.60	OK } nee
109 CLIP 2PIECE D7	909140038 ✓ (SUPP)	909140063	3.60	OK }
110 HOSE CLAMP	✓ (SUPP)	909170064	6.50	OK }
111 GRILLE ASSY F UPRHG /		91121SG210	150.85	OK
112 GRILLE ASSY F CTRHG /		91121SG240	180.00	OK
113 GRILLE ASSY F LWRHG /		91121SG280	316.80	OK
114 BRKT GRILLE LWR NA /		91165SG000	21.60	OK
115 BKT GRILLE UPP	✓ (SUPP)	91165SG020	10.80	OK nee
116 COWL PANEL ASSY RHD /		91419SG001	144.00	X nh
117 COWL PANEL SD RH /		91423SG000	7.20	OK de
118 COWL PANEL SD LH (SUPP) /		91423SG010	7.20	OK de
119 AIR B MOD ASSY D /		98211SG100VH	2400.00	OK act
120 CONT UNIT AB /		98221SG190	2380.00	OK act
121 SENSOR ASSY F SUBSUB /		98231SG010	340.00	OK act
122 AIR B SATL SEN SS /		98237SG030	144.00	OK act
123 AIR B MOD ASSY P /		98271SG030	2400.00	X nn

STORIMAGE ENTERPRISES PTE. LTD.
3 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				REMARKS
		NETT	LIST	S/NETT	S/LIST	
124 AIR B MOD ASSY K	98301SG000VH	900.00				OK
SUB TOTAL		21903.70	0.00	0.00	0.00	
LESS DISCOUNT (NETT-20 %)		4380.74	0.00	0.00	0.00	
GRAND TOTAL		17522.96	0.00	0.00	0.00	

OVERALL TOTAL

17522.96

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJN7666R

NETT ITEM	21903.70
LESS 20 %	-4380.74
NETT AMOUNT	17522.96

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00
---------------------	------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	7045.00
TOTAL SPARE PARTS CHARGES	17522.96

TOTAL CHARGES	24567.96 *
ADD 7 % GST	1719.76

GRAND TOTAL	26287.72
-------------	----------

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5394C

Vehicle Details

Vehicle No.: SJN7666R
Vehicle to be Exported: No
Intended Deregistration Date: 27 Mar 2019
Vehicle Make: SUBARU
Vehicle Model: FORESTER 2.0I-L CVT AWD SR
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: FB20YA52841
Chassis No.: JF1SJ5KC5HG093125
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$14,468.00
Original Registration Date: 26 Jul 2017
First Registration Date: 26 Jul 2017
Transfer Count: 0
Actual ARF Paid: \$14,468.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Jul 2027
PARF Rebate Amount: \$10,851.00

Intended COE Rebate Details

COE Expiry Date: 25 Jul 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$49,802.00
COE Rebate Amount: \$41,462.00
Total Rebate Amount: \$52,313.00

The information contained herein is correct as at 27 Mar 2019

OK

Mei Kwan (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Friday, 5 April, 2019 7:42 PM
To: 'Jeannie Cheng'
Cc: 'Survey.Report@ergo.com.sg'; 'ERGO Insurance Pte. Ltd. (Claims Department)'; Vic (LKKAuto); CS A Team; Admin A
Subject: RE: PRS IRO SJN7666R | OI : GBA5074A | DOA: 18/03/2019| ERGO REF: CDMCG19000492/SL/jc
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf
Categories: HMK

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

EGI ref: CDMCG19000492/SL/JC
LKK REF: CC4/EGI19005384/T1ha3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SJN 7666R

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Please take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jeannie Cheng [<mailto:jeannie.cheng@ergo.com.sg>]
Sent: Tuesday, 26 March 2019 11:39 AM
To: admin-d@lkkauto.com
Cc: sur@lkkauto.com
Subject: FW: PRS IRO SJN7666R | OI : GBA5074A | DOA: 18/03/2019| ERGO REF: CDMCG19000492/SL/jc

Hi LKK,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company to be the "Single Joint Expert".

To: Dennis Leong <dennisleong@motorimage.net>
Cc: Jeannie Cheng <jeannie.cheng@ergo.com.sg>; Survey Report (ERGO Insurance Pte. Ltd.)
<Survey.Report@ergo.com.sg>
Subject: PRS IRO SJN7666R | OI : GBA5074A | DOA: 18/03/2019| ERGO REF: CDMCG19000492/SL/jc

Step 1

WITHOUT PREJUDICE

Dear Sir,

We acknowledged receipt of your email for the PRS request as below.

In compliance with “State Courts Practice Directions Amendment No.1 of 2016”, do select an assessor from the list below.

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd

Kindly let us have your reply on the selection of the surveyor.

Thank you.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
jeannie.cheng@ergo.com.sg

www.ergo.com.sg



ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd, will not be liable for any loss or damage thereby caused.

From: Dennis Leong [<mailto:dennisleong@motorimage.net>]
Sent: Tuesday, March 26, 2019 9:24 AM

FW: PRS IRO SJN7666R | OI : GBA5074A | DOA: 18/03/2019| ERGO REF: CDMCG19000492/SL/jc

Dennis Leong

Wed 16/10/2019 6:09 PM

To: Sayedinah <sayedinah@motorimage.net>

fyi

From: Jeannie Cheng [mailto:jeannie.cheng@ergo.com.sg]

Sent: Wednesday, 27 March 2019 4:31 PM

To: Dennis Leong <dennisleong@motorimage.net>

Cc: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Subject: RE: PRS IRO SJN7666R | OI : GBA5074A | DOA: 18/03/2019| ERGO REF: CDMCG19000492/SL/jc

Hi Dennis,

Liability clear.

Thank you.

Warmest Regards,

Jeannie Cheng

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five

Singapore 038985

jeannie.cheng@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Dennis Leong [mailto:dennisleong@motorimage.net]

Sent: Wednesday, March 27, 2019 12:03 PM

To: Jeannie Cheng

Cc: Survey Report (ERGO Insurance Pte. Ltd.)

Subject: RE: PRS IRO SJN7666R | OI : GBA5074A | DOA: 18/03/2019| ERGO REF: CDMCG19000492/SL/jc

Hi Jeannie,

Kindly advise liability of claim.

Thank you

FW: SJN7666R CLAIM AGAINST GBA5074A ERGO REF: CDMCG19000492/SL/jc ***
LKK REF: CC4/EGI19005384/T1ka3

Dennis Leong

Wed 16/10/2019 6:08 PM

To: Sayedinah <sayedinah@motorimage.net>

Fyi

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]

Sent: Wednesday, 16 October 2019 3:52 PM

To: Dennis Leong <dennisleong@motorimage.net>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: SJN7666R CLAIM AGAINST GBA5074A ERGO REF: CDMCG19000492/SL/jc *** LKK REF: CC4/EGI19005384/T1ka3

WITHOUT PREJUDICE

Dear Sir/Madam,

The above matter and your e-mail below refers.

Please be informed that our principal has reviewed the claim.

Based on all documents at hand and video footage, we noted that your client had collided head to rear with our Insured vehicle
and hence, we opine that liability is down against your client.

As such, we have our principal's instruction to reject the claim and we are unable to look into your client's claim.

We will now close the matter in our end.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khanchna (LKK Auto)

Sent: Wednesday, 16 October 2019 9:54 AM

To: Su Li (LKK Auto) <suli@lkkauto.com>; Dennis Leong <dennisleong@motorimage.net>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: LKINSTEAM <LKINSTEAM@tanchong.org>; Admin A <admin-a@lkkauto.com>

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 25 February 2020 6:00 PM
To: ying@smemotor.com.sg
Cc: Admin A
Subject: Request to amend OI GIA - Accident between SJN 7666R & GBA 5074A on 17/03/2019

WITHOUT PREJUDICE

Dear Ying,

The above matter refers.

Please assist to amend the date of accident to "17/03/2019" on our mutual client's GIA and please let us have the amended GIA.

MSME19030638 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 19/03/2019 17:19
SUBMITTED BY: Chia Pei Ying

UNPUBLISHED POLICYHOLDERS' INFORMATION

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

ACCIDENT STATEMENT	
Date Of Report	19/03/2019 17:19
Date Of Accident	18/03/2019 02:00
Exact Location Of Accident	DUNEARN RD AFTER JUNCTION OF SWISS CLUB RD & DUNEARN RD
Country/State Of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBA5074A
Insured/Policyholder	
Name Of Registered Owner	SYSTEM CLEANING & SUPPLIES PTE LTD

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 3 March 2020 3:17 PM
To: Dennis Leong
Cc: Admin A
Subject: RE: SJN7666R CLAIM AGAINST GBA5074A ERGO REF: CDMCG19000492/SL/jc *** LKK REF: CC4/EGI19005384/T1ka3
Attachments: ERGO DV.pdf

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as per your LOD.

We attach herewith a copy of the DV for your further action.

Kindly e-mail the DV to us for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Dennis Leong <dennisleong@motorimage.net>
Sent: Tuesday, 25 February 2020 11:43 AM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; LKINSTEAM <LKINSTEAM@tanchong.org>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: RE: SJN7666R CLAIM AGAINST GBA5074A ERGO REF: CDMCG19000492/SL/jc *** LKK REF: CC4/EGI19005384/T1ka3

Hi Team,

Kindly advise payment status.

BREAKDOWN OF PAYMENT

VEHICLE NO : SJN7666R

ACCIDENT ON 17/03/2019 AT DUNEARN ROAD

INVOLVING VEHICLE / S GBAS074A

- 1) Repair cost \$ 26,287.72 Payable to Motor Image Enterprises Pte Ltd
- 2) GIA or ~~LTA~~
Search fees \$ 2.00 Payable to Motor Image Enterprises Pte Ltd
- 3) Medical fees \$ — Payable to —
- 4) Loss Of Use or
~~Rental Car~~ \$ 960.00 Payable to LOW WEI CHEONG
- 5) Total Claim Amount \$ 27,249.72

***KINDLY SEPARATE THE PAYMENT IN 2 CHEQUES**

*Contact Person : Dennis Leong Jia Hui
6703 8161
DennisLeong@motorimage.net

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CC4/EGI19005384/T1ka3q2

5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 17-03-2020



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 5074A	Veh. Inspected	SJN 7666R
Policy No.	DMCG18002741	Coverage (\$)	0.00
Claim No.	CDMCG19000492/SL/JC	Excess (\$)	0.00
Assign From	JEANNIE CHENG	Assign Date	26/03/2019

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JF1SJ5KC5HG093125	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/03/2019	Inspection Date	27/03/2019
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 7666R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT CP-AIR INT (N)	NOT NECESSARY	162.00	-
1	METER AY-AIR FLOW (N)	NOT NECESSARY	432.00	-
1	RADIATOR ASSY (N)	BENT	792.00	792.00
1	BRKT ASSY OIL CLR (N)	BENT	14.40	14.40
1	TANK RESERVE (N)	DEFORMED	61.20	61.20
1	HOSE -RADIATOR INLET (N)	DEFORMED	36.00	36.00
1	HOSE-RADIATOR OUTLET (N)	NOT NECESSARY	36.00	-
1	COOLANT ATF (N)	NECESSARY	396.00	396.00
1	HOSE ATF (N)	NOT NECESSARY	27.00	-
1	HOSE ATF (N)	NOT NECESSARY	36.00	-
1	HOSE ATF AIR IN (N)	NOT NECESSARY	36.00	-
1	HOSE ATF AIR OUT (N)	NOT NECESSARY	36.00	-
1	PIPE ATF COMPL (N)	NOT NECESSARY	82.80	-
1	CLAMP HOSE (N)	NOT NECESSARY	3.60	-
1	DUCT AIR INTAKE (N)	DEFORMED	36.00	36.00
1	RESONATOR (N)	NOT NECESSARY	43.20	-
1	CASE -AIR CLNR UPR (N)	NOT NECESSARY	108.00	-
1	CASE-AIR CLNR LWR (N)	NOT NECESSARY	36.00	-
1	RAD PNL COMPL RPR (N)	BENT	720.00	360.00
1	UNDER COVER COM FNA (N)	BENT	158.40	158.40
1	BRKT FENDER R CP RH (N)	NOT NECESSARY	28.80	-
1	BRKT FENDER R CP LH (N)	NOT NECESSARY	28.80	-
1	EXT FENDER F CP RH (N)	NOT NECESSARY	50.40	-
1	EXT FENDER F CP LH (N)	NOT NECESSARY	25.20	-
1	STAY ASSY F HOOD (N)	NOT NECESSARY	187.20	-
1	COVER FENDER UPR RH (N)	NOT NECESSARY	36.00	-
1	COVER FENDER UPR RH (N)	NOT NECESSARY	36.00	-
1	HINGE COMPL F HD RH (N)	BENT	86.40	43.20
1	HINGE COMPL F HD LH (N)	BENT	86.40	43.20
1	STOPPER (N)	NECESSARY	10.80	10.80
1	LOCK ASSY F HOOD ISR (N)	BENT	144.00	72.00

Report Ref No. CC4/EGI19005384/T1ka3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CABLE ASSY HD (N)	NOT NECESSARY	72.00	-
1	CLIP LEL CABLE (N)	NOT NECESSARY	3.28	-
1	BRKT CORNER F RH (N)	DISTORTED	36.00	36.00
1	BRKT CORNER F LH (N)	DISTORTED	36.00	36.00
1	BRKT SD F RH (N)	NOT NECESSARY	12.60	-
1	BRKT SD F LH (N)	NOT NECESSARY	12.60	-
1	MOLDING BMPR F (N)	CUT	43.20	43.20
1	MOLDING BMPR F (N)	CUT	43.20	43.20
1	BUMPER FACE F NA (FOR H/L WSH) (N)	DEFORMED	594.00	594.00
1	BACK BEAM CPL F (N)	BENT	288.00	288.00
1	ENERGY ABSOR F (N)	DEFORMED	126.00	126.00
1	COVER HOOK F STD (N)	NOT NECESSARY	4.40	-
1	MUD GUARD ASSY F RH (N)	NOT NECESSARY	86.40	-
1	MUD GUARD ASSY F LH (N)	DEFORMED	86.40	86.40
1	CLIP (N)	NECESSARY	1.40	1.40
1	HINGE ASSY DR F FA (N)	NOT NECESSARY	46.80	-
1	HINGE ASSY DR F FB (N)	NOT NECESSARY	46.80	-
1	BELT ASSY F OUT RH (N)	CUT	1,376.00	688.00
1	BELT ASSY F OUT LH (N)	CUT	1,376.00	688.00
1	ADJUSTER SHO ANC (N)	NOT NECESSARY	144.00	-
1	O RING (N)	NOT NECESSARY	3.60	-
1	ORING (N)	NOT NECESSARY	3.60	-
1	CONDENSER ASSY (N)	BENT	579.35	579.35
1	FAN& MOTOR ASSY (N)	DISTORTED	468.00	468.00
1	BOOT TERMINAL (N)	DISTORTED	7.20	7.20
1	TRAY BATT (N)	CRACKED	8.00	8.00
1	COVER BATT (N)	DEFORMED	28.80	28.80
1	ROD BATT FIX (N)	DISTORTED	4.35	4.35
1	ROD (N)	DISTORTED	4.35	4.35
1	HOLDER ASSY (N)	DEFORMED	13.60	13.60
1	LAMP ASSY HEAD EOF RH (N)	CRACKED	2,380.00	2,380.00
1	LAMP ASSY HEAD EOF L (N)	CRACKED	2,380.00	2,380.00
1	HORN ASSY LOW (N)	BENT	57.80	57.80

Report Ref No. CC4/EGI19005384/T1ka3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HORN ASSY HIGH (N)	BENT	57.80	57.80
1	BRKT HORN (N)	NOT NECESSARY	10.80	-
1	MOTOR & PUMP ASSYFR (N)	DISTORTED	61.20	61.20
1	MOTOR & PUMP ASSYRR (N)	JAMMED	64.80	64.80
1	MOTOR & PUMP ASSYHL (N)	NOT NECESSARY	170.00	-
1	CAP (N)	NECESSARY	7.20	7.20
1	TANK (N)	DEFORMED	93.60	93.60
1	NOZZLE F (N)	NOT NECESSARY	28.80	-
1	NOZZLE H L WASHERRH (N)	NOT NECESSARY	79.20	-
1	NOZZLE H L WASHERLH (N)	DISTORTED	79.20	79.20
1	NOZZLE COVER ASSYRH (N)	NOT NECESSARY	54.00	-
1	NOZZLE COVER ASSYLH (N)	MISSING	54.00	54.00
1	HOSE ASSY F STD (N)	NOT NECESSARY	39.60	-
1	HOSE ASSY F SUB (N)	NOT NECESSARY	7.20	-
1	HOSE ASSY H/L WAS (N)	DEFORMED	64.80	64.80
1	GRILLE ASSY F UPRHG (N)	CRACKED	150.85	150.85
1	GRILLE ASSY F CTRHG (N)	CRACKED	180.00	180.00
1	GRILLE ASSY F LWRHG (N)	CRACKED	316.80	316.80
1	BRKT GRILLE LWR NA (N)	DISTORTED	21.60	21.60
1	COWL PANEL ASSY RHD (N)	NOT NECESSARY	144.00	-
1	COWL PANEL SD RH (N)	DEFORMED	7.20	7.20
1	COWL PANEL SD LH (N)	DEFORMED	7.20	7.20
1	AIR B MOD ASSY D (N)	ACTIVATED	4,800.00	2,400.00
1	CONT UNIT AB (N)	ACTIVATED	4,760.00	2,380.00
1	SENSOR ASSY F SUBSUB (N)	CUT	340.00	340.00
1	AIR B SATL SEN SS (N)	ACTIVATED	288.00	144.00
1	AIR B MOD ASSY P (N)	NOT NECESSARY	4,800.00	-
1	AIR B MOD ASSY K (N)	ACTIVATED	1,800.00	900.00
1	GAUGE AY-OIL LVK EG (ADDITIONAL)(N)	DEFORMED	25.20	25.20
1	BRACKET ASSY-COLLECTOR COVER (ADDITIONAL)(N)	DEFORMED	25.20	25.20
1	GROM-COIL COVER (ADDITIONAL)(N)	DEFORMED	14.40	14.40
1	ELEM CP-OIL FILTER XV (ADDITIONAL)(N)	DEFORMED	14.40	14.40
1	COVER BELT-ALTERNATOR (ADDITIONAL)(N)	DISTORTED	65.55	65.55

Report Ref No. CC4/EGI19005384/T1ka3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RELAY ASSY (ADDITIONAL)(N)	DISTORTED	11.20	11.20
1	SEN REPAIR S/A (ADDITIONAL)(N)	DISTORTED	544.00	544.00
1	FAN (ADDITIONAL)(N)	CRACKED	54.00	54.00
1	SHROUD (ADDITIONAL)(N)	CRACKED	86.40	86.40
1	BARKT RAD LWR (ADDITIONAL)(N)	DISTORTED	14.40	14.40
1	BRKT RAD UPR (ADDITIONAL)(N)	DISTORTED	14.40	14.40
1	MOTOR (ADDITIONAL)(N)	JAMMED	272.00	272.00
1	CUSHION (ADDITIONAL)(N)	NECESSARY	4.00	4.00
1	CUSHION (ADDITIONAL)(N)	NECESSARY	2.40	2.40
1	CAP AY-RAD (ADDITIONAL)(N)	DEFORMED	28.80	28.80
1	PACKING RAD SD (ADDITIONAL)(N)	NECESSARY	8.65	8.65
1	PACKING RAD PNL (ADDITIONAL)(N)	NECESSARY	18.00	18.00
1	FRAME LWR B CP (ADDITIONAL)(N)	BENT	112.00	112.00
1	FRT FENDER RH (ADDITIONAL)(N)	BENT	270.00	270.00
1	FRT FENDER RH (ADDITIONAL)(N)	BENT	270.00	270.00
1	HOOD F CPL (ADDITIONAL)(N)	BENT	882.00	882.00
1	BUFFER A F HOOD (ADDITIONAL)(N)	DEFORMED	4.00	4.00
1	PACKING RAD (ADDITIONAL)(N)	DEFORMED	9.00	9.00
1	PAD & FRAMEASSY RHD (ADDITIONAL)(N)	DISTORTED	720.00	720.00
1	O RING (ADDITIONAL)(N)	NECESSARY	1.10	1.10
1	FUSE BOX COVER (ADDITIONAL)(N)	CRACKED	34.00	34.00
1	FUSE BOX COVER (ADDITIONAL)(N)	CRACKED	14.40	14.40
1	SET STRGROLL CONNECT (ADDITIONAL)(N)	DISTORTED	438.60	438.60
1	CLIP BMPR (ADDITIONAL)(N)	NECESSARY	9.60	9.60
1	CLIP 2 PIECE D7 (ADDITIONAL)(N)	NECESSARY	3.60	3.60
1	HOSE CLAMP (ADDITIONAL)(N)	NECESSARY	6.50	6.50
1	BKT GRILLE UPP (ADDITIONAL)(N)	NECESSARY	10.80	10.80
	LESS 20% DISCOUNT		-7,364.56	-4,380.74
			29,458.22	17,522.96
SPECIAL NETT ITEMS				
1	NUMBER PLATE (SN)	BENT	55.00	55.00

Report Ref No. CC4/EG19005384/T1ka3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)		
1	SUNDRIES (SN)	NECESSARY	150.00	80.00		
			205.00	135.00		
	LABOUR REPLACE FRONT BUMPER ,BUMPER BEAM ,BRKT LHS ,BRKT RHS ,BONNET ,FRT GRILLE ,HEADLAMP AND ETC. REMOVE AND REFIX EXHAUST . REMOVE & REFIX A/CON CONDENSER & RADIATOR TO FACILITATE REPAIR. REMOVE AND REFIX WIRE HARNESS. REMOVE AND REFIX DASHBOARD . REMOVE AND REFIX SEAT ,BEALT ,MODULE & RESET . REMOVE AND REPLACE DRIVER & PASSENGER AIRBAG & RESET. COOLING SYSTEM PRESSURE TEST. TO CONDUCT ANTI RUST COATING. RESPRAY FRT BUMPER ,BONNET ,FENDER LH ,FENDER RH AND BUMPER BEAM. TO CONDUCT FRONT LIGHTING TEST.	NOT NECESSARY	2,900.00	2,800.00		
			150.00	-		
			220.00	220.00		
			300.00	300.00		
			400.00	400.00		
			430.00	430.00		
			500.00	500.00		
			100.00	100.00		
			580.00	250.00		
			2,400.00	1,760.00		
			150.00	150.00		
			8,130.00	6,910.00		
			GRAND TOTAL		37,793.22	24,567.96
			RECOMMENDED COST OF REPAIRS			24,567.96

Report Ref No. CC4/EGI19005384/T1ka3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.