

OTORIMAGE ENTERPRISES PTE. LTD.
5 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/016/2019
DATE : 25-MAR-2019

AIG ASIA PACIFIC INSURANCE PTE LTD
18 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : LOW WEI CHEONG (LUO WEICHANG)
ADDRESS : 985 BUKIT TIMAH ROAD
#08-06
S(589627)
TELEPHONE NO : 8488 7666

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700031584-01
VEHICLE NO : SJN7666R
MODEL CODE : SJ5GK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YA52841
CHASSIS NO : JF1SJ5KC5HG093125
MILEAGE : 1 KM
DATE IN : 25/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 25/03/2019

Print Date : 25/03/2019
Print Time : 21:00:42

Tanpin 97495749 / 67418434
'WP'
27/3/19 @ 1130.
Resurvey before paint
10 days
save lkk auto. work

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
15 LENG KEE ROAD
SINGAPORE 159097

STIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJN7666R

/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE FRONT BUMPER, BUMPER BEAM, BRKT LHS, BRKT RHS, BONNECT, FRT GRILL, HEADLAMP AND ETC 560-	2900.00	2800
2	ZZ/002	REMOVE AND REFIX EXHAUST	150.00	? photo.
3	ZZ/003	REMOVE & REFIX A/CON CONDENSER & RADIATOR TO FACILITATE REPAIR	220.00	✓
4	ZZ/004	REMOVE AND REFIX WIRE HARNESS	300.00	✓
5	ZZ/005	REMOVE AND REFIX DASHBOARD	400.00	✓
6	ZZ/006	REMOVE AND REFIX SEAT BEALT, MODULE \$ RESET	430.00	✓
7	ZZ/007	REMOVE AND REPLACE DRIVER & PASSENGER AIRBAG & RESET	500.00	✓
8	ZZ/008	COOLING SYSTEM PRESSURE TEST	100.00	✓
9	ZZ/009	TO CONDUCT ANTI RUST COATING	580.00	250.
10	ZZ/011	NUMBER PLATE	55.00	67 ✓
11	ZZ/012	SUNDRIES	150.00	80.
12	ZZ/013	RESPRAY FRT BUMPER, BONNECT, FENDER LH, FENDER RH AND BUMPER BEAM 440	2400.00	1760
13	ZZ/10	TO CONDUCT FRONT LIGHTING TEST	150.00	✓
TOTAL LABOUR CHARGES			8335.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	BOOT CP-AIR INT	14456AA440	162.00	?		
2	METER AY-AIR FLOW	22680AA380	432.00	?		
3	RADIATOR ASSY (SUPP)	45111SG000	792.00	?		
4	BRKT ASSY OIL CLR	45124SG000	14.40	?		
5	TANK RESERVE (SUPP)	45150SG001	61.20	?		
6	HOSE-RADIATOR INLET (SUPP)	45161SC010	36.00	?		
7	HOSE-RADIATOR OUTLET	45161SC020	36.00	?		
8	COOLER ATF	45512SG000	396.00	?		
9	HOSE ATF	45520AG100	27.00	?		
10	HOSE ATF	45520AG110	36.00	?		
11	HOSE ATF AIR IN	45520SG000	36.00	?		
12	HOSE ATF AIR OUT	45520SG010	36.00	?		
13	PIPE ATF COMPL	45522SG001	82.80	?		
14	CLAMP HOSE	45527SG000	3.60	?		
15	DUCT AIR INTAKE	46012SG000	36.00	?		
16	RESONATOR	46043FG000	43.20	?		
17	CASE-AIR CLNR UPR	46052AG070	108.00	?		
18	CASE-AIR CLNR LWR	46052SG000	36.00	?		
19	RAD PNL COMPL RPR	53029SG0019P	720.00	?		
20	UNDER COVER COM FNA (SUPP)	56410SG050	158.40	?		
21	BRKT FENDER R CP RH	57150SG0009P	28.80	?		
22	BRKT FENDER R CP LH	57150SG0109P	28.80	?		
23	EXT FENDER F CP RH	57160SG0009P	50.40	?		
24	EXT FENDER F CP LH	57160SG0109P	25.20	?		
25	STAY ASSY F HOOD	57251SG001	187.20	?		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

		DAMAGED PARTS & PRICES				
/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	COVER FENDER UPR RH	57256SG020	36.00	?		
27	COVER FENDER UPR RH (SUPP)	57256SG030	36.00	?		
28	HINGE COMPL F HD RH	57260SG0009P	86.40	bt		
29	HINGE COMPL F HD LH	57260SG0109P	86.40	bt		
30	STOPPER	57275SG000	10.80	?		
31	LOCK ASSY F HOOD ISR	57310SG020	144.00	bt		
32	CABLE ASSY HD	57330SG060	72.00	?		
33	CLIP LEL CABLE	57371GA070	3.28	?		
34	BRKT CORNER F RH	57707SG000	36.00	?		
35	BRKT CORNER F LH	57707SG010	36.00	?		
36	BRKT SD F RH	57707SG020	12.60	?		
37	BRKT SD F LH	57707SG030	12.60	?		
38	MOLDING BMPR F	57708SG020	43.20	ant		
39	MOLDING BMPR F	57708SG030	43.20	ant		
40	BUMPER FACE F NA (FOR H/L WSH)	57709SG030	594.00	de		
41	BACK BEAM CPL F	57711SG0009P	288.00	? photo		
42	ENERGY ABSOR F	57722SG020	126.00	? photo		
43	COVER HOOK F STD	57731SG220	4.40	mis		
44	MUD GUARD ASSY F RH	USE SG020 59110SG021	86.40	.		
45	MUD GUARD ASSY F LH	SEE SG030 59110SG031	86.40	de		
46	CLIP	59122FA010	1.40	ur		
47	HINGE ASSY DR F FA	60079AG003	46.80	X		
48	HINGE ASSY DR F FB	60079AG013	46.80	X		
49	BELT ASSY F OUT RH	64622SG021VH	1376.00	ant		

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
50 BELT ASSY F OUT LH	64622SG031VH	1376.00	act ✓		
51 ADJUSTER SHO ANC	64703FG000ME	144.00	?		
52 O RING	73039TA030	3.60	?		
53 O RING	73039TA040	3.60	?		
54 CONDENSER ASSY (SUPP)	73210SG011	532.80	?		
55 FAN&MOTOR ASSY	73310SG000	468.00	?		
56 BOOT TERMINAL	81611YC000	7.20	?		
57 TRAY BATT	82122AG001	8.00	?		
58 COVER BATT	82123SA003	28.80	?		
59 ROD BATT FIX	82161AG001	4.32	?		
60 ROD	82161SG000	4.32	?		
61 HOLDER ASSY	82184SG000	13.60	?		
62 LAMP ASSY HEAD EOF RH	84002SG220	2380.00	act ✓		
63 LAMP ASSY HEAD EOF LH	84002SG230	2380.00	act ✓		
64 HORN ASSY LOW	86012SG000	57.80	?		
65 HORN ASSY HIGH	86029FG000	57.80	?		
66 BRKT HORN	86041FG000	10.80	?		
67 MOTOR & PUMP ASSYFR	86611SG000	61.20	?		
68 MOTOR & PUMP ASSYRR	86611SG010	64.80	?		
69 MOTOR & PUMP ASSYHL	86611VA000	170.00	?		
70 CAP	86615FJ000	7.20	?		
71 TANK (SUPP) HLS	86631SG030	93.60	?		
72 NOZZLE F	86636SG000	28.80	?		
73 NOZZLE H L WASHERRH	86636SG361	79.20	?		
74 NOZZLE H L WASHERLH	86636SG371	79.20	dis ✓ photo		

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN7666R

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
------------------------	--------------	------	------	--------	----------------

75 NOZZLE COVER ASSYRH	86636SG380TQ	54.00	?		
76 NOZZLE COVER ASSYLH	86636SG390TQ	54.00	ms ✓		
77 HOSE ASSY F STD	USE SG000 86655SG001	39.60	?		
78 HOSE ASSY F SUB	86655SG010	7.20	?		
79 HOSE ASSY H/L WAS	86655SG150	64.80	?		
80 GRILLE ASSY F UPRHG	91121SG210	140.40	as ✓		
81 GRILLE ASSY F CTRHG	91121SG240	180.00	as ✓		
82 GRILLE ASSY F LWRHG	91121SG280	316.80	as ✓		
83 BRKT GRILLE LWR NA	91165SG000	21.60	ds ✓		
84 COWL PANEL ASSY RHD	91419SG001	144.00	?		
85 COWL PANEL SD RH	91423SG000	7.20	?		
86 COWL PANEL SD LH (SUPP)	91423SG010	7.20	?		
87 AIR B MOD ASSY D	98211SG100VH	4800.00	2 act ✓		
88 CONT UNIT AB	98221SG190	4760.00	act ✓		
89 SENSOR ASSY F SUBSUB	98231SG010	340.00	act ✓		
90 AIR B SATL SEN SS	98237SG030	288.00	act ✓		
91 AIR B MOD ASSY P	98271SG030	4800.00	act ✓		
92 AIR B MOD ASSY K	98301SG000VH	1800.00	act ✓		
SUB TOTAL		32777.12	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		6555.42	0.00	0.00	0.00
GRAND TOTAL		26221.70	0.00	0.00	0.00
OVERALL TOTAL		26221.70			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
15 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJN7666R

TOTAL LABOUR CHARGES	8335.00
TOTAL SPARE PARTS CHARGES	26221.70
GRAND TOTAL	34556.70 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.