



Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 25/03/2019

Estimated repair cost for vehicle no: GBJ1389X NISSAN NV350 PANEL VAN 2.5 A '19

CHASSIS: JN1MC2E26Z0030755

CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk C #01-41 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

27/03/2019

TP ALG
Poh Icin

JN1MC2E26Z0030755

S/n	Qty	Items / Nett	U/price	Amount
				\$1,742.00 ✓
1	1	Rear Boot Lid <i>Dented</i>		\$103.20 ✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$51.60	\$398.60 ✓
3	2	Rear Boot Lid Shock Absorber <i>Damaged</i>	\$199.30	\$66.40 ✓
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$101.30 ✓
5	1	Rear Boot Lid Nv350 Logo		\$66.40 ✓
6	1	Rear Boot Lid Urvan Logo		\$511.40 370 ✓
7	1	Rear Boot Lid Center Chrome Moulding <i>Crushed</i>		\$82.00 ✓
8	1	Rear Boot Lid Number Plate Lamp <i>new</i>		\$837.00 ✓
9	1	Rear Boot Lid Windscreen <i>shattered</i>		\$166.20 ✓
10	2	Rear Boot Lid Windscreen Side Moulding <i>new</i>	\$83.10	\$653.00 X 277.1 ✓
11	1	Rear Boot Lid Auto Power Lock Motor Assy <i>Damaged</i>		\$354.50 ✓
12	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$127.50 ✓
13	1	Rear Boot Lid Inner Rubber <i>at</i>		\$223.10 X ✓
14	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$519.60 ✓
15	2	Rear Tail Lamp <i>crushed</i>	\$259.80	\$934.00 X ✓
16	2	Rear Tail Lamp Panel <i>new</i>	\$467.00	\$630.50 ✓
17	1	Rear Bumper <i>Detached</i>		\$44.20 ✓
18	2	Rear Bumper Side Retainer <i>new</i>	\$22.10	\$246.70 ✓
19	1	Rear Bumper Inner Step Panel <i> Bent</i>		\$4,483.60 X ✓
20	2	Rear Fender <i>Repair</i>	\$2,241.80	\$1,134.40 X ✓
21	2	Rear Fender Inner Trim Board <i>new</i>	\$567.20	\$140.60 X ✓
22	2	Rear Fender Air Duct <i>new</i>	\$70.30	\$264.50 ✓
23	1	Rear End Panel <i>Dented</i>		\$95.90 ✓
24	1	Rear End Panel Top Garnish <i>Bent</i>		\$2,462.00 X ✓
25	1	Rear Floor Panel <i>Repair</i>		\$376.00 X ✓
26	1	Rear Spare Tyre Lock <i>new</i>		\$80.70 X ✓
27	1	Rear Spare Tyre Bracket <i>new</i>		\$772.80 X ✓
28	1	Rear Exhaust <i>new</i>		\$74.20 X ✓
29	2	Rear Exhaust Mounting <i>new</i>	\$37.10	\$655.60 X ✓
30	1	Rear Center Exhaust		

End Panel Inner. Repair

699.20
X

6310
4 5679

Subtotal :- \$18,347.90

S/n	Qty	Items / Special Nett	U/price	Amount
31	1	Rear Boot Lid 70km/H Sticker <i>3 new</i>		\$30.00 10
32	1	Rear Boot Lid 8pax Sticker		\$30.00 10
33	1	Rear Boot Lid Number Plate <i>Not new</i>		\$50.00 X
34	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$80.00 60
35	10	Rear Boot Lid Inner Trim Board Clip <i>Not new</i>	\$6.50	\$65.00 X
36	16	Rear Fender Inner Trim Board Clip <i>Not new</i>	\$6.50	\$104.00 X
37	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$380.00 200
38	1	Rear Floor Panel Plywood <i>crushed</i>		\$450.00 200
39	1	Rear Floor Panel Carpet <i>Not new</i>		\$650.00 X
40	1	Body Sticker <i>Not new</i>		\$3,500.00 200

*Video Recorder.
Dangd*

480 380

Subtotal :- \$5,339.00

2860

Labour charges

To remove & refit rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit rear & center exhaust

~~\$380.00~~ X

To remove & refit plywood & carpet

~~\$280.00~~ 160

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 60

Towing fee

~~\$150.00~~ X

Panel beating

~~\$1,800.00~~ 1000

Spray painting

~~\$1,600.00~~ 1200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2670

total: 11209

2/5: 89K

09 Days

Subtotal :- \$4,730.00

8.9K

Total:- \$28,416.90

09 Days