

INS. CASE OWNER:

CC 3, CT1 1900 5386, Jka32

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 4400.00

Loss of Rental (LOR):

S\$ 603.48

(

6 days) x \$100.58

Loss of Use (LOU):

S\$

-

(\$

x 6 days)

Loss of Income (LOI):

S\$ 300.00

(\$

50

x 6 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☒

[Tick only one]

GIA/LTA Search

S\$ 7.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$ 5310.48

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 5310.48

Name 1:

Snr Taxi Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT  
2/3/2020

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No \_\_\_\_\_


Claims No \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC4558XYr Regn: 5 Mar 2014Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toyota PriusC.C. 1798Colour: maroon

A/C: Insured / Std / NI / NA

Sp. Reading: 723242

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKN306U405722631Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 22/3/19D.O.I. 25/3/19Survey held at SumitDes. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

03/19/2111

L/s - \$4400 (Red \$ 6696.71 / 602)

G369650D

Date/Time. File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time. File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$

) \$ + PS. SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format :

Lump Sum / I.B.E. (\$

TOTAL



## Case Details

Case Reference Number : TAX/03/19/2111  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHC4558X

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-6207-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name :  
 Accident Date and Time : 22/03/2019 08:20 AM  
 Vehicle Age(In Months) : 60

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| BOM Type        | Costing Type | Portion | Material Number | SMRT Recommendation        |     |                         |                |        |                 | Surveyor Approval |                   |                          |                | Remarks |
|-----------------|--------------|---------|-----------------|----------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
|                 |              |         |                 | Part Name                  | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |         |
| One Time Key In | Main         |         |                 | BUMPER FRT                 | 1   | 482.00                  | 482.00         | 25.00  | 361.50          | Replace           | 1                 | 0                        | Repair         |         |
| One Time Key In | Main         |         |                 | BUMPER CLIPS               | 10  | 1.61                    | 16.10          | 25.00  | 12.08           | Replace           | 10                | 12.08                    | Replace        | REC     |
| One Time Key In | Main         |         |                 | BUMPER ENERGY ABSORBER FRT | 1   | 78.80                   | 78.80          | 25.00  | 59.10           | Replace           | 0                 | 0                        | Check          |         |
| One Time Key In | Main         |         |                 | BUMPER REINFORCEMENT FRT   | 1   | 498.40                  | 498.40         | 25.00  | 373.80          | Replace           | 0                 | 0                        | Check          |         |
| One Time Key In | Main         |         |                 | ARM SUB-ASSY, FR BUMPER LH | 1   | 250.40                  | 250.40         | 25.00  | 187.80          | Replace           | 0                 | 0                        | Check          |         |
| One Time Key In | Main         |         |                 | ARM SUB-ASSY, FR BUMPER RH | 1   | 250.40                  | 250.40         | 25.00  | 187.80          | Replace           | 0                 | 0                        | Check          |         |
| One Time Key In | Main         |         |                 | BRACKET, FR BUMPER         | 1   | 110.40                  | 110.40         | 25.00  | 82.80           | Replace           | 0                 | 0                        | Check          |         |
| One Time Key In | Main         |         |                 | NUMBER PLATE               | 1   | 15.00                   | 15.00          | 0.00   | 15.00           | Replace           | 1                 | 15.00                    | Replace        | MIS     |

Total Spare Part Cost 8,094.30

Surveyor Total 2,883.74

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20



Final Spare Part Cost 6,475.44

Final Sur Total 2,306.99

Vic

## Section A - Accident Details

|                                    |                    |
|------------------------------------|--------------------|
| Registration Number                | SHC4558X           |
| Case Reference Number              | TAX/03/19/2111     |
| Registration Date                  | 5/3/2014           |
| Company Type                       | SMRT Taxis Pte Ltd |
| Make                               | TOYOTA             |
| Model                              | PRIUS              |
| Name of Driver                     | LOW KHEE HONG      |
| Type of Accident                   | Others             |
| Accident Date and Time             | 22/3/2019 4:20 PM  |
| Accident Reported Date and Time    | 23/3/2019 9:23 AM  |
| Is Surveyor Required?              | Yes                |
| Survey by                          |                    |
| Vehicle is Towed Back?             | No                 |
| Towed Back Date and Time           |                    |
| Replacement Vehicle issued?        | No                 |
| Job Card Number                    | 24100725           |
| Special Instruction to ARC, if any | TP/DROVE IN        |
| Prepared Date and Time             | 23/3/2019 10:53 AM |
| Chassis Number                     |                    |
| Mileage                            |                    |
| Work Shop                          |                    |
| Repair Completion Date and Time    |                    |



Tuck Foo

## Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |                                                                                     |                                     |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable |
| Total Labour Cost            | \$1,014.00                                                                          | \$800.00                            |
| Total Spray Cost             | \$2,052.00                                                                          | \$550.00                            |
| Total Spare Part Cost        | \$6,475.44                                                                          | \$2,306.99                          |
| Total Other Cost             | \$1,555.32                                                                          | \$718.44                            |
| <b>TOTAL COST</b>            | <b>\$11,096.76</b>                                                                  | <b>\$4,375.43</b>                   |
| Lump Sum Total               | \$11,100.00                                                                         | \$4,400.00 (L/S)                    |
| Number of Repair Days        | 7.0                                                                                 | 5.0                                 |
| Prepared / Adjusted By       | Tuck Foo Kok                                                                        | Hwee Jie (LKK) / China Taiping      |
| ARC / Surveyor Sign Off Date | 25/03/2019 2:22 PM                                                                  | 25/03/2019 2:08 PM                  |
| Signature                    |  |                                     |
| Remarks                      |                                                                                     | L/S REPAIR, PHOTO AFTER PAINT.      |

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1904-0073 | Invoice Number |  |
| Quotation Date   | 05.04.2019   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope               | Quotation from AR | Adjusted by Surveyor, if applicable |
|-------------------------|-------------------|-------------------------------------|
| TO REPAIR FRONT PORTION | \$1,014.00        | \$800.00                            |
| Total Labour            | \$1,014.00        | \$800.00                            |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                              | Quotation from ARC | Adjusted by Surveyor, if applicable |
|----------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY FRONT BUMPER                | \$378.00           | \$200.00                            |
| TO SPRAY FRONT BUMPER LOWER SUB GRILLE | \$180.00           | \$0.00                              |
| TO REPSRAY FRONT HOOD                  | \$378.00           | \$200.00                            |
| TO RESPRAY FRONT FENDER LH             | \$378.00           | \$0.00                              |
| TO RESPRAY FRONT DOOR LH               | \$378.00           | \$0.00                              |
| TO RESPRAY VIEW MIRROR                 | \$180.00           | \$50.00                             |
| TO RESPRAY FRONT PILLAR LH             | \$180.00           | \$100.00                            |
| Total Spray Painting & Panel Beating   | \$2,052.00         | \$550.00                            |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                                                    | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------------------------------------|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION                          | \$80.00            | \$20.00                             |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                      | \$100.00           | \$0.00                              |
| TO REMOVE / REFIT WINDSCREEN                                 | \$120.00           | \$100.00                            |
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)            | \$450.00           | \$450.00                            |
| TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET) | \$445.32           | \$148.44                            |
| TO REPLACE SUNDRY PARTS                                      | \$100.00           | \$0.00                              |
| TO WASH AND VACUUM                                           | \$60.00            | \$0.00                              |
| TO REMOVE AND REFIT WIRE HARDESS                             | \$200.00           | \$0.00                              |
| Total Other Costs                                            | \$1,555.32         | \$718.44                            |

## Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name                  | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|----------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 52119-47930  | BUMPER FRT                 | 1.00     | \$482.00        | 100.00       | \$0.00           | Replace            | Repair            |
|             |         | 52161-16010  | BUMPER CLIPS               | 10.00    | \$1.61          | 25.00        | \$12.08          | Replace            | Replace           |
|             |         | 52611-47080  | BUMPER ENERGY ABSORBER FRT | 0.00     | \$78.80         | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 52021-47023  | BUMPER REINFORCEMENT FRT   | 0.00     | \$498.40        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 57014-47030  | ARM SUB-ASSY, FR BUMPER LH | 0.00     | \$250.40        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 57013-47030  | ARM SUB-ASSY, FR BUMPER RH | 0.00     | \$250.40        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 52114-47140  | BRACKET, FR BUMPER         | 0.00     | \$110.40        | 0.00         | \$0.00           | Replace            | Check             |

|       |             |                               |      |             |        |            |         |           |   |      |
|-------|-------------|-------------------------------|------|-------------|--------|------------|---------|-----------|---|------|
|       |             | NUMBER PLATE                  | 1.00 | \$15.00     | 0.00   | \$15.00    | Replace | Replace   | ✓ | MIS  |
|       |             | NUMBER PLATE FRAME            | 1.00 | \$12.00     | 0.00   | \$12.00    | Replace | Replace   | ✓ | CRA  |
|       | 52116-47040 | BUMPER SUPPORT F/LH           | 0.00 | \$76.40     | 0.00   | \$0.00     | Replace | Check     | X | } NN |
|       | 52115-47040 | BUMPER SUPPORT F/RH           | 0.00 | \$76.40     | 0.00   | \$0.00     | Replace | Check     | X |      |
|       | 53102-47020 | BUMPER GRILLE SUB-ASSY, LOWER | 0.00 | \$311.10    | 0.00   | \$0.00     | Replace | Not Given | X |      |
|       | 53111-47040 | GRILLE, RADIATOR              | 0.00 | \$310.60    | 0.00   | \$0.00     | Replace | Check     | X |      |
|       | 75310-47010 | EMBLEM FRONT                  | 1.00 | \$86.50     | 25.00  | \$64.88    | Replace | Replace   | ✓ | SCR  |
|       | 75922-47020 | TAPE OUT WIN FRAME LHF, DOOR  | 1.00 | \$45.60     | 25.00  | \$34.20    | Replace | Replace   | ✓ | SCR  |
|       | 53801-47050 | FENDER FRT/RH                 | 0.00 | \$723.40    | 0.00   | \$0.00     | Replace | Not Given | ✓ | NN   |
|       | 75374-47051 | NAME PLATE (HYBRID)           | 0.00 | \$51.90     | 0.00   | \$0.00     | Replace | Not Given | X | NN   |
|       | 53301-47060 | HOOD PANEL                    | 1.00 | \$748.10    | 25.00  | \$561.08   | Replace | Replace   | ✓ | DO   |
|       | 53395-47020 | HOOD END PANEL SEAL           | 0.00 | \$35.50     | 0.00   | \$0.00     | Replace | Check     | X | } NN |
|       | 53420-47070 | HOOD HINGE LH                 | 0.00 | \$55.90     | 0.00   | \$0.00     | Replace | Not Given | X |      |
|       | 53410-47070 | HOOD HINGE RH                 | 0.00 | \$55.90     | 0.00   | \$0.00     | Replace | Not Given | ✓ |      |
|       | 53510-47102 | HOOD LOCK                     | 0.00 | \$128.90    | 0.00   | \$0.00     | Replace | Check     | X |      |
|       | 53614-47030 | CLAMP, HOOD LOCK              | 0.00 | \$5.90      | 0.00   | \$0.00     | Replace | Not Given | X |      |
|       | 75533-47050 | WINDSCREEN MOULDING FRT       | 1.00 | \$57.60     | 25.00  | \$43.20    | Replace | Replace   | ✓ | NEC  |
|       | 561014E 909 | WINDSCREEN FRT                | 1.00 | \$1,543.80  | 25.00  | \$1,157.85 | Replace | Replace   | ✓ | CRA  |
|       |             | SEALANT W/SCREEN              | 2.00 | \$37.00     | 0.00   | \$74.00    | Replace | Replace   | ✓ | NEC  |
|       | 61132-47030 | PILLAR, FR BODY, LH           | 1.00 | \$363.10    | 100.00 | \$0.00     | Replace | Repair    | ✓ |      |
|       | 81170-47500 | HEAD LAMP LH                  | 1.00 | \$945.20    | 10.00  | \$850.68   | Replace | Replace   | ✓ | SCR  |
|       | 53802-47050 | FENDER FRT/LH                 | 0.00 | \$723.40    | 0.00   | \$0.00     | Replace | Check     | X | } NN |
|       | 75374-47051 | NAME PLATE (HYBRID)           | 0.00 | \$51.90     | 0.00   | \$0.00     | Replace | Check     | X |      |
|       | 67002-47070 | DOOR FRT/LH                   | 0.00 | \$894.40    | 0.00   | \$0.00     | Replace | Not Given | ✓ |      |
|       |             | STICKER DECAL SMRT (DOOR)     | 0.00 | \$60.00     | 0.00   | \$0.00     | Replace | Not Given | X |      |
|       | 87940-47310 | MIRROR ASSY, LH               | 1.00 | \$1,224.90  | 100.00 | \$0.00     | Replace | Repair    | ✓ |      |
|       | 81740-52040 | MIRROR LAMP LH                | 1.00 | \$65.30     | 10.00  | \$58.77    | Replace | Replace   | ✓ | SCR  |
|       | 87945-74010 | COVER, OUTER MIRROR, LH       | 1.00 | \$107.40    | 100.00 | \$0.00     | Replace | Repair    | ✓ |      |
| Total |             |                               |      | \$10,485.11 |        | \$2,883.74 |         |           |   |      |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Total       |         |              |           |          |               |              |                  |           |                |

2883.74  
- 20%  
2306.99  
+ 800.00  
+ 1268.44  

---

4375.43

45 \$4400/-  
15157.92

| SMRT Recommendation   |              |         |                 |                               |     |                         |                |        |                 |                          | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|-------------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                     | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | NUMBER PLATE FRAME            | 1   | 12.00                   | 12.00          | 0.00   | 12.00           | Replace                  | 1                 | 12.00                    | Replace        | CRA     |
| One Time Key In       | Main         |         |                 | BUMPER SUPPORT F/LH           | 1   | 76.40                   | 76.40          | 25.00  | 57.30           | Replace                  | 0                 | 0                        | Check          |         |
| One Time Key In       | Main         |         |                 | BUMPER SUPPORT F/RH           | 1   | 76.40                   | 76.40          | 25.00  | 57.30           | Replace                  | 0                 | 0                        | Check          |         |
| One Time Key In       | Main         |         |                 | BUMPER GRILLE SUB-ASSY, LOWER | 1   | 311.10                  | 311.10         | 25.00  | 233.33          | Replace                  | 0                 | 0                        | Not Give       |         |
| One Time Key In       | Main         |         |                 | GRILLE, RADIATOR              | 1   | 310.60                  | 310.60         | 25.00  | 232.95          | Replace                  | 0                 | 0                        | Check          |         |
| One Time Key In       | Main         |         |                 | EMBLEM FRONT                  | 1   | 66.50                   | 66.50          | 25.00  | 64.88           | Replace                  | 1                 | 64.88                    | Replace        | SCR     |
| One Time Key In       | Main         |         |                 | TAPE OUT WIN FRAME LHF, DOOR  | 1   | 45.60                   | 45.60          | 25.00  | 34.20           | Replace                  | 1                 | 34.20                    | Replace        | SCR     |
| One Time Key In       | Main         |         |                 | FENDER FRT/RH                 | 1   | 723.40                  | 723.40         | 25.00  | 542.55          | Replace                  | 0                 | 0                        | Not Give       |         |
| One Time Key In       | Main         |         |                 | NAME PLATE (HYBRID)           | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace                  | 0                 | 0                        | Not Give       |         |
| One Time Key In       | Main         |         |                 | HOOD PANEL                    | 1   | 748.10                  | 748.10         | 25.00  | 561.08          | Replace                  | 1                 | 561.08                   | Replace        | DD      |
| One Time Key In       | Main         |         |                 | HOOD END PANEL SEAL           | 1   | 35.50                   | 35.50          | 25.00  | 26.63           | Replace                  | 0                 | 0                        | Check          |         |
| One Time Key In       | Main         |         |                 | HOOD HINGE LH                 | 1   | 55.90                   | 55.90          | 25.00  | 41.92           | Replace                  | 0                 | 0                        | Not Give       |         |
| One Time Key In       | Main         |         |                 | HOOD HINGE RH                 | 1   | 55.90                   | 55.90          | 25.00  | 41.92           | Replace                  | 0                 | 0                        | Not Give       |         |
| One Time Key In       | Main         |         |                 | HOOD LOCK                     | 1   | 128.90                  | 128.90         | 25.00  | 96.68           | Replace                  | 0                 | 0                        | Check          |         |
| Total Spare Part Cost |              |         |                 |                               |     |                         |                |        | 8,094.30        | Surveyor Total 2,883.74  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                               |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20      |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                               |     |                         |                |        | 6,475.44        | Final Sur Total 2,306.99 |                   |                          |                |         |

| SMRT Recommendation   |              |         |                 |                           |     |                         |                |        |                 |                  |                   | Surveyor Approval        |                |         |
|-----------------------|--------------|---------|-----------------|---------------------------|-----|-------------------------|----------------|--------|-----------------|------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                 | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace  | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | CLAMP, HOOD LOCK          | 1   | 5.90                    | 5.90           | 25.00  | 4.43            | Replace          | 0                 | 0                        | Not Give       |         |
| One Time Key In       | Main         |         |                 | WINDSCREEN MOULDING FRT   | 1   | 57.60                   | 57.60          | 25.00  | 43.20           | Replace          | 1                 | 43.20                    | Replace        | REC     |
| One Time Key In       | Main         |         |                 | WINDSCREEN FRT            | 1   | 1,543.80                | 1,543.80       | 25.00  | 1,157.85        | Replace          | 1                 | 1,157.8                  | Replace        | CRA     |
| One Time Key In       | Main         |         |                 | SEALANT W/SCREEN          | 2   | 37.00                   | 74.00          | 0.00   | 74.00           | Replace          | 2                 | 74.00                    | Replace        | REC     |
| One Time Key In       | Main         |         |                 | PILLAR, FR BODY, LH       | 1   | 363.10                  | 363.10         | 25.00  | 272.33          | Replace          | 1                 | 0                        | Repair         |         |
| One Time Key In       | Main         |         |                 | HEAD LAMP LH              | 1   | 945.20                  | 945.20         | 10.00  | 850.68          | Replace          | 1                 | 850.68                   | Replace        | SCR     |
| One Time Key In       | Main         |         |                 | FENDER FRT/LH             | 1   | 723.40                  | 723.40         | 25.00  | 542.55          | Replace          | 0                 | 0                        | Check          |         |
| One Time Key In       | Main         |         |                 | NAME PLATE (HYBRID)       | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace          | 0                 | 0                        | Check          |         |
| One Time Key In       | Main         |         |                 | DOOR FRT/LH               | 1   | 894.40                  | 894.40         | 25.00  | 670.80          | Replace          | 0                 | 0                        | Not Give       |         |
| One Time Key In       | Main         |         |                 | STICKER DECAL SMRT (DOOR) | 1   | 60.00                   | 60.00          | 0.00   | 60.00           | Replace          | 0                 | 0                        | Not Give       |         |
| One Time Key In       | Main         |         |                 | MIRROR ASSY, LH           | 1   | 1,224.90                | 1,224.90       | 25.00  | 918.68          | Replace          | 1                 | 0                        | Repair         |         |
| One Time Key In       | Main         |         |                 | MIRROR LAMP LH            | 1   | 65.30                   | 65.30          | 10.00  | 58.77           | Replace          | 1                 | 58.77                    | Replace        | SCR     |
| One Time Key In       | Main         |         |                 | COVER, OUTER MIRROR, LH   | 1   | 107.40                  | 107.40         | 25.00  | 80.55           | Replace          | 1                 | 0                        | Repair         |         |
| Total Spare Part Cost |              |         |                 |                           |     |                         |                |        | 8,094.30        | Surveyor Total   |                   |                          | 2,883.74       |         |
| Lump Sum Discount (%) |              |         |                 |                           |     |                         |                |        | 20.00           | Lump Sum Dis (%) |                   |                          | 20             |         |
| Final Spare Part Cost |              |         |                 |                           |     |                         |                |        | 6,475.44        | Final Sur Total  |                   |                          | 2,306.99       |         |

Labour's Cost Detail

| S.No.         | Costing Type | Job Scope               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|-------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO REPAIR FRONT PORTION | 1,014.00                | 800                     |         |
| <b>Total:</b> |              |                         | <b>1,014.00</b>         | <b>800.00</b>           |         |

**Spray Cost Detail**

| S.No.         | Costing Type | Job Scope                              | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|----------------------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO REPSRAY FRONT BUMPER                | 378.00                  | 200                     |         |
| 2             | Main         | TO SPRAY FRONT BUMPER LOWER SUB GRILLE | 180.00                  | 0                       |         |
| 3             | Main         | TO REPSRAY FRONT HOOD                  | 378.00                  | 200                     |         |
| 4             | Main         | TO RESPRAY FRONT FENDER LH             | 378.00                  | 0                       |         |
| 5             | Main         | TO RESPRAY FRONT DOOR LH               | 378.00                  | 0                       |         |
| 6             | Main         | TO RESPRAY VIEW MIRROR                 | 180.00                  | 50                      |         |
| 7             | Main         | TO RESPRAY FRONT PILLAR LH             | 180.00                  | 100                     |         |
| <b>Total:</b> |              |                                        | <b>2,052.00</b>         | <b>550.00</b>           |         |

**Other Cost Detail**

| S.No.         | Costing Type | Job Scope                                                   | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|-------------------------------------------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO CHECK WIRING AND SYSTEM FUNCTION                         | 80.00                   | 20                      |         |
| 2             | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA                     | 100.00                  | 0                       |         |
| 3             | Main         | TO REMOVE / REFIT WINDSCREEN                                | 120.00                  | 100                     |         |
| 4             | Main         | TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)           | 450.00                  | 450.00                  |         |
| 5             | Main         | TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET) | 445.32                  | 148.44                  |         |
| 6             | Main         | TO REPLACE SUNDRY PARTS                                     | 100.00                  | 0                       |         |
| 7             | Main         | TO WASH AND VACUUM                                          | 60.00                   | 0                       |         |
| 8             | Main         | TO REMOVE AND REFIT WIRE HARDESS                            | 200.00                  | 0                       |         |
| <b>Total:</b> |              |                                                             | <b>1,555.32</b>         | <b>718.44</b>           |         |

## Summary

|                          | Estimator Assesment(\$)                                                            | Surveyor Assesment(\$)                                                                |
|--------------------------|------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Total Spare Part Detail  | 6,475.44                                                                           | 2,306.99                                                                              |
| Total Labour Cost        | 1,014.00                                                                           | 800.00                                                                                |
| Total Spray Painting     | 2,052.00                                                                           | 550.00                                                                                |
| Other                    | 1,555.32                                                                           | 718.44                                                                                |
| Overall Total            | 11,096.76                                                                          | 4,375.43                                                                              |
| Lump Sum Repair Option   | <input type="checkbox"/>                                                           | <input checked="" type="checkbox"/>                                                   |
| Lump Sum Total           | 11,100.00                                                                          | 4,400.00                                                                              |
| Surveyor Approved Amount |                                                                                    | 4,400.00                                                                              |
| No of Repair Days*       | 7                                                                                  | 5                                                                                     |
| Remarks                  |                                                                                    | L/S REPAIR, PHOTO AFTER PAINT.                                                        |
| Surveyor Name            |                                                                                    | Hwee Jie                                                                              |
| Signature                |  |  |
| Survey Date              | 25/03/2019                                                                         |                                                                                       |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                                                                                         |                                      |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                                      |
| Owner ID Type:                                                                                                                                                                                                          | Company                              |
| Owner ID:                                                                                                                                                                                                               | 5369K                                |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                                      |
| Vehicle No.:                                                                                                                                                                                                            | SHC4558X                             |
| Vehicle to be Exported:                                                                                                                                                                                                 | No                                   |
| Intended Deregistration Date:                                                                                                                                                                                           | 26 Mar 2019                          |
| Vehicle Make:                                                                                                                                                                                                           | TOYOTA                               |
| Vehicle Model:                                                                                                                                                                                                          | PRIUS TAXI (SMRT)                    |
| Primary Colour:                                                                                                                                                                                                         | Maroon                               |
| Manufacturing Year:                                                                                                                                                                                                     | 2013                                 |
| Engine No.:                                                                                                                                                                                                             | 3ZR1326465                           |
| Chassis No.:                                                                                                                                                                                                            | JTDKN36U405722631                    |
| Maximum Power Output:                                                                                                                                                                                                   | 100.0 kW (134 bhp)                   |
| Open Market Value:                                                                                                                                                                                                      | \$33,120.00                          |
| Original Registration Date:                                                                                                                                                                                             | 05 Mar 2014                          |
| First Registration Date:                                                                                                                                                                                                | 05 Mar 2014                          |
| Transfer Count:                                                                                                                                                                                                         | 0                                    |
| Actual ARF Paid:                                                                                                                                                                                                        | \$8,368.00                           |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                                      |
| PARF Eligibility:                                                                                                                                                                                                       | Yes                                  |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | 04 Mar 2022                          |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$5,857.00                           |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                                      |
| COE Expiry Date:                                                                                                                                                                                                        | 04 Mar 2022                          |
| COE Category:                                                                                                                                                                                                           | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                                                                                                                                                                                                      | 8                                    |
| PQP Paid:                                                                                                                                                                                                               | \$58,745.00                          |
| COE Rebate Amount:                                                                                                                                                                                                      | \$21,540.00                          |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$27,397.00</b>                   |
| <b>Message</b>                                                                                                                                                                                                          |                                      |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                                      |

The information contained herein is correct as at 26 Mar 2019

OK



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC3/CTI19005386/Jha3

Date: 03/04/2019

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC 4558X**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/03/2019 at the premises of M/s SMRT Automotive Services Pte Ltd (Woodlands) and have the following to report:-

|                               |       |           |
|-------------------------------|-------|-----------|
| Workshop Estimate Amount      | : S\$ | 11,096.76 |
| Revised Estimate Amount       | : S\$ | 4,375.43  |
| "Check" Items Amount          | : S\$ | 1,554.90  |
| Total (Including Check Items) | : S\$ | 5,930.33  |
| Market Value                  | : S\$ | - (est.)  |
| LTA Reimbursement Value       | : S\$ | - (est.)  |
| Nett Value                    | : S\$ | - (est.)  |

**Description of Damage:**

The vehicle sustained damages at the Front Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

ONG HWEE JIE  
Licensed Appraiser

## Jia Le (LKK Auto)

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Thursday, 5 December 2019 2:37 PM  
**To:** Jia Le (LKK Auto); Admin A; Vic (LKKAuto)  
**Cc:** Ben Tang; Alfred Toh; Chee So Chow; Hsiao Tong (LKKAuto); Albert Chua  
**Subject:** RE: OUR REF: SNM19D201300/CHEONGML - FW: Direct Settlement - Accident Involving GBG9650D and SHC4558X (TP : LKK REF - CC3/CTI19005386/Jha3) on 22/03/2019  
**Attachments:** REPORT OF GBG9650D.pdf

LKK REF - CC3/CTI19005386/Jha3  
CTPIS REF – SNM19D201300C02/0(bt)

Dear Jia Le

We refer to your emails pertaining to the above matter.

Insured driver reported/"admitted" that wood flew from Insured vehicle and hit third party vehicle.

Please assist to check the consistency of damages before rejecting claim.

**Best Regards**

**Alfred Toh**  
Senior Executive  
Claims Department  
China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Jia Le (LKK Auto) [mailto:JiaLe@lkkauto.com]  
**Sent:** Thursday, 5 December, 2019 12:40 PM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Cc:** Alfred Toh <alfred.toh@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D201300/CHEONGML - FW: Direct Settlement - Accident Involving GBG9650D (OI : CTI - TBA) and SHC4558X (TP : LKK REF - CC3/CTI19005386/Jha3) on 22/03/2019

Dear Sir/Mdm,

Based on the accident report and accident scenario, BOLA 27 (a) is applicable. Thus, we would like to reject the TP claim.

Kindly let us have your approval/instructions.

Thank you.

Best Regards,

**Chan Jia Le** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jia Le (LKK Auto)

**Sent:** Thursday, 4 July 2019 9:35 AM

**To:** Claims Dept of CTI; Elaine Cheong

**Subject:** RE: OUR REF: SNM19D201300/CHEONGML - FW: Direct Settlement - Accident Involving GBG9650D (OI : CTI - TBA) and SHC4558X (TP : LKK REF - CC3/CTI19005386/Jha3) on 22/03/2019

Dear Elaine,

Attached Third Party's video footage for your viewing.

Best Regards,

**Carlor Chan** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims Dept of CTI [<mailto:claimsdept@sg.cntaiping.com>]

**Sent:** Wednesday, 3 July 2019 9:27 AM

**To:** Elaine Cheong; Jia Le (LKK Auto)

**Subject:** OUR REF: SNM19D201300/CHEONGML - FW: Direct Settlement - Accident Involving GBG9650D (OI : CTI - TBA) and SHC4558X (TP : LKK REF - CC3/CTI19005386/Jha3) on 22/03/2019

Dear Elaine,

Please revert.

Thank you

**Lim Shu Min**

Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Jia Le (LKK Auto) [<mailto:JiaLe@lkkauto.com>]

**Sent:** Tuesday, 2 July, 2019 2:27 PM

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                      |                       |                              |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------------------|------------------------------|-------------------------------------------------------------------------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                                       |                                                                                      |                       | Ref : CC3/CTI19005386/Jda3s2 |                                                                                     |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                                                                   |                                                                                      |                       | Date : 05-03-2020            |  |
|                                                                                                                                           |                                                                                      |                       | Code : CTI                   |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                      |                       |                              |                                                                                     |
| Insured Veh.                                                                                                                              | GBG 9650D                                                                            | Veh. Inspected        | SHC 4558X                    |                                                                                     |
| Policy No.                                                                                                                                | DMCVSN1769571801                                                                     | Coverage (\$)         | 0.00                         |                                                                                     |
| Claim No.                                                                                                                                 | SNM19D201300C02/0                                                                    | Excess (\$)           | 0.00                         |                                                                                     |
| Assign From                                                                                                                               |                                                                                      | Assign Date           | 25/03/2019                   |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                      |                       |                              |                                                                                     |
| Make & Model                                                                                                                              | TOYOTA PRIUS                                                                         | c.c                   | 1798                         |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                               | Year of Reg.          | 2014                         |                                                                                     |
| Chassis No.                                                                                                                               | JTDKN36U405722631                                                                    | Colour                | MAROON                       |                                                                                     |
| Odometer                                                                                                                                  | 723242                                                                               | Steering              | IN ORDER                     |                                                                                     |
| Brakes                                                                                                                                    | IN ORDER                                                                             | Modification          | SPORTS RIM                   |                                                                                     |
| General                                                                                                                                   | GOOD                                                                                 |                       |                              |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                      |                       |                              |                                                                                     |
|                                                                                                                                           | Size                                                                                 | Make                  | Balance                      |                                                                                     |
| R/H Front Tyre                                                                                                                            | 195/65 R15                                                                           | ACHILLES              | 6 mm                         |                                                                                     |
| L/H Front Tyre                                                                                                                            | 195/65 R15                                                                           | ACHILLES              | 6 mm                         |                                                                                     |
| R/H Rear Tyre                                                                                                                             | 195/65 R15                                                                           | ACHILLES              | 6 mm                         |                                                                                     |
| L/H Rear Tyre                                                                                                                             | 195/65 R15                                                                           | ACHILLES              | 6 mm                         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                      |                       |                              |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                               |                                                                                      |                       |                              |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                      |                       |                              |                                                                                     |
| Accident Date                                                                                                                             | 22/03/2019                                                                           | Inspection Date       | 25/03/2019                   |                                                                                     |
| Survey held at                                                                                                                            | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                       |                              |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                      |                       |                              |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                       |                              |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                        |                                                                                      |                       |                              |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                       |                                                                                      | <b>5 Working Days</b> |                              |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4558X

| Qty | Description of Parts                    | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------|---------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>             |               |                           |                   |
| 10  | BUMPER CLIPS @ \$1.61 (DISC 25%)        | NECESSARY     | 16.10                     | 12.08             |
| 1   | EMBLEM FRONT (DISC 25%)                 | SCRATCHED     | 86.50                     | 64.88             |
| 1   | TAPE OUT WIN FRAME LHF, DOOR (DISC 25%) | SCRATCHED     | 45.60                     | 34.20             |
| 1   | HOOD PANEL (DISC 25%)                   | DENTED        | 748.10                    | 561.08            |
| 1   | WINDSCREEN MOULDING FRT (DISC 25%)      | NECESSARY     | 57.60                     | 43.20             |
| 1   | WINDSCREEN FRT (DISC 25%)               | CRACKED       | 1,543.80                  | 1,157.85          |
| 1   | HEAD LAMP LH (DISC 10%)                 | SCRATCHED     | 945.20                    | 850.68            |
| 1   | MIRROR LAMP LH (DISC 10%)               | SCRATCHED     | 65.30                     | 58.77             |
| 1   | NUMBER PLATE (SN)                       | MISSING       | 15.00                     | 15.00             |
| 1   | NUMBER PLATE FRAME (SN)                 | CRACKED       | 12.00                     | 12.00             |
| 2   | SEALANT W/SCREEN @ \$37.00 (SN)         | NECESSARY     | 74.00                     | 74.00             |
| 1   | BUMPER ENERGY ABSORBER FRT              | NOT NECESSARY | 78.80                     | -                 |
| 1   | BUMPER REINFORCEMENT FRT                | NOT NECESSARY | 498.40                    | -                 |
| 1   | ARM SUB-ASSY, FR BUMPER LH              | NOT NECESSARY | 250.40                    | -                 |
| 1   | ARM SUB-ASSY, FR BUMPER RH              | NOT NECESSARY | 250.40                    | -                 |
| 1   | BRACKET, FR BUMPER                      | NOT NECESSARY | 110.40                    | -                 |
| 1   | BUMPER SUPPORT F/LH                     | NOT NECESSARY | 76.40                     | -                 |
| 1   | BUMPER SUPPORT F/RH                     | NOT NECESSARY | 76.40                     | -                 |
| 1   | BUMPER GRILLE SUB-ASSY, LOWER           | NOT NECESSARY | 311.10                    | -                 |
| 1   | GRILLE, RADIATOR                        | NOT NECESSARY | 310.60                    | -                 |
| 1   | FENDER FRT/RH                           | NOT NECESSARY | 723.40                    | -                 |
| 1   | NAME PLATE (HYBRID)                     | NOT NECESSARY | 51.90                     | -                 |
| 1   | HOOD END PANEL SEAL                     | NOT NECESSARY | 35.50                     | -                 |
| 1   | HOOD HINGE LH                           | NOT NECESSARY | 55.90                     | -                 |
| 1   | HOOD HINGE RH                           | NOT NECESSARY | 55.90                     | -                 |
| 1   | HOOD LOCK                               | NOT NECESSARY | 128.90                    | -                 |
| 1   | CLAMP, HOOD LOCK                        | NOT NECESSARY | 5.90                      | -                 |
| 1   | FENDER FRT/LH                           | NOT NECESSARY | 723.40                    | -                 |
| 1   | NAME PLATE (HYBRID)                     | NOT NECESSARY | 51.90                     | -                 |
| 1   | DOOR FRT/LH                             | NOT NECESSARY | 894.40                    | -                 |
| 1   | STICKER DECAL SMRT (DOOR)               | NOT NECESSARY | 60.00                     | -                 |

Report Ref No. CC3/CTI19005386/Jda3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts                                                                                                                            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | BUMPER FRT                                                                                                                                      | TO REPAIR SEE LABOUR | 482.00                    | -                 |
| 1   | PILLAR, FR BODY, LH                                                                                                                             | TO REPAIR SEE LABOUR | 363.10                    | -                 |
| 1   | MIRROR ASSY, LH                                                                                                                                 | TO REPAIR SEE LABOUR | 1,224.90                  | -                 |
| 1   | COVER, OUTER MIRROR, LH                                                                                                                         | TO REPAIR SEE LABOUR | 107.40                    | -                 |
| 1   | SOLAR FILM (SN)                                                                                                                                 | NECESSARY            | 450.00                    | 450.00            |
| 1   | ADVERTISEMENT STICKER (SN)                                                                                                                      | NECESSARY            | 445.32                    | 148.44            |
|     |                                                                                                                                                 |                      | 11,431.92                 | 3,482.18          |
|     | <b>LABOUR</b>                                                                                                                                   |                      |                           |                   |
|     | PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT; PILLAR, FR BODY, LH; MIRROR ASSY, LH AND COVER, OUTER MIRROR, LH. SPRAY PAINT. |                      | 1,014.00                  | 800.00            |
|     | TO CHECK WIRING AND SYSTEM FUNCTION.                                                                                                            |                      | 2,052.00                  | 550.00            |
|     | TO APPLY RUST-PROOFING ON AFFECTED AREA.                                                                                                        | NOT NECESSARY        | 80.00                     | 20.00             |
|     | TO REMOVE / REFIT WINDSCREEN.                                                                                                                   |                      | 100.00                    | -                 |
|     | TO REPLACE SUNDRY PARTS.                                                                                                                        | NOT NECESSARY        | 120.00                    | 100.00            |
|     | TO WASH AND VACUUM.                                                                                                                             | NOT NECESSARY        | 100.00                    | -                 |
|     | TO REMOVE AND REFIT WIRE HARDESS.                                                                                                               | NOT NECESSARY        | 60.00                     | -                 |
|     |                                                                                                                                                 |                      | 200.00                    | -                 |
|     |                                                                                                                                                 |                      | 3,726.00                  | 1,470.00          |
|     | <b>GRAND TOTAL</b>                                                                                                                              |                      | <b>15,157.92</b>          | <b>4,952.18</b>   |

|                                                                             |  |  |                 |
|-----------------------------------------------------------------------------|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>4,400.00</b> |
|-----------------------------------------------------------------------------|--|--|-----------------|

Report Ref No. CC3/CTI19005386/Jda3s2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.