

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

CHINA TAIPING INSURANCE (S) PTE LTD

WP 2120472 A564955

3, Anson Rd #16-00

Springleaf Tower

Asker

S,pore 079909

Accident date:23/03/2019

Date:25/03/2019

Estimate cost to repair vel: SLJ 5088U (Mercedes E250) claims under vel: SLA 4294U.

2pcs headrest @\$936 <i>Repair</i>	\$ 1,872.00 <i>x</i>
1pce dashboard lower air cover centre <i>new</i>	213.00 <i>x</i>
1pce boot lid <i>Replaced</i>	2,295.00 <i>2196</i>
2pcs boot lid hinges@\$155 <i>new</i>	310.00 <i>x</i>
1pce boot lid top lock <i>Replaced</i>	320.00 <i>✓</i>
1pce boot lid lower lock <i>new Replaced</i>	470.00 <i>35</i>
2pcs boot lid reflector@\$452 <i>cut</i>	904.00 <i>✓</i>
1pce boot lid emblem <i>2</i>	51.00 <i>✓</i>
1pce boot lid E250 plate <i>new</i>	80.00 <i>✓</i>
1pce boot lid cc plate	20.00 <i>✓</i>
1pce boot lid 7G-Tronic plate	98.00 <i>✓</i>
1pce boot lid centre chrome <i>new Replaced</i>	140.00 <i>x 2</i>
1pce boot lid rubber <i>cut</i>	185.00 <i>✓</i>
2pcs tail lamps@\$715 <i>cut</i>	1,430.00 <i>✓</i>
1pce tail lamp inner panel <i>Repair</i>	85.00 <i>x</i>
2pcs rear fender top side cover@\$30 <i>cut</i>	60.00 <i>✓</i>
8pcs rear fender top side cover clips@\$9 <i>new</i>	72.00 <i>✓</i>
1pce rear bumper <i>Replaced</i>	1,637.00 <i>1380</i>
4pcs rear bumper reverse sensors@\$288 <i>3 pieces. new</i>	1,152.00 <i>864</i>
1pce rear bumper lower spoiler <i>Replaced</i>	532.00 <i>✓</i>
10pcs rear bumper inner clips@\$12 <i>new</i>	120.00 <i>50</i>
10pcs rear bumper lower spoiler@\$12 <i>new</i>	120.00 <i>30</i>
2pcs rear bumper side chromes@\$135 <i>new</i>	270.00 <i>✓</i>
1pce rear bumper centre chrome <i>new</i>	180.00 <i>✓</i>
2pcs rear bumper side holders@\$45 <i>new</i>	90.00 <i>✓</i>
1pce rear bumper reinforcement <i>Replaced</i>	820.00 <i>725</i>

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

CHINA TAIPING INSURANCE (S) PTE LTD

3, Anson Rd #16-00

Springleaf Tower

S,pore 079909

Accident date:23/03/2019

Date:25/03/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate cost to repair vel: SLJ 5088U (Mercedes E250) claims under vel: SLA 4294U.

Page 2	
2pcs rear fender inner shields@\$172 <i>Replaced</i>	\$ 344.00 ✓
1pce rear panel <i>Replaced</i>	1,265.00 ✓
1pce rear panel outer bumper holder <i>could</i>	325.00 ✓
1pce rear spare tyer panel <i>Repair</i>	490.00 +
1pce rear spare tyer top cover <i>borad Replaced</i>	395.00 ✓
1pce rear spare tyer carpet <i>NEW</i>	285.00 ✓
1pce rear side right member <i>Repair</i>	603.00 x
1pce rear lower lock cover <i>could</i>	215.00 ✓
1pce rear exhaust pipe right <i>new</i>	1,310.00 +
1pce rear exhaust pipe outer chrome <i>Bo test</i>	365.00 ✓
1pce rear exhaust pipe top heat cover <i>NEW</i>	72.00 ✓
2pcs rear exhaust pipe mounting@\$30 <i>new</i>	60.00 x
	\$ 19,755.00
Less 10%	1,975.50
	\$ 17,779.50
To towing	180.00 - 120
To rustproof	300.00 - 60
1pce rear number plate with cover	100.00 x
To dismantle/renew headrest	300.00 - 200
To dismantle/renew exhaust pipe	150.00 x
To dismantle/renew reverse sensors	150.00 - 60
To remove/refit rear interior to effect repair	200.00 - 80
To check wiring	100.00 - 30
To computer reset headrest	200.00 x
To dismantle/renew dashboard cover	100.00 x

To dismantle/renew accident portion
To spray paint

~~2,000.00~~ 1,800.00 1,500.00

TOTAL \$ 23,359.50

Supplementary: 1355.40 6/3
total: 15764.30
H/S: 12.6K

Adrian Ling.
26/03/19.

12.000

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

CHINA TAIPING INSURANCE (S) PTE LTD

3, Anson Rd #16-00

Springleaf Tower

S,pore 079909

Accident date:23/03/2019

Date;26/03/2019

To supplementary

[illegible]