

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 199003867C
WINSON PRESS PTE LTD
NO 20 BEDOK ROAD

SINGAPORE 469277
TEL : FAX :
PH : 98299830 (OFFICE)
ATTN :

ESTIMATE BILL

Number : EB00005071
Date : 28/01/2019
Case No : AD00010211
Vehicle No : GZ4699M
Chassis : JTFHS02P600043708
Year of Mfr : 2006
Policy No : 5053391115-06
Model : TOYOTA HIACE 2.5
M

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE <i>20/8ent</i>	1.0	1,950.00	25	1,462.50
2	TAILGATE EMBLEM <i>rec</i>	1.0	88.51	25	66.38
3	TAILGATE LOGO - TOYOTA <i>rec</i>	1.0	76.85	25	57.64
4	TAILGATE LOGO - HIACE <i>rec</i>	1.0	76.85	25	57.64
5	TAILGATE DAMPER LH <i>11</i>	1.0	295.00	25	221.25
6	TAILGATE DAMPER RH <i>11</i>	1.0	295.00	25	221.25
7	TAILGATE INNER LOCK <i>11</i>	1.0	264.00	25	198.00
8	TAILGATE INNER RUBBER <i>11</i>	1.0	391.00	25	293.25
9	REAR BUMPER <i>11</i>	1.0	697.90	25	523.43
10	REAR BUMPER RETAINER RH <i>11</i>	1.0	67.70	25	50.78
11	REAR BUMPER RETAINER LH <i>11</i>	1.0	67.70	25	50.78
12	TAIL LAMP RH <i>11</i>	1.0	410.97	25	308.23
13	TAILLAMP CORNER GARNISH RH <i>11</i>	1.0	85.12	25	63.84
14	REAR BUMPER CLIP <i>11</i>	5.0	4.96	25	18.60
15	END PANEL <i>11</i>	1.0	425.81	25	319.36
List Price - Parts Sub Total					3,912.93
16	TAILGATE COMPANY LOGO STICKERS <i>11</i>	1.0	350.00	0	350.00
17	REAR NUMBER PLATE <i>11</i>	1.0	30.00	0	30.00
18	TAILGATE STICKER - 70KM/H <i>11</i>	1.0	20.00	0	20.00
19	REVERSE SENSOR <i>11</i>	1.0	280.00	0	280.00
20	WINDSCREEN SEALANT <i>11</i>	2.0	24.00	0	48.00
Special Nett Price - Parts Sub Total					728.00
Parts Total					4,640.93
21	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
22	SPRAY PAINT ON THE AFFECTED AREAS	1.0	700.00	0	700.00
23	ANTI-RUST COATING	1.0	180.00	0	180.00
24	WIRING	1.0	40.00	0	40.00
25	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
26	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,150.00

E. & O. E.

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE

CUSTOMER SIGNATURE

not Attached
26/3/19
2/5/19
The photo shop
5 day.

4474.39
283
P. 3385.79
S.N. - 250
L - 1350
4588.79
3964