

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005092

LONPAC INSURANCE BHD

300 Beach Road 07 The Concourse
#17-04 SINGAPORE 199555

ATTENTION :
CONTACT : -

DATE : 05/08/2019
ACCIDENT DATE : 14/03/2019
VEHICLE NO : YP4587S
CHASSIS/ENG.NO : JHHUCT3H40K018241
VEHICLE MODEL : HINO XZU710R
CLAIM NO : CC4/LPC19005403/HB3
POLICY NO :
REMARK : 4587 TP LONPAC AGST
YP5611Z

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FAX NO: 6296 3767

I acknowledge by Repairer
Signature:

**** LIST PRICE ****

SUB-TOTAL: 0.00

** SPECIAL NETT PRICE **

1	1	PC	REAR NUMBER PLATE	15.00	15.00	15.00
2	1	PC	REAR STEP WOODEN BEAM	100.00	100.00	100.00
3	2	PC	REAR CHASSIS WOODEN BEAM	700.00	700.00	1,400.00
4	6	PC	REAR DECK 'U' BOLT	50.00	50.00	300.00
5	1	PC	REAR DECK GATE	1,200.00	1,200.00	1,200.00
6	1	PC	60KM/H STICKER	20.00	20.00	20.00

SUB-TOTAL 3,035.00

** WORK LABOUR **

TO LIFT UP REAR DECK AND ALIGN REAR DECK	600.00	400	600.00
TO KNOCK, WELD AND REPLACE ABOVE PARTS	500.00	400	500.00
TO CHECK WIRING	30.00	✓	30.00
TO REDRAW LOGO	150.00	120	150.00

SUB-TOTAL 1,280.00

JOYCE

PAGE: 1 of 1

SUB-TOTAL : S\$ 4,315.00
ADD 7% GST. S\$ 302.05
GRAND TOTAL : S\$ 4,617.05

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.