

small

ALL PPS BY

FCI CS/FCI 19005409 / Gvd3 / 12

Special Section

Ministry

GA

ASSIGNMENT (Office)

WS

Hunnykao

FCI

Date/Time: 12-16pmg 26/3/19

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / US

To Inspect Vehicle No.

SJS 9689K

Insured

SHC 7049D

at Workshop no.

premium Automobile

Tel

63882323

of

55 Ubi Rd 1

Policy No.

Claim No.

D19002034MPST

Sum Insured

Percent

Make of Veh
(Client's Record)

D.O.A

21/03/19

CA / REV / REP. / REV 24 HRS 'DS'

HOLD, Endorsement

Date/Time

1:51pm 26/3/19

Person Contacted

Sheila

Vehicle IN

(OUT)

Date/Time

Action/Instruction

(✓)

Estimate

SJS 9689K - X

CC3 / FCI 14013212 / K+bo 2

D.O.A = 22/04/2014

2/4/19

Email preli revised to FCI

10/6/19

Final fig \$ 5015.50 confirmed by email (Red 156).50, 24/6)

62

Signature

Date: 1/4/2019

Vol. No. 5759689K Yr. Regn. 18 Sep 2017

Type: ☒ M.Car ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover /

Truck / Trailer or

Make: Audi A4 CC 1395

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading 24505 T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No WA4ZZZ, F43HA 182243

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R. ... M.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO of Continental

Front _____ Reoar _____

R/Bal.	7	mm	R/Bal.	1	mm
--------	---	----	--------	---	----

L/Bal.	7	mm	L/Bal.	7	mm
--------	---	----	--------	---	----

DOA DOI 01-04-19

Survey held at W/S 3.0m

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or /

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 10 JUN 2019

□: Prel. Report

☐: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 141

Survey Fee:

Transportation

[illegible]

References

2. Others

TOTAL

Report Format : CWS

Lump Sum / I.B.L. (\$) 5015.50

Add Fee: Site Insp (\$☐ Interview (\$

☐ Tech. invs (\$)

☐ Weekend (\$)

145

90

$$50 + 50$$

30

325



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19002034MFSH

Our ref: CS/FCI19005409/Gvd3

Date: 2/4/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LIMITED

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJS 9689K


We thank you for your instruction on 26/3/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 1/4/2019 at the premises of M/s PREMIUM AUTOMOBILES and have the following to report:-

Workshop Estimate Amount	:S\$6,578.00
Revised Estimate Amount	:S\$4,048.00
"Check" Items Amount	:S\$1,606.00
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)

M.MATAL, AMSAE-A

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-03-2019	Our Ref No. D19002034MFSH
Accident Date	21-03-2019	Claim Type. Third Party
Insured Vehicle	SHC7049D	Third Party Vehicle. SJS9689K
Survey Location	55 UBI ROAD 1	
Contact Person.	SHEILA M ISMAIL	
Contact No.	63882323/ 67689911	Fax No. 68411183
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIUM AUTOMOBILES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 10 June 2019 9:36 AM
To: Carrine Leong
Cc: jiajee.yap@premiumauto.com.sg; SUR; claims@premiumauto.com.sg
Subject: RE: FINAL REVISION - SJS9689K - TP FIRSTCAP - SURVEYED 1 APR 19

Dear Carrine,

WITHOUT PREJUDICE

Confirm repair cost of \$5015.50 before GST @ 3 days

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Friday, 7 June 2019 5:10 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: jiajee.yap@premiumauto.com.sg
Subject: FW: FINAL REVISION - SJS9689K - TP FIRSTCAP - SURVEYED 1 APR 19

Hi Veron,

Revised estimate and photographs is attached.

Please confirm repair cost of \$5015.50 @ 3 days

Your early closure is well appreciated.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak [<mailto:boojohnny@gmail.com>]

Sent: Wednesday, 29 May, 2019 5:54 PM

To: Guo Qiang (LKK Auto) <guoqiang@lkkauto.com>; cs-a@lkkauto.com; admin-a@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SJS9689K - TP FIRSTCAP - SURVEYED 1 APR 19

Hi Guo Qiang and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$5015.50 @ 3 days

Your early closure is well appreciated.

Best regards - jb

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 2 April 2019 2:41 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002034MFSH/1, SJS 9689K
Attachments: SJS 9689K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJS 9689K
Date of survey: 1/4/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 26 March 2019 4:42 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002034MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 26 March, 2019 12:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002034MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6737I
Vehicle Details	
Vehicle No.:	SJS9689K
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Apr 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CVN041398
Chassis No.:	WAUZZZF43HA182243
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,096.00
Original Registration Date:	18 Sep 2017
First Registration Date:	18 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$26,935.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Sep 2027
PARF Rebate Amount:	\$20,201.00
Intended COE Rebate Details	
COE Expiry Date:	17 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$41,459.00
Total Rebate Amount:	\$61,660.00

The information contained herein is correct as at 01 Apr 2019

OK

Accident Photo



AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : YEO CHEE KIAT (YANG ZHIJI)
Period of Insurance : 18 Sep 2018 To 17 Sep 2019
Engine No. : CVN041398
Chassis No. : WAUZZZF43HA182243

Vehicle No. : SJS9689K
Policy No. : 1700051477-01
Endorsement No. :
Issued Date : 03 Aug 2018

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

YEO CHEE KIAT (YANG ZHIJI) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 406689 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCD9K

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

License Number: **S77267371**

Name: **YEO CHEE KIAT (YANG ZHIJI)**

Birth Date: **18 Sep 1977**

Issue Date: **26 May 2008**

000513405H



REPUBLIC OF SINGAPORE

IDENTITY CARD NO: **S77267371**



Name: **YEO CHEE KIAT (YANG ZHIJI)**

杨志杰

Race: **CHINESE**

Date of birth: **18-09-1977**

Sex: **M**

Country of birth: **SINGAPORE**

S77267371

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which, unladen, does not exceed 2500 kilograms	25 Jul 1996

NP 428A

NP 428A

Licence No: S77267371



4194283



NRIC No: **S77267371**



Date of issue: **25-03-2008**

APT BLK 128 BEDOK RESERVOIR ROAD #08-1313 SINGAPORE 470128

NRIC No: **S77267371** Date: **01/07/2012** No: **6894899**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0375/2019/GW
Date	:	23-Mar-19

Vehicle not IN workshop. Kindly assist to arrange for survey.

Your insured vehicle : SHC 7049 D

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name	:	Mr. Yeo Chee Kiat
Address	:	Blk 629 Bedok Reservoir Rd #11-1630 Singapore 470629
Telephone	:	HP +65 96896998
Type of Claim	:	Thid Party Claims
Policy No.	:	1700051477-01
Vehicle No	:	SJS 9689 K
Model Code	:	Audi A4 Sedan 1.4 TFSI
Model / Year	:	Sep-17
Engine No	:	CVN 041398
Chassis No	:	WAUZZZF43HA182243
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	21-Mar-19
Place of Accident	:	PIE Paya Lebar Flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 9689 K

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00	600 ✓
3	To respray rear bumper.	\$ 800.00	600 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 2,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 9689 K

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER / Re .	\$ 2,015.00	3015
2	REAR BUMPER FIXING PARTS DEC X NN	\$ 66.00	
3	REAR BUMPER SECURING STRIP / DEC X	\$ 203.00	303
4	REAR BUMPER SPOILER X DEC X	\$ 227.00	306-50
5	REAR LIGHT REFLECTOR LIGHT-LH/RH X NN 2	\$ 76.00	
6	REAR BUMPER CARRIER A DEC X BT	\$ 819.00	819
7	REAR BUMPER SEAL A X NN 2	\$ 25.00	
8	REAR BUMPER GUIDE SECTION-LH X	\$ 40.00	
9	REAR BUMPER GUIDE SECTION-RH X	\$ 41.00	
10	REAR BUMPER UPPER GUIDE SECTION-LH/RH X 2	\$ 40.00	
11	REAR SENSOR X 2	\$ 462.00	
12	REAR SENSOR SEAL RING X DEC X NN 4	\$ 12.00	
13	SUNDRIES X X	\$ 300.00	
TOTAL SPARE PARTS		\$ 4,326.00	
TOTAL LABOUR CHARGES		\$ 2,252.00	
GRAND TOTAL		\$ 6,578.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax



Name : Gao Qiang - 82880282
Surveyed Date :
Authorised Date : 3 Days.
Excess Cost :
Liability : before paint photos.
Remarks : 01/4/19.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 16 April 2019 1:45 PM
To: Admin-D (LKKAUTO)
Subject: FW: Check item photos and before paint photos for SJS 9689 K
Attachments: WhatsApp Image 2019-04-15 at 6.51.32 PM (1).jpeg; WhatsApp Image 2019-04-15 at 6.51.32 PM (2).jpeg; WhatsApp Image 2019-04-15 at 6.51.32 PM.jpeg; WhatsApp Image 2019-04-15 at 6.51.33 PM (1).jpeg; WhatsApp Image 2019-04-15 at 6.51.33 PM.jpeg; WhatsApp Image 2019-04-15 at 6.51.34 PM.jpeg; WhatsApp Image 2019-04-16 at 1.25.24 PM (1).jpeg; WhatsApp Image 2019-04-16 at 1.25.24 PM.jpeg; WhatsApp Image 2019-04-16 at 1.26.53 PM.jpeg; WhatsApp Image 2019-04-16 at 1.26.54 PM.jpeg; WhatsApp Image 2019-04-16 at 10.36.25 AM.jpeg; WhatsApp Image 2019-04-16 at 10.36.26 AM (1).jpeg; WhatsApp Image 2019-04-16 at 10.36.26 AM.jpeg

Importance: High

[CS/FCI19005409/Gvd3](#)

From: glory.tan@premiumauto.com.sg <glory.tan@premiumauto.com.sg>
Sent: Tuesday, 16 April, 2019 1:41 PM
To: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: allan.wu@premiumauto.com.sg; 'Claims' <claims@premiumauto.com.sg>; claims@premiumautocare.com.sg
Subject: Check item photos and before paint photos for SJS 9689 K

Dear all,

Please refer to the attached for check items, before paint photos for SJS 9689 K.

Check Item number in marked estimate,

- 4. Rear bumper spoiler. (SGD 227)
- 6. Rear bumper carrier. (SGD 819)

Thank you.

Best Regard,
Glory Tan
Bodyworks Department

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 f. +65 6841 1183

e. glory.tan@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0375/2019/GW
Date : 23-Mar-19

Vehicle not IN workshop. Kindly assist to arrange for survey.

Your insured vehicle : SHC 7049 D

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Hi Guo Qiang

3 days - ok - jb - 29 May 19

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Mr. Yeo Chee Kiat
Address : Blk 629 Bedok Reservoir Rd
#11-1630
Singapore 470629
Telephone : HP +65 96896998
Type of Claim : Third Party Claims
Policy No. : 1700051477-01
Vehicle No : **SJS 9689 K**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Sep-17
Engine No : CVN 041398
Chassis No : WAUZZZF43HA182243
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Mar-19
Place of Accident : PIE Paya Lebar Flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 9689 K

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$	360.00	\$ 360.00
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.		\$	900.00	\$ 600.00
3	To respray rear bumper.		\$	800.00	\$ 600.00
4	To carry out diagnostic check.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$	<u>2,252.00</u>	<u>\$ 1,752.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 9689 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 2,015.00	\$ 2,015.00
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SECURING STRIP	\$ 203.00	\$ 203.00
4	REAR BUMPER SPOILER	\$ 227.00	\$ 226.50
5	REAR LIGHT REFLECTOR LIGHT-LH/RH	2 \$ 76.00	
6	REAR BUMPER CARRIER	\$ 819.00	\$ 819.00
7	REAR BUMPER SEAL	2 \$ 25.00	
8	REAR BUMPER GUIDE SECTION-LH	\$ 40.00	
9	REAR BUMPER GUIDE SECTION-RH	\$ 41.00	
10	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$ 40.00	
11	REAR SENSOR	2 \$ 462.00	
12	REAR SENSOR SEAL RING	4 \$ 12.00	
13	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		\$ 4,326.00	\$ 3,263.50
TOTAL LABOUR CHARGES		\$ 2,252.00	\$ 1,752.00
GRAND TOTAL		\$ 6,578.00	\$ 5,015.50

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19005409/Gvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-06-2019		
		Code : FC12		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7049D	Veh. Inspected	SJS 9689K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002034MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	26/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WAUZZZF43HA182243	Colour	BLUE	
Odometer	21505	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CONTINENTAL	7 mm	
L/H Front Tyre	205/60 R16	CONTINENTAL	7 mm	
R/H Rear Tyre	205/60 R16	CONTINENTAL	7 mm	
L/H Rear Tyre	205/60 R16	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/03/2019	Inspection Date	01/04/2019	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1, SINGAPORE 408699			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 9689K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	2,015.00	2,015.00
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	66.00	-
1	REAR BUMPER SECURING STRIP (SN)	NECESSARY	203.00	203.00
1	REAR BUMPER SPOILER (SN)	CUT	227.00	226.50
2	REAR LIGHT REFLECTOR LIGHT-LH/RH (SN)	NOT NECESSARY	76.00	-
1	REAR BUMPER CARRIER (SN)	BENT	819.00	819.00
2	REAR BUMPER SEAL (SN)	NOT NECESSARY	25.00	-
1	REAR BUMPER GUIDE SECTION-LH (SN)	NOT NECESSARY	40.00	-
1	REAR BUMPER GUIDE SECTION-RH (SN)	NOT NECESSARY	41.00	-
2	REAR BUMPER UPPER GUIDE SECTION-LH/RH (SN)	NOT NECESSARY	40.00	-
2	REAR SENSOR (SN)	NOT NECESSARY	462.00	-
4	REAR SENSOR SEAL RING (SN)	NOT NECESSARY	12.00	-
1	SUNDRIES (SN)	NOT NECESSARY	300.00	-
			4,326.00	3,263.50
LABOUR				
	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.		360.00	360.00
	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		900.00	600.00
	TO RESPRAY REAR BUMPER.		800.00	600.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			2,252.00	1,752.00
GRAND TOTAL			6,578.00	5,015.50
RECOMMENDED COST OF REPAIRS				5,015.50

Report Ref No. CS/FC119005409/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.