

22/03/2012

ASS. REC. BY:

REF: CS/C7119005413/ Et d307 Special Instruction:

Surveyor: SteveASSIGNMENT (Office)

menmen

From (Person): Chong Boon Sen of C71 Date/Time: 22.3.19 11.16p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: 4P591E Insured: _____at Workshop m/s Goldbell Leasing Pte Ltd Tel: 64675257of 18 Tuas Avenue 10 Level 6Policy No: DMCVSU 307661800 Claim No: SNM19D 2012 6360Sum Insured: _____ Excess: \$450.00Make of Veh: _____ D.O.A. 19.3.19(Client's Record) 27.3.19 After 3.00pmCA REV / REP. / REV 24 HRS H.O.D. Endorsement: _____Date/Time: 26.3.19 5.00pm Person Contacted: Bryan Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
<u>28/3/19</u>	<u>Revert na menmen</u>	
<u>29/3/19</u>	<u>09:31am approval by Boon Sen</u>	
<u>29/3/19@10:28am</u>	<u>email to engkuok long authorise repair</u>	<u>excess \$4507.</u>
	<u>lump sum \$6300f (Red: 75+3.33; 54%)</u>	

Steve

REF: C11

ASSIGNMENT

From:

Date: 27.3.2019

Veh No:

YP591E

Yr Regn:

11/12/15

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

YP591E

Make:

Mitsubishi Canter

C.C.

1998

at Workshop m/s

Goldbell Leasing

Colour:

A/C: Insured / Std / NI / NA

of 18 Tuns Avenue

10 level 6

Sp. Reading

19/278

T/Radio: Insured / Std / NI / NA

Insured

Eng/No:

FE021EA10713

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

\$450.00

Steering: Good / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Good / Jammed / Leaked / Burnt or

Make of Veh:

After 3.00 p.m.

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

195/85R15C

R:

Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

KOMENDO

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

19/3/19

D.O.I.

27/3/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Goldbell

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-53,000

11/4/19

Finalize with Ryan \$6300, 5 days

RECEIVED 12 APR 2019

Date/Time, File Pass to?



Preli. Report



Final Report

1) D/H Typist

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

220

Transportation:

Add Fee:



Site Insp (\$)

) \$ + RS. \$



Interview (\$)

) Photos



Tech. Invs (\$)

) Others



Week-end (\$)

)

Report Format:

OD

Lump Sum / L.B.I. (\$)

6300/-

TOTAL

220

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2019		26 Mar 2019 16:16 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	VHL ENGINEERING PTE LTD, Co. Reg. No.: 200807357E		
Vehicle Reg. No.:	YP591E	Date of Loss:	19/03/2019 16:00 - :59
Claim Type:	OD / SNM19D201263C01	Policy/Cover Note No.:	DMCVSN3077661800 (Comprehensive)
		Excess:	S\$450.00
Repairer:	Goldbell Leasing Pte Ltd (HQ) 18, Tuas Avenue 10, Level 6, 639142 Tuas - Tel: 64675257		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/04/2019]		
Driver/Custodian:	PERIYAKARUPPAN DURAI (41 / Male) , NRIC: F7791774T, Tel: +6594871374 Email: NOEMAIL		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Steve Chen (LKK Auto)

From: Steve Chen (LKK Auto)
Sent: Thursday, April 11, 2019 10:07 AM
To: 'Brian Eng Kwok Long'
Subject: Finalise - YP 591 E

Dear Brian,

We confirm the finalize \$6,300 L/S and 5 days.

Thanks.

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Brian Eng Kwok Long [<mailto:EngKwokLong@goldbell.com.sg>]
Sent: Wednesday, April 10, 2019 7:22 PM
To: Steve Chen (LKK Auto)
Cc: Denise Tay (LKKAuto); Ramesh; Ashlyn Chng
Subject: Finalise - YP 591 E

Dear Mr Steve,

Kindly refer to the attached above.

Can we finalise the amount @ **\$6300?**

Thanks & Best Regards



GOLDBELL
ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>

Sales | Leasing | Financing | Insurance | Fuel Card | Advanced Fleet Management System

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 29 March 2019 10:28 AM
To: 'ENGKWOKLONG@GOLDBELL.COM.SG'
Cc: SUR; 'WilliamOhSL@goldbell.com.sg'; Ashlyn Chng; 'Ramesh@goldbell.com.sg'
Subject: YP 591E / OD / CHINA TAI PING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle YP 591E (Excess \$450/-). Repair on Lump Sum.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***YP591E (SNM19D201263C01)**

OD

Mar 19 2019 4:00PM

[VHL ENGINEERING PTE LTD]

Goldbell Leasing Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 29/03/2019 09:31 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9500.00) - YP591E - Claim Handler: Chong Boon Sen

Approved:9500.00.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 28 Mar 2019

Preliminary Advice

Vehicle No	: YP591E	Accident Date	: 19/03/2019
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3077661800
Assignment Date	: 26/03/2019	Excess	: S\$450.00
Date of Inspection	: 27/03/2019	Est. Duration of Repair	: 5.00
Inspection At	: GOLDBELL LEASING PTE LTD (HQ) 18, TUAS AVENUE 10, LEVEL 6 SINGAPORE 639142		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,873.83
Revised Amount	:S\$	7,873.28
Check Items (Estimated)	:S\$	3,940.48
		11,813.76
Lump Sum Repair	:S\$	9,500.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	53,000.00
COE / PARF Rebate	:S\$	28,339.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,661.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7357E
Vehicle Details	
Vehicle No.:	YP591E
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER3SDEB
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4P10B91598
Chassis No.:	FEB21EA10713
Maximum Power Output:	-
Open Market Value:	\$31,202.00
Original Registration Date:	11 Dec 2015
First Registration Date:	11 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$1,561.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,303.00
COE Rebate Amount:	\$28,339.00
Total Rebate Amount:	\$28,339.00

The information contained herein is correct as at 28 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2019 15:08
Date Of Accident	19/03/2019 16:15
Exact Location Of Accident	PAYA LEBAR RD BEF UBI AVE 3 T-JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP591E
Insured/Policyholder	
Name Of Registered Owner	VHL ENGINEERING PTE LTD
Co Reg No	200807357E
Email Address	ARUN@VHLEE.COM.SG
Mobile Phone No	(LOCAL) +65-90274404
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER-3.0 D FEB21 (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3077661800
Cover Note Number	

Driver

Name of Driver	PERIYAKARUPPAN DURAI
Passport No/FIN	F7791774T
Date Of Birth	01/04/1977
Occupation	OUTDOOR
Date Of Driving Pass	19/09/2008
Driving Experience	10 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94871374
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	N/A
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 19/03/2019 AT AROUND 1615HRS, I WAS TRAVELLING ALONG PAYA LEBAR RD TOWARDS UPP PAYPA LEBAR RD. WHILE DRIVING NEAR THE TRAFFIC JUNCTION OF UBI AVE 3, SUDDENLY VEHICLE B JAMMED HER BRAKE AND I APPLIED MY BRAKE BUT IT ALREADY TOO LATE AND CAUSED ME COLLIDED ONTO HER REAQR. I WENT DOWN TO SEE AND NOTICES THAT THIS ACCIDENT ALSO INVOLVED WITH VEHICLE C.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ5898Y
Vehicle Make/Model/Colour	
Details Of Properties	<i>Honda Fit</i>
Vehicle Category	PRIVATE CAR
Name of Driver	TAN POH LIN
NRIC/Passport Number	S1129807I
Contact Number	92746278
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJF7898E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAM LEE CHIN
NRIC/Passport Number	S7564322E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAY'S TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN

① YP591Z.

② SJJ5884.

③ SJF7898Z.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the circumstances.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

☒ Claim own policy
☒ Claim third party
☒ Claim OD/TP at other workshop
☐ For record purpose

Policy No. DMCVSN27766180
Insurer CUN Veh. No. YP591Z

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

MZ300/C
N SN
AN0663A
COMPREHENSIVE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMCVSN3077661600	Engine No :4P10B91598 Chassis No:FEB21EA10713
1. Index Mark and Registration Number of Vehicle	YF591E	
2. Name of Policy Holder	M/S VHL ENGINEERING PTE LTD	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	11 DECEMBER 2018	EX SECT. IS\$450.00 EX ON WINDSCREENS\$100.00
4. Date of Expiry of Insurance	10 DECEMBER 2019	
5. Persons or Classes of Persons entitled to drive *		

ANY PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH THEIR PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: *

- (1) USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
- (2) USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
- (3) USE FOR SOCIAL, DOMESTIC OR PLEASURE PURPOSES.

THE POLICY DOES NOT COVER.

- (1) USE FOR HIRE OR REWARD OR RACING, FACE-MAKING, RELIABILITY TRIAL OR SPEED TESTING.
- (2) USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

HIRE PURCHASE CO. : DAIMLER FINANCIAL SERVICES AFRICA & ASIA PACIFIC LTD AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.



Countersigned By:

Authorised Officer

Authorised Signatory



Om

Mitsubishi Canter

Price Range ▼

Depreciation ▼

2015 ▼

Vehicle Type ▼



Advanced Search

Home » Used Cars » Think One Automobile & Trading » Mitsubishi Fuso Canter FEB21

Mitsubishi Fuso Canter FEB21

Overview

Financial

Accessories

Similar

Research

Photos

Map



Think One Automobile



Price	\$53,800	Lifespan	24-Nov-2035
Depreciation ?	\$8,070 /yr View models with similar depre	Reg Date	25-Nov-2015 (6yrs 7mths 27days COE left)
Mileage	83,000 km (24.9k /yr)	Manufactured ?	2015
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$3,056 as of today (change)	OMV ?	\$30,433
COE ?	\$4,585	ARF ?	\$1,522
Engine Cap	2,998 cc	No. of Owners ?	2
Curb Weight ?	2,400 kg		
Type of Vehicle	Truck		

Features

View specs of the Mitsubishi Fuso Canter (2015)

Description

\$994 Monthly Only! 14 Feet Truck With Box. Payload 2.6 Ton. No Need VPC. Class 3 Can Drive.!

Category

-

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Valuation - Free


Compare the market value of your existing car for free. Get started



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3026 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co Reg No: 198003963G

Page 1 / 2

ESTIMATE

Date	: 20/03/2019	Reg No	: YP591E
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER3SDEB C/C AMT
Attn.	:	Chassis No	: FEB21EA10713
Office / Mobile	:	Engine No	: 4P10B91598
Email Address	:	Quotation No.	: 84058
		Ref. No.	: GBE/SVC/SALES-4838/190320
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 19/03/2019
Attn.	: ENKWOKLONG	Policy No.	: DMCVSN3077661800
Office / Mobile	: +65 6864 0637 ✓	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	MC978995 (448)	GARNISH, FR PANEL CUT ✓	1	373.08	-25	279.81	279.81
2	ML230271	PANEL ASSY, FR ✓ DD	1	2,367.22	-25	1,775.42	1,775.42
3	MK707621	PANEL, FRONT (inner) ? XNN	1	1,090.52	-25	817.89	817.89
4	MC975899 (1244)	GRILLE, FRONT (NATURALWH) ✓ MEC OR	1	719.33	-25	539.50	539.50
5	MK546617	MARK, FUSO ✓ MEC	1	150.59	-25	112.94	112.94
6	MK546616	MARK, 3-DIA ✓ MEC	1	80.22	-25	60.17	60.17
7	MK675497	EMBLEM, CANTER ✓ MEC ✓	1	76.22	-25	57.17	57.17
8	MK580528	LAMP ASSY, TURN SIGNAL, FR -RH ✓ (LH) ✓ CUT	1	250.07	-25	187.55	187.55
9	MC978516	BUMPER, FR ✓ DD	1	948.37	-25	711.28	711.28
10	MK580523	STAY, RR VIEW MIRROR -LH ✓ X NN	1	445.95	-25	334.46	334.46
11	MK580752	MIRROR, UNDER VIEW ✓ X NN	1	55.22	-25	41.42	41.42
12	MC978784	PANEL, CAB FR CORNER -RH ✓ X NN	1	492.41	-25	369.31	369.31
13	MC978783	PANEL, CAB FR CORNER -LH ✓ CUT	1	492.41	-25	369.31	369.31
14	MK583357	AIR INTAKE BOX, HEATER UNIT ? XNN	1	845.66	-25	634.25	634.25
15	MK583365	HEATER UNIT (Superseded to ML298316) ? XNN	1	2,384.46	-25	1,788.35	1,788.35

PARTS TOTAL : 8,078.83

SPECIAL NETT ITEMS

1	NUMBER PLATE BT	1	35.00
---	-----------------	---	-------

PARTS TOTAL: 35.00

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC. 610	1800	2700.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC 350	1750	2100.00
3	TO REMOVE AND REFIX AIRCONSISTEM, TO CHECK FUNCTION X ?		700.00
4	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR ✓		180.00
5	SUNDRIES 50		80.00

LABOUR TOTAL : 5,760.00



Certificate No: AIA/59191241

Certificate No: AIA/59191241



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co Reg No: 168003963G

Page 2 / 2

ESTIMATE

Date :	20/03/2019	Reg No :	YP591E
To :	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model :	FEB21ER3SDEB C/C AMT
Attn. :		Chassis No :	FEB21EA10713
Office / Mobile :		Engine No :	4P10B91598
Email Address :		Quotation No. :	84058
		Ref. No. :	GBE/SVC/SALES-4838/190320
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	19/03/2019
Attn. :	ENGKWOKLONG	Policy No. :	DMCVSN3077661800
Office / Mobile :	+65 6864 0637	Claim Type :	OD CLAIM - CHINA TAIPING
Email / Fax No. :	EngKwokLong@goldbell.com.sg	Workshop :	8 TUAS AVE 18

SUB-TOTAL : 13,873.83

GST @ 7% for \$ 13,873.83 971.17

GRAND TOTAL (S\$) : 14,845.00

PREPARED BY : ENGKWOKLONG

DATE / TIME :

27/3/19 2.30pm

SURVEYOR :

Steve Chen

MOBILE NO :

8322 8813

OFFICE FAX NO :

EMAIL ADDRESS :

stevechen@lkkarb.com

EXCESS AMOUNT :

REPAIR TYPE :

PART-BY-PART / LUMP SUM

AUTHORISATION :

AUTHORISED / NOT AUTHORISED

RE-SURVEY :

BEFORE PAINT / AFTER PAINT

NO. OF DAYS :

5 days

REMARKS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

biSAFE
STAR

AIA
SAC
Certificate No: AIA/S301Q1241

AIA
UKAS
Certificate No: AIA1384



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 636894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co Reg No: 188003963G

Page 1 / 2

ESTIMATE

Date	: 20/03/2019	Reg No	: YP591E
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER3SDEB C/C AMT
Attn.	:	Chassis No	: FEB21EA10713
Office / Mobile	:	Engine No	: 4P10B91598
Email Address	:	Quotation No.	: 84058
From	: GOLDBELL ENGINEERING PTE LTD	Ref. No.	: GBE/SVC/SALES-4838/190320
Attn.	: ENKWOKLONG	D.O.A.	: 19/03/2019
Office / Mobile	: +65 6864 0637	Policy No.	: DMCVSN3077661800
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Claim Type	: OD CLAIM - CHINA TAIPING
		Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	MC978995 (10mm)	GARNISH, FR PANEL CUT /	1	373.08	-25	279.81	279.81
2	ML230271	PANEL ASSY, FR / DD	1	2,367.22	-25	1,775.42	1,775.42
3	MK707621	PANEL, FRONT (10mm) X	1	1,090.52	-25	817.89	817.89
4	MC975899 (10mm)	GRILLE, FRONT (NATURALWH) DR	1	719.33	-25	539.50	539.50
5	MK546617	MARK, FUSO / NEC	1	150.59	-25	112.94	112.94
6	MK546616	MARK, 3-DIA / NEC	1	80.22	-25	60.17	60.17
7	MK675497	EMBLEM, CANTER / NEC	1	76.22	-25	57.17	57.17
8	MK580528	LAMP ASSY, TURN SIGNAL, FR - RH (LH) / CUT	1	250.07	-25	187.55	187.55
9	MC978516	BUMPER, FR / DD	1	948.37	-25	711.28	711.28
10	MK580523	STAY, RR VIEW MIRROR - LH X NEC	1	445.95	-25	334.46	334.46
11	MK580752	MIRROR, UNDER VIEW X / NN	1	55.22	-25	41.42	41.42
12	MC978784	PANEL, CAB FR CORNER - RH X / NN	1	492.41	-25	369.31	369.31
13	MC978783	PANEL, CAB FR CORNER - LH / CUT	1	492.41	-25	369.31	369.31
14	MK583357	AIR INTAKE BOX, HEATER UNIT X / NN	1	845.66	-25	634.25	634.25
15	MK583365	HEATER UNIT (Superseded to ML298316) X / NN	1	2,384.46	-25	1,788.35	1,788.35

PARTS TOTAL : 8,078.83

SPECIAL NETT ITEMS

1	NUMBER PLATE	1	35.00
---	--------------	---	-------

PARTS TOTAL: 35.00

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	1800	2700.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1750	2100.00
3	TO REMOVE AND REFIX AIRCON SYSTEM TO CHECK FUNCTION	700.00	
4	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR	180.00	
5	SUNDRIES	50	80.00

LABOUR TOTAL : 5,760.00





GOLDBELL ENGINEERING

Industrial Vehicles,
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638294
Tel: +65 6861 0007 Fax: +65 6861 3576 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co Reg No: 188003963G

Page 2 / 2

ESTIMATE

Date	: 20/03/2019	Reg No	: YP591E
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER3SDEB C/C AMT
Attn.	:	Chassis No	: FEB21EA10713
Office / Mobile	:	Engine No	: 4P10B91598
Email Address	:	Quotation No.	: 84058
		Ref. No.	: GBE/SVC/SALES-4838/190320
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 19/03/2019
Attn.	: ENKWOKLONG	Policy No.	: DMCVSN3077661800
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

SUB-TOTAL : 13,873.83

GST @ 7% for \$ 13,873.83 971.17

GRAND TOTAL (S\$) : 14,845.00

PREPARED BY : ENKWOKLONG

DATE / TIME : 27/3/19 2.30pm

SURVEYOR : Steve Chin

MOBILE NO : 8322 8813

OFFICE FAX NO :

EMAIL ADDRESS : SteveChin@IKKarb.com

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 5 days

REMARKS :

to lump sum
62410184
Revert
EXCUR \$450

P: 4093.15 7908.15
S/W: 35 -20%
L: 3780 \$6300
T \$7908.15



Certificate No: AIA/S/16121241 Expiry Date: 31/03/2021

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2019		26 Mar 2019 16:16 Edit Adj Rpt	S\$6,300.00 Edit Estimates	S\$6,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	VHL ENGINEERING PTE LTD, Co. Reg. No.: 200807357E								
Vehicle Reg. No.:	YP591E	Date of Loss:	19/03/2019 16:00 - :59 [39 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D201263C01	Policy/Cover Note No.:	DMCVSN3077661800 (Comprehensive)						
		Excess:	S\$450.00						
Repairer:	Goldbell Leasing Pte Ltd (HQ) 18, Tuas Avenue 10, Level 6, 639142 Tuas - Tel: 64675257								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 04/04/2019]								
Driver/Custodian:	PERIYAKARUPPAN DURAI (41 / Male), NRIC: F7791774T, Tel: +6594871374 Email: NOEMAIL								
Adj Asg. Remarks:	SURVEY REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> CHINA_TAIPING (29/03/2019): Alert - Adj Mandate Approved (S\$9500.00) - YP591E - Claim Handler: Chong Boon Se... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents










*YP591E (SNM19D201263C01)
OD
Mar 19 2019 4:00PM
[VHL ENGINEERING PTE LTD]
Goldbell Leasing Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print					
1	20/03/19 17:35	Accident Statement		Load HTM						
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	28/03/19 17:09	Adjuster Immediate Advice		Load HTM						
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print					
1	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
10	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
11	20/03/19 17:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
2	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
3	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
4	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
5	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
6	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
7	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
8	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
9	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
10	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
11	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
12	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
13	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
14	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
15	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
16	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
17	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					
18	28/03/19 08:44	General View		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
19	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
20	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
21	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
22	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
23	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
24	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
25	28/03/19 08:44	Odometer Reading		<input checked="" type="checkbox"/>
26	28/03/19 08:44	Chassis Number		<input checked="" type="checkbox"/>
27	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
28	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
29	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
30	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
31	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
32	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
33	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
34	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
35	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
36	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
37	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
38	28/03/19 08:44	General View		<input checked="" type="checkbox"/>
39	12/04/19 14:26	Reinspection Photo		<input checked="" type="checkbox"/>
40	12/04/19 14:26	Reinspection Photo		<input checked="" type="checkbox"/>
41	12/04/19 14:26	Reinspection Photo		<input checked="" type="checkbox"/>
42	12/04/19 14:26	Reinspection Photo		<input checked="" type="checkbox"/>
43	12/04/19 14:26	Reinspection Photo		<input checked="" type="checkbox"/>
44	12/04/19 14:26	Reinspection Photo		<input checked="" type="checkbox"/>
45	12/04/19 14:26	Reinspection Photo		<input checked="" type="checkbox"/>
46	12/04/19 14:26	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/03/19 16:33	od contact detail		
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	20/03/19 17:35	Sketch Plan [Linked Accident Report Documents]		
2	20/03/19 17:35	CI,IC,DL [Linked Accident Report Documents]		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/19 17:11	ESTIMATE		

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	20/03/19 17:35	Accident Statement		
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	20/03/19 17:34	Accident Photo		<input checked="" type="checkbox"/>
2	20/03/19 17:34	Accident Photo		<input checked="" type="checkbox"/>
3	20/03/19 17:34	Accident Photo		<input checked="" type="checkbox"/>
4	20/03/19 17:34	Accident Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
5	20/03/19 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	20/03/19 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	20/03/19 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	20/03/19 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	20/03/19 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	20/03/19 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	20/03/19 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	20/03/19 17:35	Sketch Plan	 Load TIF	
2	20/03/19 17:35	CI,IC,DL	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19005413/ETD3E2

Date: 25/04/2019

REFERENCE

Insured/Claimant: VHL ENGINEERING PTE LTD Policy No: DMCVSN3077661800
Date of Loss: 19/03/2019 Nature of Claim: OD Claim No: SNM19D201263C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP591E**
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21 (M) Engine No: 4P10B91598
Reg. Date: 11/12/2015 (Man. Year: 2015) Chassis No: FEB21EA10713
Colour: White Odometer: 191278 km
Engine Capacity: 2998 cc
Market Value/New Car Price: S\$53,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15C Rear Tyre Size: 195/85 R15C
Front Left Side: KOMENDO 5 mm Rear Left Side: KOMENDO 5 mm
Front Right Side: KOMENDO 5 mm Rear Right Side: KOMENDO 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,193.80	4,178.13	4,015.67	49.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	3,730.00	1,950.00	34.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,873.80	7,908.13	5,965.67	43.00
Approved Total (Overridden) (S\$)		6,300.00		
- Excess (S\$)	450.00	450.00	0.00	0.00
(S\$)	13,423.80	5,850.00	7,573.80	56.42
+ GST 7.00/7.00% (S\$)	939.67	409.50	530.17	56.42
Nett Amount (S\$)	14,363.47	6,259.50	8,103.97	56.42

INSPECTION

Date of Assignment: 26/03/2019

Date Inspected: 27/03/2019 Inspected At:

Goldbell Leasing Pte Ltd (HQ)
18, Tuas Avenue 10, Level 6
Singapore 639142

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Apr 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP591E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GARNISH, FR PANEL	Cut	373.08 FL	*373.08 FL
2	1		*PANEL ASSY, FR	Dented	2,367.22 FL	*2,367.22 FL
3	1		*PANEL, FRONT	Not Necessary	1,090.52 FL	*- FL
4	1		*GRILLE, FRONT (NATURALWH	Broken	719.33 FL	*719.33 FL
5	1		*MARK, FUSO	Necessary	150.59 FL	*150.59 FL
6	1		*MARK, 3-DIA	Necessary	80.22 FL	*80.22 FL
7	1		*EMBLEM, CANTER	Necessary	76.22 FL	*76.22 FL
8	1		*LAMP ASSY, TURN SIGNAL, FR - RH	Cut	250.07 FL	*250.07 FL
9	1		*BUMPER, FR	Dented	948.37 FL	*948.37 FL
10	1		*STAY, RR VIEW MIRROR, - LH	Not Necessary	445.95 FL	*- FL
11	1		*MIRROR, UNDER VIEW	Not Necessary	55.22 FL	*- FL
12	1		*PANEL, CAB FR CORNER - RH	Not Necessary	492.41 FL	*- FL
13	1		*PANEL, CAB FR CORNER - LH	Cut	492.41 FL	*492.41 FL
14	1		*AIR INTAKE BOX, HEATER UNIT	Not Necessary	845.66 FL	*- FL
15	1		*HEATER UNIT (SUPERSEDED TO ML298316)	Not Necessary	2,384.46 FL	*- FL
16	1		*NUMBER PLATE	Bent	35.00 FS	*35.00 FS
17	1		*SUNDRIES	Necessary	80.00 FS	*50.00 FS
					Sub Total (S\$)	10,886.73 5,542.51
					- List Item Discount on L Items 25.00/25.00% (S\$)	2,692.93 1,364.38
					Total Parts (S\$)	8,193.80 4,178.13

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	2,700.00	1,800.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	2,100.00	1,750.00
3	TO REMOVE AND REFIX AIRCON SYSTEM. TO CHECK FUNCTION	New	700.00	0.00
4	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR	New	180.00	180.00
Gross Labour Cost (\$\$)			5,680.00	3,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >