PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762 Tel: 6271 4618 Fax: 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBD 840Y

DATE ACCIDENT : 18.10.2018

MAKE / MODEL : YAMAHA/WR 250X

S/No	DESCRIPTION	AMOUNT	
1	HANDLE BAR	\$	285.00
2	HANDLE GUARD	\$	285.00
3	UNDER BRACKET	\$	485.00
4	STEERING CON	\$	180.00
5	HEADLIGHT	\$	195.00
6	HEADLIGHT MASK	\$	260.00
7	HEADLIGHT BRACKET	\$	165.00
8	SIGNAL LIGHT x2	\$	136.00
9	FRONT FENDER	\$	165.00
10	FRONT FORK INNER x2	\$	770.00
11	FRONT WHEEL RIM	\$	480.00
12	FRONT BRAKE DISC	\$	380.00
13	FRONT WHEEL SHAFT	\$	165.00
14	HANDLE CRAMP	\$	450.00
15	REAR FENDER	\$	265.00
16	SUB FRAME	\$	795.00
17	FRONT SLIDER	\$	165.00
18	REAR SLIDER	\$	165.00
19	MUFFLER	\$	780.00
20	CLUTCH LEVER HOLDER	\$	85.00
21	FORK SEAL x2	\$	90.00
21	ADJUST RIM	\$	120.00
22	FORK OIL	\$	90.00
23	RADIATOR ASSY	\$	680.00
24	· COOLANT	\$	50.00
24	COLANI	Ť	
	TRANSPORT		
	LABOUR		
		Total \$	7,686.0



Traffic Police 10 Ubi Avenue 3 Singapore 408865 Tel +65 6547 0000 Fax +65 6547 4883 www.police.gov.sg

Our Ref Date

: TP/IP/60211/2018 : 8 FEBRUARY 2019

NIZAMUDDIN BIN SHAH MOHAMED .
BLK 182 YUNG SHENG ROAD #06-51
SINGAPORE 610182

Dear Sir/Madam

ROAD TRAFFIC ACCIDENT INVOLVING FBD 840 Y AND SHB 4341 J ALONG YUAN CHING ROAD ON 18/10/2018 AT ABOUT 10.20PM

I refer to the above accident.

Please be informed that we have completed our investigations which revealed that the driver of SHB 4341 J had committed an offence of Inconsiderate Driving under Section 65(b) of the Road Traffic Act Chapter 276. Action has been initiated against the driver for the said offence.

Yours faithfully

HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE

This is a computer-generated letter. No signature is required.

