



VIL

Section A - Accident Details

Registration Number	SHD6130C
Case Reference Number	TAX/03/19/2100
Registration Date	6/5/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LIM POO LEP
Type of Accident	Head to Rear
Accident Date and Time	20/3/2019 12:05 PM
Accident Reported Date and Time	21/3/2019 9:28 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100691
Special Instruction to ARC, if any	TP
Prepared Date and Time	21/3/2019 2:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



P/P

P/P #1375 011- 2 days

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$588.00	\$300.00
Total Spray Cost	\$738.00	\$300.00
Total Spare Part Cost	\$1,734.21	\$735.01
Total Other Cost	\$260.00	\$40.00
TOTAL COST	\$3,320.21	\$1,375.01 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / EQ
ARC / Surveyor Sign Off Date	21/03/2019 2:18 PM	22/03/2019 2:50 PM
Signature		
Remarks	Initial estimates = 3 days Request number of days to extend 2 days	P/P REPAIR, PHOTO BEFORE PAINT.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1905-0005	Invoice Number	
Quotation Date	02.05.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$338.00	\$200.00
TO REPAIR REAR END PANEL	\$250.00	\$100.00
Total Labour	\$588.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$738.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$260.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given X
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
Total					\$1,761.01		\$476.03		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
Total					345.30		258.98		

735.01
+ 300.00
+ 340.00
1375.01