

2/28/2019

ASS. REC. BY:

REF: CS/MSG19005439/Dgd3⁷²

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

Minid

From (Person): Christin Wong of MSG

Date/Time: 26-3-2019 16:42pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHC 1472D

Insured: SKU 1087C

at Workshop m/s Soon Hock Motor Pte Ltd

Tel: 64836016

of BIK 10 Ang Mo Kio Industrial Park 2A #01-05/06

Policy No: B29/00055mcy

Claim No: 588436

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22.3.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 27.3.19 9:48AM

Person Contacted: Doreen

Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate (✓)	hsp: chunni motor (rmk)
	SHC 1472D - MBA/MSG19005220/K4		D.O.A - 22/3/2019
	SKU 1087C - MBA/MSG19005220/K4		D.O.A - 22/3/2019
08/4/19 @ 11:41am	revised to Christina Wong via Maxine.		

COB 2020 April

2012 April

Vehicle: SHC 1472D

Type: 400 cc / 44 cc / 45 cc / 46 cc / 47 cc / 48 cc / 49 cc / 50 cc / 51 cc / 52 cc / 53 cc / 54 cc / 55 cc / 56 cc / 57 cc / 58 cc / 59 cc / 60 cc / 61 cc / 62 cc / 63 cc / 64 cc / 65 cc / 66 cc / 67 cc / 68 cc / 69 cc / 70 cc / 71 cc / 72 cc / 73 cc / 74 cc / 75 cc / 76 cc / 77 cc / 78 cc / 79 cc / 80 cc / 81 cc / 82 cc / 83 cc / 84 cc / 85 cc / 86 cc / 87 cc / 88 cc / 89 cc / 90 cc / 91 cc / 92 cc / 93 cc / 94 cc / 95 cc / 96 cc / 97 cc / 98 cc / 99 cc / 100 cc

Color: Blue

Year: 1991

Engine No: 349458

Chassis No: D4BAC071066

VIN: KMHE141VMCA823022

Gen. Cond: Good

Steering: Good

Brake: Good

Mod: 5/Rim / STD A/Rim

Tire Size: 215/60 R16

Body Condition: The veh had commenced its repair at the time of inspection.

Gen. Cond: Good

Body: Consistent? Yes or No

Chassis: Consistent? Yes or No

Ld. Deposits: 9 day, Rev: Yes or No

Lump Sum: 20 %, Val: Yes or No

CA / REV / REP / 24 HRS

Date: Person Contacted

Vehicle: IN / OUT

Date / Time: Action / Instruction

MSIG SKU 1087C

Vehicle below 12 mths.

25/04/2019 Jnaphu 2/3 11,000/- situ 9 dgr 2 rev
Cred 8988.36, 45/07

RECEIVED 25 APR 2019

Date/Time: File Path for



Prel. Report

25/4/2019 Jnaphu



Final Report

Date/Time: File Path for

If

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee

Transportation

1. 1000

2. 1000

3. 1000

4. 1000

5. 1000

6. 1000

7. 1000

200
10

210

Report Format: MER-TP

Lump Sum / 11000

Add Fee: ☐ Date/Time: 13☐ Interview: 13☐ Tech. Serv: 13☐ Wash and: 13

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 08 Apr 2019

Preliminary Advice

Insured Vehicle No	: SKU1087C	Accident Date	: 22/03/2019
TP Vehicle No	: SHC1472D	Assignment Date	: 26/03/2019
Make	: HYUNDAI SONATA NF	Est. Duration of Repair	: 9.00
Date of Inspection	: 28/03/2019		
Inspection At	: SOON HOCK MOTOR PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,988.36
Revised Amount	:S\$	14,338.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,338.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Mar 2019 14:37		26 Mar 2019 16:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Sime Darby Services Pte Ltd, Co. Reg. No.: 197501065W								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC1472D	Date of Loss:	22/03/2019 09:00 - :59 [83 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 588436	Policy/Cover Note No.:	B29100055MCY (Comprehensive) Coverage: 01/10/2018 - 30/09/2019						
Vehicle Reg. No. (Insured):	SKU1087C	Policy No. (Claimant):							
		Excess:							
Repairer:	Soon Hock Motor Pte Ltd (HQ) Bldg 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/03/2019]								
Driver/Custodian (Insured):	D'SILVA SONIA ELICIA (), NRIC: S9114696G Email:								
Adj Asg. Remarks:	Liability no clear. TP agree SJE- assign LKK Contact - Ms Lynn 6542 5119 / Ms Irene 6542 7162. On WP.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD819037991 / ComfortDelGro Engineering Pte Ltd - Layan
 ENTRY DATE & TIME: 22/03/2019 16:56
 SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/03/2019 16:56
 Date Of Accident 22/03/2019 09:15
 Exact Location Of Accident SOUTH BUONA VISTA TWDS NUH
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC1472D
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model SONATA
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number MCOM0015
 Cover Note Number
 Driver
 Name of Driver SEET ONN CHUEN
 NRIC No S0050309F
 Date Of Birth 07/10/1954
 Occupation OUTDOOR
 Date Of Driving Pass 16/12/1974
 Driving Experience 44 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98181362
 Fax Number
 Contact Number
 EMail Address SEET_OC@HOTMAIL.COM

Address BLK 787 YISHUN RING ROAD #07-3490
Postcode 760787
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY
Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED
Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKU1087C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver O'SILVA SONIA ELICIA
NRIC/Passport Number S9114696G
Contact Number
Address
Postcode
Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage FRT LEFT
No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 22.03.2019@ 1300HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June

SKETCH PLAN

Amended on 25-03-2019

A-SHG-1472D

B-SKU 1087C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22.03.2019 @ 0915HRS I was travelling along South Buona Vista Twds NUH with no passenger onboard.

As I was travelling straight suddenly veh(B) SKU 1087C hit onto my vehicle right portion. After the impact my vehicle spinned.

As the accident took place too fast I could not take evasive action to prevent the accident.

I have company video and photos at scene to support my claims.

No injury in this accident.

Veh(B) SKU 1087C MS O'Silva Sonia Elicia S 9114696G

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 22.03.2019@ 1300HRS

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: June

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 1472D

DATE : 22.03.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

MRICG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Lamp (RH) <i>okuc</i>			\$ 565.60
	Rear Bumper <i>Dental</i>			\$ 578.40
	Rear Bumper Clip <i>huc</i>			\$ 22.00
	Rear Bumper Bracket, RH <i>2 bt / broken</i>			\$ 49.00
	Rear Bumper Protector (RH) <i>bt</i>			\$ 38.00
	Tail Lamp (RH) <i>broken</i>			\$ 697.80
	Tail Lamp Quarter Panel (RH) <i>2 Dental</i>			\$ 226.50
	Tail Lamp Panel Top (RH) <i>HN</i>			\$ 545.90
	Rear Fender (RH) <i>Buc</i>			\$ 2,171.40
	Rear Fender Inner Panel (RH) <i>2 Dental</i>			\$ 1,310.60
	Rear Fender Inner Lining (RH) <i>HN</i>			\$ 169.30
	Rear Tray Lugg Side (RH) <i>bt</i>			\$ 39.10
	Rear Fender Mudflap (RH) <i>cut</i>			\$ 15.80
	Rear Fender Trim Board (RH) <i>bt</i>			\$ 188.75
	Rear Windscreen Moulding <i>huc</i>			\$ 60.00
	Rear Door (RH) <i>Buc</i>			\$ 2,201.10
	Rear Door Gear/Regulator (RH) <i>HN</i>			\$ 625.00
	Rear Door Motor (RH) <i>HN</i>			\$ 280.40
	Rear Door Protector (RH) <i>bt</i>			\$ 56.90
	Front Door (RH) <i>bt</i>			\$ 2,256.40
	Front Door Protector (RH) <i>cut</i>			\$ 78.25
	Door Centre Pillar Outer (RH) <i>HN</i>			\$ 2,527.80
	Rear Tyre Rim (RH) <i>2 distorted</i>			\$ 325.30
	Rear Wheel Hub-Cap (RH) <i>cut</i>			\$ 145.00
	Rear Wheelbearing ING & Hub <i>2 Done</i>			\$ 384.60
	Rear Trailing Arm (RH) <i>2 distorted</i>			\$ 192.00
	Rear Assist (RH) <i>2 distorted</i>			\$ 145.70
	Rear Shock Absorber (RH) <i>2 bt</i>			\$ 276.30
	Rear Shock Absorber Mounting (RH) <i>HN</i>			\$ 81.30
	Rear Crossmember <i>3 distorted</i>			\$ 1,140.40
	Stabilizer Bar <i>2 distorted</i>			\$ 199.60
	Stabilizer Link <i>2 distorted</i>			\$ 85.90
	Rear Upper Arm (RH) <i>2 distorted</i>			\$ 335.75
	Rear Lower Arm (RH) <i>2 distorted</i>			\$ 353.80
	Rear Knuckle Arm (RH) <i>2 distorted</i>			\$ 550.80
			14690.75	
			11752.60	
	SUB TOTAL			\$ 18,920.45
	LESS 20%			\$ 3,784.09
	DISCOUNTED TOTAL			\$ 15,136.36

SHC 1472D

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender Comfort Apps Sticker (RH) <i>hlc</i>			\$ 30.00	Nett ✓
	Rear Windscreen Sealant <i>hlc</i>			\$ 46.00	Nett ✓
	Rear Door Tel No. Sticker (RH) <i>hlc</i>			\$ 10.00	Nett ✓
	Front Door Advertisement Logo (RH) <i>hlc</i>		186.00	\$ 100.00	Nett ✓
	Rear Tyre (RH) <i>SWC</i>			\$ 216.00	Nett X
				\$ 402.00	
	Labour Charge				
	Panel Beating			\$ 1,800.00	900/-
	Spray Painting Charge			\$ 1,500.00	900/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Towing Charge			\$ 50.00	20/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Undercarriage (RR)			\$ 200.00	750/-
	Transfer of Door		\$ 120.00	\$ 240.00	120/-
	Rear Wheel Alignment		2400.00	\$ 120.00	60/-
				\$ 4,450.00	
	TOTAL LABOUR				
	ESTIMATE TOTAL			\$ 19,988.36	
	<i>28/03/2019 @ 1045hrs</i>		14338.60		
	<i>Nett Amount</i>		1/311000/-		
	<i>2/5000 9 days.</i>				
	<i>1 year</i>				
	<i>LKK Auto</i>				
	<i>[Signature]</i>				
	<div><div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</div><div>Acknowledged by Repairer Signature: Date:</div></div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 1472 D

Technician:

Mileage: 349458

Time Printed 28.3.19 11:03 AM

Hyundai : Sonata : 2005-

Front : Left

Actual	BEFORE	Specified Range
-0°18'		-0°30' 0°30'
3°59'		3°50' 5°50'
-0°03'		-0°05' 0°05'
12°13'		
11°55'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
0°03'		-0°30' 0°30'
3°44'		3°50' 5°50'
-0°03'		-0°05' 0°05'
9°53'		
9°56'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°21'		
0°15'		
2°20'		
-0°06'		-0°09' 0°09'

Rear : Left

Actual	BEFORE	Specified Range
-0°52'		-1°00' 0°00'
-0°07'		0°00' 0°09'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°23'		-1°00' 0°00'
-1°55'		0°00' 0°09'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°29'		
-2°02'		0°00' 0°19'
0°54'		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19005439/KQD3N2
Date: 03/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29100055MCY
Claimant Vehicle No :	SHC1472D	Insured Vehicle No :	SKU1087C
Date of Loss:	22/03/2019	Nature of Claim:	TP
		Claim No:	588436

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1472D	Engine No:	D4EAC071066
Make & Model:	HYUNDAI SONATA NF, 2.0 CRDI AT ABS 2WD 4DR TURBO (A)	Chassis No:	KMHET41VMCA823022
Reg. Date:	19/04/2012 (Man. Year: 2012)	Odometer:	349458 km
Colour:	Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,538.36	11,938.60	3,599.76	23.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,450.00	2,400.00	2,050.00	46.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,988.36	14,338.60	5,649.76	28.27
Approved Total (Overridden) (\$\$)		11,000.00		
(\$\$)	19,988.36	11,000.00	8,988.36	44.97
+ GST 7.00/7.00% (\$\$)	1,399.19	770.00	629.19	44.97
Nett Amount (\$\$)	21,387.55	11,770.00	9,617.55	44.97

INSPECTION

Date of Assignment: 26/03/2019
Date Inspected: 28/03/2019 Inspected At:

CHUNNI MOTOR WORK PTE LTD
BLK 10 ANG MO KIO IND. PARK 2A,
#03-19 AMK AUTOPOINT
SINGAPORE 568047

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2019)
Parts:	143	HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1472D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOT LID LAMP RH	Cracked	565.60 FL	*565.60 FL
2	1	*REAR BUMPER	Dented	578.40 FL	*578.40 FL
3	10	*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
4	1	*REAR BUMPER BRACKET,RH	Bent/Broken	49.00 FL	*49.00 FL
5	1	*REAR BUMPER PROTECTOR (RH)	Bent	38.00 FL	*38.00 FL
6	1	*TAIL LAMP (RH)	Broken	697.80 FL	*697.80 FL
7	1	*TAIL LAMP QUARTER PANEL (RH)	Dented	226.50 FL	*226.50 FL
8	1	*TAIL LAMP PANEL TOP (RH)	Not Necessary	545.90 FL	*- FL
9	1	*REAR FENDER (RH)	Buckled	2,171.40 FL	*2,171.40 FL
10	1	*REAR FENDER INNER PANEL (RH)	Dented	1,310.60 FL	*1,310.60 FL
11	1	*REAR FENDER INNER LINING (RH)	Not Necessary	169.30 FL	*- FL
12	1	*REAR TRAY LUGG SIDE (RH)	Bent	39.10 FL	*39.10 FL
13	1	*REAR FENDER MUDFLAP (RH)	Cut	15.80 FL	*15.80 FL
14	1	*REAR FENDER TRIM BOARD (RH)	Bent	188.75 FL	*188.75 FL
15	1	*REAR WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL
16	1	*REAR DOOR (RH)	Buckled	2,201.10 FL	*2,201.10 FL
17	1	*REAR DOOR GEAR/REGULATOR (RH)	Not Necessary	625.00 FL	*- FL
18	1	*REAR DOOR MOTOR (RH)	Not Necessary	280.40 FL	*- FL
19	1	*REAR DOOR PROTECTOR (RH)	Bent	56.90 FL	*56.90 FL
20	1	*FRONT DOOR (RH)	Bent	2,256.40 FL	*2,256.40 FL
21	1	*FRONT DOOR PROTECTOR (RH)	Cut	78.25 FL	*78.25 FL
22	1	*DOOR CENTRE PILLAR OUTER (RH)	Not Necessary	2,527.80 FL	*- FL
23	1	*REAR TYRE RIM (RH)	Distorted	325.30 FL	*325.30 FL
24	1	*REAR WHEEL HUP-CAP (RH)	Cut	145.00 FL	*145.00 FL
25	1	*REAR WHEELBEARING ING & HUB	Damaged	384.60 FL	*384.60 FL
26	1	*REAR TRAILING ARM (RH)	Distorted	192.00 FL	*192.00 FL
27	1	*REAR ASSIST (RH)	Distorted	145.70 FL	*145.70 FL
28	1	*REAR SHOCK ABSORBER (RH)	Bent	276.30 FL	*276.30 FL
29	1	*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	81.30 FL	*- FL
30	1	*REAR CROSSMEMBER	Distorted	1,140.40 FL	*1,140.40 FL
31	1	*STABILIZER BAR	Distorted	199.60 FL	*199.60 FL
32	1	*STABILIZER LINK	Distorted	85.90 FL	*85.90 FL
33	1	*REAR UPPER ARM (RH)	Distorted	335.75 FL	*335.75 FL
34	1	*REAR LOWER ARM (RH)	Distorted	353.80 FL	*353.80 FL
35	1	*REAR KNUCKLE ARM (RH)	Distorted	550.80 FL	*550.80 FL
36	1	*REAR FENDER COMFORT APPS STICKER (RH)	Necessary	30.00 FS	*30.00 FS
37	1	*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
38	1	*REAR DOOR TEL NO STICKER (RH)	Necessary	10.00 FS	*10.00 FS
39	1	*FRONT DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
40	1	*REAR TYRE (RH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 19,322.45 14,876.75
 - List Item Discount on L Items 20.00/20.00% (\$\$) 3,784.09 2,938.15

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	15,538.36	11,938.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,800.00	900.00
2	SPRAY PAINTING CHARGE	New	1,500.00	900.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
10	TRANSFER OF DOOR	New	240.00	120.00
11	REAR WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			4,450.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >