

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9868M**AAD1903-163***Not Not hair*
11/12/14 @ 4350/

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9868M

VF1ABL15AUC277496

RENAULT

LATITUDE

22.3.2019

TOKIO MARINE

9/5/2014

PART**LIST**

1	DOOR PANEL FRT LH	\$	<i>Del/wap</i> 2,844.66	✓
1	DOOR HINGE UPPER LH	\$	<i>R</i> 261.28	X
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55	X
1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77	X
1	DOOR LOCK FRT LH	\$	<i>R</i> 908.75	X
1	DOOR CATCH FRT LH	\$	<i>Sn</i> 131.23	X
1	DOOR HANDLE OUTER FRT LH	\$	<i>Bu</i> 477.76	✓
1	DOOR HANDLE COVER FRT LH	\$	<i>mir</i> 13.22	—
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i> 133.60	}
1	DOOR REGULATOR FRT LH	\$	<i>R</i> 505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sn</i> 796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sn</i> 120.97	
1	DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	
1	DOOR GUIDE REAR LH	\$	<i>Sn</i> 176.82	
1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50	
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55	
1	DOOR CHECK REAR LH	\$	<i>Sn</i> 203.06	
1	DOOR LOCK REAR LH	\$	<i>R</i> 908.75	
1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49	
1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52	
1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89	
1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22	
1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60	
1	DOOR REGULATOR REAR LH	\$	<i>Sn</i> 1,135.10	}
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>Sn</i> 893.75	
1	DOOR REGULATOR NUT REAR LH	\$	<i>Sn</i> 12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i> 6.31	
1	DOOR FINISHER REAR LH	\$	<i>Sn</i> 423.10	
1	DOOR MOULDING REAR LH	\$	<i>Sn</i> 176.82	
1	DOOR MOULDING CLIP L70Y	\$	<i>Sn</i> 5.92	
1	DOOR MOULDING SCREW L70Y	\$	<i>Sn</i> 6.91	X

Trans-cab Auto Services Pte Ltd**AAD1903-163**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9868M

1	DOOR CASING REAR LH	\$	SH 1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	SH 30.39	
1	DOOR CASING CLIP	\$	SH 12.63	
1	DOOR CASING LIGHT L70Y	\$	SH 48.74	
1	DOOR FINISHER INNER REAR LH	\$	SH 323.44	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	SH 46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	SH 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	SH 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	SH 20.33	
1	DOOR GRAB HANDLE REAR LH	\$	SH 210.96	
1	DOOR BLIND REAR LH	\$	SH 741.80	
1	DOOR WHEATHESTRIP REAR LH	\$	SH 410.66	
1	DOOR SEAL REAR LH	\$	SH 162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	SH 229.31	
1	DOOR WAIST SEAL OUTER REAR LH	\$	SH 334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	SH 115.64	
1	FENDER PANEL REAR LH	\$	SH 3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	SH 671.45	
1	WHEELARCH REAR LH	\$	SH 543.47	
1	BUMPER COVER REAR	\$	SH 1,108.46	
1	BUMPER LOWER REAR	\$	SH 768.84	
1	BUMPER BRACKET CTR REAR	\$	SH 113.47	
1	BUMPER RETAINER LH REAR	\$	SH 44.99	
1	BUMPER BEAM REAR	\$	SH 777.52	
1	BUMPER BEAM BRACKET LH REAR	\$	SH 225.95	
1	DOOR MIRROR ASSY LH	\$	CM 1,483.40	
1	TAILLAMP LH	\$	SH 552.55	X
1	ROCKER PANEL INNER GARNISH LH	\$	SH 466.51	X
1	ROCKER PANEL INNER LH	\$	SH 1,024.79	X
1	ROCKER PANEL CENTER LH	\$	SH (N-C) 990.25	X

\$	30,681.93
10% \$	3,068.19
\$	27,613.74

Specical Nett

1SET	BUMPER CLIP FRT	\$	SH 66.00	X
1	BUMPER BRACKET CLIP FRT LH	\$	SH 12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	SH 10.50	X

Trans-cab Auto Services Pte Ltd**AAD1903-163**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9868M

1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	60na
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	15na
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	60na
1	DOOR CHECK BOLT	\$	na	22.69	} X
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
1	FRONT LEFT TYRE RIM	\$	na	380.00	
1	FRONT LEFT TYRE	\$	na	330.00	

TOTAL	\$	1,329.63
--------------	-----------	-----------------

TOTAL PARTS	\$	28,943.37
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,200.00	400l
----	----------	------

To apply paint protection system (PPS) maintain and enhancement

\$	na	380.00	X
----	----	--------	---

Putty and spray painting of the affected portion.

\$	4,200.00	500l
----	----------	------

To rust-proofing of the affected areas.

\$	170.00	30l
----	--------	-----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	na	380.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd**AAD1903-163**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9868M

To check steering geometry and computer wheel alignment	\$	220.00X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X
To lift-up engine with gear box and refit.	\$	440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 X
To remove and refit air bag system and reset.	\$	480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 X
To replace, refix and top up coolant for radiator	\$	170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be approved by insurance company
- is subject to final approval from Insurance Company

TOTAL \$ 13,280.00**Over All Total \$ 42,223.37****LUMP SUM REPAIR DAY)**

Acknowledged by Repairer

Signature:

Date:

20 DAYS*2 1/2 days*