

ASS. REC. BY:

REF: TMI / CC3 / TMI 19005448 / Kvd302

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SLC 1679C

Policy No. MK000199

Claims No. M1902054


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 1/2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S1-10 9868M Yr Regn: 03, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Renault Latitude c.c. 1995

Colour: M. white / Red A/C: Insured / Std / NI / NA

Sp. Reading 797740 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF1ABL15AUC 277496

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 22/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to

27/3/19 C. / P. 843501 (Red 37,873.37, 8990)

SHD 9868M - CC4 / A.M 19003067 / Kpb3 D.O.A - 28/01/2019

SLC 1679C - X

27/3/19 Email GIA to TMI RECEIVED 28 MAR 2019

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 2 1/2

Resurvey No. of Trip: -

1)

☐ : Final Report

Date/Time, File Return to?

2) 28/3 - typist

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

merimen

4350/-

250

10

260

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2019		28 Mar 2019 15:38 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LCRF PTE. LTD, Co. Reg. No.: 201624597K		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD9868M	Date of Loss:	22/03/2019 02:00 - :59
Claim Type:	TP / M1902054	Policy/Cover Note No.:	MK000199 (Third Party Only) Coverage: 25/02/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	SLC1679C	Policy No. (Claimant):	
		Excess:	\$1,600.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/04/2019]		
Adj Asg. Remarks:	OUR INSD HAS NOT RPT THE ACCIDENT		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Veron Chen (LKKAUTO)

---

**From:** Too Joon Hwa <shirleytoo@tokiomarine.com.sg> on behalf of Motor Claims <motorclaims@tokiomarine.com.sg>  
**Sent:** Thursday, 28 March 2019 3:37 PM  
**To:** Veron Chen (LKKAUTO); Motor Claims; SUR  
**Subject:** M1902054-TG - RE: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 22/3/2019, SHD 9868M (TP VEHICLE), SLC 1679C (OI VEHICLE)

Hi Veron

We have assign through Merimen.

Our insured has not report the accident.

Thanks.

### Shirley Too

Administrative Assistant, Motor Claims

Tokio Marine Insurance Singapore Ltd.  
20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046  
T (65) 6592 6409 | F (65) 6221 2101 |  
E [shirleytoo@tokiomarine.com.sg](mailto:shirleytoo@tokiomarine.com.sg) | W [www.tokiomarine.com](http://www.tokiomarine.com)

A member of the  
Tokio Marine Group

Please note that all personal information provided to Tokio Marine Insurance Singapore Ltd. is subject to the Personal Data Protection Policy Statement posted at [www.tokiomarine.com](http://www.tokiomarine.com).

---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Wednesday, 27 March, 2019 4:00 PM  
**To:** Motor Claims <motorclaims@tokiomarine.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 22/3/2019, SHD 9868M (TP VEHICLE), SLC 1679C (OI VEHICLE)

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9868M at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 25/3/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 27 March 2019 4:00 PM  
**To:** motorclaims@tokiomarine.com.sg; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD,  
DOA: 22/3/2019, SHD 9868M (TP VEHICLE), SLC 1679C (OI VEHICLE)  
**Attachments:** GIA.pdf; MARK EST.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9868M at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 25/3/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 27 March 2019 4:05 PM  
**To:** Ng Wai Yin; calvin.er@transcab.com.sg  
**Cc:** SUR; jasminetan@transcab.com.sg  
**Subject:** SHD 9868M-DOA: 22/3/2019  
**Attachments:** MARK EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Finalize amount \$4350/- before GST @ 2.5 days.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAUTO)**

---

**From:** weichunkong <weichunkong@transcab.com.sg>  
**Sent:** Tuesday, 26 March 2019 2:24 PM  
**To:** 'Candy Kong'  
**Cc:** Kenneth Kong (LKKAUTO)  
**Subject:** RE: Book Value FOR SHD9868M

Hi all,

SHD9868M net book value is \$46,811.80

Thanks  
Best regards

CK



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Candy Kong [mailto:candy.kong@transcab.com.sg]  
**Sent:** Tuesday, 26 March, 2019 9:29 AM  
**To:** 'weichunkong' <weichunkong@transcab.com.sg>  
**Cc:** 'Kenneth Kong (LKKAUTO)' <KennethKong@lkkauto.com>  
**Subject:** Book Value FOR SHD9868M

HI CK,

Can you forward us book value for the below mentioned vehicle?

SHD9868M – 22/3/2019 2:50 AM

*Thks & Rdgs*  
*Candy Kong*  
*Claims Service Assistant*



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

#### Vehicle Details

Vehicle No.:	SHD9868M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001311
Chassis No.:	VF1ABL15AUC277496
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	09 May 2014
First Registration Date:	09 May 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

#### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 May 2022
PARF Rebate Amount:	\$9,373.00

#### Intended COE Rebate Details

COE Expiry Date:	08 May 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$60,414.00
COE Rebate Amount:	\$23,614.00
<b>Total Rebate Amount:</b>	<b>\$32,987.00</b>

#### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/03/2019 09:38
Date Of Accident	22/03/2019 02:50
Exact Location Of Accident	DUNLOP STREET X PERAK ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9868M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	KHOO PAK MIANG ALBERT
NRIC No	S0189060C
Date Of Birth	25/07/1949
Occupation	OUTDOOR
Date Of Driving Pass	06/11/1967
Driving Experience	51 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98232989
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	BLK 320D ANCHORVALE DRIVE #10-170
Postcode	544320
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 22/03/2019 AT ABOUT 0250HRS, I WAS TRAVELLING STRAIGHT ALONG DUNLOP STREET. WHILE I REACH THE JUNCTION OF PERAK ROAD, I SUDDENLY FELT AN IMPACT FROM THE LEFT SIDE OF MY TAXI. VEHICLE B(SLC1679C) WHICH WAS STATIONARY ON MY LEFT SIDE SUDDENLY OPENED THE REAR RIGHT DOOR AND HIT ONTO MY TAXI'S LEFT SIDE MIRROR AND DOOR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC1679C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GZA Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

AAD1903-163

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9868M

SHD 9868M

VF1ABL15AUC277496

RENAULT

LATITUDE

22.3.2019

TOKIO MARINE

9/5/2014

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

**PART****LIST**

1	DOOR PANEL FRT LH	\$	<i>Del/wrap</i> 2,844.66	✓
1	DOOR HINGE UPPER LH	\$	<i>R</i> 261.28	X
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55	X
1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77	X
1	DOOR LOCK FRT LH	\$	<i>R</i> 908.75	X
1	DOOR CATCH FRT LH	\$	<i>Sn</i> 131.23	X
1	DOOR HANDLE OUTER FRT LH	\$	<i>Bro</i> 477.76	✓
1	DOOR HANDLE COVER FRT LH	\$	<i>mis</i> 13.22	—
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i> 133.60	}
1	DOOR REGULATOR FRT LH	\$	<i>R</i> 505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sn</i> 796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sn</i> 120.97	
1	DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	
1	DOOR GUIDE REAR LH	\$	<i>Sn</i> 176.82	
1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50	
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55	
1	DOOR CHECK REAR LH	\$	<i>Sn</i> 203.06	
1	DOOR LOCK REAR LH	\$	<i>R</i> 908.75	
1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49	
1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52	
1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89	
1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22	
1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60	
1	DOOR REGULATOR REAR LH	\$	<i>Sn</i> 1,135.10	}
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>Sn</i> 893.75	
1	DOOR REGULATOR NUT REAR LH	\$	<i>See</i> 12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i> 6.31	
1	DOOR FINISHER REAR LH	\$	<i>Sn</i> 423.10	
1	DOOR MOULDING REAR LH	\$	<i>Sn</i> 176.82	}
1	DOOR MOULDING CLIP L70Y	\$	<i>Sn</i> 5.92	
1	DOOR MOULDING SCREW L70Y	\$	<i>Sn</i> 6.91	

*Not Not haim*  
*11/5/14 @ 4350h*

**Trans-cab Auto Services Pte Ltd****AAD1903-163**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9868M**

1	DOOR CASING REAR LH	\$	Sm 1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	Sm 30.39	
1	DOOR CASING CLIP	\$	na 12.63	
1	DOOR CASING LIGHT L70Y	\$	Sm 48.74	
1	DOOR FINISHER INNER REAR LH	\$	Sm 323.44	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	R 46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	R 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	R 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	R 20.33	
1	DOOR GRAB HANDLE REAR LH	\$	Sm 210.96	
1	DOOR BLIND REAR LH	\$	Sm 741.80	
1	DOOR WHEATHESTRIIP REAR LH	\$	Sm 410.66	
1	DOOR SEAL REAR LH	\$	Sm 162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	Sm 229.31	
1	DOOR WAIST SEAL OUTER REAR LH	\$	Sm 334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	Sm 115.64	
1	FENDER PANEL REAR LH	\$	R 3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	Sm 671.45	
1	WHEELARCH REAR LH	\$	Sm 543.47	
1	BUMPER COVER REAR	\$	Sm 1,108.46	
1	BUMPER LOWER REAR	\$	Sm 768.84	
1	BUMPER BRACKET CTR REAR	\$	Sm 113.47	
1	BUMPER RETAINER LH REAR	\$	Sm 44.99	
1	BUMPER BEAM REAR	\$	R 777.52	
1	BUMPER BEAM BRACKET LH REAR	\$	R 225.95	
1	DOOR MIRROR ASSY LH	\$	CM 1,483.40	✓
1	TAILLAMP LH	\$	Sm 552.55	X
1	ROCKER PANEL INNER GARNISH LH	\$	Sm 466.51	X
1	ROCKER PANEL INNER LH	\$	R 1,024.79	X
1	ROCKER PANEL CENTER LH	\$	na (n-c) 990.25	X

**\$ 30,681.93**10% **\$ 3,068.19****\$ 27,613.74****Special Nett**

1SET	BUMPER CLIP FRT	\$	na 66.00	X
1	BUMPER BRACKET CLIP FRT LH	\$	na 12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	na 10.50	X

**Trans-cab Auto Services Pte Ltd****AAD1903-163**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9868M**

1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	60.00
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	15.00
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	60.00
1	DOOR CHECK BOLT	\$	na	22.69	} X
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
1	FRONT LEFT TYRE RIM	\$	sh	380.00	} 61
1	FRONT LEFT TYRE	\$	sh	330.00	
<b>TOTAL</b>		<b>\$</b>		<b>1,329.63</b>	

**TOTAL PARTS \$ 28,943.37****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 *4000*

To apply paint protection system (PPS) maintain and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 4,200.00 *5000*

To rust-proofing of the affected areas.

\$ 170.00 *300*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

**Trans-cab Auto Services Pte Ltd**

AAD1903-163

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9868M

To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
To lift-up engine with gear box and refit.	\$	~ 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	~ 440.00 X
To remove and refit air bag system and reset.	\$	~ 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	~ 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	~ 380.00 X
To replace, refix and top up coolant for radiator	\$	~ 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00 X

**TOTAL \$ 13,280.00****Over All Total \$ 42,223.37****LUMP SUM(REPAIR DAY)****20 DAYS****2 1/2 day**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19005448/KVD3N2

Date: 03/04/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000199
Claimant Vehicle No :	SHD9868M	Insured Vehicle No :	SLC1679C
Date of Loss:	22/03/2019	Nature of Claim:	TP
		Claim No:	M1902054

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD9868M	Engine No:	M9R8839C001311
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC277496
Reg. Date:	09/05/2014 (Man. Year: 2014)	Odometer:	797740 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	28,943.34	4,472.14	24,471.20	84.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,280.00	950.00	12,330.00	92.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>42,223.34</b>	<b>5,422.14</b>	<b>36,801.20</b>	<b>87.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,350.00</b>		
(S\$)	42,223.34	4,350.00	37,873.34	89.70
+ GST 7.00/7.00% (S\$)	2,955.63	304.50	2,651.13	89.70
<b>Nett Amount (S\$)</b>	<b>45,178.97</b>	<b>4,654.50</b>	<b>40,524.47</b>	<b>89.70</b>

## INSPECTION

Date of Assignment:	28/03/2019	
Date Inspected:	25/03/2019	Inspected At:
		Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111
Estimated Period of Repair:	2.5 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our



*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
Parts:	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9868M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT LH	Dented/Warped	2,844.66 FL	*2,844.66 FL
2	1		*DOOR HINGE UPPER LH	Repair	261.28 FL	*- FL
3	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
4	1		*DOOR CHECK FRT LH	Serviceable	194.77 FL	*- FL
5	1		*DOOR LOCK FRT LH	Repair	908.75 FL	*- FL
6	1		*DOOR CATCH FRT LH	Serviceable	131.23 FL	*- FL
7	1		*DOOR HANDLE OUTER FRT LH	Broken	477.76 FL	*477.76 FL
8	1		*DOOR HANDLE COVER FRT LH	Missing	13.22 FL	*13.22 FL
9	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*- FL
10	1		*DOOR REGULATOR FRT LH	Repair	505.19 FL	*- FL
11	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	796.46 FL	*- FL
12	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	120.97 FL	*- FL
13	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
14	1		*DOOR GUIDE REAR LH	Serviceable	176.82 FL	*- FL
15	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
16	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
17	1		*DOOR CHECK REAR LH	Serviceable	203.06 FL	*- FL
18	1		*DOOR LOCK REAR LH	Repair	908.75 FL	*- FL
19	1		*DOOR HANDLE OUTER REAR LH	Serviceable	126.49 FL	*- FL
20	1		*DOOR HANDLE CAP REAR LH	Serviceable	35.52 FL	*- FL
21	1		*DOOR HANDLE SEAL REAR LH	Serviceable	7.89 FL	*- FL
22	1		*DOOR HANDLE COVER REAR LH	Serviceable	13.22 FL	*- FL
23	1		*DOOR HANDLE MODULE REAR LH	Serviceable	133.60 FL	*- FL
24	1		*DOOR REGULATOR REAR LH	Serviceable	1,135.10 FL	*- FL
25	1		*DOOR REGULATOR MOTOR REAR LH	Serviceable	893.75 FL	*- FL
26	1		*DOOR REGULATOR NT REAR LH	Serviceable	12.43 FL	*- FL
27	1		*DOOR REGULATOR MOTOR SCREW REAR L70Y	Serviceable	6.31 FL	*- FL
28	1		*DOOR FINISHER REAR LH	Serviceable	423.10 FL	*- FL
29	1		*DOOR MOULDING REAR LH	Serviceable	176.82 FL	*- FL
30	1		*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*- FL
31	1		*DOOR MOULDING SCREW L70Y	Not Necessary	6.91 FL	*- FL
32	1		*DOOR CASING REAR LH	Serviceable	1,509.06 FL	*- FL
33	1		*DOOR WATER SHIELD REAR LH	Serviceable	30.39 FL	*- FL
34	1		*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
35	1		*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*- FL
36	1		*DOOR FINISHER INNER REAR LH	Serviceable	323.44 FL	*- FL
37	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	46.97 FL	*- FL
38	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
39	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
40	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
LH						
41	1		*DOOR GRABE HANDLE REAR LH	Serviceable	210.96 FL	*- FL
42	1		*DOOR BLIND REAR LH	Serviceable	741.80 FL	*- FL
43	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	410.66 FL	*- FL
44	1		*DOOR SEAL REAR LH	Serviceable	162.02 FL	*- FL
45	1		*DOOR GLASS RUNNER SEAL REAR LH	Serviceable	229.31 FL	*- FL
46	1		*DOOR WAIST SEAL OUTER REAR LH	Serviceable	334.69 FL	*- FL
47	1		*DOOR WAIST SEAL INNER REAR LH	Serviceable	115.64 FL	*- FL
48	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
49	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
50	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
51	1		*BUMPER COVER REAR	Serviceable	1,108.46 FL	*- FL
52	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
53	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
54	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
55	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
56	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
57	1		*DOOR MIRROR ASSY LH	Cracked	1,483.40 FL	*1,483.40 FL
58	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
59	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
60	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
61	1		*ROCKER PANEL CENTER LH (DENTED)	Not Consistent With The Impact	990.25 FL	*- FL
62	1		*SET BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
63	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
64	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
65	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
66	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
67	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
68	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
69	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
70	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
71	1		*FRONT DOOR STICKER CHASSIS	Necessary	50.00 FS	*15.00 FS
72	1		*REAR DOOR STICKER 6555 3333	Necessary	80.00 FS	*60.00 FS
73	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
74	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
75	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
76	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS
77	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
78	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
79	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS
80	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS
81	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
82	1		*FRONT LEFT TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>32,011.53</b>	<b>4,954.04</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,068.19	481.90
<b>Total Parts (\$\$)</b>	<b>28,943.34</b>	<b>4,472.14</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	400.00
2	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	500.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF DYDRAULIC PNEUMATIC JACK	New	380.00	0.00
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
11	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
12	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
13	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET	New	480.00	0.00
14	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING	New	380.00	0.00
15	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
16	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
17	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
18	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>13,280.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;