

ASS. REC. BY:

REF: CS/CT119005451/AT1302

Special Instruction:

SURVIVOR: Adrian

ASSIGNMENT (Office)

From (Person): Cheng from Sun of CT

Date/Time: 26/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 6607J

Insured: SKC 951J

at Workshop m/a VISION AUTOWORK

Tel: 6341 6789 / 9856 4815 Michael

of 8 LACI BUCIT AVE 4 #08-09 PREMIER LACI BUCIT

Policy No: DMPCSN13116218055

Claim No: SNM1AD201338C02

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 26/3/19

CA / REV / REP. / REV 24 HRS IMP?

N.O.D. Endorsement:

Date/Time: 27.3.19

Person Contacted:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLP 6607J x</u>
	<u>SKC 951J x</u>
	<u>Finalise 19,0007, 14 days Cred: 22975.68: 54%</u>

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 26 March 2019 3:13 PM
To: Vision Autowork
Cc: assignments
Subject: RE: SLP6607J (Pre-inspection) / Your vehicle : SKC951J
Attachments: 26032019142427.pdf

Without prejudice

Dear Sir,

We appoint LKK.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Vision Autowork [<mailto:visionautowork@gmail.com>]

Sent: Tuesday, 26 March, 2019 3:11 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: SLP6607J (Pre-inspection) / Your vehicle : SKC951J

Dear Boon Sen,

Please arrange the below surveyor to survey the above vehicle.

ADRIAN LING

**** KINDLY ADVISE LIABILITY ****

Thank You

Yours faithfully,

*Adrian Ling Pte Ltd
my signed.*

Michelle
Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778

On Tue, Mar 26, 2019 at 2:42 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Vision Autowork [mailto:visionautowork@gmail.com]

Sent: Tuesday, 26 March, 2019 2:34 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: SLP6607J (Pre-inspection) / Your vehicle : SKC951J

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**** GIA REPORT WILL E-MAIL TO YOUR ONCE RECEIVE FROM MY CLIENT ****

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,

#08-09, Premier @ Kaki Bukit,

Singapore 415875

Tel: 6341 6789

Fax: 6341 6778

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7809B
Vehicle Particulars	
Vehicle No.:	SLP6607J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520451715
Chassis No.:	JM6BN22ABH0159111
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,108.00
Original Registration Date:	14 Jun 2017
First Registration Date:	14 Jun 2017
Transfer Count:	1
Actual ARF Paid:	\$10,108.00
Intended PARF Rebate Amount	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jun 2027
PARF Rebate Amount:	\$7,581.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$40,711.00
Total Rebate Amount:	\$48,292.00

The information contained herein is correct as at 26 Mar 2019

OK



Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?
Sell it on Marketplace. Posting an advertisement is FREE!

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad |
 Advertiser Login |
 Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A

2.88% P.A Low Interest @ Gov
 Finance 2 Years Warranty,
 \$2500 Down Monthly From \$638
 For Credit For 1st StarAd

PRIME MOTOR & LEASING

With over 200 units of vehicles
 to choose from, ranging from
 all European to Japanese Makes.

Browse by Category |
 Save Search |
 Print |
 Sort by Date Posted |
 20 results/page

13 vehicles | **Search** | [Advanced Search](#) | [Search](#) | [View All](#)

|
 |
 |
 |
 |
 |
 |
 |

Search Selection	mazda 3	Any	Any	2017	Any	Any	Any	Available
------------------	---------	-----	-----	------	-----	-----	-----	-----------



Mazda 3 1.5A \$63,000 \$7,450 /yr 12-Jan-2017 1,496 cc - Sedan Available

Warranty By Agent, Sunroof Model. Well Maintained. Flexible Loan Options Call To Arrange Viewing

[Home](#) | [18-Mar-2017](#) | [Tags](#) | [2017 Mazda 3](#) | [2017 Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Used Mazda 3](#)



Mazda 3 1.5A Sunroof \$65,000 \$7,700 /yr 12-Jan-2017 1,496 cc 32,000 km Sedan Available

Enjoy Loan Interest Rate At 2.28%. Financing Possible. Trade In Welcome. 100% Accident-Free. Well Maintained, View To Believe. Don't Miss This Elegant Beauty, Call/SMS To Arrange A Viewing Now. Viewin...

[Home](#) | [19-Mar-2017](#) | [Tags](#) | [2017 Mazda 3](#) | [2017 Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Used Mazda 3](#)



Mazda 3 1.5A Deluxe \$68,800 \$7,720 /yr 22-Feb-2017 1,496 cc - Sedan Available

Deluxe Model With Sunroof And Many Other Additional Features Compared To Basic Model! 100% Not PHV! 1 Owner! Full Service Records With Eurokars. High Trade In And In-House Financing Available! Call Fo...

[Henly Enterprises Co](#)

[Home](#) | [13-Mar-2017](#) | [Tags](#) | [2017 Mazda 3](#) | [2017 Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Used Mazda 3](#)



Mazda 3 1.5A Deluxe \$73,800 \$8,420 /yr 28-Feb-2017 1,496 cc 39,000 km Sedan Available

Latest Addition~! 1 Owner Deluxe Model With Navigation And Active Display, I-Eloop Technology Fuel Savings, Like New, Guarantee Condition, x 3 Times Free Servicing At Mazda~ In House Loan Available, C...

[Home](#) | [24-Mar-2017](#) | [Tags](#) | [2017 Mazda 3](#) | [2017 Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Used Mazda 3](#)



Mazda unveils 30th anniversary MX-5

After 30 years and more than one million units sold, Mazda has made 3,000 anniversary editions of the MX-5, exclusively offered in Racing Orange.

[Read this article](#)



Mazda 3 1.5A Sunroof \$68,888 \$7,950 /yr 17-Apr-2017 1,496 cc - Sedan Available

Facelifted Model! Low Depreciation, Popular And Spacious Sedan Vehicle. Remarkable Fuel Consumption Of 15 Km/Litre. Accident-Free, Like Brand New. Low Mileage. View To Believe. Don't Miss!

[Home](#) | [18-Mar-2017](#) | [Tags](#) | [2017 Mazda 3](#) | [2017 Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Used Mazda 3](#)



Mazda 3 1.5A \$66,966 \$7,710 /yr 21-Apr-2017 1,496 cc 16,788 km Sedan Available

Reason For Sale: See Photos In My Car Porch. Originally A Second Family Car, The First Being A MPV Where We Took Delivery A Week Ago. Tight Space Constraint In My Porch Led To Decision To Sell. The Ma...

[Home](#) | [04-Mar-2017](#) | [Tags](#) | [2017 Mazda 3](#) | [2017 Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Used Mazda 3](#)



Mazda 3 1.5A \$75,800 \$8,470 /yr 28-Apr-2017 1,496 cc - Sedan Available

As Good As New. Consignment Until Trade In Welcome! Loan And Insurance Available! Call Now For Viewing Appointment!

[Prem Roy Motoring](#)

[Home](#) | [17-Feb-2017](#) | [Tags](#) | [2017 Mazda 3](#) | [2017 Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Mazda 3](#) | [Used Mazda 3](#)

Compare

Mazda 3 1.5A \$63,555 \$7,130 /yr 07-Jun-2017 1,496 cc 17,000 km Sedan Available



Road Tax Till June 2019! Enjoy 2.28% Loan Interest! 100% Loan Available! Don't Miss It! 1 Owner Only! 100% Loan Available. Free Car SPA Polishing! Free Servicing, Free 1 Year Warranty, Highest Trade L...

Cars Inn Credit Pte Ltd

Posted: 13-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda



Mazda 3 1.5A Deluxe \$73,800 \$8,100 /yr 08-Jun-2017 1,496 cc 14,300 km Sedan Available

\$2,000 Workshop Service Credit, 3 Years Warranty By Eurocars, Fully Serviced & Maintained By Eurocars, Low Mileage, High ARF \$14,5631, Sunroof, Head Up Display, Fully Keyless, Call/SMS For Viewing

Republic Auto

Posted: 06-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda



Mazda 3 1.5A \$68,000 \$7,630 /yr 28-Jun-2017 1,496 cc 30,000 km Sedan Available

Thinkware F800 Pro Camera Included, Beautiful Midnight Blue Exterior And Black Interior. Warranty Till June 2020, Trade In Are Available. View To Believe. Viewing By Appointment Only.

360 VR Cars

Posted: 17-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda



Don't be fooled by these car insurance myths!

Is it true that my NCD will still be affected even if the accident is not my fault? Let's find out what is true and false about car insurance in Singapore.

Find out more!



Mazda 3 1.5A \$98,800 \$11,280 /yr 19-Jul-2017 1,496 cc 17,000 km Sedan Available

Year-end Clearance Sale! \$0 Down. 100% Loan Amount And 100% Accident Free. No Guarantor Needed, High Tradein, Overloan Up To \$4000. Call Now.

Posted: 20-Jan-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda



Mazda 3 1.5A \$71,800 \$7,750 /yr 09-Nov-2017 1,496 cc 16,000 km Sedan Available

High Trade In/ Loan Available 1 Owner, Original Stock Condition, Very Well Maintained, Agent Serviced With 3 Years/100,000km Warranty, Price Negotiable, Please Call Or Visit Our Showroom For Viewing N...

BKW Automobile Pte Ltd

Posted: 23-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda



Mazda 3 1.5A \$78,800 \$8,410 /yr 29-Dec-2017 1,496 cc 14,000 km Sedan Available

Spent More Than \$8k For Accessories Upgrade. Elegant Outlook, Tip Top Condition, Accident Free And Under 3 Years Warranty. List Of Items Upgraded By Owner: 17" Sport Rims With Michelin 3rd Tyres, 3m S...

SWEEP OWNER

Posted: 17-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda 3, Used Mazda

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for private import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, utility cars, luxury cars, sports cars or stationwagons, SUV, MPV, Hatchback, 1st COE cars & OPC cars. You can also buy from a car auction, look for car loans, finance services, low mileage cars, car brands, compare rates & car insurance. Find the used Mazda 3, Mazda 3 Singapore, used Mazda 3 Singapore, used Mazda 3, used Mazda 3 Singapore or even the used Mazda 3 Singapore. We have new car dealers, financing partner companies, authorized car dealers, and used car dealers on our site. Find new car price lists, new car leases and new car promotions. Visit our partner sites for car openings in Singapore, car maintenance services for sale, review, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

SHARE LISTING

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/03/2019 18:19
Date Of Accident	26/03/2019 08:20
Exact Location Of Accident	JALAN BOON LAY TOWDRDS JURONG PIER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP6607J
Insured/Policyholder	
Name Of Registered Owner	KOH HONG CHOO
NRIC No	S7217809B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84841484
Alternative Phone No	OFFICE-84841484

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-005403
Cover Note Number	

Driver

Name of Driver	KOH HONG CHOO
NRIC No	S7217809B
Date Of Birth	24/04/1972
Occupation	INDOOR
Date Of Driving Pass	16/07/1999
Driving Experience	19 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84841484
Fax Number	
Contact Number	OFFICE-84841484
EMail Address	NOEMAIL

Address	144 WESTWOOD CRESCENT
Postcode	648511
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKC951J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGK1022P
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

KOH HONG CHOO

Approximate Age

Injuries Sustain

BODY PAIN

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORTDELGRO ENGINEERING PTE LTD
320 UBI ROAD 3
SINGAPORE 408619
TEL: 6746 7556, FAX: 6743 6072



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 1

SKETCH PLAN



A = SLP6607J

B = SKC951J

C = SGK1022P

Jalan Boon Lay
towards Jurong Pier Road
(In front opp BIK 695
Bus stop: 21369)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature


Driver's Signature

COMFORTDELORO ENGINEERING PTE LTD
320 UBI ROAD 3
SINGAPORE 408649
TEL: 6746 7556 FAX: 6743 6079

Reporting Centre Personnel's Signature

On 26.03.19 at about 08:20 hours along Jalan Boon Lay towards Jurong Pier Road (In front Opp BLK 695 Bus Stop: 21369). I was travelling straight on the lane 3, when my front vehicle (C) slowed down and stopped hence I follow suit.

Suddenly I heard a loud bang from behind and the impact forced my vehicle (A) to move forward and hit onto rear portion of vehicle (C). When I alighted I realised it was vehicle (B) who hit my rear portion of my vehicle (A) causing damages to my front & rear portion of my vehicle (A). It was a chain collision of total 3 vehicles involved.

Vehicle (A): SLP 6607J

Vehicle (B): SKC 951J

Vehicle (C): SGK 1022P

AE

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLP6607J
 MODEL : MAZDA 3
 DATE OF ACCIDENT : 26.03.19
 TIME OF ACCIDENT : 08:20HRS

27	BONNET LOCK <i>Neu Neu</i>	1	\$ 183.00	\$ 183.00	x
28	BONNET LOCK BRACE PANEL <i>Neu</i>	1	\$ 67.00	\$ 67.00	+
29	FRONT SUPPORT PANEL (TOP) <i>Best</i>	1	\$ 250.00	\$ 250.00	-
30	FRONT SUPPORT PANEL TOP COVER GARNISH <i>ald</i>	1	\$ 143.00	\$ 143.00	-
31	FRONT SUPPORT PANEL LOWER GARNISH <i>Neu</i>	1	\$ 89.00	\$ 89.00	+
32	FRONT SUPPORT PANEL APRON GARNISH <i>Neu</i>	1	\$ 146.00	\$ 146.00	+
33	WIPER WASHER TANK <i>Neu</i>	1	\$ 145.00	\$ 145.00	+
34	WIPER WASHER TANK MOTOR <i>Neu</i>	1	\$ 176.00	\$ 176.00	+
35	RADIATOR <i>Neu</i>	1	\$ 1,265.00	\$ 1,265.00	x
36	RADIATOR TOP PANEL <i>Neu</i>	1	\$ 457.00	\$ 457.00	+
37	RADIATOR SUPPORT PANEL <i>embd</i>	1	\$ 798.00	\$ 798.00	-
38	RADIATOR FAN COWLING <i>Neu</i>	1	\$ 326.00	\$ 326.00	+
39	AIR CON CONDENSER SIDE GARNISH <i>embd</i>	2	\$ 47.00	\$ 94.00	-
40	AIRCON CONDENSER <i>Best</i>	1	\$ 1,345.00	\$ 1,345.00	-
41	HORN <i>Neu</i>	1	\$ 464.00	\$ 464.00	x
42	TEMPERATURE SENSOR <i>Neu</i>	1	\$ 194.00	\$ 194.00	-
43	FRONT CHASSIS MEMBER RH <i>Repair</i>	1	\$ 1,985.00	\$ 1,985.00	+
44	FRONT CHASSIS ABSOR PANEL <i>Repair</i>	2	\$ 190.00	\$ 380.00	+
45	BOOT LID <i>dent</i>	1	\$ 889.00	\$ 889.00	-
46	BOOT LID REFLECTOR <i>cut</i>	2	\$ 246.00	\$ 492.00	-
47	BOOT LID LOGO <i>Neu</i>	1	\$ 69.00	\$ 69.00	-
48	BOOT LID EMBLEM 'MAZDA 3'	1	\$ 64.00	\$ 64.00	-
49	BOOT LID EMBLEM 'SKYACTIV TECHNOLOGY' <i>Neu</i>	1	\$ 59.00	\$ 59.00	-
50	BOOT LID STOPPER (UPPER) <i>Neu Neu</i>	4	\$ 20.00	\$ 80.00	+
51	BOOT LID TOP LOCK <i>dent</i>	1	\$ 175.00	\$ 175.00	-
52	BOOT LID TOP LOCK MOTOR <i>Neu</i>	1	\$ 164.50	\$ 164.50	+
53	BOOT LID LOWER LOCK <i>Neu</i>	1	\$ 31.00	\$ 31.00	+
54	BOOT LID WEATHERSTRIP <i>cut</i>	1	\$ 165.00	\$ 165.00	-
55	BOOT LID HINGE <i>Neu</i>	2	\$ 64.00	\$ 128.00	x
56	REAR BUMPER <i>dent</i>	1	\$ 1,276.00	\$ 1,276.00	-1075
57	REAR BUMPER REFLECTOR <i>embd</i>	2	\$ 54.90	\$ 109.80	-
58	REAR BUMPER TOW HOOK COVER <i>missing</i>	2	\$ 18.00	\$ 36.00	-
59	REAR BUMPER CENTER BRACKET <i>Neu</i>	1	\$ 49.00	\$ 49.00	+
60	REAR BUMPER SIDE RETAINER <i>Neu</i>	2	\$ 34.30	\$ 68.60	-
61	REAR BUMPER LOWER BRACKET <i>Neu</i>	2	\$ 73.50	\$ 147.00	x
62	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 679.00	\$ 679.00	-538

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLP6607J
 MODEL : MAZDA 3
 DATE OF ACCIDENT : 26.03.19
 TIME OF ACCIDENT : 08:20HRS

63	TAIL LAMP <i>crushed</i>	2	\$ 1,039.00	\$ 2,078.00	✓ 10960
64	TAIL LAMP PANEL <i>Dented</i>	2	\$ 268.00	\$ 536.00	✓
65	REAR FENDER <i>Buckled</i>	2	\$ 1,769.00	\$ 3,538.00	✓ 2350
66	REAR FENDER INNER TRIM <i>new</i>	2	\$ 375.00	\$ 750.00	✓
67	REAR FENDER INNER COWLING <i>new</i>	2	\$ 160.00	\$ 320.00	✓
68	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 168.00	\$ 168.00	✓
69	REAR DOOR LOCK <i>new Drgd</i>	2	\$ 436.00	\$ 872.00	✓
70	REAR DOOR WEATHERSTRIP <i>new</i>	2	\$ 169.00	\$ 338.00	✓
71	REAR DOOR INNER TRIM <i>new</i>	2	\$ 793.00	\$ 1,586.00	✓
72	REAR END PANEL <i>Dented</i>	1	\$ 679.00	\$ 679.00	✓
73	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 210.00	\$ 210.00	✓
74	REAR FLOOR PANEL SPONGE <i>crushed</i>	2	\$ 375.00	\$ 750.00	✓ 190
75	REAR FLOOR PANEL TOP BOARD <i>parted</i>	1	\$ 498.00	\$ 498.00	✓ 185
76	REAR EXHAUST PIPE <i>2 Bent</i>	1	\$ 1,270.00	\$ 1,270.00	✓ 952.80
77	REAR EXHAUST INSULATOR <i>not completed</i>	1	\$ 178.00	\$ 178.00	✓
78	REAR EXHAUST GASKET (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	✓
79	REAR EXHAUST MOUNTING <i>new</i>	2	\$ 39.00	\$ 78.00	✓

23378.50
 18702.80

TOTAL PRICE \$ 37,919.60
 LESS 20% \$ 7,583.92
 SUB TOTAL PRICE \$ 30,335.68

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00	✓
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓ 30
3	FRONT BUMPER LOWER QUARTER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00	✓ 20
4	FRONT NUMBER PLATE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓ 10
5	FRONT BUMPER TOP SUPPORT GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	✓
6	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓
7	FRONT ENGINE UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓
8	BONNET SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	✓
9	BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓
10	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓
11	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	✓
12	FRONT SUPPORT PANEL TOP COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	✓ 10
13	FRONT SUPPORT PANEL LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓
14	FRONT SUPPORT PANEL APRON GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓
15	AIR CON CONDENSER SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓ 10

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLP6607J
 MODEL : MAZDA 3
 DATE OF ACCIDENT : 26.03.19
 TIME OF ACCIDENT : 08:20HRS

16	RADIATOR COOLANT	<i>New</i>	1	\$ 60.00	\$ 60.00	40
17	REAR NUMBER PLATE	<i>Not New</i>	1	\$ 50.00	\$ 50.00	+
18	REAR BUMPER CLIP (SET)	<i>new</i>	1	\$ 80.00	\$ 80.00	30
19	TAIL LAMP CLIP (SET)	<i>new</i>	1	\$ 30.00	\$ 30.00	+
20	TAIL LAMP PANEL INSULATION SEAL	<i>new</i>	2	\$ 40.00	\$ 80.00	+
21	BOOT LID SEALANT	<i>new</i>	1	\$ 80.00	\$ 80.00	+
22	BOOT LID INSULATOR CLIP (SET)	<i>new</i>	1	\$ 50.00	\$ 50.00	+
23	REAR FENDER SEALANT	<i>new</i>	2	\$ 150.00	\$ 300.00	+
24	REAR FENDER COWLING CLIPS (SET)	<i>new</i>	2	\$ 50.00	\$ 100.00	+
25	REAR FENDER INNER TRIM CLIPS (SET)	<i>new</i>	2	\$ 50.00	\$ 100.00	+
26	REAR WINDSCREEN SEALANT	<i>new</i>	1	\$ 80.00	\$ 80.00	40
27	REAR WINDSCREEN INNER SEAL	<i>new</i>	1	\$ 60.00	\$ 60.00	40
28	REAR DOOR INNER TRIM CLIP (SET)	<i>new</i>	1	\$ 50.00	\$ 50.00	+
29	REAR END PANEL TOP GARNISH CLIPS (SET)	<i>new</i>	1	\$ 30.00	\$ 30.00	10
30	REAR END PANEL INSULATION SEAL	<i>new</i>	1	\$ 150.00	\$ 150.00	60
31	REVERSE SENSOR	<i>new</i>	1	\$ 220.00	\$ 220.00	200
				580	TOTAL	\$ 2,280.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	500
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
5	REFOCUS HEADLAMP BEAM	\$ 60.00	x

1420

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,800.00	1600
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,500.00	1400

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLP6607J
 MODEL : MAZDA 3
 DATE OF ACCIDENT : 26.03.19
 TIME OF ACCIDENT : 08:20HRS

3	TUFF COAT	\$	250.00	100
4	WIRING CHECK	\$	80.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$	350.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	80.00	50
7	TRANSFER BOOTLID MECHANISM	\$	80.00	x
8	CONDUCT WATER LEAKAGE TEST	\$	80.00	x
9	REMOVE AND REFIX REAR EXHAUST PIPE		\$180.00	80
10	REMOVE AND REFIX REAR WINDSCREEN	\$	120.00	✓
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00	x

TOTAL \$ **9,360.00** 3460.

ESTIMATE REPORT

TOTAL PARTS COST : \$ 32,615.68
 TOTAL LABOUR COST : \$ 9,360.00
 TOTAL REPAIR COST : \$ 41,975.68

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

ABBY Auto Consultants hence notify
 SERVICE ADVISOR of the following:
 ABBY
 HP : 9856 4815

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lij total 24162.80
 h/s 26/03/19. h/s: 19.31k.
 14 days.

19.31k

Nett: 19.71k

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Mar 2019		28 Mar 2019 08:20 Edit Adj Rpt	S\$19,000.00 Edit Estimates	S\$19,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	KOH HONG CHOO , ID: S72178098								
Vehicle Reg. No.:	SLP6607J	Date of Loss:	26/03/2019 08:00 - :59 [21 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201338C02	Policy/Cover Note No.:	DMPCSN13116218055						
Vehicle Reg. No. (Insured):	SKC951J	Policy No. (Claimant):	DMPPHQ18-005403						
		Excess:	S\$0.00						
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/04/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP6607J (SNM19D201338C02)
[SKC951J]
TP
KOH HONG CHOO
Mar 26 2019 8:00AM
[-]
Vision Autowork Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)						Thumbnail	Print		
1	27/03/19 08:00	Accident Statement						Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)						Thumbnail	Print		
1	27/03/19 07:59	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
2	27/03/19 07:59	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
3	27/03/19 07:59	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
4	27/03/19 07:59	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
5	27/03/19 07:59	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
6	27/03/19 07:59	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
7	27/03/19 07:59	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
8	27/03/19 07:59	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
2	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
3	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
4	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
5	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
6	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
7	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
8	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
9	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
10	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
11	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
12	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
13	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
14	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
15	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
16	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
17	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
18	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
19	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
20	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
21	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		
22	09/04/19 15:16	General View						Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubl)		Thumbnail Print
23	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
24	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
25	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
26	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
27	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
28	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
29	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
30	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
31	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
32	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
33	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
34	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
35	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
36	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
37	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
38	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
39	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
40	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
41	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
42	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
43	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
44	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
45	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
46	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
47	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
48	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
49	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
50	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
51	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
52	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
53	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
54	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
55	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
56	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
57	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
58	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
59	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
60	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
61	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
62	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
63	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
64	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
65	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
66	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
67	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
68	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
69	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
70	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
71	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>
72	09/04/19 15:16	General View		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubl)	Thumbnail	Print
73	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
74	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
75	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
76	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
77	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
78	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
79	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
80	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
81	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
82	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
83	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
84	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
85	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
86	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
87	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
88	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
89	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
90	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
91	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
92	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
93	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
94	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
95	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
96	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
97	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
98	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
99	09/04/19 15:16	General View		<input checked="" type="checkbox"/>
100	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
101	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
102	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
103	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
104	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
105	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
106	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
107	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
108	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
109	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
110	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
111	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
112	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
113	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
114	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
115	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
116	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
117	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
118	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
119	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
120	09/04/19 15:17	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/03/19 08:21	pri contact		Load PDF
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
1	27/03/19 07:59	Sketch Plan <small>[Linked Accident Report Documents]</small>		Load TIF

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
1	27/03/19 08:00	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
1	27/03/19 07:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	27/03/19 07:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	27/03/19 07:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	27/03/19 07:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	27/03/19 07:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	27/03/19 07:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	27/03/19 07:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	27/03/19 07:59	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
1	27/03/19 07:59	Sketch Plan		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119005451/ATD3E2

Date: 03/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN13116218055
 Claimant Vehicle No: SLP6607J Insured Vehicle No: SKC951J
 Date of Loss: 26/03/2019 Nature of Claim: TP Claim No: SNM19D201338C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP6607J Engine No: P520451715
 Make & Model: MAZDA 3, 1.5 SEDAN EU6 (A) Chassis No: JM6BN22A8H0159111
 Reg. Date: 14/06/2017 (Man. Year: 2017) Odometer: 18035 km
 Colour: Black
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,615.68	19,282.80	13,332.88	40.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,360.00	4,880.00	4,480.00	47.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,975.68	24,162.80	17,812.88	42.44
Approved Total (Overridden) (S\$)		19,000.00		
	(S\$)	19,000.00	22,975.68	54.74
+ GST 7.00/7.00% (S\$)	2,938.30	1,330.00	1,608.30	54.74
Nett Amount (S\$)	44,913.98	20,330.00	24,583.98	54.74

INSPECTION

Date of Assignment: 28/03/2019
 Date Inspected: 26/03/2019 Inspected At: Vision Autowork Pte Ltd (HQ)
 8 KAKI BUKIT AVE 4, #08-09 PREMIER
 @ KAKI BUKIT
 Singapore 415875
 Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2019)
Parts: 143	MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP6607J)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,001.00 FL	*1,001.00 FL
2	1		*FRONT BUMPER (TOP)	Deformed	426.00 FL	*426.00 FL
3	2		*FRONT BUMPER LOWER QUARTER GARNISH	Missing	138.00 FL	*138.00 FL
4	2		*FRONT BUMPER FOGLAMP COVER	Cracked	148.00 FL	*148.00 FL
5	2		*FRONT BUMPER FOGLAMP HOUSING	Cracked	98.00 FL	*98.00 FL
6	1		*FRONT NUMBER PLATE GARNISH	Deformed	135.00 FL	*135.00 FL
7	1		*FRONT BUMPER TOWING COVER	Not Necessary	90.00 FL	*-FL
8	2		*FRONT BUMPER SIGNAL LAMP	Cracked	296.00 FL	*296.00 FL
9	1		*FRONT BUMPER TOP SUPPORT GARNISH	Deformed	180.00 FL	*180.00 FL
10	1		*FRONT BUMPER TOP SUPPORT GARNISH COVER	Deformed	136.00 FL	*136.00 FL
11	2		*FRONT BUMPER BRACKET	Damaged	110.00 FL	*110.00 FL
12	2		*FRONT BUMPER SIDE RETAINER	Necessary	90.00 FL	*90.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	524.70 FL	*524.70 FL
14	1		*FRONT BUMPER REINFORCEMENT COVER GARNISH	Cracked	79.00 FL	*79.00 FL
15	1		*FRONT BUMPER UNDER COVER GARNISH	Not Necessary	88.00 FL	*-FL
16	1		*FRONT ENGINE UNDER COVER GARNISH	Not Necessary	197.00 FL	*-FL
17	2		*FRONT FENDER INNER COWLING (FRONT) RH	Not Necessary	340.00 FL	*-FL
18	2		*HEADLAMP	Cracked	4,590.00 FL	*4,078.00 FL
19	2		*HEADLAMP SUPPORT BRACKET	Cracked	60.00 FL	*60.00 FL
20	1		*FRONT GRILLE	Cracked	545.00 FL	*545.00 FL
21	2		*FRONT GRILLE CHROME	Cracked	328.00 FL	*328.00 FL
22	1		*FRONT GRILLE LOGO	Necessary	49.00 FL	*49.00 FL
23	1		*BONNET	Dented	991.00 FL	*991.00 FL
24	1		*BONNET INNER RUBBER	Not Necessary	86.00 FL	*-FL
25	1		*BONNET STOPPER	Not Necessary	20.00 FL	*-FL
26	2		*BONNET HINGE	Not Necessary	76.00 FL	*-FL
27	1		*BONNET LOCK	Not Necessary	183.00 FL	*-FL
28	1		*BONNET LOCK BRACE PANEL	Not Necessary	67.00 FL	*-FL
29	1		*FRONT SUPPORT PANEL (TOP)	Bent	250.00 FL	*250.00 FL
30	1		*FRONT SUPPORT PANEL TOP COVER GARNISH	Deformed	143.00 FL	*143.00 FL
31	1		*FRONT SUPPORT PANEL LOWER GARNISH		89.00 FL	*-FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*FRONT SUPPORT PANEL APRON GARNISH	Not Necessary	146.00 FL	*- FL
33	1		*WIPER WASHER TANK	Not Necessary	145.00 FL	*- FL
34	1		*WIPER WASHER TANK MOTOR	Not Necessary	176.00 FL	*- FL
35	1		*RADIATOR	Not Necessary	1,265.00 FL	*- FL
36	1		*RADIATOR TOP PANEL	Not Necessary	457.00 FL	*- FL
37	1		*RADIATOR SUPPORT PANEL	Cracked	798.00 FL	*798.00 FL
38	1		*RADIATOR FAN COWLING	Not Necessary	326.00 FL	*- FL
39	2		*AIR CON CONDENSER SIDE GARNISH	Cracked	94.00 FL	*94.00 FL
40	1		*AIRCON CONDENSER	Bent	1,345.00 FL	*1,345.00 FL
41	1		*HORN	Not Necessary	464.00 FL	*- FL
42	1		*TEMPERATURE SENSOR	Necessary	194.00 FL	*194.00 FL
43	1		*FRONT CHASSIS MEMBER RH	Repair	1,985.00 FL	*- FL
44	2		*FRONT CHASSIS ABSOR PANEL	Repair	380.00 FL	*- FL
45	1		*BOOT LID	Dented	889.00 FL	*889.00 FL
46	2		*BOOT LID REFLECTOR	Cut	492.00 FL	*492.00 FL
47	1		*BOOT LID LOGO	Necessary	69.00 FL	*69.00 FL
48	1		*BOOT LID EMBLEM MAZDA 3	Necessary	64.00 FL	*64.00 FL
49	1		*BOOT LID EMBLEM SKYACTIV TECHNOLOGY	Necessary	59.00 FL	*59.00 FL
50	4		*BOOT LID STOPPER (UPPER)	Not Necessary	80.00 FL	*- FL
51	1		*BOOT LID TOP LOCK	Damaged	175.00 FL	*175.00 FL
52	1		*BOOT LID TOP LOCK MOTOR	Not Necessary	164.50 FL	*- FL
53	1		*BOOT LID LOWER LOCK	Not Necessary	31.00 FL	*- FL
54	1		*BOOT LID WEATHERSTRIP	Cut	165.00 FL	*165.00 FL
55	2		*BOOT LID HINGE	Not Necessary	128.00 FL	*- FL
56	1		*REAR BUMPER	Deformed	1,276.00 FL	*1,075.00 FL
57	2		*REAR BUMPER REFLECTOR	Cracked	109.80 FL	*109.80 FL
58	2		*REAR BUMPER TOW HOOK COVER	Missing	36.00 FL	*36.00 FL
59	1		*REAR BUMPER CENTER BRACKET	Not Necessary	49.00 FL	*- FL
60	2		*REAR BUMPER SIDE RETAINER	Necessary	68.60 FL	*68.60 FL
61	2		*REAR BUMPER LOWER BRACKET	Not Necessary	147.00 FL	*- FL
62	1		*REAR BUMPER REINFORCEMENT	Bent	679.00 FL	*538.00 FL
63	2		*TAIL LAMP	Cracked	2,078.00 FL	*1,019.60 FL
64	2		*TAIL LAMP PANEL	Dented	536.00 FL	*536.00 FL
65	2		*REAR FENDER	Buckled	3,538.00 FL	*2,350.00 FL
66	2		*REAR FENDER INNER TRIM	Not Necessary	750.00 FL	*- FL
67	2		*REAR FENDER INNER COWLING	Not Necessary	320.00 FL	*- FL
68	1		*REAR WINDSCREEN MOULDING	Necessary	168.00 FL	*168.00 FL
69	2		*REAR DOOR LOCK	Damaged	872.00 FL	*872.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
70	2		*REAR DOOR WEATHERSTRIP	Not Necessary	338.00 FL	*-FL
71	2		*REAR DOOR INNER TRIM	Not Necessary	1,586.00 FL	*-FL
72	1		*REAR END PANEL	Dented	679.00 FL	*679.00 FL
73	1		*REAR END PANEL TOP GARNISH	Deformed	210.00 FL	*210.00 FL
74	2		*REAR FLOOR PANEL SPONGE	Cracked	750.00 FL	*190.00 FL
75	1		*REAR FLOOR PANEL TOP BOARD	Deformed	498.00 FL	*185.00 FL
76	1		*REAR EXHAUST PIPE	Bent	1,270.00 FL	*953.80 FL
77	1		*REAR EXHAUST INSULATOR	Crumpled	178.00 FL	*178.00 FL
78	1		*SET REAR EXHAUST GASKET	Necessary	60.00 FL	*60.00 FL
79	2		*REAR EXHAUST MOUNTING	Not Necessary	78.00 FL	*-FL
80	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
81	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
82	1		*SET FRONT BUMPER LOWER QUARTER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
83	1		*SET FRONT NUMBER PLATE GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
84	1		*SET FRONT BUMPER TOP SUPPORT GARNISH CLIP	Not Necessary	30.00 FS	*-FS
85	1		*SET FRONT BUMPER UNDER COVER GARNISH CLIP	Not Necessary	50.00 FS	*-FS
86	1		*BONNET SEALANT	Not Necessary	120.00 FS	*-FS
87	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*-FS
88	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*-FS
89	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FS	*30.00 FS
90	1		*SET FRONT SUPPORT PANEL TOP COVER GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
91	1		*SET FRONT SUPPORT PANEL LOWER GARNISH CLIP	Not Necessary	50.00 FS	*-FS
92	1		*SET FRONT SUPPORT PANEL APRON GARNISH CLIP	Not Necessary	50.00 FS	*-FS
93	1		*SET AIR CON CONDENSER SIDE GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
94	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
95	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*-FS
96	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
97	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*-FS
98	2		*TAIL LAMP PANEL INSULATION SEAL	Not Necessary	80.00 FS	*-FS
99	1		*BOOT LID SEALANT	Not Necessary	80.00 FS	*-FS
100	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	50.00 FS	*-FS
101	2		*REAR FENDER SEALANT	Not Necessary	300.00 FS	*-FS
102	2		*SET REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*-FS
103	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*-FS
104	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
105	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
106	1		*SET REAR DOOR INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
107	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
108	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
109	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
110	1		*SET FRONT ENGINE UNDER COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	40,199.60	23,958.50
- List Item Discount on L Items 20.00/20.00% (S\$)	7,583.92	4,675.70
Total Parts (S\$)	32,615.68	19,282.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	500.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
5	REFOCUS HEADLAMP BEAM	New	60.00	0.00
6	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	2,800.00	1,600.00
7	TO SPRAY PAINT AFFECTED AREA	New	2,500.00	1,400.00
8	TUFF COAT	New	250.00	100.00
9	WIRING CHECK	New	80.00	30.00
10	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	350.00	80.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
12	TRANSFER BOOTLID MECHANISM	New	80.00	0.00
13	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
14	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	80.00
15	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			9,360.00	4,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >