

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Jimmy Goh KI
CLAIM DEPARTMENT
DID : 66547618
FAX :

Date : 26/03/2019

To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTHCVE000153

Accident Date : 13/03/2019

Vehicle No : GBH-4233-C

Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (M

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	FRONT BUMPER	645.10	Dis 852.90	✓
1	FRONT BUMPER BRACKET (RH)	165.50	Ref 193.80	✓
1	FRONT BUMPER BRACKET LH		117 193.80	X
1	FRONT BUMPER REINFORCEMENT		1 237.50	X
1	FOG LAMP COVER RH		11 141.50	X
1	HEADLAMP (RH)		520 1,147.10	✓
1	HEADLAMP (LH)		11 1,147.10	X
1	FRONT GRILLE		one 676.50	✓
10	FRONT GRILLE CLIPS		111 45.00	✓

Date : 26/03/2019

To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTHCVE000153

Accident Date : 13/03/2019

Vehicle No : GBH-4233-C

Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (M

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT GRILLE LOGO 66.50	1100 107.20	2
1	FRONT PANEL RESTORE	1100 92.90	X
1	FRONT PANEL EMBLEM "DYNA"	1100 356.30	
1	FRONT CORNER PANEL (RH)	1100 356.30	
1	FRONT DOOR PILLAR (R/H) RESTORE	1100 1,894.20	X
1	FRONT DOOR (RH) 1605.30	1100 1,894.20	
1	FRONT DOOR UPPER HINGE RH	1100 135.80	X
1	FRONT DOOR LOWER HINGE RH	1100 135.80	
1	FRONT DOOR WEATHER STRIP R/H 188.20	1100 243.80	
1	STEP GARNISH R/H 241.50	1100 361.30	

Date : 26/03/2019
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D18MTHCVE000153 Accident Date : 13/03/2019
Vehicle No : GBH-4233-C Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (M

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	7962.50	
	Discount 25% On Parts	(1990.63)	
	<u>Special Nett Item</u>		
1	LTA DOOR STICKER	20.00	✓
1	FRONT NUMBER PLATE	30.00	20
1	TOWING FEE	50.00	✓
	Sub Total	100.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,050.00	600
	TO REMOVE & INSTALL RHF DOOR COMPONENTS	100.00	60

P-53657
402427
5674.27
4839

Date : 26/03/2019
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D18MTHCVE000153 Accident Date : 13/03/2019
Vehicle No : GBH-4233-C Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO RUST PROOF AFFECTED AREA	80.00	30
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	20
	TO SPRAY PAINT ON AFFECTED AREAS	1,250.00	850
	Sub Total	2530.00	

Remarks:

not attach

2/5 # 4500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to prior approval from Insurance Company

8,601.88

Acknowledged by Repairer
Signature:

SUB TOTAL Date:

GST 7.0 % 602.13

TOTAL 9,204.01

Surveyor's name: Marcus Wai

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 27/3/19 @ 11am.

Take photo before repair, 4h