

ASS. REC. BY:

REF: CS/FCI/9005460/Ktd3

Special Instruction:

Surveyor: KalvinASSIGNMENT (Office)From (Person): Joanne Yong of FCI Date/Time: 27/3/19

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1551D Insured: SHA 7627 Xat Workshop m/s: PREMIER Tel: 6214 8880of 23 CHAN YAT SOUTH AVE 2 #01-02Policy No: _____ Claim No: D190 2055 MPST

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24/3/19
(Client's Record)CA / REV / REP. / REV 24 HRS (WP) H.O.D. Endorsement: _____Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SHD 1551D X
	SHA 7627 X CS/FCI/8018418/UTd302 DOB: 06/10/18
28/3-	Revised preliminary advice. NS/NC/8007464/Ktd302 DOA: 31/4/18

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD15510 Yr Regn: 4 Oct 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Truck~~ / Prime Mover /

Truck / Trailer or

Make: Hyundai 2.0 cc 1582

Colour: Silver A/C: Insured / Std / Nil / NA

Sp. Reading: 229/93 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: TM AD 28/4 VHJ14183

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 24/3/19 D.O.I. 27/3/19

Survey held at Premises

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

O/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
9/4/19	the 1118 680/267, Cred. 1454.65; 69% FRZ.
	check with Denise RECEIVED 09 APR 2019
	d.o.a is 24/3/2019.

Date/Time, File Pass to? ☐ : Prel. Report

11/4/19 Typist ☒ : Final Report

Date/Time, File Return to?

Q)

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

110
50
50
20
230

Report Format:

TP

Lump Sum / (E) \$ 640



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002055MFSH

Date: 28/3/2019

Our Ref: CS/FCI19005460/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1551D

Please be informed that we had conducted the inspection of the abovementioned vehicle 27/3/2019 at the premises of M/s Premier have the following to report: -

Workshop Estimate Amount	: S\$	<u>2,094.65</u>
Revised Estimate Amount	: S\$	<u>640.00</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-03-2019	Our Ref No. D19002055MFSH
Accident Date	24-03-2019	Claim Type. Third Party
Insured Vehicle	SHA7627X	Third Party Vehicle. SHD1551D
Survey Location	23 CHANGI SOUTH AVENUE 2 #1-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 0	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Celine Fong (LKKAUTO)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 27 March 2019 9:28 AM
To: assignments
Cc: CWS Motor Claims; Joanne Yong Lai fong
Subject: PRI: SURVEY ASSESSMENT - D19002055MFSH/1
Attachments: Jobsheet_D19002055MFSH_TPD1.pdf

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 28 March 2019 3:48 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; assignments
Subject: RE: SURVEY ASSESSMENT - D19002055MFSH/1
Attachments: PRELI ADVISED SHD 1551D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 1551D**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 27 March 2019 9:28 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002055MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1551D
 Previous Vehicle No.: -
 Effective Date of Ownership: 04 Oct 2017
 Original Regn Date: 04 Oct 2017
 Registration Date: 04 Oct 2017
 Year of Manufacture: 2017
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ141813
 Engine No.: D4FBHZ172577
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$19,970.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 03 Oct 2025
 Minimum PARF Benefit: \$7,482.00
 No. of Transfers: 0
 IU Label No.: 1050709808
 COE No.: 2017100401003674M
 COE Expiry Date: 03 Oct 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$42,564.00
 PQP Paid: \$34,052.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

25-Mar-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1551 D

1 pc	Rear bumper <i>X repair</i>	\$	811.11
1 pc	Rear bumper o/s side bracket <i>X sc</i>	\$	52.20
1 pc	Rear bumper o/s reflector <i>X sc</i>	\$	107.50
	<i>Rear o/s fender X repair</i>	\$	970.81
	Less 20%	\$	194.16
		\$	776.65

S/NETT

1 set	Rear bumper clips <i>X 2</i>	\$	48.00
1 pc	Rear o/s fender sticker <i>1</i>	\$	60.00
	Sundry	\$	50.00 <i>20 net</i>
	To dismantle and refit reverse sensor to new bumper	\$	80.00 <i>X 2</i>
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s fender etc	\$	600.00 <i>200</i>
	To putty and spray painting on the rear bumper, rear o/s fender	\$	400.00 <i>360</i>
	To apply rustproofing on the repaired and replaced panels	\$	80.00 <i>X 2</i>
	Total	\$	2,094.65

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalin 10/04

27/3/19
10:5h

*2 days.
PIP*

Adha Repair p.ltd.

*...on a 'no-fault' basis
...is subject to final approval from Insurance Company*
Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19005460/K1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7627X	Veh. Inspected	SHD 1551D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002055MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	27/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ141813	Colour	SILVER	
Odometer	229193	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	6 mm	
L/H Front Tyre	195/65 R15	MAXXIS	6 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/03/2019	Inspection Date	27/03/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1551D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	811.11	-
1	REAR BUMPER O/S SIDE BRACKET	SERVICEABLE	52.20	-
1	REAR BUMPER O/S REFLECTOR	SERVICEABLE	107.50	-
1	REAR O/S FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-194.16	-
			776.65	-
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			158.00	80.00
	<u>LABOUR</u>			
	TO DISMANTLE AND REFIT REVERSE SENSOR TO NEW BUMPER.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE OF THE REAR O/S FENDER ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	200.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER,REAR O/S FENDER.		400.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	-
			1,160.00	560.00
	GRAND TOTAL		2,094.65	640.00
RECOMMENDED COST OF REPAIRS				640.00

Report Ref No. CS/FCI19005460/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.