

Kd
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKQ3787Z
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 25/03/2019

TP Veh Reg No: SLC4191Y

Estimate No: ES1991313/WS

Date: 26 Mar 2019

Policy No: D18MTPV01006968

Veh Reg No: **SKQ3787Z**

Make/Model: AUDI A6 2.0T FSI MU

Chassis No: WAUZZZ8K0CA021496

Engine No: CDH142046

Reg. Date: 29/09/2011

Estimate Repair Cost to Vehicle No :SKQ3787Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	1,298.09	1 PC	<i>Bu</i> 1,298.09	✓
2 REAR BUMPER REINFORCEMENT	454.54	1 PC	<i>Bu</i> 454.54	✓
3 REAR BUMPER REINFORCEMENT BRACKETS	169.44	2 PCS	<i>Bu</i> 338.88	✓
4 REAR BUMPER RH SIDE RETAINER	47.10	1 PC	<i>Bu</i> 47.10	✓
5 REAR BUMPER LOWER GRILLE	<i>Dis/100%</i> 467.45	1 PC	467.45	✓
6 REAR BOOT	1,640.37	1 PC	<i>Bu</i> 1,640.37	✓
7 REAR BOOT LOGO	107.77	1 PC	<i>Bu</i> 107.77	✓
8 REAR BOOT EMBLEM (A 4)	71.22	1 PC	<i>Bu</i> 71.22	✓
9 REAR BOOT EMBLEM (1.8 T)	73.84	1 PC	<i>Bu</i> 73.84	✓
10 REAR BOOT INNER RUBBER	<i>80.435m</i> 160.87	1 PC	<i>Bu</i> 160.87	✓ <i>508m</i>
11 REAR BOOT REFLECTOR	212.76	1 PC	<i>Bu</i> 212.76	✓
12 REAR CENTRE PANEL	645.65	1 PC	<i>Bu</i> 645.65	✓
13 REVERSE SENSORS (CENTRE)	174.66	2 PCS	<i>Shut</i> 349.32	✓
14 REAR RH FENDER INNER SHIELD	129.10	1 PC	<i>cm</i> 129.10	✓
15 REAR RH FENDER AIR SCROP GRILLE	58.60	1 PC	<i>cm</i> 58.60	✓
16 RH TAILLAMP LOWER RETAINER	33.80	1 PC	<i>cm</i> 33.80	✓
			6,089.36	
		Less 5%	304.47	5,784.89
Labour				
17 PANEL BEATING	900.00	1 LA	900.00	✓ <i>750</i>
18 PUTTY & RESPRAY PAINTING	800.00	1 LA	800.00	✓ <i>700</i>
19 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,760.00	1,760.00

Total S\$ 7,544.89

Add GST @ 7% 528.14

Total Amount Payable S\$ 8,073.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

CoR -
Retn - 8x120-960
78-8