

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19005464/KGA3Q2

Date: 11/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SME7852G	Insured Vehicle No :	SH6383M
Date of Loss: 21/03/2019	Nature of Claim: TP	Claim No: MCT19030554

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME7852G		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB6740416
Reg. Date:	17/10/2018 (Man. Year: 2018)	Chassis No:	RU31320405
Colour:	Metallic Dark Blue	Odometer:	45356 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,411.36	561.60	849.76	60.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	1,130.00	330.00	22.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,871.36	1,691.60	1,179.76	41.09
+ GST 7.00/7.00% (S\$)	201.00	118.41	82.59	41.09
Nett Amount (S\$)	3,072.36	1,810.01	1,262.35	41.09
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	26/03/2019	
Date Inspected:	26/03/2019	Inspected At: Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME7852G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	987.20 FL	*- FL
2	1		*FRONT BUMPER SIDE BRACKET LH	Distorted	25.30 FL	*25.30 FL
3	1		*FRONT FENDER LH	Buckled	498.00 FL	*498.00 FL
4	1		*FRONT FENDER EMBLEM HYBRID	Necessary	58.70 FL	*58.70 FL
5	1		*FRONT ALLOY RIM	Dented	120.00 FL	*120.00 FL
6	1		*FRONT FENDER ARCH GARNISH LH (NPA)	Repair	0.00 FL	*- FL
7	1		*FRONT BONNET (NPA)	Repair	0.00 FL	*- FL
8	1		*SET FRONT BUMPER CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,749.20	702.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	337.84	140.40
Total Parts (\$\$)	1,411.36	561.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES REMOVE & KNOCKING /REPLACE FRONT ACCIDENT AREA & ETC	New	600.00	400.00
2	LABOUR CHARGES FOR PAINTING & SUPPLY PAINTS & FURNISHING MATERIAL	New	800.00	700.00
3	TO TUFF KOTE /ANTI-RUST	New	60.00	30.00
Gross Labour Cost (\$\$)			1,460.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >