

Date: 26.03.2019

Vehicle No: SME7852G

Model: HONDA VEZEL HYBRID 1.5X

Chassis: RU31320405 - 2018

Reg.Year: 2018

Third Party Insurer:

INDIA INTERNATIONAL
INSURANCE PTE LTD

Third Party Veh No:

SH6383M

Date of Accident:

21.03.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		\$987.20
2	FRONT BUMPER SIDE BRACKET LH	1		DIY \$25.30
3	FRONT FENDER LH	1		R \$498.00
4	FRONT FENDER EMBLEM 'HYBRID'	1		RM \$58.70
5	FRONT ALLOY RIM --- REPAIR	1		R R \$120.00
6	FRONT FENDER ARCH GARNISH LH	1		REPAIR
7	FRONT BONNET	1		REPAIR
SUB TOTAL				\$1,689.20
LESS 20%				-\$337.84
PARTS TOTAL				\$1,351.36

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1 SET		R \$60.00
S/N TOTAL				\$60.00

LABOUR CHARGES:

LABOUR CHARGES REMOVE & KNOCING/REPLACE FRONT ACCIDENT AREA & ETC

4000 \$600.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINTS & FURNISHING MATERIAL

7000 \$800.00

TO TUFF KOTE / ANTI-RUST

\$60.00

LABOUR TOTAL \$1,460.00

PEI TING TOTAL \$2,871.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 8868 | Fax: (+65) 6452 9223

