

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05948

Vehicle Insured : SLH6733U

Accident Date : 21-Mar-2019

Date : 25-Mar-2019

Our Ref : 219049 (AIG) / CHAN

PAGE : 1

LEE BOON KWONG

BLK 521 HOUGANG AVE 6

#01-53

Singapore 530521

*Not Authored  
1 Day @ ?  
Recovery After Part*

*5 days*

## ESTIMATED COST OF REPAIR FOR TOYOTA WISH SGQ3254S

- 1 pc Tail gate
- 1 pc Tail gate glass moulding
- 1 pc Tail gate inner lock
- 1 pc Tail gate rubber
- 1 pc Rear bumper fascia
- 2 pcs Rear bumper bracket
- 2 pcs Rear bumper reflector
- 2 pcs Rear bumper side retainer-L
- 1 pc Rear bumper side retainer-S
- 1 pc O/s taillamp
- 1 pc Rear end panel -top
- 1 pc Rear end panel -lower
- 1 pc End panel top garnish

|             |          |            |
|-------------|----------|------------|
|             | 1,210.40 | ✓          |
|             | 80.40    | ✓          |
|             | 443.50   |            |
|             | 304.10   | <i>50%</i> |
|             | 491.90   | ✓          |
| @ S\$ 48.50 | 97.00    | ?          |
| @ S\$ 54.10 | 108.20   | X          |
| @ S\$ 57.10 | 114.20   | ✓          |
|             | 20.10    | ✓          |
|             | 472.60   | ?          |
|             | 441.20   | ?          |
|             | 199.50   | ?          |
|             | 232.90   | ✓          |
|             | 4,216.00 |            |
| Less 25% :  | 1,054.00 |            |

- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper reverse sensor(set
- 1 pc Rear no. plate with box

|  |          |    |
|--|----------|----|
|  | 3,162.00 |    |
|  | 60.00    | sn |
|  | 300.00   | sn |
|  | 50.00    | sn |

To remove & refix rear windscreen glass and conduct water leak test.

*120h*  
150.00

To remove roof lining, front and rear seats, trim board and carpet

*60h*  
120.00

LKK Auto Consultants hence notify the Reparer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
Acknowledged by Reparer  
Signature:  
Date:

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH6733U

Page : 2

To apply undersealing

✓  
60.00

To putty and spray replaced parts

900.00 720/-

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

600/-  
800.00

Total : S\$ 5,602.00

=====

Singapore Dollars Five Thousand Six Hundred and  
Two Only