

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05948

Vehicle Insured : SLH6733U

Accident Date : 21-Mar-2019

Date : 25-Mar-2019

Our Ref : 219049 (AIG) / CHAN

PAGE : 1

LEE BOON KWONG

BLK 521 HOUGANG AVE 6

#01-53

Singapore 530521

*Not Notified  
61 Days @ 4200h  
Penalty After 30 days*

## ESTIMATED COST OF REPAIR FOR TOYOTA WISH SGQ3254S

- 1 pc Tail gate
- 1 pc Tail gate glass moulding
- 1 pc Tail gate inner lock
- 1 pc Tail gate rubber
- 1 pc Rear bumper fascia
- 2 pcs Rear bumper bracket
- 2 pcs Rear bumper reflector
- 2 pcs Rear bumper side retainer-L
- 1 pc Rear bumper side retainer-S
- 1 pc O/s taillamp
- 1 pc Rear end panel -top
- 1 pc Rear end panel -lower
- 1 pc End panel top garnish

|             |             |            |
|-------------|-------------|------------|
| B           | 1,210.40    | ✓          |
| m           | 80.40       | ✓          |
|             | 443.50      | ✓          |
| m           | 304.10      | 50% 152.05 |
| R           | 491.90      | ✓          |
| @ S\$ 48.50 | R 97.00     | ✓ X        |
| @ S\$ 54.10 | sn 108.20   | ✓ X        |
| @ S\$ 57.10 | also 114.20 | ✓          |
|             | D.V 20.10   | ✓          |
| m           | 472.60      | ✓          |
| R           | 441.20      | ✓          |
| R           | 199.50      | ✓          |
| B           | 232.90      | ✓          |
|             | 4,216.00    | 3649.60    |
| Less 25% :  | 1,054.00    | 912.40     |
|             |             | 2737.20    |

- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper reverse sensor(set
- 1 pc Rear no. plate with box

|      |          |    |
|------|----------|----|
| m    | 3,162.00 |    |
| sn   | 60.00    | sn |
| 2000 | 300.00   | sn |
| 650  | 50.00    | sn |

To remove & refix rear windscreen glass and conduct water leak test.

120h  
150.00

To remove roof lining, front and rear seats, trim board and carpet

60h  
120.00

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH6733U

Page : 2

To apply undersealing

60.00

To putty and spray replaced parts

900.00 *7201*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

*6001*  
800.00

Total : S\$ 5,602.00

Singapore Dollars Five Thousand Six Hundred and  
Two Only

*L/SUM*  
*4400*  
*Kenward PUS*  
*Company*  
*7/28*

*P 2737.20*  
*S.P 785.70*  
*SN 437.05*  
*L 1560.00*  

---

*5519.95*  
*1103.99*  

---

*2415.96*

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH6733U (AIG)

Accident Date : 21-03-2019

Date : 28-03-2019

Our Ref : 219049 /CHAN

LEE BOON KWONG

C/O ALAN'S UNITED AUTO PTE LTD

## SUPPLEMENTARY ITEM PRICE FOR TOYOTA WISH SGQ3254S

1 PC REAR O/S FENDER INNER TRIM

*cm* \$697.40 ✓

1 PC REAR FLOOR PANEL COVER TOP GARNISH

*sc* \$350.20 X

\$1,047.60

LESS 25% \$261.90

\$785.70

Singapore Dollars Seven Hundred Eighty Five And Cents Seventy Only