

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5984L**AAD1903-176***Not Authorised**Resony Bepain**8 H4.45*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5984L

JTDKB3FU903077270

TOYOTA

PRIUS

24.3.2019

AIG

4/12/2018

PART**LIST**

1	1 REAR BUMPER	\$	<i>11</i>	458.60	<i>X</i>
2	1 REAR BUMPER RE-INFORCEMENT	\$	<i>11</i>	318.80	<i>✓</i>
3	1 REAR BUMPER TOWING COVER	\$	<i>12</i>	14.70	<i>X</i>
4	1 REAR BUMPER UNDER COVER (BLACK)	<i>Net \$ / 12</i>	<i>12</i>	552.60	<i>✓</i>
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>12</i>	112.70	<i>X</i>
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>12</i>	112.70	
7	1 REAR TAILGATE	\$	<i>11</i>	1,547.27	
8	1 REAR TAILGATE OUTER GARNISH	\$	<i>12</i>	905.10	
9	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>12</i>	54.70	
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>12</i>	54.70	
11	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>12</i>	93.60	
12	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>12</i>	93.60	
13	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>12</i>	254.40	
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>12</i>	51.20	
15	1 REAR TAILGATE WEATHERSTRIP	\$	<i>12</i>	365.20	
16	1 REAR END PANEL	\$	<i>11</i>	602.10	
17	1 TAILLAMP LOWER RH	\$	<i>12</i>	548.40	
18	1 TAILLAMP UPPER RH	\$	<i>12</i>	557.90	
19	1 REAR BUMPER SIDE RH	\$	<i>12</i>	232.00	
20	1 REAR BUMPER SIDE LH	\$	<i>12</i>	232.00	
21	1 TAILLAMP LOWER LH	\$	<i>12</i>	548.40	
22	1 TAILLAMP UPPER LH	\$	<i>12</i>	557.90	
		\$		8,268.57	
		25% \$		2,067.14	
		\$		6,201.43	

Specical Nett

1 1SET PARKING AID

\$ *12* 700.00 *X*

Trans-cab Auto Services Pte Ltd**AAD1903-176**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5984L

2 1SET REAR BUMPER CLIP	\$	na	22.00	}	X
3 2 REAR WINDSCREEN SELANT	\$	na	80.00		
4 1 WINDSCREEN MOULDING	\$	na	100.00		
5 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
6 1 REAR TAILGATE TOYOTA LOGO	\$	na	47.00		
7 1 REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90		
8 1 REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50		
9 1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00		
10 1 REAR TAILGATE STICKER '6555-3333'	\$	na	80.00		
11 1 REAR BUMPER PROTECTOR	\$	na	100.00		

TOTAL \$ 1,315.40**TOTAL PARTS \$ 7,516.83****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	22cl
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	15cl
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X
To reinstall rear bumper parking sensor.	\$	↪	170.00 X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	↪	170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	↪	170.00 X
To repair and realign rear exhaust pipe.	\$	↪	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	↪	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1903-176**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5984L

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *na* 170.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ *na* 170.00 X

To check steering geometry and computer wheel alignment

\$ *na* 220.00 X**TOTAL \$ 7,580.00****Over All Total \$ 21,298.26****(PART-BY-PART) Repair Days**~~10 DAYS~~*1 1/2 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: