

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5662X

AAD1903-188

Not Authored

U/Sing @ 1850/hr

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHC 5662X
 VF1ABL15AUC281236
 RENAULT
 LATITUDE
 24.3.2019
AXA
 23/1/2015

PART

LIST

1	1 BUMPER COVER REAR	\$	<i>Bulnet</i> 1,108.46	—
2	1 BUMPER LOWER REAR	\$	<i>Ad/ln</i> 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	<i>ln</i> 113.47	} X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>ln</i> 135.97	
5	1 BUMPR RETAINER RH REAR	\$	<i>ln</i> 44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>ln</i> 43.61	
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>ln</i> 135.97	
8	1 BUMPER RETAINER LH REAR	\$	<i>ln</i> 44.99	
9	1 BUMPER REFLECTOR LH	\$	<i>ln</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>n</i> 777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>n</i> 1,471.77	
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>ln</i> 404.56	
15	1 BOOT REAR	\$	<i>n</i> 2,872.68	
16	1 TAILLAMP RH	\$	<i>ln</i> 552.55	
17	1 TAILLAMP PANEL RH	\$	<i>n</i> 986.70	
18	1 TAILLAMP LH	\$	<i>ln</i> 552.55	
19	1 TAILLAMP PANEL LH	\$	<i>n</i> 986.70	

\$ **11,496.85**

10% \$ **1,149.69**

\$ **10,347.17**

Special Nett

1	1SET PARKING AID	\$	<i>ln</i> 700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>n</i> 66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>n</i> 33.00	—

Trans-cab Auto Services Pte Ltd

AAD1903-188

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5662X

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	<i>na</i> 17.82 X
11	2 REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00 X
12	1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00 X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00 X
14	1 REAR BOOT STICKER 'Trans-cab'	\$	<i>na</i> 80.00 X
15	1 REAR BOOT STICKER '6555-3333'	\$	<i>na</i> 80.00 X
TOTAL		\$	605.82
TOTAL PARTS		\$	10,952.99

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 <i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1903-188

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5662X

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *na* 170.00 X

To check steering geometry and computer wheel
alignment

\$ *na* 220.00 X**TOTAL \$ 7,410.00****Over All Total \$ 28,710.15****(LUMP SUM)****Repair Days***10 DAYS**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: