

000000

INS. CASE OWNER

NONAME

CC 4 AGM AXA1900 5473

LKK IDAC

Surveyor

Mr Lim

DOI

ASSIGNMENT 23/06/19

Date / Time

24/7/19

Registered in Merimen

Pre-assign / CCU / FTE



Insured Vehicle No. : 547343H

Name of Insured : YN KHEW EAT

Insured Tel No. : _____ HP: _____

Excess Sec II : \$\$ _____ D.O.A. : 26/7/19

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : WD SUE HUANG

Driver Tel No. : _____ (V/L: YES / NO)

Claim No. :

59M0175/106529

Policy No. :

6420801

Make / Model :

MERCEDES

Place of Accident :

AME ME 5

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

59M4983K



INSRS: WSP: Tel: Liability: RMKS:

antowork



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time

23/6/19

*Gmmt/Aim

O/WB

23/6 - call OI, aware of TP claim, agreed to settle & aware NCD issue. Send LOD

26/6/19 - TP LOD IN BY EMAIL JPLOHD MANAGER IT IN OC

27/6/19 - AXA APPROVED WARRANT SEND GET OFFER TO TP.

10/7/19 - TP ACCEPTED OFFER. ALL DONE IN ORDER TO CLOSE.

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI

CPL 23/6/19

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

PRELIMINARY ADVICE

Date/Time

Sent By

FINALIZATION

Date/Time

Confirm with

Confirm by

Repair Cost

\$S

(days) Reduction

%

Email

Call

FINAL SETTLEMENT

Date/Time

Confirm with

Email

Call

Final Liability

%

100

(Agreed / Assessed) BOLA S/N No. : 15

Repair Cost

\$S

3,920.00

Loss of Rental (LOR) (After)

\$S

642.00

(6 days) X \$100.00

Loss of Use (LOU)

\$S

-

(5 days)

Loss of Income (LOI)

\$S

-

(5 days)

LOR only ☒ LOU only ☐

\$S

LOR + LOU

LOR + LOU

[Tick only one]

GIA/TA Search

\$S

2.00

Medical

\$S

-

Disbursement

\$S

-

Legal Cost

\$S

-

(e.g. Tow/Independent)

1) Claim status: Norm/Reject/Private Settle

2) Report Format

3) Survey fee

\$350.00

Total

\$S

4,594.00

Global Sum \$S

4,590.00

FINAL PAYMENT

Date/Time

Confirm with

Email

Call

Payee 1

\$S

4,590.00

Name 1

AUTOWORK HOUSE

Payee 2 (Strike if N.A.)

\$S

-

Name 2

-

Payee 3 (Strike if N.A.)

\$S

-

Name 3

-

COPY SENT 11/7/19

REF: ASM(AxA)

P

ASSIGNMENT

From:

Date:

28/03/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGM 4983K

at Workshop m/s

Autoworx House

of

176 Sin Ming Drive # 02-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGM 4983K

Yr Regn:

20/10/2006

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Latio 1.5

C.C 1498

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

146240

T/Radio: Insured / Std / NI / NA

Eng/No:

HR15019182A

C/No:

JN1BAAC11Z0002131

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order

/ Jammed / Leaked / Burnt or

Brake: ☒ In order

/ Jammed / Leaked / Burnt or

Modi:

Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 185/65/15

R: 185/65/15

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A

D.O.I

28/3/19

Survey held at

Autoworx House

Des. of Damages: Fnt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 6000/2 - 8000/2

LH 43,950.00

(RUB: 45,639.91/59%)

HS 3950/2 Term lim 22/11/19

MV 19,000/2

PV 13,279/2

NV 5,721/2

Term lim 1/4/19

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / L.B.I: (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

AUGUSTINE SIEW HUANG YEOW

c/o 46 Lentor Plain
Singapore 786548

Date : 28/3/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: NISSAN LATIO / SGM 4983 K	
1 pc	front bumper <i>DDV</i> ✓	675.00 836.00
1 pc	front bumper side retainer DDV <i>NEC</i> ✓	✓ 32.10
1 pc	front fender <i>DDV</i> ✓	✓ 727.20
	<i>1434.30</i> sub-total	1,595.30
	<i>430.29</i> less 30%	478.59
	<i>1004.01</i> sub-total (a)	1,116.71
10 pcs	front fender dust cover clip <i>NEC</i> ✓	✓ 37.00
1 pc	front fender dust cover <i>DDV</i> ✓	✓ 270.10
1 pc	front fender signal lamp <i>CUT</i> ✓	230.00 285.20
	front side mirror signal lamp <i>CUT</i> ✓	✓ 278.30
1 pc	front side mirror <i>CUT</i> ✓	212.90 696.30
1 pc	head lamp assy <i>BRV</i> ✓	558.00 786.90
1 pc	front steering tie rod <i>NNX</i> ✓	189.90
1 pc	front steering tie rod end <i>NNX</i> ✓	187.90
1 pc	front lower arm <i>DD</i> ✓	✓ 498.50
1 pc	front wheel bearing <i>NNX</i> ✓	399.70
1 pc	front knuckle arm <i>NNX</i> ✓	695.50
1 pc	front shock absorber <i>NNX</i> ✓	594.70
1 pc	front wheel hub <i>NNX</i> ✓	299.70
1 pc	front anti roll bar linkage <i>NNX</i> ✓	178.30
	<i>2087.8</i> sub-total	5,398.00
	<i>208.82</i> less 10%	539.80
	<i>1876.32</i> sub-total (b)	4,858.20
1 pc	front bumper lower kit <i>CUT</i> ✓	475.30 580.00
1 pc	alloy rim <i>CUT</i> ✓	300.00 500.00
	<i>775.30</i> sub-total (c)	1,080.00
	Sub -total for (a) + (b) + (c) <i>3655.63</i>	7,054.91

balance brought forwards.	7,054.91
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	500.00 800.00
To check wiring system.	✓ 50.00
To apply rust proofing on affected areas.	60.00 120.00
To apply waterproof sealant on affected areas.	NN X 120.00
To apply putty & spray painting on affected areas.	500.00 1,000.00
To remove and install front undercarriage parts to enable repair.	100.00 220.00
To replace alloy rim and perform wheel balancing.	25.00 40.00
To machine press wheel bearing.	20.00 40.00
To perform 4 wheels computerise alignment.	60.00 85.00
Towing Charges.	NN X 60.00
Total	9,589.91
@ 20%	4970.63 994.13 <u>3976.50</u>
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	? photo Repair days 4 TGM Lin 28/3/19 1300 hrs 97361577
4/5 3950/2	TGM Lin 22/11/19

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2684C
Vehicle Details	
Vehicle No.:	SGM4983K
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Apr 2019
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L T
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	HR15019182A
Chassis No.:	JN1BAAC11Z0002131
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,593.00
Original Registration Date:	20 Oct 2006
First Registration Date:	20 Oct 2006
Transfer Count:	0
Actual ARF Paid:	\$17,153.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$26,054.00
COE Rebate Amount:	\$13,279.00
Total Rebate Amount:	\$13,279.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Apr 2019

OK

MV 19,000/2
PV 13,279/2
NV 5,721/2

lin
1/4/19



Service Request Details

Claim

S9M01I75

Reference

None

Loss Date

26 March 2019

Report Date

26 Mar 2019 4:49:48 PM

Request Date

26 March 2019

Due Date

27 March 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Approved

Cancel

Insured

66m H983K

Vehicle Information

Incident Vehicle Registration #

TPVD NISSAN

Model

Service Address

...

Primary Contact

AUTOWORX HOUSE

176 SIN MING DRIVE, #02-01 SIN MING, 575721, Singapore

Claim Handler

DHAKAL Raghav

Contact only through email

raghav.dhakal@axa.com.sg

Additional Instructions

GIA NOT REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)



Re:<MANDATE IA>

Type

🔗 Question

Message

Please proceed

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26/11/2019

Survey Details:

Date of loss	26-Mar-19
Date of appointment	27-Mar-19
Date of survey	28-Mar-19
Location of survey	AUTOWORX HOUSE

Vehicle Details:

Claim Type:	Third party
Vehicle number	SGM 4983K
Make and Model	NISSAN LATION 1.5L T
Date of registration	20-Oct-06
Excess	
Market Value (est)	\$19,000.00
Part Rebate (est)	\$13,279.00
Nett Loss (est)	\$5,721.00

Repair details:

Initial Estimate	\$ 9,589.91
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,655.63
Check items (estimate)	\$ -
Labour	\$ 1,315.00
Total	\$ 4,970.63
Lump Sum(if applicable)	\$ 3,950.00

Number of days for repair	4 DAYS
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX.: (065) 62564315

Remarks:

We have not authorized repairs. It was reported that Insured vehicle changed lane when collided to the TP vehicle. We had spoken to the Insured and was informed on the TP claim, agreed to settle and aware of NCD issue. A letter was sent out to the Insured and no feedback till date. TP LOD IN.

Mandate:

Liability(TP)		100%
Proposed Repair Cost	\$	3,950.00
Loss of Use	\$	- no. of days
Loss of Rental (w/gst)	\$	642.00 \$100 x 6 days
Loss of Income	\$	- no. of days
GIA Search Fees	\$	2.00
Others (Medical Bills)	\$	-
Proposed Total	\$	4,594.00
***TBC - To Be Confirmed		

AUTOWORX HOUSE

176 Sin Ming Drive, #02-01 Sin Ming Autocare Singapore 575721

Email: claims.autoworxhouse@gmail.com

•TEL: 6452 8211 •FAX: 6451 7420

Direct Settlement THIRD PARTY CLAIM

Your ref:

Our ref: SGM 4983 K

AXA INSURANCE PTE LTD

Attn: Officer In Charge

(Motor Claim Department)

12/11/2019

Dear Sir,

RE : ACCIDENT INVOLVING SGM4983K & SLP4343H ON 26/03/2019.

We have been authorized by AUGUSTINE SIEW HUANG YEOW, the registered owner of vehicle number SGM4983K, which was involved in the above accident and at the material time to make a 3rd party claims against vehicle number SLP4343H.

The accident was clearly caused by your insured's negligence. We, therefore seeking compensation from you for our client financial losses as itemized below: -

Repair cost	S\$	3,950.00
Loss of Rental (8days x \$110.00) 1 Sunday involved + GST	S\$	941.60
Search Fee	S\$	2.00
Total	S\$	4,893.60

We have enclosed copies of relevant documents to support our claims.

Please settle this matter within 7 days.

Your prompt settlement of our claim would be much appreciated.

Do contact us at 64528211 for any clarification.

Thank you.

Yours faithfully,


Autoworx House

AUTOWORX HOUSE

C/O. 176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 64528211 FAX: 64517420

Registration No. 5296929B

INVOICE 5377

AXA INSURANCE PTE LTD

12/11/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE : SGM 4983 K / NISSAN LATIO</u>	
	Lump sum repair for the above mentioned vehicle.	3,950.00
	Total	3,950.00



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19005473/Bhb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:YVONNE

Date : 16-12-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 4343H	Veh. Inspected	SGM 4983K
Policy No.	GA208021	Coverage (\$)	0.00
Claim No.	S9M0117S	Excess (\$)	0.00
Assign From		Assign Date	27/03/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN LATIO 1.5	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JN1BAAC11Z0002131	Colour	SILVER
Odometer	146240	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	DUNLOP	6 mm
L/H Front Tyre	185/65 R15	DUNLOP	6 mm
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/03/2019	Inspection Date	28/03/2019
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGM 4983K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	DENTED	836.00	675.00
1	FRONT BUMPER SIDE RETAINER(CONSISTENT)	NECESSARY	32.10	32.10
1	FRONT FENDER (CONSISTENT)	DENTED	727.20	727.20
	LESS 30% DISCOUNT		-478.59	-430.29
			1,116.71	1,004.01
NETT ITEMS				
10	FRONT FENDER DUST COVER CLIP @\$3.70 (N) (CONSISTENT)	NECESSARY	37.00	37.00
1	FRONT FENDER DUST COVER (N) (CONSISTENT)	DENTED	270.10	270.10
1	FRONT FENDER SIGNAL LAMP (N) (CONSISTENT)	CUT	285.20	230.00
1	FRONT SIDE MIRROR SIGNAL LAMP (N) (CONSISTENT)	CUT	278.30	278.30
1	FRONT SIDE MIRROR (N) (CONSISTENT)	CUT	696.30	212.90
1	HEAD LAMP ASSY (N) (CONSISTENT)	BROKEN	786.90	558.00
1	FRONT STERRING TIE ROD (N) (CONSISTENT)	NOT NECESSARY	189.90	-
1	FRONT STEERING TIE ROD END (N) (CONSISTENT)TH	NOT NECESSARY	187.90	-
1	FRONT LOWER ARM (N) (CONSISTENT)	DENTED	498.50	498.50
1	FRONT WHEEL BEARING (N) (CONSISTENT)	NOT NECESSARY	399.70	-
1	FRONT KNUCKLE ARM (N) (CONSISTENT)	NOT NECESSARY	695.50	-
1	FRONT SHOCK ABSORBER (N) (CONSISTENT)	NOT NECESSARY	594.70	-
1	FRONT WHEEL HUB (N) (CONSISTENT)	NOT NECESSARY	299.70	-
1	FRONT ANTI ROLL BAR LINKAGE (N) (CONSISTENT)	NOT NECESSARY	178.30	-
	LESS 10% DISCOUNT		-539.80	-208.48
			4,858.20	1,876.32
SPECIAL NETT ITEMS				
1	FRONT BUMPER LOWER KIT (SN) (CONSISTENT)	CUT	580.00	475.30
1	ALLOY RIM (SN) (CONSISTENT)	CUT	500.00	300.00
			1,080.00	775.30
LABOUR				
	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND ALIGN THE NECESSARY AFFECTED AREAS.		800.00	500.00

Report Ref No. CC4/ASM19005473/Bhb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING SYSTEM.		50.00	50.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		120.00	60.00
	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	500.00
	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR .		220.00	100.00
	TO REPLACE ALLOY RIM AND PERFORM WHEEL BALANCING.		40.00	25.00
	TO MACHINE PRESS WHEEL BEARING.		40.00	20.00
	TO PERFORM 4 WHEELS COMPUTERISE ALIGNMENT.		85.00	60.00
	TOWING CHARGES.	NOT NECESSARY	60.00	-
			2,535.00	1,315.00
	GRAND TOTAL		9,589.91	4,970.63
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,950.00

Report Ref No. CC4/ASM19005473/Bhb3q2

LIM TEOW GUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

ClaimSYN01075

ReferenceCC4/ASH19005473/BH03a2

Loss Date26 March 2019

Report Date26 Mar 2019 4:49:48 PM

Request Date2 November 2019

Due Date

Vendor NameL&K AUTO CONSULTANTS PTE LTD (TP)

Type of LossThird Party Vehicle Damage

ServicesPending verification - Direct Settlement

Actions

Next StepWait for Approve Invoice

Add Invoice

Insured

YU CHEN KAI
3 AMBER GARDENS, #21-12, ONE AMBER,
439972, Singapore
ADMIN@ALFACREDIT.COM.SG

Vehicle Information

Incident Vehicle Registration #SGM49B3K

MakeTPVD NISSAN

Model

Service Address

Primary Contact
AUTOWORK HOUSE
176 SIN MING DRIVE, #02-01 SIN MING, 575721,
Singapore

Claim Handler
ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

QIA NOT REPORTED

Messages3

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type		Document SubType	
•		•	
✚ Upload Documents			
NAME	TYPE	SUB-TYPE	AUTHOR
LKKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	L&K AUTO CONSULTANTS PTE LTD (TP)
			DATE UPLOADED
			20 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LKKInspection (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LKKAdjustment1a (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 GMA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 AUTHORISATION TO ACT FOIRM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 MANDATE IA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2019
 TP LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2019
 LKK AFTER REPAIR PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2019
 LKK REINSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2019
 LKK INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2019
 TP ESTIMATE - MAINXED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2019
 SLF4343H OI REPORT.pdf	Reports & Statement	GIA Report	CHAN Kian Chuan	28 March 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 EMAIL.mig	Letters and Correspondence	Others	VISHNU BATHAM Shekhar	28 March 2019
 EMAIL TP PSL.mig	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	26 March 2019