

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 443P**AAD1903-182***Not Notarized
Reserve B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 443P

VF1ABL15AUC283458

RENAULT

LATITUDE

24.3.2019

AXA

3/7/2017

PART**LIST**

1	BUMPER COVER FRT
1	HEADLAMP LH
1	HEADLAMP HARNESS
1	FENDER PANEL FRT LH
1	WHEELARCH FRT LH
1	FENDER BRACKET LOWER LH
1	FENDER INSULATOR LH
1	DOOR PANEL FRT LH
1	DOOR HINGE UPPER LH
1	DOOR HINGE LOWER LH
1	DOOR CHECK FRT LH
1	DOOR LOCK FRT LH
1	DOOR CATCH FRT LH
1	DOOR HANDLE OUTER FRT LH
1	DOOR HANDLE COVER FRT LH
1	DOOR HANDLE MODULE FRT LH
1	DOOR REGULATOR FRT LH
1	DOOR REGULATOR MOTOR FRT LH
1	DOOR REGULATOR GUIDE FRT LH
1	DOOR PANEL REAR LH
1	DOOR GUIDE REAR LH
1	DOOR HINGE UPPER LH
1	DOOR HINGE LOWER LH
1	DOOR CHECK REAR LH
1	DOOR LOCK REAR LH
1	DOOR HANDLE OUTER REAR LH
1	DOOR HANDLE CAP REAR LH
1	DOOR HANDLE SEAL REAR LH
1	DOOR HANDLE COVER REAR LH
1	DOOR HANDLE MODULE REAR LH
1	DOOR REGULATOR REAR LH

\$	R	1,259.42	X
\$	Sn	1,184.43	X
\$	Sn	928.29	X
\$	R	783.83	✓
\$	Sn	278.84	X
\$	Sn	15.79	X
\$	Sn	130.84	X
\$	R	2,844.66	✓
\$	R	261.28	X
\$	Dir	300.55	✓
\$	Sn	194.77	X
\$	R	908.75	X
\$	Sn	131.23	X
\$	R	477.76	X
\$	R	13.22	X
\$	Sn	133.60	X
\$	R	505.19	✓
\$	Sn	796.46	✓
\$	Sn	120.97	X
\$	R	2,844.66	✓
\$	Sn	176.82	} X
\$	R	274.50	
\$	R	300.55	
\$	Sn	203.06	
\$	R	908.75	
\$	Sn	126.49	
\$	Sn	35.52	
\$	Sn	7.89	
\$	Sn	13.22	
\$	Sn	133.60	
\$	R	1,135.10	

Trans-cab Auto Services Pte Ltd**AAD1903-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 443P

1	DOOR REGUALTOR MOTOR REAR LH	\$	893.75	
1	DOOR REGULATOR NUT REAR LH	\$	12.43	
1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	6.31	
1	DOOR FINISHER REAR LH	\$	423.10	
1	DOOR MOULDING REAR LH	\$	176.82	
1	DOOR MOULDING CLIP L70Y	\$	5.92	
1	DOOR MOULDING SCREW L70Y	\$	6.91	
1	DOOR CASING REAR LH	\$	1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	30.39	
1	DOOR CASING CLIP	\$	12.63	
1	DOOR CASING LIGHT L70Y	\$	48.74	
1	DOOR FINISHER INNER REAR LH	\$	323.44	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33	
1	DOOR GRAB HANDLE REAR LH	\$	210.96	
1	DOOR BLIND REAR LH	\$	741.80	
1	DOOR WHEATHESTRIIP REAR LH	\$	410.66	
1	DOOR SEAL REAR LH	\$	162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31	
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64	
1	FENDER PANEL REAR LH	\$	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	671.45	
1	WHEELARCH REAR LH	\$	543.47	
1	DOOR MIRROR ASSY LH	\$	1,483.40	
1	ROCKER PANEL INNER GARNISH LH	\$	466.51	
1	ROCKER PANEL INNER LH	\$	1,024.79	
1	ROCKER PANEL CENTER LH	\$	990.25	

\$	31,671.59
10% \$	3,167.16
\$	28,504.43

Specical Nett

1SET	BUMPER CLIP FRT	\$	66.00	X
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X

Trans-cab Auto Services Pte Ltd**AAD1903-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 443P

1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	605a
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	155a
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	605a
1	DOOR CHECK BOLT	\$	na	22.69	X
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
1	FRONT LEFT TYRE RIM	\$	5a	380.00	
1	FRONT LEFT TYRE	\$	5a	330.00	

TOTAL	\$	1,329.63
--------------	-----------	-----------------

TOTAL PARTS	\$	29,834.06
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	900a 4,200.00
----	------------------

To apply paint protection system (PPS) maintain and enhancement

\$	na 380.00 X
----	-------------

Putty and spray painting of the affected portion.

\$	1320a 4,200.00
----	-------------------

To rust-proofing of the affected areas.

\$	170.00 120a
----	-------------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00 100a
----	-------------

Trans-cab Auto Services Pte Ltd**AAD1903-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 443P

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>2ol</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>

TOTAL	\$	10,060.00
--------------	-----------	------------------

Over All Total	\$	39,894.06
-----------------------	-----------	------------------

LUMP SUM(REPAIR DAY)*20 DAYS**7 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: