

SECTION

ASS. REC. BY:

REF: CS/MSG 19005479/E + d3

Special Instruction:

Surveyor: STAVE

ASSIGNMENT (Office)

Merimen

From (Person): Pauline Tham

of MSG

Date/Time: 26.3.19 17:00 PM

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 3510L

Insured: SKG 6746P

at Workshop m/s Trans Eurokars Pte Ltd

Tel: 63957877

of 27A Tanjong Pagar

Policy No: A29087468 AMX

Claim No: 578005

Sum Insured:

Excess:

Make of Veh:

D.O.A 1/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 27.3.19

Person Contacted:

Vehicle IN/OUT


Date/Time	Action/Instruction
	Estimate (✓)
	SLD 3510L - NBA/MSG 1802/1655/4
	SKG 6746P - NBA/MSG 1802/1654/4
	08/3@15:21 revised preliaduse via merimen
	Finalized \$2938.74, 3days

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: _____
 at: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLD 3510L 14/06/16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mazda 3 cc: 1.5
 Colour: Blue A/C Insured / Std / NI / NA
 Sp. Reading: 56953 T/Radin: Insured / Std / NI / NA

Eng/No: _____
 C/N: JMGBM 42A8G 0343975
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim STD A/Rim or
 Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 11/12/18 D.O.I. 27/28/19
 Survey held at Trans
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : _____ Action / Instruction
24/4/19 Final Report \$2938.74 3 days (Red: 4418.47 (60%))

RECEIVED 26 APR 2019

26/4/19

Date/Time: File Pass to: ☐ : Procl. Report

26/4 Typst ☒ : Final Report

Date/Time: File Return to:

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

☐ : G + R: \$

☐ : Photos

☐ : Index

Report Format :

Lump Sum / I.B.I: 2938.74

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018		26 Mar 2019 17:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TEO BOON HOWE, ID: S1358382Z								
Main Claimant:	MYO MYINT AUNG, ID: S7667650Z								
Vehicle Reg. No.:	SLD3510L	Date of Loss:	01/12/2018 18:00 - :59 [29 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 578005	Policy/Cover Note No.:	A29087468QMX (Comprehensive) Coverage: 08/09/2018 - 07/09/2019						
Vehicle Reg. No. (Insured):	SKG6946P	Policy No. (Claimant):							
Repairer:	Trans Eurokars Pte Ltd - Tanjong Penjurur (HQ) 27A Tanjong Penjurur, 609025 West Coast - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/03/2019]								
Adj Asg. Remarks:	LIABILITY 100%. CONTACT: VION - 6395 7877 Please arrange survey for the above vehicle tomorrow 27/3/19 @ 27A Tanjong Penjurur anytime. Vehicle is in. On WP.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Steve Chen (LKK Auto)
Sent: Wednesday, 24 April 2019 6:01 PM
To: catherinechua@eurokars.com.sg
Cc: Denise Tay (LKKAuto)
Subject: SLD3510L - FINALIZATION OF COR

Dear Catherine,

We confirm the finalize \$2,938.74 and 3 days.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]
Sent: Wednesday, April 24, 2019 11:47 AM
To: Steve Chen (LKK Auto)
Cc: vion.lim@eurokars.com.sg; CS A Team; Admin A
Subject: SLD3510L - FINALIZATION OF COR

Dear Steve

Our COR computation and B4 paint photos are attached for your agreement.

COR: \$2938.74 before GST

3 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards

 **EUROKARS GROUP**

Driving luxury experiences since 1985

Catherine Chua

Insurance Claims Executive

23 Leng Kee Road Singapore 159095

T: (65) 6603 6128 D: (65) 6603 6121 F: (65) 6476 7417

E: catherinechua@mazda.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <mazdacanon@mazda.com.sg>
Sent: 24 April 2019 10:47 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/12/2018 13:18
Date Of Accident	01/12/2018 18:05
Exact Location Of Accident	ADAM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD3510L
Insured/Policyholder	
Name Of Registered Owner	MYO MYINT AUNG
NRIC No	S7667650Z
Email Address	MMA007@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91259457
Alternative Phone No	OTHERS-92302094

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100474545-02
Cover Note Number	

Driver

Name of Driver	MYO MYINT AUNG
NRIC No	S7667650Z
Date Of Birth	11/03/1976
Occupation	INDOOR
Date Of Driving Pass	04/08/2008
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91259457
Fax Number	
Contact Number	OTHERS-92302094
Email Address	MMA007@GMAIL.COM

Address	BLK 391 BUKIT BATOK WEST AVE 5 #03-418
Postcode	650391
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ERICIA LOW XIN YI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG6946P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	VICTOR KAN ZHEN WEI
NRIC/Passport Number	S9027540B
Contact Number	81009190
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ERICIA LOW XIN YI
Approximate Age	
Injuries Sustain	NECK PAIN
Injured person in which vehicle?	SLD3510L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 461D BUKIT BATOK WEST AVE 8
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 4 Dec 2018

Driver's Signature


(If driver is not the policyholder)
Date & Time:

* Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SLD 3510 L

ACCIDENT DATE: 1 Dec 2018

CONTACT NUMBER: 9125 6457

ACCIDENT TIME: 6:05 PM

EMAIL: mma007@gmail.com

LOCATION: Adam Road

Travelling on Adam Road to PIE together with 1 passenger (hitch rider) on 1 Dec 2018 about 6:05 pm with heavy traffic and a little rain condition, suddenly heard a bang sound and feel a little impact. ~~from~~ found out that the vehicle, SK66946P, driven by Vitor Kan Zhen Wei hit our vehicle, SLD3510L, from the rear. There is minor damage to rear bumper of the vehicle, SLD3510L, and one of the passengers in vehicle, SLD3510L, feel neck pain. According to the neck pain passenger, she was given 7 days MC.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: ☐ CLAIM OWN POLICY ☐ CLAIM THIRD PARTY ☐ REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 1 Dec 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

See back of Report Form for details

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7650Z
Vehicle Details	
Vehicle No.:	SLD3510L
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	P520368845
Chassis No.:	JM6BM42A8G0343075
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,819.00
Original Registration Date:	14 Jun 2016
First Registration Date:	14 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$13,819.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jun 2026
PARF Rebate Amount:	\$10,364.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$38,717.00
Total Rebate Amount:	\$49,081.00

The information contained herein is correct as at 28 Mar 2019

OK



Steve (LKK)
8322 8813
Ry befo spray

W/L M/L 27/3/19 4-00pm
P/P 3 chys

TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L		NAME : Mr Myo Myint Aung		WIP : 29723	
4 SHENTON WAY #21-01		ADDRESS : Apt Blk 391 Bukit Batok West Ave 5		EXCESS :	
SGX CENTRE 2		#03-418		DATE: 4-Dec-18	
SINGAPORE 068807		Singapore 650391			
ATTN. : MOTOR CLAIMS		TEL : 91259457			
FAX :					
VEH NO :	SLD3510L	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM68M42A8G0343075	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	16-Jun-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MBPD8-50-221ABB		\$ 949.17
2	BRACKET CENTER	1	MKD53-50-251		\$ 5.10
3	RETAINER, SENSOR	4	MKD47-67-UC5A83		\$ 69.20
4	SENSOR, ULTRASONIC	4	MKD47-67-UC1 83		\$ 775.60
5	TAPE PROTECTOR, SENSOR	3	MG51D-50-EM1A		\$ 24.30
6	REAR REINFORCEMENT	1	MB45A-50-260		\$ 537.30
7	CLIP, REAR BUMPER	2	MGJ21-50-049		\$ 6.40
8	GROMMET, REAR BUMPER	4	MBHN1-50-021A		\$ 10.00
9	RIVET, REAR BUMPER	4	MBBM4-50-355		\$ 16.80
10	GROMMET, REAR BUMPER	2	M9991-00-501		\$ 5.60
11	FASTENER, REAR BUMPER	4	MB45A-56-146A		\$ 11.20
12	GASKET LHS, TAILLAMP	1	MBHN1-51-163		\$ 20.90
13	GASKET RHS, TAILLAMP	1	MBHN1-51-153		\$ 20.90
TOTAL PARTS					\$ 2,452.47
LESS 10%					\$ 245.25
TOTAL PARTS COST					\$ 2,207.22
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,980.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL.			\$ 1,890.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.			\$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00

5	④ MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$	250.00
6	⑤ MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$	350.00
7	⑥ MZ-BR-SUNDRI	SUNDRIES. <i>Net</i>	30	NETT	\$ 100.00
			TOTAL LABOUR	\$ -	\$ 5,150.00
			TOTAL PARTS	\$ -	\$ 2,207.22
			TOTAL	\$ -	\$ 7,357.22
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ -	
			GST 7%	\$ -	\$ -
			GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Myo Myint Aung ADDRESS : Apt Blik 391 Bukit Batok West Ave 5 #03-418 Singapore 650391 TEL : 91259457		WIP : 29723 EXCESS : DATE: 4-Dec-18	
VEH NO :	SLD3510L	DATE IN :		CONTACT PERSON :	Vlan 63957877
CHASSIS NO :	JM6BM42A8G0343075	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	16-Jun-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MBPD8-50-221ABB	\$ 949.17	\$ 949.17
2	BRACKET CENTER	1	MKD53-50-251		\$ 5.10
3	RETAINER, SENSOR	4	MKD47-67-UC5A83		\$ 69.20
4	SENSOR, ULTRASONIC	4	MKD47-67-UC1 83		\$ 775.60
5	TAPE PROTECTOR, SENSOR	3	MG51D-50-EM1A	\$ 24.30	\$ 24.30
6	REAR REINFORCEMENT	1	MB45A-50-260		\$ 537.30
7	CLIP, REAR BUMPER	2	MGJ21-50-049	\$ 6.40	\$ 6.40
8	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.00	\$ 10.00
9	RIVET, REAR BUMPER	4	M8BM4-50-355	\$ 16.80	\$ 16.80
10	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 5.60	\$ 5.60
11	FASTENER, REAR BUMPER	4	MB45A-56-146A	\$ 11.20	\$ 11.20
12	GASKET LHS, TAILLAMP	1	MBHN1-51-163	\$ 20.90	\$ 20.90
13	GASKET RHS, TAILLAMP	1	MBHN1-51-153	\$ 20.90	\$ 20.90
TOTAL PARTS				\$ 1,065.27	\$ 2,452.47
LESS 10%				\$ 106.53	\$ 245.25
TOTAL PARTS COST				\$ 958.74	\$ 2,207.22
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER. TO REPAIR AREAS AFFECTED BY THE ACCIDENT.		\$ 660.00	\$ 1,980.00
2		TO RESPRAY REAR BUMPER.		\$ 630.00	\$ 1,890.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		\$ 330.00	\$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150.00	\$ 250.00

6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
TOTAL LABOUR			\$ 1,980.00	\$ 5,150.00
TOTAL PARTS			\$ 958.74	\$ 2,207.22
TOTAL			\$ 2,938.74	\$ 7,357.22
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 2,938.74	
GST 7%			\$ 205.71	\$ -
GRAND TOTAL			\$ 3,144.45	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018		26 Mar 2019 17:00 Edit Adj Rpt	\$52,938.74 Edit Estimates	\$52,938.74 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TEO BOON HOWE , ID: S1358382Z								
Main Claimant:	MYO MYINT AUNG , ID: S7667650Z								
Vehicle Reg. No.:	SLD3510L	Date of Loss:	01/12/2018 18:00 - :59 [29 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 578005	Policy/Cover Note No.:	A29087468QMX (Comprehensive) Coverage: 08/09/2018 - 07/09/2019						
Vehicle Reg. No. (Insured):	SKG6946P	Policy No. (Claimant):							
		Excess:							
Repairer:	Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru, 609025 West Coast - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 25/04/2019]								
Adj Asg. Remarks:	LIABILITY 100%. CONTACT: VION - 6395 7877 Please arrange survey for the above vehicle tomorrow 27/3/19 @ 27A Tanjong Penjuru anytime. Vehicle is in. On WP.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD3510L (578005)
[SKG6946P]
TP
MYO MYINT AUNG
Dec 1 2018 6:00PM
[TEO BOON HOWE]
Trans Eurokars Pte Ltd - Tanjong Penjuru

Upload Documents	Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	06/12/18 09:19	Accident Statement From: SC - Reg. No: SKG6946P, Claimant: TEO BOON HOWE		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/03/19 15:21	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
2	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
3	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
4	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
5	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
6	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
7	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
8	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
9	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
10	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
11	28/03/19 08:29	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
12	28/03/19 08:29	Chassis Number		Load JPG <input checked="" type="checkbox"/>
13	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
14	28/03/19 08:29	General View		Load JPG <input checked="" type="checkbox"/>
15	24/04/19 18:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
16	24/04/19 18:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
17	24/04/19 18:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	06/12/18 09:06	TP ESTIMATE		Load PDF
2	06/12/18 09:06	TP PRI Request EMAIL		Load PDF
3	06/12/18 09:20	SLD3510L e-file report From: SC - Reg. No: SKG6946P, Claimant: TEO BOON HOWE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

--

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19005479/ETD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29087468QMX

Claimant Vehicle No: SLD3510L

Insured Vehicle No: SKG6946P

Date of Loss: 01/12/2018

Nature of Claim: TP

Claim No: 578005

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD3510L

Make & Model: MAZDA M3, 1.6 (A)

Reg. Date: 14/06/2016 (Man. Year: 2006)

Colour: Blue

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: P520368845

Chassis No: JM6BM42A8G0343075

Odometer: 56953 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,307.22	988.74	1,318.48	57.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,050.00	1,950.00	3,100.00	61.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,357.22	2,938.74	4,418.48	60.06
+ GST 7.00/7.00% (S\$)	515.01	205.71	309.30	60.06
Nett Amount (S\$)	7,872.23	3,144.45	4,727.78	60.06

INSPECTION

Date of Assignment: 26/03/2019

Date Inspected: 27/03/2019 Inspected At:

Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)

27A Tanjong Penjuru
Singapore 609025

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts: 143	MAZDA M3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD3510L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	949.17 FL	*949.17 FL
2	1		*BRACKET CENTER	Not Necessary	5.10 FL	*- FL
3	4		*RETAINER ,SENSOR	Not Necessary	69.20 FL	*- FL
4	4		*SENSOR ,ULTRASONIC	Not Necessary	775.60 FL	*- FL
5	3		*TAPE PROTECTOR ,SENSOR	Necessary	24.30 FL	*24.30 FL
6	1		*REAR REINFORCEMENT	Not Necessary	537.30 FL	*- FL
7	2		*CLIP,REAR BUMPER	Necessary	6.40 FL	*6.40 FL
8	4		*GROMMET ,REAR BUMPER	Necessary	10.00 FL	*10.00 FL
9	4		*RIVET ,REAR BUMPER	Necessary	16.80 FL	*16.80 FL
10	2		*GROMMET ,REAR BUMPER	Necessary	5.60 FL	*5.60 FL
11	4		*FASTENER ,REAR BUMPER	Necessary	11.20 FL	*11.20 FL
12	1		*GASKET LHS ,TAILLAMP	Necessary	20.90 FL	*20.90 FL
13	1		*GASKET RHS ,TAILLAMP	Necessary	20.90 FL	*20.90 FL
14	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	2,552.47	1,095.27
- List Item Discount on L Items 10.00/10.00% (\$\$)	245.25	106.53
Total Parts (\$\$)	2,307.22	988.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT .TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT	New	1,980.00	660.00
2	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT ,REAR END PANEL	New	1,890.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	330.00	330.00
4	TO CARRY -OUT BODY CAVITY PRESERVATION	New	250.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (S\$)			5,050.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >