

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0402/2019/GW
Date : 28-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No: SKD 9922 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Koh Kwang Haw
Address : 56 Bukit Batok St 31
#25-15
Singapore 659445
Telephone : (HP)96774028
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SKV 1136 P**
Model Code : Audi A6 1.8 TFSI Ultra S
Model / Year : Aug-15
Engine No : CYG 005827
Chassis No : WAUZZZ4G3FN091668
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Mar-19
Place of Accident : Along PIE Near Toa Payoh Exit Towards Jurong

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 1136 P

S/N	Nature of Jobs	Estimated Charges
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper.	\$ 1,050.00 500
3	To respray front bumper.	\$ 900.00 550
TOTAL LABOUR CHARGES - FRONT		: \$ <u>2,430.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1136 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Regis</i>	\$ 2,549.00	X
2	FRONT BUMPER GRILLE <i>new ?</i>	\$ 598.00	?
3	FRONT BUMPER CHROME TRIM ?	\$ 276.00	?
4	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 45.00	X
5	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 199.00	X
6	FRONT BUMPER SPOILER <i>new</i>	\$ 227.00	X
7	RADIATOR GRILLE <i>new</i>	\$ 1,766.00	✓
8	RADIATOR GRILLE COVER ?	\$ 33.00	?
9	RADIATOR GRILLE SENSOR SUPPORT-LH/RH <i>new</i>	2 \$ 122.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>new</i>	2 \$ 638.00	X
11	FRONT BUMPER COVER-LH/RH ?	2 \$ 92.00	?
12	FRONT BUMPER COVER CAP-LH/RH <i>new</i>	2 \$ 104.00	X
13	FRONT BUMPER LIFT CYLINDER-LH/RH <i>new</i>	2 \$ 432.00	X
14	FOAM FILLER PIECE <i>new</i>	\$ 215.00	X
15	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	\$ 754.00	X
16	FRONT BUMPER COVER CAP-LH/RH <i>new</i>	\$ 112.00	X
17	SIGN ' CAUTION ' <i>green</i>	\$ 13.00	X
18	AIR CONDITIONER STICKER	\$ 18.00	✓
19	FRONT SENSOR-INNER <i>new</i>	2 \$ 419.00	X
20	FRONT SENSOR SEAL RING <i>new</i>	4 \$ 5.00	X
SUB-TOTAL SPARE PARTS CHARGES - FRONT		\$ 8,617.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1136 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT AIR GUIDE -LH/RH <i>all n</i>	2 \$	50.00 ↗
22	RADIATOR GRILLE UPPER CENTRE COVER ↗	\$	27.00 ↗
23	RADIATOR LOWER SUPPORT SEAL STRIP ↗	\$	21.00 ↗
TOTAL SPARE PARTS CHARGES - FRONT		:	\$ 8,715.00
TOTAL LABOUR CHARGES - FRONT		:	\$ 2,430.00
GRAND TOTAL - FRONT		:	\$ 11,145.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 1136 P

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500
3	To respray rear bumper.	\$ 900.00 550
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ <u>2,502.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1136 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>reformed</i>	\$ 2,438.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 247.00	x
3	REAR BUMPER SPOILER <i>cut</i>	\$ 437.00	✓
4	REAR BUMPER SECURING STRIP <i>new</i>	\$ 203.00	✓
5	REAR BUMPER CLOSING ELEMENT-LH/RH <i>2 new</i>	2 \$ 146.00	+
6	CABLE TERMINAL HOLDER RETAINER	13 \$ 90.00	+
7	REAR LID CONTROL UNIT <i>2 new</i>	\$ 387.00	+
8	EXHAUST TAIL PIPE TRIM <i>2 new</i>	\$ 517.00	+
9	REAR BUMPER CARRIER <i>2 new</i>	\$ 887.00	x
10	REAR BUMPER SEAL-LH/RH	2 \$ 26.00	+
11	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$ 60.00	x
12	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 96.00	+
13	REAR BUMPER CONNECTING PIECE	2 \$ 22.00	+
14	REAR BUMPER GUIDE PROFILE-LH/RH	2 \$ 120.00	+
15	REAR BUMPER CENTER GUIDE SECTION	\$ 96.00	+
16	REAR BUMPER HOLDING STRAP-LH/RH	2 \$ 116.00	x
17	REAR SENSOR SEAL RING <i>2 new</i>	4 \$ 5.00	x
18	REAR SENSOR-OUTER	2 \$ 462.00	x
19	FRONT NO. PLATE <i>best</i>	S/N \$ 25.00	✓
20	REAR NO. PLATE <i>not n</i>	S/N \$ 25.00	x
21	SUNDRIES	\$ 800.00	?
TOTAL SPARE PARTS - REAR		\$ 7,205.00	
TOTAL LABOUR CHARGES - REAR		\$ 2,502.00	
GRAND TOTAL - REAR		\$ 9,707.00	
GRAND TOTAL - FRONT/REAR		\$ 20,852.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Addian hiny
Surveyed Date : 29/03/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorized, 06 days.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant