

**ACCIDENT REPAIR ESTIMATES**

Our Ref: TP / GBD7070G

Type of Claim : TP

Vehicle No. : GBD7070G

Make &amp; Model : NISSAN NV200 1.5L MT

Year of Manufacture : 2014

Chassis No. : VSKYBAM20Z0092675

Ins Company : AIG ASIA PACIFIC  
INSURANCE PTE LTD

Motor No. : K9KC400D064230

Excess : 0

Policy No. : 0

Date of Accident : 09.01.2019

Time of Accident : 15:50

Suggested Days of Repair : 7

Case Owner : SP POWERASSETS LIMITED

**Repair Estimates**

Parts (a) List Price Items	\$	260.00
Plus/Less 20%	\$	52.00
Total of Cost / List	\$	208.00
(b) Nett Price Items	\$	-
Less 5%	\$	-
Total of Nett Item	\$	-
(c) Special Nett Items	\$	750.00
<b>Total Parts Cost (Appendix A)</b>	<b>\$</b>	<b>958.00</b>
<b>Labour (Appendix B)</b>	<b>\$</b>	<b>750.00</b>
<b>Total Repair Cost</b>	<b>\$</b>	<b>1,708.00</b>

The above total will be subjected to 7% G.S.T.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Guo Qiang - 82880282Company : LKKSurvey conducted on : 28/3/19 at \_\_\_\_\_**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4-5 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

part by part.  
After repair photos.

*Newton*  
*05/20/14*

**ESTIMATED REPAIR COST DETAILS**

1  
SP POWERASSETS LIMITED

Vehicle No : GBD7070G Case Owner : \_\_\_\_\_  
 Make & Model : NISSAN NV200 1.5L MT Year Manufactur: 2014  
 Chassis No : VSKYBAM20Z0092675 Engine No : K9KC400D054230  
 Date & Time : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Unit Price	List Price	Nett Price	S/N	Remarks
1	REAR LH TAILLAMP <del>GA</del> <del>XX</del> NN	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
2	DOOR HINGE <del>X</del> NN	4	\$ 45.00	\$ 180.00	\$ -	\$ -	-
3	STICKER (REAR LH FENDER, REAR BUMPER & )	1	\$ -	\$ -	\$ -	\$ 750.00	150-
4	0	1	\$ -	\$ -	\$ -	\$ -	-
5	0	1	\$ -	\$ -	\$ -	\$ -	-
6	0	1	\$ -	\$ -	\$ -	\$ -	-
7	0	1	\$ -	\$ -	\$ -	\$ -	-
8	0	1	\$ -	\$ -	\$ -	\$ -	-
9	0	1	\$ -	\$ -	\$ -	\$ -	-
10	0	1	\$ -	\$ -	\$ -	\$ -	-
11	0	1	\$ -	\$ -	\$ -	\$ -	-
12	0	1	\$ -	\$ -	\$ -	\$ -	-
13	0	1	\$ -	\$ -	\$ -	\$ -	-
14	0	1	\$ -	\$ -	\$ -	\$ -	-
15	0	1	\$ -	\$ -	\$ -	\$ -	-
16	0	1	\$ -	\$ -	\$ -	\$ -	-
17	0	1	\$ -	\$ -	\$ -	\$ -	-
18	0	1	\$ -	\$ -	\$ -	\$ -	-
19	0	1	\$ -	\$ -	\$ -	\$ -	-
20	0	1	\$ -	\$ -	\$ -	\$ -	-
21	0	1	\$ -	\$ -	\$ -	\$ -	-
22	0	1	\$ -	\$ -	\$ -	\$ -	-
23	0	1	\$ -	\$ -	\$ -	\$ -	-
24	0	1	\$ -	\$ -	\$ -	\$ -	-
25	0	1	\$ -	\$ -	\$ -	\$ -	-
26	0	1	\$ -	\$ -	\$ -	\$ -	-
27	0	1	\$ -	\$ -	\$ -	\$ -	-
28	0	1	\$ -	\$ -	\$ -	\$ -	-
29	0	1	\$ -	\$ -	\$ -	\$ -	-
30	0	1	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL**      \$125.00    \$ 260.00    \$ -    \$ 750.00

