

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / GBD7070G

Type of Claim : TP

Vehicle No. : GBD7070G

Make & Model : NISSAN NV200 1.5L MT

Year of Manufacture : 2014

Chassis No. : VSKYBAM20Z0092675

Ins Company : AIG ASIA PACIFIC INSURANCE PTE LTD

Motor No. : K9KC400D054230

Excess : 0

Policy No. : 0

Date of Accident : 09.01.2019

Time of Accident : 15:50

Suggested Days of Repair : 7

Case Owner : SP POWERASSETS LIMITED

Repair Estimates

Parts (a) List Price Items	\$	260.00
Plus/Less 20%	\$	52.00
Total of Cost / List	\$	208.00
(b) Nett Price Items	\$	-
Less 5%	\$	-
Total of Nett Item	\$	-
(c) Special Nett Items	\$	750.00
Total Parts Cost (Appendix A)	\$	958.00
Labour (Appendix B)	\$	750.00
Total Repair Cost	\$	1,708.00

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Eric Qiang - 82880282

Company : LKK

Survey conducted on : 28/3/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4-5 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

part by part. After repair photos.

Newton
05/2014

ESTIMATED REPAIR COST DETAILS

1

SP POWERASSETS LIMITED

Vehicle No : GBD7070G Case Owner : _____
 Make & Model : NISSAN NV200 1.5L MT Year Manufactur: 2014
 Chassis No : VSKYBAM20Z0092675 Engine No : K9KC400D054230
 Date & Time : _____ - Supplier : _____ -
 Order By : _____ - Type of Claim : TP

S/No	Part Description	QTY	Unit Price	List Price	Nett Price	S/N	Remarks
1	REAR LH TAILLAMP FOA ?	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
2	DOOR HINGE ?	4	\$ 45.00	\$ 180.00	\$ -	\$ -	-
3	STICKER (REAR LH FENDER, REAR BUMPER & FOA)	1	\$ -	\$ -	\$ -	\$ 750.00	-
4	0	1	\$ -	\$ -	\$ -	\$ -	-
5	0	1	\$ -	\$ -	\$ -	\$ -	-
6	0	1	\$ -	\$ -	\$ -	\$ -	-
7	0	1	\$ -	\$ -	\$ -	\$ -	-
8	0	1	\$ -	\$ -	\$ -	\$ -	-
9	0	1	\$ -	\$ -	\$ -	\$ -	-
10	0	1	\$ -	\$ -	\$ -	\$ -	-
11	0	1	\$ -	\$ -	\$ -	\$ -	-
12	0	1	\$ -	\$ -	\$ -	\$ -	-
13	0	1	\$ -	\$ -	\$ -	\$ -	-
14	0	1	\$ -	\$ -	\$ -	\$ -	-
15	0	1	\$ -	\$ -	\$ -	\$ -	-
16	0	1	\$ -	\$ -	\$ -	\$ -	-
17	0	1	\$ -	\$ -	\$ -	\$ -	-
18	0	1	\$ -	\$ -	\$ -	\$ -	-
19	0	1	\$ -	\$ -	\$ -	\$ -	-
20	0	1	\$ -	\$ -	\$ -	\$ -	-
21	0	1	\$ -	\$ -	\$ -	\$ -	-
22	0	1	\$ -	\$ -	\$ -	\$ -	-
23	0	1	\$ -	\$ -	\$ -	\$ -	-
24	0	1	\$ -	\$ -	\$ -	\$ -	-
25	0	1	\$ -	\$ -	\$ -	\$ -	-
26	0	1	\$ -	\$ -	\$ -	\$ -	-
27	0	1	\$ -	\$ -	\$ -	\$ -	-
28	0	1	\$ -	\$ -	\$ -	\$ -	-
29	0	1	\$ -	\$ -	\$ -	\$ -	-
30	0	1	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$125.00 \$ 260.00 \$ - \$ 750.00

