

ASS. REC. BY:

REF:

CS / FC119005493 / Jtd3

Special Instruction:

Surveyor: Hwa Jie

ASSIGNMENT (Office)

From (Person): Eileen Lee (CWS) of FCI Date/Time: 27/3/2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLN 6650T Insured: SHC 3008Z

at Workshop m/s Automotive Repair Tel: 64688834 Raymond

of 38 Woodlands Ind Pk Rd #05-18

Policy No: Claim No: D19002076MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 26/3/2019

CA / REV / REP. / REV 24 HRS

28/3/2019

H.O.D. Endorsement:

Date/Time: 27/3. Person Contacted: Raymond Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 6650T-X
	SHC 3008Z-X
114-3:32pm	Revised via email prevl advise.

Surveillance Area Jie

REF:

FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLN 6650T
 at Workshop m/s Automotive Repair Centre
 of 38 Woodlands Ind Pk #05-18
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
28/3/2019 After 12pm.
 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: SLN6650T Yr Regn: 12 May 2017
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Vezel C.C. 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 31720 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RV11204713
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60 R16
 R: _____
 BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 26/3/19 D.O.I. 28/3/19
 Survey held at ARC
 Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
5/4/19 Confirmed P/P #37821- 5day of repair. CRed: 1803.40, 32%

RECEIVED 05 APR 2019

Date/Time, File Pass to? ☐ : Preli. Report
☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5
 Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format: TP
 Lump Sum / I.B.I.: (\$) 3782

Survey Fee:
 Transportation:
 S + R5, SI
 Photos
 Others
 TOTAL

140
50
50
41
281



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002076MFSH

Date: 1/4/2019

Our Ref: CS/FCI19005493/Jtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 6650T

Please be informed that we had conducted the inspection of the abovementioned vehicle
28/3/2019 at the premises of M/s Automotive Repair have the following to report: -

Workshop Estimate Amount	: S\$	<u>5,585.40</u>
Revised Estimate Amount	: S\$	<u>4,310.00</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Hwee Jie

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-03-2019	Our Ref No. D19002076MFSH
Accident Date	26-03-2019	Claim Type. Third Party
Insured Vehicle	SHC3008Z	Third Party Vehicle. SLN6650T
Survey Location	38 WOODLANDS INDUSTRIAL PARK E1 #05-18	
Contact Person.	RAYMOND TAN	
Contact No.	64688834/ 0	Fax No. 64622278
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AUTOMOTIVE REPAIR CENTRE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

*Vehi Out
28/3 After 12pm*

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 1 April 2019 3:32 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002076MFSH/1
Attachments: PRELI ADVISED SLN 6650T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLN 6650T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 27 March 2019 6:07 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002076MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 27 March 2019 2:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002076MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2422Z
Vehicle Details	
Vehicle No.:	SLN6650T
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4404713
Chassis No.:	RU11204713
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,846.00
Original Registration Date:	12 May 2017
First Registration Date:	12 May 2017
Transfer Count:	0
Actual ARF Paid:	\$13,985.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 May 2027
PARF Rebate Amount:	\$10,488.00
Intended COE Rebate Details	
COE Expiry Date:	11 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$42,201.00
Total Rebate Amount:	\$52,689.00

The information contained herein is correct as at 29 Mar 2019

OK

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1903-030

DATE : 26-Mar-2019

POLICY NO. : DIRECTASIA MT/00477781

VEHICLE REG. NO. : SLN6650T

VEHICLE MAKE : HONDA VEZEL 1.5X A

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

TO Motor Claim Department
MS First Capital Insurance Limited
36 Robinson Road #16-01 City House
Singapore 068877
Tel: 6507 3848, Fax: 65073849

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Door RH BUC /	1	\$ 980.00	\$ 980.00
2	Front Door Sash Tape Sticker RH nec /	1	\$ 30.00	\$ 30.00
3	Front Door Sub Seal RH nn cut x	1	\$ 30.00	\$ 30.00
4	Front Door Lower Seal RH nn x	1	\$ 20.00	\$ 20.00
5	Rear Door RH BUC /	1	\$ 980.00	\$ 980.00
6	Rear Door Sash Tape Sticker RH nec /	1	\$ 30.00	\$ 30.00
7	Rear Door Sub Seal Center RH CUT /	1	\$ 40.00	\$ 40.00
8	Rear Door Rear Seal RH nn x	1	\$ 20.00	\$ 20.00
9	Rear Door Lower Seal RH DEF /	1	\$ 20.00	\$ 20.00
10	Rear Door Hinge Upper RH nn x	1	\$ 50.00	\$ 50.00
11	Rear Door Hinge Lower RH nn x	1	\$ 50.00	\$ 50.00
12	Rear Wheel Arch Garnish RH SCR /	1	\$ 180.00	\$ 180.00
13	Rear Bumper Panel RH Repair x	1	\$ 200.00	\$ 200.00
14	Side Sill Garnish RH SCR /	1	\$ 380.00	\$ 380.00
20% Discount on Parts Total Spare Parts				\$ 3,010.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
15	Spray Painting Rear Bumper Panel RH, Fender RH & 2 Doors RH	1	\$ 1,000.00	\$ 700 1,000.00
16	Repair, Replace and Refill Affected Accident Area	1	\$ 700.00	\$ 600 700.00
17	Transfer Door Fitting and Window Mechanism to New Door	2	\$ 80.00	\$ 100 160.00
18	Repair and Respray Rear Rim RH	1	\$ 100.00	\$ 60 100.00
19	Reset Fault Code	1	\$ 150.00	\$ 120 150.00
20	Wheels Computer Alignment	1	\$ 70.00	\$ 60 70.00
21	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,210.00
Amount Before Excess	\$ 5,220.00
Add GST @ 7%	365.40
Total Amount Payable	5,585.40

Please arrange this vehicle to be surveyed soonest possible. Thank you

Total - \$3782.6

Huxia - LK
28/3/19
P/P 5 days
an



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19005493/Jtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3008Z	Veh. Inspected	SLN 6650T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002076MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	27/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11204713	Colour	GREY	
Odometer	31720	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/03/2019	Inspection Date	28/03/2019	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 6650T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR RH	BUCKLED	980.00	980.00
1	FRONT DOOR SASH TAPE STICKER RH	NECESSARY	30.00	30.00
1	FRONT DOOR SUB SEAL RH	NOT NECESSARY	30.00	-
1	FRONT DOOR LOWER SEAL RH	NOT NECESSARY	20.00	-
1	REAR DOOR RH	BUCKLED	980.00	980.00
1	REAR DOOR SASH TAPE STICKER RH	NECESSARY	30.00	30.00
1	REAR DOOR SUB SEAL CENTER RH	CUT	40.00	40.00
1	REAR DOOR REAR SEAL RH	NOT NECESSARY	20.00	-
1	REAR DOOR LOWER SEAL RH	DEFORMED	20.00	20.00
1	REAR DOOR HINGE UPPER RH	NOT NECESSARY	50.00	-
1	REAR DOOR HINGE LOWER RH	NOT NECESSARY	50.00	-
1	REAR WHEEL ARCH GARNISH RH	SCRATCHED	180.00	180.00
1	REAR BUMPER PANEL RH	TO REPAIR SEE LABOUR	200.00	-
1	SIDE SILL GARNISH RH	SCRATCHED	380.00	380.00
	LESS 20% DISCOUNT		-	-528.00
			3,010.00	2,112.00
LABOUR				
	SPRAY PAINTING REAR BUMPER PANEL RH, FENDER RH & 2 DOORS RH.		1,000.00	700.00
	REPAIR, REPLACE AND REFILL AFFECTED ACCIDENT AREA, INCLUSIVE OF THE REPAIR OF REAR BUMPER PANEL RH.		700.00	600.00
	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR.		160.00	100.00
	REPAIR AND RESPRAY REAR RIM RH.		100.00	60.00
	RESET FAULT CODE.		150.00	120.00
	WHEELS COMPUTER ALIGNMENT.		70.00	60.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			2,210.00	1,670.00
GRAND TOTAL			5,220.00	3,782.00



RECOMMENDED COST OF REPAIRS			3,782.00
-----------------------------	--	--	----------

Report Ref No. CS/FCI19005493/Jtd3n2

ONG HWEE JIE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.