

Special Instruction:

ASSIGNMENT (Office)

From (Person): Lee Ming Yao of AGA Date/Time: 24/3/2019
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant: Dickel

Surveyor: PAL/e

Workshop: Devol Care

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLR 8339J Insured: SLP 57148
at Workshop m/s _____ Tel: 9697 9374 Dong Kok Heng
of Harbourfront Tower 1 Carpark

Policy No: _____ Claim No: 441331039DS6

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/11/2018

(Client's Record)

29/3/2019 11am

H.O.D. Enlistment/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 21/10 Confirmed with Final Fig , days (Red S / %; Original days)

Date/Time: 17/4/19 Submit Final Fig 15 3100, 5 days (Red \$ 3800 / 55 %; Original 7 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 17 APR 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

20x

201

1) Date/Time 17/4-12 File Pass to

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

4) Date/Time File Return to

6) Date/Time _____ File Return to _____

Celine Fong (LKKAUTO)

From: Lee Ming-Yao <MingYao.Lee@aig.com>
Sent: Wednesday, 27 March 2019 10:20 AM
To: Corene
Cc: assignments; Admin A
Subject: RE: Our Ref : 44133103925G-005 | Your Ref : AJ.tk.6259.2018.Revol-PD | Accident Involving SLP5714P, SLR8339J & Other Vehicle on 07/11/2018

Without Prejudice

Hi Corene,

I will inform m/s LKK Auto Consultants Pte Ltd for the arrangement.

By copy to m/s LKK Auto Consultants Pte Ltd,

Please arrange for re-inspection. Details as below:

- | | |
|----------|---|
| 2. | Please note that our client's vehicle is available for re-inspection as follows:- |
| Date : | Friday, 29 March 2019 |
| Time : | 11.00am |
| Venue : | HabourFront Tower 1 Carpark |
| Contact: | Wong Kok Heng – 9697 9394 (Please contact him one day before the RI date) |

Supporting documents will be submitted in follow up email.

Regards,
Lee Ming Yao
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1769
MingYao.Lee@AIG.com | www.aig.sg



Follow us:



IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2018 14:52
Date Of Accident	07/11/2018 08:30
Exact Location Of Accident	AYE TOWARDS CITY AFTER EXIT 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8339J
Insured/Policyholder	
Name Of Registered Owner	WONG KOK HENG
NRIC No	S8628601G
Email Address	J.TENSEI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96979394
Alternative Phone No	OTHERS-96979394

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093459169-01
Cover Note Number	29/08/2018 - 28/08/2019

Driver

Name of Driver	WONG KOK HENG
NRIC No	S8628601G
Date Of Birth	30/09/1988
Occupation	INDOOR
Date Of Driving Pass	19/07/2005
Driving Experience	13 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96979394
Fax Number	
Contact Number	OTHERS-96979394
EMail Address	J.TENSEI@GMAIL.COM

Address	BLK 622B #14-266 PUNGGOL CENTRAL PUNGGOL SPECTRA
Postcode	822622
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP5714P
Vehicle Make/Model/Colour	SUBARU FORESTER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KENNETH CHOW ZHI QIANG
NRIC/Passport Number	S8500998B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKH8808L
Vehicle Make/Model/Colour	PEUGEOT 3008

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

ANG YEE KWANG KELVIN

NRIC/Passport Number

S8031967C

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SLP8339J
INSURER : NTUC
DATE & TIME: 07/11/2018 @ 0830

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 7/11/18

Driver's Signature

(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature

Name: Somya (AMK) 07/11/18
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Date of Accident: 07-Nov-2018 Time: 08.30AM Location: AYE towards City After Exit 8
 My Vehicle A: SLR8339J Vehicle B: SLP5714P Vehicle C: SKH8808L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7th Nov 2018 at around 8.30am, I am driving Vehicle A SLR8339J along aye towards city after exit 8
When vehicle B SLP5714P knocked into my rear!
After when I aligned I realized it is a chain collision involving 3 cars with Vehicle C SKH8808L
I have in car video
Note: Please take note that your insurer have 14 days timeframe for you to submit Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect


 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's
 Name: (AMK)
 NRIC/FIN No.:

() Claim Own Policy () Claim Third Party () Reporting Only
☒ Claim OD/TP at other workshop ()

Email: enquiry@revol.com.sg

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SLR8339J [SLP6714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



1/66: Chassis Number



2/66: Odometer Reading



3/66: Inspection Photo



4/66: Inspection Photo

SLR8339J [SLP6714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



5/66: Inspection Photo



6/66: Inspection Photo



7/66: Inspection Photo



8/66: Inspection Photo

SLR8339J [SLP6714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)




9/66: Inspection Photo



10/66: Inspection Photo



11/66: Inspection Photo



12/66: Inspection Photo

SLR8339J /SLP5714P1 - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/66: Inspection Photo



14/66: Inspection Photo



15/66: Inspection Photo



16/66: Inspection Photo

SLR8339J [SLP6714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



17/66: Inspection Photo



18/66: Inspection Photo



19/66: Inspection Photo



20/66: Inspection Photo

SLR8339J [SLP6714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)




21/66: Inspection Photo



22/66: Inspection Photo



23/66: Inspection Photo




24/66: Inspection Photo


SLR8339J [SLP5714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. [SG]




25/06: Inspection Photo



26/06: Inspection Photo



27/06: Inspection Photo



28/06: Inspection Photo

SLR8339J [SLP5714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



29/66: Inspection Photo



30/66: Inspection Photo



31/66: Inspection Photo



32/66: Inspection Photo


SLR8339J / SLP5714P1 - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



33/66: Inspection Photo



34/66: Inspection Photo



35/66: Inspection Photo



36/66: Inspection Photo

SLR8339J [SLP5714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



37/66 Inspection Photo



38/66 Inspection Photo



39/66 Repairer's Photo



40/66 Repairer's Photo

SLR8339J [SLP5714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



41/66: Repairer's Photo



42/66: Repairer's Photo




43/66: Repairer's Photo




44/66: Repairer's Photo


SLR8339J (SLP5714P) - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)




45/66: Repairer's Photo



46/66: Repairer's Photo




47/66: Repairer's Photo




48/66: Repairer's Photo


SLR8339J [SLP5714P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



49/66: Repairer's Photo



50/66: Repairer's Photo



51/66: Repairer's Photo




52/66: Repairer's Photo


SLR8339J [SLP8714PI] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)




53/66: Repairer's Photo



54/66: Repairer's Photo



55/66: Repairer's Photo




56/66: Repairer's Photo

SLR8339J (SLP6714P) - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



57/66: Repairer's Photo



58/66: Repairer's Photo



59/66: Repairer's Photo



60/66: Repairer's Photo

SLR8339J (SLP5714P) - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



61/66: Repairer's Photo



62/66: Repairer's Photo



63/66: Repairer's Photo



64/66: Repairer's Photo

SLR8339J (SLP5714P1) - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



65/66 Repairer's Photo



66/68 Repairer's Photo

Revol Carz Garage Pte Ltd

Blk 10 Ang Mo Kio Industrial Park 2a, Ang Mo Kio Autopoint #02-18

Singapore 568047

Tel: 65551171 Fax: 62679317

PHOTOCOPY

Name : Wong Kok Heng

Date : 28-Nov-18

Address : Blk 622B Punggol Central
#14-266 Punggol Spectra
Singapore 822622

Final repair bill for Honda Vezel SLR 8339 J

To supply and replace parts, labour charges for
repairing, knocking, welding and to respray painting
(Lump Sum Repair)

\$ 6,900.00

Dollars : Six Thousand Nine Hundred Only

PAL'S

APPRAISER PTE LTD

PHOTOCOPY

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417853
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Billing Name & Address

Wong Kok Heng
Blk 622B Punggol Central
#14-266 Punggol Spectra
Singapore 822622

Invoice No 11-18007/AY

Date 28 Nov 2018

Vehicle No : SLR 8339 J

Model : Honda Vezel

Item	Descriptions	Amount S\$
1	Date of inspection : <u>8 Nov 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>106</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 781.00</u>
	SDLS : SEVEN HUNDRED AND EIGHTY-ONE ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 11-18007/AY / 2018

Date of Report : 28 Nov 2018

Wong Kok Heng
Blk 622B Punggol Central
#14-266 Punggol Spectra
Singapore 822622

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 7 Nov 2018

As per your instruction dated 8 Nov 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLR 8339 J. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLR 8339 J
Model : Honda Vezel
Year / Capacity : 2017/1496
Chassis No : RU3-1245356
Engine No : LEB5945359
Mileage : 59197
Colour : Silver

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 215/55 R17	Yokohama	6.00	mm	Sport
REAR	O/S	: 215/55 R17	Yokohama	6.00	mm	Sport
FRONT	N/S	: 215/55 R17	Yokohama	6.00	mm	Sport
REAR	N/S	: 215/55 R17	Yokohama	6.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Revol Carz Garage Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
#02-18 Ang Mo Kio Autopoint
Singapore 568047

5. Estimated normal period of repair : 7 working days to complete.
6. Enclosed number of photograph : 106 copies.
7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SLR 8339 J
Report No: TP/ 11-18007/AY / 2018

X-SVC, 16/4/19 RGS41

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear windscreen inner seal	Necessary	\$ 85.00	\$ 85.00
1	Rear tailgate	Damage	\$ 1583.50	\$ 1583.50/072
1	Rear tailgate inner board	Damage	\$ 638.00	\$ 638.00 288
2	Rear tailgate lamps	Intact <i>nn</i>	\$ 560.00	\$
1	Rear tailgate lock	Damage	\$ 210.00	\$ 210.00
1	Rear tailgate logo	Intact <i>nn</i>	\$ 32.00	\$
1	Rear tailgate outer garnish	Intact <i>nn</i>	\$ 187.00	\$
1	Rear tailgate rubber	Necessary	\$ 195.00	\$ 195.00
1	Rear tailgate 'VEZEL' emblem	Necessary	\$ 75.00	\$ 75.00 48
1	Rear tailgate 'HYBRID' emblem	Necessary	\$ 76.00	\$ 76.00
2	Rear taillamps	O/S Damage	\$ 1500.00	\$ 750.00 X SVC
1	Rear end panel	Repair	\$ 675.90	\$
1	Rear end panel inner garnish	Damage	\$ 128.90	\$ 128.90
1	Rear o/s side bumper	Damage	\$ 259.00	\$ 259.00 repair
1	Rear bumper	Damage	\$ 936.10	\$ 936.10 762
1	Rear bumper o/s reflector	Damage	\$ 181.00	\$ 181.00 X SVC
2	Rear bumper side retainers	Damage	\$ 88.00	\$ 88.00 X SVC
1	Rear exhaust silencer	Damage	\$ 990.00	\$ 990.00 X SVC
2	Rear exhaust silencer mountings	Necessary	\$ 47.00	\$ 47.00 X SVC
1	Rear o/s fender	Repair	\$ 995.00	\$
1	Rear o/s fender arch garnish	Damage	\$ 395.00	\$ 395.00 X SVC
			\$ 9837.40	\$ 6637.50 2864.90
	Discount 20.0%		\$ 1967.48	\$ 1327.50 208
			\$ 7869.92	\$ 5310.00 2291.92
<u>Special Nett Items</u>				
1	Rear quarter glass sealant	Necessary	\$ 60.00	\$ 50.00 X SVC
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00 200
1	Rear reverse camera	Intact <i>nn</i>	\$ 480.00	\$
1	Paint protection (ze tough foundation)	Necessary	\$ 1200.00	\$ 1200.00 X
			\$ 2020.00	\$ 1530.00

no invoice

200

Spare Parts Total \$ 9889.92 \$ 6840.00

Vehicle No: SLR 8339 J
Report No: TP/ 11-18007/AY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 9889.92	\$ 6840.00
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00 X
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 120.00	\$ 80.00 60
3	To remove and refit rear bumper sensor.	\$ 120.00	\$ 80.00 60
4	To remove and refit rear windscreen glass.	\$ 200.00	\$ 120.00 /
5	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 100.00	\$ 80.00 X
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1100.00	\$ 660.00 500
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1100.00	\$ 660.00 600
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 90.00 40
Total		\$ 12829.92	\$ 8650.00 1380

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 6900.00

SDLS: SIX THOUSAND NINE HUNDRED ONLY


Qualified Appraiser

2291.92
200.00
1380.00
3871.92
202
3097.53
45-3,100
5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/AIG19005494/R1vd3e2		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 22-04-2019		
ATTN : LEE MING YAO		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SLP 5714P	Veh. Inspected	SLR 8339J	
Policy No.		Coverage (\$)	0.00	
Claim No.	4413310392SG	Excess (\$)	0.00	
Assign From	LEE MING YAO	Assign Date	27/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID 1.5X A	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31245356	Colour	GREY	
Odometer	669600	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	MICHELIN	5 mm	
L/H Front Tyre	225/50 R18	MICHELIN	5 mm	
R/H Rear Tyre	225/50 R18	MICHELIN	5 mm	
L/H Rear Tyre	225/50 R18	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	07/11/2018	Inspection Date	29/03/2019	
Survey held at	HABOURFRONT TOWER 1 CARPARK			
Repairer	REVOL CARZ GARAGE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8339J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN INNER SEAL	REPLACED	85.00	85.00
1	REAR TAILGATE	REPLACED	1,583.50	1,072.00
1	REAR TAILGATE INNER BOARD	REPLACED	638.00	288.00
2	REAR TAILGATE LAMPS	NOT NECESSARY	560.00	-
1	REAR TAILGATE LOCK	REPLACED	210.00	210.00
1	REAR TAILGATE LOGO	NOT NECESSARY	32.00	-
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	187.00	-
1	REAR TAILGATE RUBBER	REPLACED	195.00	195.00
1	REAR TAILGATE "VEZEL" EMBLEM	REPLACED	75.00	48.00
1	REAR TAILGATE "HYBRID" EMBLEM	REPLACED	76.00	76.00
2	REAR TAILLAMPS	SERVICEABLE	1,500.00	-
1	REAR END PANEL	REPAIRED SEE LABOUR	675.90	-
1	REAR END PANEL INNER GARNISH	REPLACED	128.90	128.90
1	REAR O/S SIDE BUMPER	REPAIRED SEE LABOUR	259.00	-
1	REAR BUMPER	REPLACED	936.10	762.00
1	REAR BUMPER O/S REFLECTOR	SERVICEABLE	181.00	-
2	REAR BUMPER SIDE RETAINERS	SERVICEABLE	88.00	-
1	REAR EXHAUST SILENCER	SERVICEABLE	990.00	-
2	REAR EXHAUST SILENCER MOUNTINGS	SERVICEABLE	47.00	-
1	REAR O/S FENDER	REPAIRED SEE LABOUR	995.00	-
1	REAR O/S FENDER ARCH GARNISH	SERVICEABLE	395.00	-
	LESS 20% DISCOUNT		-1,967.48	-572.98
			7,869.92	2,291.92
SPECIAL NETT ITEMS				
1	REAR QUARTER GLASS SEALANT (SN)	SERVICEABLE	60.00	-
1	SET REAR REVERSE SENSOR (SN)	REPLACED	280.00	200.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	480.00	-

Report Ref No. CS/AIG19005494/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PAINT PROTECTION (ZE LOUGH FOUNDATION)(SN)	NO INVOICE	1,200.00	-
			2,020.00	200.00
	LABOUR			
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.	NOT NECESSARY	50.00	-
	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.		120.00	60.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		120.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		200.00	120.00
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	100.00	-
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR END PANEL, REAR O/S SIDE BUMPER AND REAR O/S FENDER.		1,100.00	500.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,100.00	600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		150.00	40.00
			2,940.00	1,380.00
GRAND TOTAL			12,829.92	3,871.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CS/AIG19005494/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.