

ASS. REC. BY:

REF: CS/MSG 190054961 UV d3 n2

Special Instruction:

SUPERVISOR: Marcus
Merimen

ASSIGNMENT (Office)

From (Person): Katherine Wong Chow Shong of MSLG Date/Time: 27.3.2017

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJU 8394 G Insured: GY 5023 L

at Workshop m/s ACE Autolutionⁿ Tel: 6844 1184

of 13 kaki Bukit Road 4 # 03-29

Policy No: MSD/VCFT/18-001083 Claim No: MSC/V/19-000357

Sum Insured: Excess:

Make of Veh: D.O.A. 22.3.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement:

Date/Time: 28.3.19 9.16a.m Person Contacted: Anna Vehicle: IN OUT


Date/Time	Action/Instruction (✓) Estimate
	SJU 8394 G - A
	GY 5023 L - CS / CTI 19005356 / Asd 3 D.O.A. - 22/3/2019
29/3/19	Informed Katherine pending workshop est via merimen
28/6/19	Send preli revised via merimen

ASSIGNMENT

From: _____ Date: 28.3.2019
 Estimated Cost: _____
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJU 83949
 at Workshop m/s ACE AutoLution
 of 13 Kaki Bukit Road 4 #03-29
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJU 83949 Yr Regn: 3/12/09
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda stream c.c. 1799
 Colour: black A/C: Insured / Std / NI / NA
 Sp. Reading: 115534 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMRN 6809.5 200929
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/60R16
 R: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 20k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS "w/p"
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 22/3/19 D.O.I. 28/3/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>LTA 14/87 9th. 2445819</u>
<u>27/6/19</u>	<u>confund r/s #4022 with Ann9 (Red 889.12, 6910)</u>

RECEIVED 28 JUN 2019

[Signature]
28/6/2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) 28/6 - typist
 Report Format: merimen
 Lump Sum / I.B.I: (\$) 4000

Days Of Repair: 5
 Resurvey No. of Trip: 2
 Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee:	<u>200</u>
Transportation:	<u>11</u>
S + RS, SI	
Photos	
Others	
TOTAL	<u>211</u>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Katherine Wong	
Date: 28 Jun 2019	
<h3 style="margin: 0;">Preliminary Advice</h3>	

Insured Vehicle No : GY5023L	Accident Date : 22/03/2019
TP Vehicle No : SJU8394G	Assignment Date : 27/03/2019
Make : HONDA STREAM	Est. Duration of Repair : 5
Date of Inspection : 28/3/2019	
Inspection At : ACE AUTOLUTION PTE LTD	

PTE LTD

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,891.12
Revised Amount	:S\$	4,000.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,000.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Mar 2019 11:55		27 Mar 2019 17:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	SUNPRO PTE LTD, Co. Reg. No.: 198402742Z		
Main Claimant:	CHUA HONG KEE, ID: S7609651A		
Vehicle Reg. No.:	SJU8394G	Date of Loss:	22/03/2019 10:00 - :59 [110 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/19-000357	Policy/Cover Note No.:	MSD/VCFT/18-001083 (TP, Fire & Theft) Coverage: 28/10/2018 - 27/10/2019
Vehicle Reg. No. (Insured):	GY5023L	Policy No. (Claimant):	
Repairer:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/03/2019]		
Driver/Custodian (Insured):	LEE PUNG (), NRIC: S1455133F Email:		
Adj Asg. Remarks:	Liability clear. TP want to use Marcus Chua frm LKK as the SJE. Contact Person: Ms Anna / 6844 1184. On WP.		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

View Sent Message

This mail is associated with :

***SJU8394G (MSC/V/19-000357)**
[GY5023L]

TP
CHUA HONG KEE
Mar 22 2019 10:00AM
[SUNPRO PTE LTD]
Ace Autolution

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **29/03/2019 14:14 PM.**
To MSI_WCS
Subject TP SURVEY SJU 8394G

Dear Katherine,

Please be informed that we have inspected the vehicle SJU 8394G on 28/3/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.



DON'T FALL FOR HER ONLINE PURCHASE SCAM

CLICK TO FIND OUT MORE AT www.scamalert.sg



honda stream Price Range Depreciation 2009 Vehicle Type Submit

Advanced Search

Home » Used Cars » Phoenix Motor Trading Enterprise » Honda Stream 1.8A X

Honda Stream 1.8A X

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$16,800	Reg Date	07-Jul-2009 (3mths 8days COE left)
Depreciation	N.A.	Manufactured	2008
Mileage	126,438 km (13k /yr)	Transmission	Auto
Road Tax	\$978 /yr	OMV	\$22,151
Dereg Value	\$11,489 as of today (change)	ARF	\$22,151
COE	\$15,100	Power	103.0 kW (138 bhp)
Engine Cap	1,799 cc	No. of Owners	4
Curb Weight	1,350 kg		
Type of Vehicle	MPV		



Location Map

Shortlist Compare Add note
Report Error More Actions

Features

View specs of the Honda Stream (2007-2014)

Description

100% Loan. Good Condition.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 28-Mar-2019 | Last Updated on: 28-Mar-2019

» more Financial info

Upfront Payment

Transfer Fee	\$25	
Down Payment	\$5,040 (change)	Maximum 70% Loan
1st Instalment	\$3,949	Based on 2.98% interest rate

Compare

Seller Information

Company	Phoenix Motor Trading Enterprise » dealer's pricelist » 5 vehs sold 9 vehs available	
Address	Blk 152 Mei Ling Street #01-06 Search cars nearby this location	
Office No	62766662	
Contact Person (s)	Patrick Mr Ng Eng Jie Cindy	93881918 91456234 91000173 91841055
Enquiry	Contact Seller	

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9651A
Vehicle Details	
Vehicle No.:	SJU8394G
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	R18A13800930
Chassis No.:	JHMRN68609S200929
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$25,671.00
Original Registration Date:	30 Dec 2009
First Registration Date:	30 Dec 2009
Transfer Count:	2
Actual ARF Paid:	\$25,671.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2019
PARF Rebate Amount:	\$12,835.00
Intended COE Rebate Details	
COE Expiry Date:	29 Dec 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$13,836.00
COE Rebate Amount:	\$1,346.00
Total Rebate Amount:	\$14,181.00

The information contained herein is correct as at 28 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/03/2019 16:55
Date Of Accident	22/03/2019 10:20
Exact Location Of Accident	PIE TOWARDS TUAS(JALAN BAHAR EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU8394G
Insured/Policyholder	
Name Of Registered Owner	CHUA HONG KEE
NRIC No	S7609651A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90102908
Alternative Phone No	OTHERS-90102908

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM 1.8L A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHUA HONG KEE
NRIC No	S7609651A
Date Of Birth	01/04/1976
Occupation	INDOOR
Date Of Driving Pass	04/03/1994
Driving Experience	25 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90102908
Fax Number	
Contact Number	OTHERS-90102908
EMail Address	NOEMAIL

Address 357A ADMIRALTY DRIVE #05-154 SPORE 751357
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GY5023L
 Vehicle Make/Model/Colour MITSUBISHI L300 HR M
 Details Of Properties
 Vehicle Category GOODS VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJQ2389H

Vehicle Make/Model/Colour	TOYOTA VIOS G AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: _____

Driver's Signature
(if driver is not the policyholder)
Date & Time: _____


Reporting Centre Personnel's Signature
Name: **SUHAIMI**
NRIC/FIN No.: **58040377A**

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/2/19 AT 10:20AM I WAS DRIVING ALONG PJE TO T4AS EXIT TO JALAN BAHAR. WHEN APPROACHING TO EXIT AT JALAN BAHAR I HAD STOP AT THE EXIT WHILE WAITING FOR THE MAIN JUNCTION TRAFFIC TO BE CLEAR, SUDDENLY I FELT AN IMPACT TO MY CAR FROM BEHIND ME GY 5033 L AND LAST VEHICLE FOLLOW BEHIND SSQ 2389 H. ~~THEY WERE IN~~

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: SUHAIMI
 NRIC/FIN No.: 58040377A



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

not Adjusted
 Mark
 2/5 \$4000
 Schy.
 28/3/18

Page No. 1
 Zuhairi-Attorney

Vehicle No. SJU8394G HONDA STREAM

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR TAILGATE	Soldy 20	1083.80	/
1	REAR TAILGATE LOCK	20/shokh	135.00	/
1	REAR TAILGATE LOCK CATCH	11	84.00	X
2	REAR TAILGATE DAMPER LH & RH @\$335.00	11	670.00	X
2	REAR TAILGATE HINGE LH & RH @\$101.00	11	202.00	X
1	REAR TAILGATE WEATHERSTRIP	7w1	150.90	/
1	REAR TAILGATE "STREAM" EMBLEM	rel	70.00	/
1	REAR TAILGATE LOGO	rel	80.00	/
1	REAR TAILGATE OUTER HANDLE	Daye/cne	95.00	/
1	REAR TAILGATE GLASS MOULDING	rel	101.00	/
1	REAR TAILGATE OUTER MOULDING	Rejurd	210.00	X
1	REAR TAILGATE 3RD BRAKE LAMP	11	235.00	X
1	REAR TAILGATE INNER BOARD	Re/cne	320.00	/
1	REAR BUMPER	20/70-1	859.00	/
2	REAR BUMPER SIDE RETAINER LH & RH @\$91.00	11	182.00	X
1	REAR BUMPER TOW HOCK COVER	70-1	131.00	/
2	REAR TAILLAMP LH & RH @\$510.00	M/cne	1020.00	100
2	REAR TAILLAMP PANEL LH & RH @\$215.00	R	430.00	X
2	REAR FENDER LH & RH @\$816.30	R	1632.60	X
2	REAR FENDER GLASS MOULDING LH & RH @\$80.00	11	160.00	X
1	REAR WIPER MOTOR	11	118.60	X
1	REAR END PANEL INNER	NS	375.00	X
1	REAR END PANEL OUTER	Soldy 20	445.00	/
1	REAR END PANEL TOP GARNISH	20/7w1	175.00	/
1	REAR CHASSIS MEMBER RH	11	625.00	X
1	REAR SPARE TYRE BRACKET	11	189.00	X
1	REAR SPARE TYRE ADJUSTER LEVEL	11	210.00	X
			9988.90	
		less 20%	1997.78	20%
			7991.12	
SPECIAL NETT ITEMS				
1 SET	REVERSE SENSOR	shokh	280.00	200
1	REAR END PANEL SEALANT	rel	100.00	50
1 SET	REAR END PANEL TOP GARNISH CLIPS	11	80.00	X
1 SET	REAR TAILGATE INNER TRIM CLIPS	rel	60.00	35
1 SET	REVERSE CAMERA	rel	430.00	X SVC
1	REAR WINDSCREEN SEALANT	rel	100.00	40
1	REAR WINDSCREEN INNER seal	rel	120.00	40
1 SET	REAR BUMPER CLIPS	rel	80.00	40
1 SET	REAR CAR PLATE WITH HOLDER	11	70.00	X
Total Parts			9311.12	

3069.7
 2455.70



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

Vehicle No. SJU8394G HONDA STREAM

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00 -	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00 -	1000
3	To remove and refix wiring at damaged areas	180.00 -	30
4	To perform anti rust treatment on affected areas	150.00 -	80
5	To remove / refix windscreen	150.00 -	120
6	To transfer bootlid mechanism	100.00 -	60
7	To remove and replace reverse sensor , and test	100.00 -	50
8	To conduct water seepage test	100.00 ✓	X
	Labour Total :	3580.00	
TOTAL (PARTS & LABOUR) :		12891.12	

5000.70

ACE Auto Consultants hence notify the Repairer of the following:

- To resurvey before the repair is starting
- To conduct the repair work actively
- To provide the required completion
- To provide the repair on "Without Prejudice" basis
- No to be held liable for any accident
- Supplemental charges must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19005496/UVD3N2
Date: 03/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCFT/18-001083
Claimant Vehicle No :	SJU8394G	Insured Vehicle No :	GY5023L
Date of Loss:	22/03/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000357

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU8394G	Engine No:	R18A13800930
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN68609S200929
Reg. Date:	30/12/2009 (Man. Year: 2008)	Odometer:	115534 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,311.12	2,860.76	6,450.36	69.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,140.00	1,440.00	40.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,891.12	5,000.76	7,890.36	61.21
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	12,891.12	4,000.00	8,891.12	68.97

INSPECTION

Date of Assignment:	27/03/2019	
Date Inspected:	28/03/2019	Inspected At:
		Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2019)	
Parts: M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SJU8394G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,083.80 FL	*903.20 FL
2	1		*REAR TAILGATE LOCK	Dented/Shorted	135.00 FL	*109.40 FL
3	1		*REAR TAILGATE LOCK CATCH	Not Necessary	84.00 FL	*- FL
4	2		*REAR TAILGATE DAMPER LH & RH	Not Necessary	670.00 FL	*- FL
5	2		*REAR TAILGATE HINGE LH & RH	Not Necessary	202.00 FL	*- FL
6	1		*REAR TAILGATE WEATHERSTRIP	Twisted	150.90 FL	*121.60 FL
7	1		*REAR TAILGATE STREAM EMBLEM	Necessary	70.00 FL	*31.60 FL
8	1		*REAR TAILGATE LOGO	Necessary	80.00 FL	*30.80 FL
9	1		*REAR TAILGATE OUTER HANDLE	Damaged/Cracked	95.00 FL	*95.00 FL
10	1		*REAR TAILGATE GLASS MOULDING	Necessary	101.00 FL	*65.10 FL
11	1		*REAR TAILGATE OUTER MOULDING	Repeated	210.00 FL	*- FL
12	1		*REAR TAILGATE 3RD BRAKE LAMP	Not Necessary	235.00 FL	*- FL
13	1		*REAR TAILGATE INNER BOARD	Deformed/Cracked	320.00 FL	*241.10 FL
14	1		*REAR BUMPER	Dented/Torn	859.00 FL	*638.00 FL
15	2		*REAR BUMPER SIDE RETAINER LH & RH	Not Necessary	182.00 FL	*- FL
16	1		*REAR BUMPER TOW HOCK COVER	Torn	131.00 FL	*25.00 FL
17	1		*REAR TAILLAMP LH & RH	N/s Cracked	1,020.00 FL	*385.50 FL
18	2		*REAR TAILLAMP PANEL LH & RH	Repair	430.00 FL	*- FL
19	2		*REAR FENDER LH & RH	Repair	1,632.60 FL	*- FL
20	2		*REAR FENDER GLASS MOULDING LH & RH	Not Necessary	160.00 FL	*- FL
21	1		*REAR WIPER MOTOR	Not Necessary	118.60 FL	*- FL
22	1		*REAR END PANEL INNER	No such part	375.00 FL	*- FL
23	1		*REAR END PANEL OUTER	Badly Dented	445.00 FL	*306.70 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed/Twisted	175.00 FL	*116.70 FL
25	1		*REAR CHASSIS MEMBER RH	Not Necessary	625.00 FL	*- FL
26	1		*REAR SPARE TYRE BRACKET	Not Necessary	189.00 FL	*- FL
27	1		*REAR SPARE TYRE ADJUSTER LEVEL	Not Necessary	210.00 FL	*- FL
28	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
30	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
31	1		*SET REAR TAILGATE INNER TRIM CLIPS	Necessary	60.00 FS	*35.00 FS
32	1		*SET REVERSE CAMERA	Serviceable	430.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*REAR WINDSCREEN INNER SEAL	Necessary	120.00 FS	*40.00 FS
35	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
36	1		*SET REAR CAR PLATE WITH HOLDER	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,308.90	3,474.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,997.78	613.94
Total Parts (\$\$)	9,311.12	2,860.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	800.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	1,000.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	80.00
5	TO REMOVE/REFIX WINDSCREEN	New	150.00	120.00
6	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
7	TO REMOVE AND REPLACE REVERSE SENSOR,AND TEST	New	100.00	50.00
8	TO CONDUCT WATER SEEPAGE TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			3,580.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >