

23/03/2019

ASS. REC. BY:

REF:

CS/ICS19005511/A40307

Special Instruction:

Mentem

Admin

ASSIGNMENT (Office)

From (Person):

Desmond Lee

of

ICS

Date/Time:

28/3/19 @ 11:29am

Estimated Cost:

Bill to:

 OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV /  CS

To Inspect Vehicle No:

SJE 2266S

Insured:

Prog -  
mr Wong - 82983043

at Workshop n/s

First Autoworks

Tel:

68441985 / 82925595

of

23 Kaki Bukit Ave 4

Policy No:

MPC 18A 00336201

Claim No:

DMPC 1900081H / DL

Sum Insured:

Excess:

TBA 400

Make of Veh:

(Client's Record)

D.O.A. 23/03/2019

CA /  REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:40am @ 28/3/19

Person Contacted:

Rony

Vehicle IN /  OUT

Date/Time	Action/Instruction (✓) Estimate	*Pls ref to Insurance Instruction pg. 3
	SJE 2266S-CS/ICS19005511/A403	Dot: 28/3/19
11/4 @ 9:40am	- sent quotation to workshop.	
11/4 @ 11:35	- Revert via menmen.	
3/4 @ 2:35pm	- email kelun if able repair. within \$35k	
5/4 @ 10:15	- veimandate on all in \$35k, upload email to menmen from workshop undertake at \$35k.	

REF: ICS

## ASSIGNMENT

From: \_\_\_\_\_ Date: 29/3/19

Estimated Cost: \_\_\_\_\_

OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV

To inspect Vehicle No: SJE2266S

at Workshop mis: First Autoworks

of: 23 Kalki Bkt Ave 4 #04-01

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: TBA

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 12 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA /  REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

N/S	O/S

Veh No: SJE2266S- Yr Regn: 2017 / REC.

Type:  M.Cap /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Opel Astra Sports Tourer 999

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WOVBE8EAG48101850

Gen. Cond:  Good /  Fair /  Poor /  Burnt

Steering:  Inorder /  Jammed /  Leaked /  Burnt or \_\_\_\_\_

Brake:  Inorder /  Jammed /  Leaked /  Burnt or \_\_\_\_\_

Modi: Nil /  S/Rim /  STD A/Rim or \_\_\_\_\_

Tyre Size: F: 225/45R17.

R: 225/45R17.

BS /  DUN /  EXNOVA /  GY /  FS /  LIZA /  MIC /  OHTSU /  PIR /  SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 29/03/19.

Survey held at: First Auto Germany.

Des. of Damages:  Fnt /  Rear /  O/S /  N/S /  U/C /  Roof/top or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD ECICS.

The vehicle is rare

05/4/19 @ 5.39 AM Jeffrey Chew informed CIA at 635K on Meridian.

MV: 73K

PV: 35K

Nett: 42K.

08/4/19 @ 9.07 AM Informed Vincent Sim CIA at 635K (Call-in) on PIP B 8084000 by email.

Final PIP @ 35000, 12 days (Red @ 25058.60, 42%).

Date/Time, File Pass to?  : Preli. Report

1) 30/4/19  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 12

Resurvey No. of Trip: 1

Report Format: MER-09

Lump Sum / I.B.I. (\$) 35000

Add Fee:  Site Insp (\$ )

Interview (\$ )

Tech Invs (\$ )

Weekend (\$ )

Survey Fee:	460
Transportation:	
S + RS, \$	
Photos	
Others	11
TOTAL	471

**Nivitha (LKK Auto)**

---

**From:** Desmond Lee Ker Wen (ECICS, Claims) <Desmond\_Lee@ecics.com.sg>  
**Sent:** Thursday, 28 March 2019 11:36 AM  
**To:** assignments; olivialau@lkkauto.com  
**Subject:** FW: SJE2266S - OPEL ASTRA - OWN DAMAGED CLAIM - ECICS - DOA 23-3-2019 // OUR CLAIMS REF NO: DMPC1900081H/DL  
**Attachments:** SJE2266S- OWN DAMAGED.PDF; SJE2266S\_ESTIMATE PG 3.jpg; SJE2266S\_ESTIMATE PG 2.jpg; SJE2266S\_ESTIMATE PG 1.jpg; LIST OF AUTHORISED WORKSHOPS-REVISED AS OF 02.05.18 (2).pdf  
**Importance:** High

Dear Sir / Madam

I have special instructions for you guys in this case.

\*\*\*\*\*

For the abovementioned workshop,  
Please get a 2<sup>nd</sup> quote from one of our authorised workshop. ( Please find attached list of authorised workshop)  
No approval is to be granted to Alpine Motor and/or it's associated workshops till we obtain the 2<sup>nd</sup> COR after the adjustment by the surveyor.

If the 2<sup>nd</sup> COR is lower, offer to Alpine based on the 2<sup>nd</sup> COR that has been adjusted by surveyor.

If they cannot agreed, we will tow the vehicle the vehicle to the authorised workshop or alternative, policyholder top up the different.

\*\*\*\*\*

Please do not share the above information.

Thank you.

Do contact me if you need more details.

Best regards

**Desmond Lee**

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email [Desmond\\_Lee@ecics.com.sg](mailto:Desmond_Lee@ecics.com.sg)

Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** Desmond Lee Ker Wen (ECICS, Claims)  
**Sent:** Thursday, 28 March 2019 11:29 AM  
**To:** 'assignments'; suhalmi@alpinemotors.sg; Kelvin Chew; vincent.sim@alpinemotors.sg

**Nivitha (LKK Auto)**

---

**From:** Desmond Lee Ker Wen (ECICS, Claims) <Desmond\_Lee@ecics.com.sg>  
**Sent:** Thursday, 28 March 2019 11:29 AM  
**To:** assignments; suhaimi@alpinemotors.sg; Kelvin Chew; vincent.sim@alpinemotors.sg  
**Subject:** FW: SJE2266S - OPEL ASTRA - OWN DAMAGED CLAIM - ECICS - DOA 23-3-2019 // OUR CLAIMS REF NO: DMPC1900081H/DL  
**Attachments:** SJE2266S- OWN DAMAGED.PDF; SJE2266S\_ESTIMATE PG 3.jpg; SJE2266S\_ESTIMATE PG 2.jpg; SJE2266S\_ESTIMATE PG 1.jpg

Dear Sirs

We will be appointing LKK for the OD survey.

Best regards

**Desmond Lee**

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email [Desmond\\_Lee@ecics.com.sg](mailto:Desmond_Lee@ecics.com.sg)

Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** motorsurvey

**Sent:** Thursday, 28 March 2019 11:03 AM

**To:** Desmond Lee Ker Wen (ECICS, Claims)

**Cc:** suhaimi@alpinemotors.sg; Kelvin Chew; motorsurvey; vincent.sim@alpinemotors.sg

**Subject:** RE: SJE2266S - OPEL ASTRA - OWN DAMAGED CLAIM - ECICS - DOA 23-3-2019

Dear Desmond

Ref : DMPC1900081H/DL

FYNA.

Best regards

**Crystabelle Tan**

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg)

Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

**From:** Vincent Sim [mailto:vincent.sim@alpinemotors.sg]  
**Sent:** Thursday, 28 March, 2019 8:20 AM  
**To:** motorsurvey  
**Cc:** suhaimi@alpinemotors.sg; Kelvin Chew  
**Subject:** SJE2266S - OPEL ASTRA - OWN DAMAGED CLAIM - ECICS - DOA 23-3-2019

Dear Sir/Madam,  
Kindly dispatch surveyor to inspect on the above .

Vehicle location is at :  
Person in charge :-  
Suhaimi , Kelvin – 82925595 H/P .  
68441985 – office phone  
E-mail ;  
[suhaimi@alpinemotors.sg](mailto:suhaimi@alpinemotors.sg)  
[Kelvin.chew@alpinemotors.sg](mailto:Kelvin.chew@alpinemotors.sg)

Add;  
First Autoworks Pte Ltd  
23, Kaki Bukit Ave 4  
#04-01 ( South Wing )  
singapore 415933  
( Vicom Building )  
tel; 6844-1985

Regards,  
Vincent Sim- Claims Dept

Alpine Motors Pte Ltd / Auto Germany Pte Ltd

[vincent.sim@alpinemotors.sg](mailto:vincent.sim@alpinemotors.sg)

65113022 ext 343

H/P 9247-8842

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 8 April 2019 9:07 AM  
**To:** vincent.sim@alpinemotors.sg; suhaimi@firstautoworks.com.sg  
**Cc:** SUR; Kelvin.chew@alpinemotors.sg  
**Subject:** RE: SJE 2266S / OD / ECICS

Dear Vincent,

As instructed by our client , please proceed to repair the insured vehicle SJE 2266S at repair cost \$35,000.00 (all-in) on part by part basis (Excess \$4,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewse@lkkauto.com](mailto:siewse@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 5 April 2019 9:57 AM  
**To:** vincent.sim@alpinemotors.sg; suhaimi@firstautoworks.com.sg  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Kelvin.chew@alpinemotors.sg  
**Subject:** RE: SJE 2266S / OD / ECICS

Dear Vincent,

Excess \$4000,

Noted on your undertake of all in \$35k, we will update you on the authorization after insurance approve has been given.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Vincent Sim <[vincent.sim@alpinemotors.sg](mailto:vincent.sim@alpinemotors.sg)>  
**Sent:** Friday, 5 April 2019 9:43 AM  
**To:** Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>; [suhaimi@firstautoworks.com.sg](mailto:suhaimi@firstautoworks.com.sg)

Cc: SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; [Kelvin.chew@alpinemotors.sg](mailto:Kelvin.chew@alpinemotors.sg)

Subject: RE: SJE 2266S / OD / ECICS

Denise,  
Could we know the excess \$ ???

Regards,  
Vincent Sim- Claims Dept

Alpine Motors Pte Ltd / Auto Germany Pte Ltd

[vincent.sim@alpinemotors.sg](mailto:vincent.sim@alpinemotors.sg)

65113022 ext 343

H/P 9247-8842

---

**From:** "Suhaimi" <[suhaimi@firstautoworks.com.sg](mailto:suhaimi@firstautoworks.com.sg)>  
**Sent:** Friday, April 05, 2019 10:37 AM  
**To:** "Denise Tay (LKKAuto)" <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>  
**Cc:** "SUR" <[sur@lkkauto.com](mailto:sur@lkkauto.com)>, [vincent.sim@alpinemotors.sg](mailto:vincent.sim@alpinemotors.sg), "Kelvin.chew@alpinemotors.sg" <[Kelvin.chew@alpinemotors.sg](mailto:Kelvin.chew@alpinemotors.sg)>  
**Subject:** RE: SJE 2266S / OD / ECICS

Hi Denise,  
We'll undertake the repairs at \$35K

Thanks & Regards

Suhaimi Ong  
Service Executive  
1st Autoworks Pte Ltd  
23 Kaki Bukit Ave 4,  
#04-01 (South Wing)  
S'pore 415933  
Tel : 6844 1985  
Fax : 6844 5185

---

**From:** "Denise Tay (LKKAuto)" <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>  
**Sent:** Friday, 5 April, 2019 9:30 AM  
**To:** "[Kelvin.chew@alpinemotors.sg](mailto:Kelvin.chew@alpinemotors.sg)" <[Kelvin.chew@alpinemotors.sg](mailto:Kelvin.chew@alpinemotors.sg)>  
**Cc:** "[suhaimi@firstautoworks.com.sg](mailto:suhaimi@firstautoworks.com.sg)" <[suhaimi@firstautoworks.com.sg](mailto:suhaimi@firstautoworks.com.sg)>, "SUR" <[sur@lkkauto.com](mailto:sur@lkkauto.com)>, "[VINCENT.SIM@ALPINEMOTORS.SG](mailto:VINCENT.SIM@ALPINEMOTORS.SG)" <[VINCENT.SIM@ALPINEMOTORS.SG](mailto:VINCENT.SIM@ALPINEMOTORS.SG)>  
**Subject:** RE: SJE 2266S / OD / ECICS

Dear Vincent/Kelvin,

Please update check if you are able to repair all in \$35K.

Best Regards,  
Denise Tay | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)

**Sent:** Wednesday, 3 April 2019 2:36 PM

**To:** [Kelvin.chew@alpinemotors.sg](mailto:Kelvin.chew@alpinemotors.sg)

**Cc:** [suhaimi@firstautoworks.com.sg](mailto:suhaimi@firstautoworks.com.sg); SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** SJE 2266S / OD / ECICS

Dear Kelvin,

Please check if you are able to repair all in \$35K.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 Mar 2019 12:37	<b>Clim Dtl Modified</b>	Insured Name: -> CHIN YEW WEN. Insured ID: -> S1737239D.	[A] Nivitha Govindasamy
2	28 Mar 2019 12:37	<b>Clim Veh Model Changed</b>	(202407) OPEL ASTRA 1.4 J (A).	[A] Nivitha Govindasamy
3	28 Mar 2019 12:37	<b>Clim Created</b>	Reg No: SJE2266S. Policy No: MPC18A00336201. Acct Date: 2019/03/23. Claim Type: OD. Insurer: ECICS Limited (HQ). Workshop: First Autoworks Pte Ltd (HQ)	[A] Nivitha Govindasamy
4	28 Mar 2019 12:37	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ); RR Region: ECICS EXT ADJ - OD/TP. Suggested Adj. : Raleigh Services.	[A] Nivitha Govindasamy
5	28 Mar 2019 12:37	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/04/08	[A] Nivitha Govindasamy
6	28 Mar 2019 12:37	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
7	28 Mar 2019 12:38	<b>Adj Adjuster Assigned</b>	[None] -> ADRIAN LING	[A] Nivitha Govindasamy
8	01 Apr 2019 10:13	<b>Clim Registration Modified</b>	Rep:201872->201367.	[A] Nivitha Govindasamy
9	01 Apr 2019 10:18	<b>Adj Rpt Initiated</b>		[A] DENISE TAY KWEE CHENG
10	01 Apr 2019 10:18	<b>Ins Email Updated</b>	[None] -> [LENNON_YWCHIN@SINGNET.COM.SG]	[A] DENISE TAY KWEE CHENG
11	01 Apr 2019 10:18	<b>Clim Dtl Modified</b>	JPJ Reg. Date: -> 2019/03/01.	[A] DENISE TAY KWEE CHENG
12	01 Apr 2019 10:18	<b>Clim Details Notified</b>		[A] DENISE TAY KWEE CHENG
13	01 Apr 2019 11:05	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2019/04/08	[A] DENISE TAY KWEE CHENG
14	01 Apr 2019 11:35	<b>Adj Mandate Request</b>	Cur.Req:44148.80:PENDING 2ND QUOTATION FROM AUTHORIZE WORKSHOP	[A] DENISE TAY KWEE CHENG
15	02 Apr 2019 10:59	<b>Clim Registration Modified</b>	Excess: -> 1000.00.	[I] Desmond Lee
16	02 Apr 2019 11:06	<b>Clim Registration Modified</b>	Excess: 1000.00 -> 4000.00.	[I] Desmond Lee
17	02 Apr 2019 11:07	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/04/08. Mandate Remarks: Pending 2nd quote from authorize workshop	[I] Desmond Lee
18	02 Apr 2019 11:07	<b>Adj Mandate Set</b>	Maintained:Pending 2nd quote from authorize workshop	[I] Desmond Lee
19	05 Apr 2019 10:01	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2019/04/08	[A] DENISE TAY KWEE CHENG
20	05 Apr 2019 10:15	<b>Adj Mandate Request</b>	Cur.Req:35000.00:REPAIRER WILL UNDERTAKE AT \$35K ALL IN. DAMAGE CONSISTENT	[A] DENISE TAY KWEE CHENG
21	05 Apr 2019 16:19	<b>Adj Mandate Request Cancelled</b>		[A] DENISE TAY KWEE CHENG
22	05 Apr 2019 16:22	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2019/04/08	[A] DENISE TAY KWEE CHENG
23	05 Apr 2019 16:22	<b>Adj Mandate Request</b>	Cur.Req:35000.00:REPAIRER WILL UNDERTAKE AT \$35K ALL IN. DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
24	05 Apr 2019 17:39	<b>Adj Next Rpt Changed</b>	Cur Rpt:Final Rpt. Cur Due Date:2019/04/08. Mandate Remarks: Pending 2nd quote from authorize workshop	[I] Jeffrey Chew
25	05 Apr 2019 17:39	<b>Adj Mandate Set</b>	Approved:35000.00:Pending 2nd quote from authorize workshop	[I] Jeffrey Chew
26	05 Apr 2019 17:53	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2019/04/08	[A] DENISE TAY KWEE CHENG
27	05 Apr 2019 17:55	<b>Adj Mandate Request</b>	Cur.Req:35000.00:REPAIRER WILL UNDERTAKE AT \$35K ALL IN. DAMAGE CONSISTENT, REPAIR COST ECONOMICAL TO REPAIR	[A] DENISE TAY KWEE CHENG

Date From



Date To

Audit Type 

Go

### ACTIVITY

[28/03/2019 12:38] Nivitha Govindasamy:  
Please be informed that vehicle is not in the workshop, repairer will arrange.

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name	Ref 1	Ref 2	Amount
-------------	-----------	----------	----------	---------	-------	-------	--------

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Desmond Lee

Date: 05 Apr 2019

**Preliminary Advice**

Vehicle No	: SJE2266S	Accident Date	: 23/03/2019
Make	: OPEL ASTRA	Policy No.	: MPC18A00336201
Assignment Date	: 28/03/2019	Excess	: S\$4,000.00
Date of Inspection	: 29/03/2019	Est. Duration of Repair	: 12.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	59,913.80
Revised Amount	:S\$	35,864.80
Check Items (Estimated)	:S\$	8,284.00
Total	:S\$	44,148.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	34,955.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,045.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Repairer will undertake the repair at \$35,000/-.  
Base on repair cost \$35,000/-, the vehicle is economical to repair.  
Capacity: 999 Make and Model Opel Astra St 1.0AT

## Denise Tay (LKKAuto)

---

**From:** Suhaimi <suhaimi@firstautoworks.com.sg>  
**Sent:** Friday, 5 April 2019 9:37 AM  
**To:** Denise Tay (LKKAuto)  
**Cc:** SUR; vincent.sim@alpinemotors.sg; Kelvin.chew@alpinemotors.sg  
**Subject:** RE: SJE 2266S / OD / ECICS

Hi Denise,  
We'll undertake the repairs at \$35K

Thanks & Regards

Suhaimi Ong  
Service Executive  
1st Autoworks Pte Ltd  
23 Kaki Bukit Ave 4,  
#04-01 (South Wing)  
S'pore 415933  
Tel : 6844 1985  
Fax : 6844 5185

---

**From:** "Denise Tay (LKKAuto)" <denisetay@lkkauto.com>  
**Sent:** Friday, 5 April, 2019 9:30 AM  
**To:** "Kelvin.chew@alpinemotors.sg" <Kelvin.chew@alpinemotors.sg>  
**Cc:** "suhaimi@firstautoworks.com.sg" <suhaimi@firstautoworks.com.sg>, "SUR" <sur@lkkauto.com>, "VINCENT.SIM@ALPINEMOTORS.SG" <VINCENT.SIM@ALPINEMOTORS.SG>  
**Subject:** RE: SJE 2266S / OD / ECICS

Dear Vincent/Kelvin,

Please update check if you are able to repair all in \$35K.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 3 April 2019 2:36 PM  
**To:** Kelvin.chew@alpinemotors.sg  
**Cc:** suhaimi@firstautoworks.com.sg; SUR <sur@lkkauto.com>  
**Subject:** SJE 2266S / OD / ECICS

Dear Kelvin,

Please check if you are able to repair all in \$35K.

Best Regards,

PH - Wen Zheng. - unable quote. 冷门车.

Jenny Lai Hui - unable quote need new parts (busy)

Progressive - 35K all in (new parts) follow marking

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 01 Apr 2019

**Preliminary Advice**

Vehicle No	: SJE2266S	Accident Date	: 23/03/2019
Make	: OPEL ASTRA	Policy No.	: MPC18A00336201
Assignment Date	: 28/03/2019	Excess	: S\$0.00
Date of Inspection	: 29/03/2019	Est. Duration of Repair	: 12.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,913.80
Revised Amount	:S\$	35,864.80
Check Items (Estimated)	:S\$	8,284.00
Total	:S\$	44,148.80

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	34,955.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,045.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Pending 2nd quotation from authorise workshop

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 7239D

### Vehicle Details

Vehicle No.: SJE22665  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 25 Mar 2019  
Vehicle Make: OPEL  
Vehicle Model: ASTRA ST 1.0 AT  
Primary Colour: Black  
Manufacturing Year: 2017  
Engine No.: B1171587HRXX0070  
Chassis No.: W0VBE8EA6H8101850  
Maximum Power Output: 77.0 kW (103 bhp)  
Open Market Value: \$20,614.00  
Original Registration Date: 27 Dec 2017  
First Registration Date: 27 Dec 2017  
Transfer Count: 0  
Actual ARF Paid: \$5,860.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 26 Dec 2027  
PARF Rebate Amount: \$4,395.00

### Intended COE Rebate Details

COE Expiry Date: 26 Dec 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$38,200.00  
COE Rebate Amount: \$30,560.00  
**Total Rebate Amount: \$34,955.00**

The information contained herein is correct as at 25 Mar 2019

OK

Message Help Tell me what you want to do

File

Ignore Delete Archive Reply Forward More

Team Email Reply & Delete

Quick Steps To Manager Done Create New

Move OneNote Actions

Assign Policy Unread

Mark Categorize Follow Up

Translate

Find Related Select

Read Aloud Speech

Zoom

Mon 1/4/2019 9:40 AM

Denise Tay (LXKAUTO)

2ND OPINION QUOTATION OF S/E 22665

To

Cc

Bcc

'dramotor@singnet.com.sg'; 'progauto@progauto.com.sg'; 'jacob.arte@smemotor.com.sg'; 'sebastian@umemotor.com.sg'; 'unimasik@gmail.com'; 'BHAS - Mop Wen Zheng'; 'Ashley Tan'; 'janice.koh@bhauto.com.sg'; 'service@kkumbin.com.sg'; 'Jenny Lim'; 'simon@kkumbin.com.sg'; 'BHAS - Bernard Kee'; 'claims@progressbhauto.sg'

This is the most recent version, but you made changes to another copy. Click here to see the other versions.

LTA.pdf 183 KB

S/E 22665 PHOTOS.pdf 4 MB

ESTIMATE.pdf 859 KB

Dear All,

We have instructed by ECICS to get an 2<sup>nd</sup> opinion on the quotation for the above mention vehicle.

Hereby, we enclose the estimate, photograph and LTA record for your reference.

If there are any queries, please contact the undersign.

Please let us your quotation asap.

Best Regards,

Denise Tay | Case Handler

LXK Auto Consultants Pte Ltd

Microsoft Word 2013 Document - 2ND OPINION QUOTATION OF S/E 22665

Windows taskbar with icons for File Explorer, Mail, Internet Explorer, and others.

System tray: 9:47 AM, 1/4/2019, ENG, and notification icons.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 1 April 2019 9:31 AM  
**Cc:** SUR  
**Subject:** 2ND OPINION QUOTATION OF SJE 2266S  
**Attachments:** LTA.pdf; SJE 2266S PHOTOS.pdf; SJE 2266 ESTIMATE.pdf

Dear All,

We have instructed by ECICS to get an 2<sup>nd</sup> opinion on the quotation for the above mention vehicle.

Hereby, we enclose the estimate, photograph and LTA record for your reference.

If there are any queries, please contact the undersign.

Please let us your quotation asap.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/03/2019 14:00
Date Of Accident	23/03/2019 11:40
Exact Location Of Accident	PIE KALLANG AREA
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJE2266S
Insured/Policyholder	
Name Of Registered Owner	CHIN YEW WEN
NRIC No	S1737239D
Email Address	LENNON_YWCHIN@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-90672627
Alternative Phone No	OFFICE-90672627
Vehicle Particulars	
Manufacturer	OPEL
Model	ASTRA-1.4 J (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00336201
Cover Note Number	
Driver	
Name of Driver	ZENG TENG GABRIEL
NRIC No	S9902044Z
Date Of Birth	15/01/1999
Occupation	INDOOR
Date Of Driving Pass	25/01/2019
Driving Experience	0 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98369162
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	497B TAMPINES ST 45
Postcode	521497
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE REPORT ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD8521J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMH5516A
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

5 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

was driving and the second car was  
 the first then I couldn't stop in time  
 and being the second car

DECLARATION

(We declare the foregoing particulars are true in every respect)

*[Signature]*

Policeholder's Signature  
Date & Time:

25/3/2019

*[Signature]* 25/3/19

Driver's Signature  
(If driver is not the policeholder)  
Date & Time

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/ATS No:

## Sketch Plan #2

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1 - You must **correctly** the details of the accident to suit how the claims process.
- 2 - This form must be **completed by the Policyholder and/or the Authorized Driver**.
- 3 - Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow the insurer companies to **deny** its policy liability.
- 4 - The giving and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 - **Any false reporting may be referred to the Police for investigation.**
- 6 - The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 - By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 6 - Consent under the Personal Data Protection Act (PDPA)

I understand, am knowledgeable and consent that

- (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (ii) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (iii) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (iv) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (v) the information so collected under (i) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
  - (ii) regulators, law enforcement and government agencies as reasonable required for the purposes stated; or
  - (iii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time

23/3/2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

E 230319

Signature of the Personnel's Submission  
Name: \_\_\_\_\_  
NRIC/ID No.: \_\_\_\_\_



**CERTIFICATE OF INSURANCE**

Motor Vehicles (Third Party Risk Compensation) Act (Chapter 187)  
 Motor Vehicles (Third Party Risk and Compensation) Rules 1997  
 Road Transport Act, 1987 (Malaysia)  
 Motor Vehicles (Third Party Risk) Rules, 1997 (Malaysia)

**OPEL WORKSHOPS**  
 M200  
 COMPREHENSIVE  
 ORIGINAL

CERTIFICATE NO: **MPIC24818201**      Class No: **MPIC24818201000**  
 Agency Name: **ALPINE INSURANCE AGENCY PTB LTD**      Reg No: **00105170000000**  
 Agency Code: **3000002**

1. Index Mark and Registration Number of Vehicle: **NR22865**

2. Name of Policyholder: **CHIN YEW WEN**

3. Period of Insurance Cover dates inclusive: **21 December 2006 to 26 December 2006**


4. Permitted Classes of Persons entitled to use:  
 a) The Policyholder and all named drivers declared under the policy.  
 b) Any other person who is driving on the Policyholder's order or with his permission.  
 Provided that the person driving is conversant in accordance with the licensing or other laws of Singapore.  
 No other law motor vehicle is permitted nor is not authorized by order of a Court of Law or by order of any competent or jurisdiction in that regard from driving the motor vehicle.

5. Limitations of Use:  
 This cover is for the use of the vehicle for the purposes set out in the Policyholder's Declaration. The policy does not cover use for hire or reward, business, public liability, liability to third parties, or for any purpose not authorized with the Motor Trade.

6. EXCESS AND LIMITS:

WARRANTY	SGD 100.00
SECTION 7 - THIRD PARTY DAMAGE	SGD 1,000,000
SECTION 8 - LOSS OF USE AND LOSS OF PROFITS	SGD 1,000,000
SECTION 9 - LOSS OF USE AND LOSS OF PROFITS	SGD 1,000,000

7. Insured Vehicle Company: **AG BANK**

Signed for and on behalf of ECIC Limited  
  
 M. THIRUGANANATHAN

**Important Notice:**

- Policyholders are hereby advised that it shall be allowed for any person to be named as a driver or other person to use a motor vehicle under the policy.
- On the sale of a motor vehicle, Policyholders must surrender all insurance papers (including the Car/Bus/Truck) to the relevant authority and the policy to the relevant authority. If the Certificate of Insurance has been lost or destroyed, a duplicate Certificate of Insurance may be issued by the relevant authority with the appropriate fee in accordance with the Motor Vehicles (Third Party Risk and Compensation) Act (Chapter 187).
- The Certificate of Insurance and the Policy will cease to be valid once the motor vehicle is sold and is provided as follows:
- The Policyholder must advise the relevant authority in writing of the sale of the motor vehicle and the relevant authority will issue a new Certificate of Insurance.

Driving License





Identification Card- OWNER





# ANNOUNCING Autolink Holdings as sgCarMart Premium Dealer 2019



**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

For sale Alpha 2.44 Hybrid (New 10 Year COES)



Direct Owner

**Lake View Credit Pte Ltd** [www.lvc.com.sg](http://www.lvc.com.sg)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

opel astra

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
opel astra	Any	Any	2017	Any	Any	Any	Available



**Opel Astra 1.0A** \$69,000 \$7,990 /yr 18-Jul-2017 999 cc 19,000 km Hatchback Available

Near Perfect 9.5:10 Ratio Condition! Warranty And Fully Maintained By Agent From Day 1! Still Smells Like New In Cabin Due To Under Utilize! Low Mileage Done At 19,000KM! Comes With Free Servicing By ...

Posted: 23-Mar-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



**Opel Astra Sports Tourer 1.0A** \$74,900 \$8,500 /yr 28-Sep-2017 999 cc 35,000 km Stationwagon Available

5 Years Warranty & 5 Years Services (3 Years 7 Months Remaining), Excellent Condition! 100% Accident Free! Preferred Handover 29th March 2019.

Posted: 17-Mar-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



**Opel Astra Sports Tourer 1.0A** \$72,000 \$8,410 /yr 29-Jun-2017 999 cc 20,218 km Stationwagon Available

100% Accident Free, New Arrival! Auto Germany Unit! Full Agent Serviced And Maintained Since Day 1. 5 Years Warranty Until June 2022 Plus 3 Years Free Servicing. No Repairs Needed., Well Pristine Cond...

The Car Shop

Posted: 16-Mar-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



**Opel Astra Sports Tourer 1.0A** \$82,800 \$9,030 /yr 27-Dec-2017 999 cc 5,100 km Stationwagon Available

Best Value For Money Family Car With Adv Safety Features (6 Airbags), Classy Luxurious Interiors, Largest Boot Available In A Sedan/SUV. Powerful Turbo Engine FC 19 Kms/L. Doctor Owned And Driven As 2...

Carro

Posted: 13-Feb-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



**Opel's new Astra faces the Ford Focus**  
Opel has reinvented the Astra but are its segment-leading features and cabin space enough to sway buyers away from the well-loved Ford Focus?  
Read this article



**Opel Astra 1.4A** \$80,900 \$8,900 /yr 08-Jun-2017 1,399 cc 43,000 km Hatchback Available

Look No Further! Genuine Mileage With 1 Owner! Best Value For Your Money. Direct Owner's Beautiful White, Jun/2017 Opel Astra HB 1.4 AT(LED) With Grey Leather Upholstery, Selling Due To Upgrading To N...

Posted: 02-Feb-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



**Opel Astra 1.0A (OPC)** \$75,000 \$8,670 /yr 04-Aug-2017 999 cc 16,000 km Hatchback Available

Stylish, Comfortable And Performance-driven. Schedule A Test Drive Today, Viewing Is Strictly By Appointment Only.

Carro

Posted: 19-Jan-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel

Save this search criteria, to get email alerts whenever a match is found.

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Ex

20 results/page

Company



Date :25/03/2019

Reference: OPEL  
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE .:SJE2266S  
CHASSIS NO.: W0VBE8EA6H8101850  
ENGINE NO.: B1171587HRXX0070

Name of insured .: CHIN YEW WEN  
Date of accident.: 23.03.2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>distorted</i>	\$ 1,758.00
2	1	FRT BONNET LOCK <i>end</i>	\$ 312.00
3	1	FRT BONNET LOCK CABLE <i>Not nec</i>	\$ 277.00
4	1	FRT BONNET HINGE LH <i>Best</i>	\$ 186.00
5	1	FRT BONNET HINGE RH	\$ 186.00
6	4	FRT BONNET STOPER <i>missing</i>	\$ 40.00
7	1	FRT BUMPER <i>distorted</i>	\$ 1,994.00
8	1	FRT BUMPER TOW COVER <i>missing</i>	\$ 128.00
9	1	FRT BUMPER LOW LIP RH <i>3 for the other one</i>	\$ 156.00
10	1	FRT BUMPER LOW LIP LH	\$ 156.00
11	15	FRT BUMPER CLIP <i>new</i>	\$ 97.50
12	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>?</i>	\$ 136.00
13	1	FRT BUMPER SIDE RETAINER LH - UPP <i>?</i>	\$ 106.00
14	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
15	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
16	1	FRT BUMPER BRACKET LH <i>?</i> <i>distorted</i>	\$ 192.00
17	1	FRT BUMPER BRACKET RH <i>?</i> <i>distorted</i>	\$ 192.00
18	1	FRT BUMPER UNDER DUST COVER <i>new</i>	\$ 290.00
19	1	FRT BUMPER BRACKET TOP CENTRE <i>end</i>	\$ 198.00
20	1	FRT BRACE BRACKET CENTRE <i>?</i> <i>distorted</i>	\$ 229.00
21	1	FRT BRACE BRACKET RH <i>?</i> <i>distorted</i>	\$ 118.00
22	1	FRT BRACE BRACKET LH <i>?</i> <i>distorted</i>	\$ 118.00
23	1	FRT BUMPER SPONGE <i>end</i>	\$ 254.00
24	1	FRT BUMPER REINFORCEMENT UPP (metal) <i>Best</i>	\$ 798.00
25	1	FRT BUMPER REINFORCEMENT LOW (firbe) <i>Not new</i>	\$ 374.00
26	2	FRT BUMPER PARKING SENSOR <i>1 piece damaged</i>	\$ 544.00
27	2	FRT BUMPER PARKING SENSOR SEAL <i>1 piece new</i>	\$ 24.00
28	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>new</i>	\$ 394.00
29	1	FRT GRILLE ASSY <i>Smashed</i>	\$ 800.00
30	1	FRT GRILLE LOGO <i>new</i>	\$ 160.00
31	1	FRT LOW CENTRE GRILLE <i>new</i>	\$ 202.00
32	1	RH HEADLAMP <i>cracked</i>	\$ 820.00
33	1	LH HEADLAMP <i>LT</i>	\$ 820.00
34	1	RH FOG LAMP <i>new</i>	\$ 434.00

35	1	RH FOG LAMP COVER	Not in	\$	120.00	+
36	1	FRT FENDER SIGNAL LAMP RH	Not in	\$	146.00	+
37	1	FRT FENDER BRACKET RH	Best	\$	192.00	+
38	10	FENDER INNERSHIELD CLIP	in	\$	65.00	+
39	1	FRT FENDER RH	Distorted	\$	682.00	+
40	1	FRT FENDER INNERSHIELD RH	Not in	\$	138.00	+
41	1	FRT WHEELHOUSE PANEL RH	Best	\$	1,608.00	+
42	1	RADIATOR SUPORT PANEL TOP GARNISH RH	3 covered	\$	152.00	+
43	1	RADIATOR SUPORT PANEL TOP GARNISH LH		\$	152.00	+
44	1	RADIATOR SUPORT PANEL TOP	Distorted	\$	334.00	+
45	1	FRT HEADLAMP PANEL RH	Best	\$	160.00	+
46	1	FRT HEADLAMP PANEL LH	Best	\$	160.00	+
47	1	RADIATOR	Distorted	\$	1,424.00	+
48	1	RADIATOR COOLANT	in	\$	164.00	+
49	1	RADIATOR FAN ASSY	Distorted	\$	1,806.00	+
50	1	RADIATOR TOP BRACKET LH	3 covered	\$	124.00	+
51	1	RADIATOR TOP BRACKET RH		\$	124.00	+
52	1	RADIATOR TOP MOUTING	in	\$	18.00	+
53	1	RADIATOR BRACKET LOWER LH	3 in	\$	162.00	+
54	1	RADIATOR BRACKET LOWER RH		\$	162.00	+
55	1	A/C CONDENSER	Distorted	\$	730.00	+
56	1	A/C CONDENSER TOP SEAL	in	\$	112.00	+
57	1	A/C CONDENSOR AIR GUIDE TOP CENTRE	3 Distorted	\$	158.00	+
58	1	A/C CONDENSOR AIR GUIDE RH		\$	134.00	+
59	1	A/C CONDENSOR AIR GUIDE LH		\$	138.00	+
60	1	A/C PIPE (comp to cooling coil)	Not in	\$	934.00	2x
61	1	A/C PIPE (cooling coil to condenser)	Not in	\$	916.00	2x
62	1	A/C AMBIENT SENSOR	Not in	\$	317.00	+
63	1	INTERCOOLER, TURBOCHARGER AIR GUIDE	Not in	\$	514.00	2x
64	1	INTERCOOLER, TURBOCHARGER	Best	\$	1,060.00	2x
65	1	INTERCOOLER HOSE(turbo to intercooler), INLET	Not in	\$	302.00	2x
66	1	INTERCOOLER HOSE(intercooler to throttle body), OUTLET	Best	\$	292.00	2x
67	1	TURBO ASSY	Damaged	\$	2,700.00	2x
68	1	FRT WINDSCREEN WITH MLDG	covered	\$	795.00	+
69	1	FRT WINDSCREEN MLDG RH	in	\$	160.00	+
70	1	FRT WINDSCREEN GARNISH	Best	\$	140.00	+
71	1	FRT WINDSCREEN PILLAR PANEL RH	3 Best	\$	856.00	+
72	1	FRT WINDSCREEN PILLAR PANEL LH		\$	856.00	+
73	1	ENGINE AIR INTAKE DUCT	covered	\$	166.00	+
74	1	ENGINE AIR INTAKE DUCT HOSE	Best	\$	120.00	+
75	1	ENGINE AIR FILTER ASSY	Not in	\$	754.00	2x
76	1	FRT ARLARM SIREN RH	Not in	\$	420.00	2x
77	1	FRT ARLARM SIREN BRACKET RH	Not in	\$	60.00	2x
78	1	FRT DASHBOARD ASSY	Best	\$	3,940.00	+
79	1	FRT PASSENGER DASHBOARD AIR BAG	Activated	\$	2,959.00	+
80	1	FRT DRIVER STEERING AIR BAG	2	\$	2,959.00	+
81	1	FRT DRIVER STEERING CLOCK SPRING		\$	332.00	+
82	2	AIR BAG IMPART SENSOR	Activated	\$	496.00	+
83	1	AIR BAG CONTROL UNIT		\$	782.00	+
84	1	FRT DRIVER SEAT BELT		\$	922.00	+
85	1	FRT DRIVER SEAT BELT BUCKLE	Not in	\$	238.00	2x
86	1	FRT DRIVER SEAT BELT PRETENSIONER	Activated	\$	332.00	2x
87	1	FRT PASSENGER SEAT BELT	Activated	\$	922.00	2x
88	1	FRT PASSENGER SEAT BELT BUCKLE	Not in	\$	238.00	2x
89	1	FRT PASSENGER SEAT BELT PRETENSIONER	Activated	\$	332.00	2x
90	1	RR PASSENGER SEAT BELT RH	Activated	\$	898.00	+
91	1	RR PASSENGER SEAT BELT GARNISH RH	Best	\$	254.00	+
92	1	RR FENDER INNER TRIM BOARD RH	Not in	\$	306.00	2x
93	1	RR PASSENGER SEAT BELT LH	Activated	\$	898.00	+
94	1	RR PASSENGER SEAT BELT GARNISH LH	Best	\$	254.00	+

95	1	RR FENDER INNER TRIM BOARD LH <i>Not New</i>	\$ 306.00	<i>2x</i>
96	1	FRT DRIVER SEAT CUSHION AIR BAG	\$ 994.00	<i>x</i>
97	1	FRT PASSENGER SEAT CUSHION AIR BAG	\$ 944.00	<i>x</i>
98	1	RH SIDE CURTAIN AIR BAG	\$ 2,465.00	<i>x</i>
99	1	LH SIDE CURTAIN AIR BAG	\$ 2,465.00	<i>x</i>

Parts Total: \$ 57,498.50  
Less 20%: \$ 11,499.70  
Total: \$ 45,998.80

**Labour**

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 4,400.00 <i>2750</i>
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT WHEELHOUSE PANEL RH, FRT FENDER RH, FRT DOOR RH, FRT FENDER LH, FRT WINDSCREEN PILLAR PANEL RH, FRT WINDSCREEN PILLAR PANEL LH	\$ 4,050.00 <i>2450 7x350=2450</i>
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00 <i>120</i>
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00 <i>✓</i>
5	To remove and refit radiator and conduct pressure test	\$ 120.00 <i>x</i>
6	To remove and replace dashboard system, interior trimming, seat cushion, e.t.c	\$ 2,200.00 <i>1650</i>
7	To conduct reset of engine light on	\$ 350.00 <i>175</i>
8	To conduct reset of air bag light on	\$ 350.00 <i>175</i>
9	Remove and refit front windscreen	\$ 220.00 <i>150</i>

Labour Total: \$ 12,510.00

**Others**

No.	Other Description	Price (SGD)
1	FRT NUMBER PLATE <i>222 on</i>	\$ 65.00 <i>x</i>
2	FRT WINDSCREEN SEALANT	\$ 65.00 <i>✓</i>
3	FRT WINDSCREEN INNER SEAL	\$ 40.00 <i>✓</i>
4	FRT IU BRACKET	\$ 35.00 <i>✓</i>
5	FRT WINDSCREEN SOLAR FILM	\$ 200.00 <i>✓</i>

Other Total: \$ 405.00

TOTAL: \$ 58,913.80  
GST (7%): \$ 4,123.97

GRAND TOTAL: \$ 63,037.77 *65058.60*

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

*Adrian L*  
P/P 29/03/19  
12 Days



## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 5 April 2019 9:28 AM  
**To:** Kelvin.chew@alpinemotors.sg  
**Cc:** suhaimi@firstautoworks.com.sg; SUR; 'VINCENT.SIM@ALPINEMOTRS.SG'  
**Subject:** RE: SJE 2266S / OD / ECICS

Dear Vincent/Kelvin,

Please update check if you are able to repair all in \$35K.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 3 April 2019 2:36 PM  
**To:** Kelvin.chew@alpinemotors.sg  
**Cc:** suhaimi@firstautoworks.com.sg; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** SJE 2266S / OD / ECICS

Dear Kelvin,

Please check if you are able to repair all in \$35K.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Date :25/03/2019

Reference: OPEL  
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SJE2266S  
CHASSIS NO.: W0VBE8EA6H8101850  
ENGINE NO.: B1171587HRXX0070

Name of insured : CHIN YEW WEN  
Date of accident.: 23.03.2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Distorted</i>	\$ 1,758.00
2	1	FRT BONNET LOCK <i>2nd</i>	\$ 312.00
3	1	FRT BONNET LOCK CABLE <i>2</i>	\$ 277.00
4	1	FRT BONNET HINGE LH <i>3 Beat</i>	\$ 186.00
5	1	FRT BONNET HINGE RH	\$ 186.00
6	4	FRT BONNET STOPED <i>Missing</i>	\$ 40.00
7	1	FRT BUMPER <i>Distorted</i>	\$ 1,994.00
8	1	FRT BUMPER TOW COVER <i>Missing</i>	\$ 128.00
9	1	FRT BUMPER LOW LIP RH <i>3 Beat New</i>	\$ 156.00
10	1	FRT BUMPER LOW LIP LH	\$ 156.00
11	15	FRT BUMPER CLIP <i>new</i>	\$ 97.50
12	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>?</i>	\$ 136.00
13	1	FRT BUMPER SIDE RETAINER LH - UPP <i>?</i>	\$ 106.00
14	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
15	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
16	1	FRT BUMPER BRACKET LH <i>3 Distorted</i>	\$ 192.00
17	1	FRT BUMPER BRACKET RH	\$ 192.00
18	1	FRT BUMPER UNDER DUST COVER <i>new</i>	\$ 290.00
19	1	FRT BUMPER BRACKET TOP CENTRE <i>cut</i>	\$ 198.00
20	1	FRT BRACE BRACKET CENTRE <i>?</i>	\$ 229.00
21	1	FRT BRACE BRACKET RH <i>?</i>	\$ 118.00
22	1	FRT BRACE BRACKET LH	\$ 118.00
23	1	FRT BUMPER SPONGE <i>cut</i>	\$ 254.00
24	1	FRT BUMPER REINFORCEMENT UPP (metal) <i>Best</i>	\$ 798.00
25	1	FRT BUMPER REINFORCEMENT LOW (firbe) <i>?</i>	\$ 374.00
26	2	FRT BUMPER PARKING SENSOR <i>1 piece change</i>	\$ 544.00
27	2	FRT BUMPER PARKING SENSOR SEAL <i>1 piece New</i>	\$ 24.00
28	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>New</i>	\$ 394.00
29	1	FRT GRILLE ASSY <i>Smashed</i>	\$ 800.00
30	1	FRT GRILLE LOGO <i>new</i>	\$ 160.00
31	1	FRT LOW CENTRE GRILLE <i>new</i>	\$ 202.00
32	1	RH HEADLAMP <i>cracked</i>	\$ 820.00
33	1	LH HEADLAMP <i>lt</i>	\$ 820.00
34	1	RH FOG LAMP <i>New</i>	\$ 434.00

35	1	RH FOG LAMP COVER	New	\$	120.00
36	1	FRT FENDER SIGNAL LAMP RH	New	\$	146.00
37	1	FRT FENDER BRACKET RH	Best	\$	192.00
38	10	FENDER INNERSHIELD CLIP	in	\$	65.00
39	1	FRT FENDER RH	Distorted	\$	682.00
40	1	FRT FENDER INNERSHIELD RH	New	\$	138.00
41	1	FRT WHEELHOUSE PANEL RH	Repair	\$	1,608.00
42	1	RADIATOR SUPORT PANEL TOP GARNISH RH	3 cancelled	\$	152.00
43	1	RADIATOR SUPORT PANEL TOP GARNISH LH		\$	152.00
44	1	RADIATOR SUPORT PANEL TOP	3 cancelled	\$	334.00
45	1	FRT HEADLAMP PANEL RH	Best	\$	160.00
46	1	FRT HEADLAMP PANEL LH	Best	\$	160.00
47	1	RADIATOR	Distorted	\$	1,424.00
48	1	RADIATOR COOLANT	in	\$	164.00
49	1	RADIATOR FAN ASSY	Distorted	\$	1,806.00
50	1	RADIATOR TOP BRACKET LH	3 cancelled	\$	124.00
51	1	RADIATOR TOP BRACKET RH		\$	124.00
52	1	RADIATOR TOP MOUTING	in	\$	18.00
53	1	RADIATOR BRACKET LOWER LH	3 in	\$	162.00
54	1	RADIATOR BRACKET LOWER RH		\$	162.00
55	1	A/C CONDENSER	Distorted	\$	730.00
56	1	A/C CONDENSER TOP SEAL	in	\$	112.00
57	1	A/C CONDENSOR AIR GUIDE TOP CENTRE	3 Distorted	\$	158.00
58	1	A/C CONDENSOR AIR GUIDE RH		\$	134.00
59	1	A/C CONDENSOR AIR GUIDE LH		\$	138.00
60	1	A/C PIPE (comp to cooling coil)	?	\$	934.00
61	1	A/C PIPE (cooling coil to condenser)	?	\$	916.00
62	1	A/C AMBIENT SENSOR	New	\$	317.00
63	1	INTERCOOLER, TURBOCHARGER AIR GUIDE	?	\$	514.00
64	1	INTERCOOLER, TURBOCHARGER	Best	\$	1,060.00
65	1	INTERCOOLER HOSE(turbo to intercooler), INLET	Best	\$	302.00
66	1	INTERCOOLER HOSE(intercooler to throttle body), OUTLET	?	\$	292.00
67	1	TURBO ASSY	3	\$	2,700.00
68	1	FRT WINDSCREEN WITH MLDG	Cancelled	\$	795.00
69	1	FRT WINDSCREEN MLDG RH	in	\$	160.00
70	1	FRT WINDSCREEN GARNISH	Best	\$	140.00
71	1	FRT WINDSCREEN PILLAR PANEL RH	3 Repair	\$	856.00
72	1	FRT WINDSCREEN PILLAR PANEL LH		\$	856.00
73	1	ENGINE AIR INTAKE DUCT	Cancelled	\$	166.00
74	1	ENGINE AIR INTAKE DUCT HOSE	Best	\$	120.00
75	1	ENGINE AIR FILTER ASSY	?	\$	754.00
76	1	FRT ARLARM SIREN RH	?	\$	420.00
77	1	FRT ARLARM SIREN BRACKET RH	?	\$	60.00
78	1	FRT DASHBOARD ASSY	Repair	\$	3,940.00
79	1	FRT PASSENGER DASHBOARD AIR BAG	Activated	\$	2,959.00
80	1	FRT DRIVER STEERING AIR BAG	?	\$	2,959.00
81	1	FRT DRIVER STEERING CLOCK SPRING	Activated	\$	332.00
82	2	AIR BAG IMPART SENSOR		\$	496.00
83	1	AIR BAG CONTROL UNIT		\$	782.00
84	1	FRT DRIVER SEAT BELT		\$	922.00
85	1	FRT DRIVER SEAT BELT BUCKLE		\$	238.00
86	1	FRT DRIVER SEAT BELT PRETENSIONER	Distorted	\$	332.00
87	1	FRT PASSENGER SEAT BELT	Activated	\$	922.00
88	1	FRT PASSENGER SEAT BELT BUCKLE	?	\$	238.00
89	1	FRT PASSENGER SEAT BELT PRETENSIONER	Distorted	\$	332.00
90	1	RR PASSENGER SEAT BELT RH	Activated	\$	898.00
91	1	RR PASSENGER SEAT BELT GARNISH RH	Best	\$	254.00
92	1	RR FENDER INNER TRIM BOARD RH	?	\$	306.00
93	1	RR PASSENGER SEAT BELT LH	Activated	\$	898.00
94	1	RR PASSENGER SEAT BELT GARNISH LH	Best	\$	254.00

95	1	RR FENDER INNER TRIM BOARD LH	\$	306.00	?
96	1	FRT DRIVER SEAT CUSHION AIR BAG	\$	994.00	x
97	1	FRT PASSENGER SEAT CUSHION AIR BAG	\$	944.00	x
98	1	RH SIDE CURTAIN AIR BAG	\$	2,465.00	x
99	1	LH SIDE CURTAIN AIR BAG	\$	2,465.00	x

Parts Total: \$ 57,498.50  
Less 20%: \$ 11,499.70  
Total: \$ 45,998.80

**Labour**

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 4,400.00	2750
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT WHEELHOUSE PANEL RH, FRT FENDER RH, FRT DOOR RH, FRT FENDER LH, FRT WINDSCREEN PILLAR PANEL RH, FRT WINDSCREEN PILLAR PANEL LH	\$ 4,050.00	2450 7 x 350 = 2450
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00	120
4	To remove and refit aircon condenser, vacuum, refill and check air con gas system	\$ 600.00	✓
5	To remove and refix radiator and conduct pressure test	\$ 120.00	x
6	To remove and replace dashboard system, interior trimming, seat cushion, e.t.c	\$ 2,200.00	1650
7	To conduct reset of engine light on	\$ 350.00	175
8	To conduct reset of air bag light on	\$ 350.00	175
9	Remove and refit front windscreen	\$ 220.00	150

Labour Total: \$ 12,510.00

**Others**

No.	Other Description	Price (SGD)	
1	FRT NUMBER PLATE	\$ 65.00	x
2	FRT WINDSCREEN SEALANT	\$ 65.00	✓
3	FRT WINDSCREEN INNER SEAL	\$ 40.00	✓
4	FRT IU BRACKET	\$ 35.00	✓
5	FRT WINDSCREEN SOLAR FILM	\$ 200.00	✓

Other Total: \$ 405.00

TOTAL: \$ 58,913.80  
GST (7%): \$ 4,123.97

GRAND TOTAL: \$ 63,037.77

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

Adrian L  
P/P 29/03/19  
12 Days



Wir leben Autos.

**FINALIZE**

ECICS LIMITED

GST Ref. No: 20-0000274-Z

Vehicle No: SJE2266S  
 Chasis No: W0VBE8EA6H8101650  
 Engine No: B1171587HRXX0070  
 Date of accident :23/03/2019

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

**Parts**

No.	Qty.	Description	Price (SGD)
1	1	FRT BONNET	\$ 1,758.00
2	1	FRT BONNET LOCK	\$ 312.00
3	1	FRT BONNET HINGE LH	\$ 186.00
4	1	FRT BONNET HINGE LRH	\$ 186.00
5	4	FRT BONNET STOPED	\$ 40.00
6	1	FRT BUMPER	\$ 1,994.00
7	1	FRT BUMPER TOW COVER	\$ 128.00
8	15	FRT BUMPER CLIP	\$ 97.50
9	1	FRT BUMPER SIDE RETAINER LH - GUIDE	\$ 136.00
10	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
11	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
12	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
13	1	FRT BUMPER BRACKET LH	\$ 192.00
14	1	FRT BUMPER BRACKET RH	\$ 192.00
15	1	FRT BUMPER BRACKET TOP CENTRE	\$ 198.00
16	1	FRT BRACE BRACKET CENTRE	\$ 229.00
17	1	FRT BRACE BRACKET RH	\$ 118.00
18	1	FRT BRACE BRACKET LH	\$ 118.00
19	1	FRT BUMPER SPONGE	\$ 254.00
20	1	FRT BUMPER REINFORCEMENT UPP ( METAL )	\$ 798.00
21	1	FRT BUMPER PARKING SENSOR	\$ 272.00
22	1	FRT BUMPER PARKING SENSOR SEAL	\$ 12.00
23	1	FRT GRILLE ASSY	\$ 800.00
24	1	FRT GRILLE LOGO	\$ 160.00
25	1	RH HEADLAMP	\$ 820.00
26	1	LH HEADLAMP	\$ 820.00
27	1	FRT FENDER BRACKET RH	\$ 192.00
28	10	FENDER INNERSHIELD CLIP	\$ 65.00
29	1	FRT FENDER RH	\$ 682.00
30	1	RADIATOR SUPPORT PANEL TOP GARNISH RH	\$ 152.00
31	1	RADIATOR SUPPORT PANEL TOP GARNISH LH	\$ 152.00

32	1	RADIATOR SUPPORT PANEL TOP	\$	334.00
33	1	FRT HEADLAMP PANEL RH	\$	160.00
34	1	FRT HEADLAMP PANEL LH	\$	160.00
35	1	RADIATOR	\$	1,424.00
36	1	RADIATOR COOLANT	\$	164.00
37	1	RADIATOR FAN ASSY	\$	1,806.00
38	1	RADIATOR TOP BRACKET LH	\$	124.00
39	1	RADIATOR TOP BRACKET RH	\$	124.00
40	1	RADIATOR TOP MOUTING	\$	18.00
41	1	RADIATOR BRACKET LOWER LH	\$	162.00
42	1	RADIATOR BRACKET LOWER RH	\$	162.00
43	1	A/C CONDENSER	\$	730.00
44	1	A/C CONDENSER TOP SEAL	\$	112.00
45	1	A/C CONDENSER AIR GUIDE TOP CENTRE	\$	158.00
46	1	A/C CONDENSER AIR GUIDE RH	\$	134.00
47	1	A/C CONDENSER AIR GUIDE LH	\$	138.00
48	1	INTERCOOLER , TURBOCHARGE	\$	1,060.00
49	1	INTERCOOLER HOSE ( Intercooler to throttle body ) OUTLET	\$	292.00
50	1	TURBO ASSY	\$	2,700.00
51	1	FRT WINDSCREEN WITH MLDG	\$	795.00
52	1	FRT WINDSCREEN MLDG RH	\$	160.00
53	1	FRT WINDSCREEN GARNISH	\$	140.00
54	1	ENGINE AIR INTAKE DUCT	\$	166.00
55	1	ENGINE AIR INTAKE DUCT HOSE	\$	120.00
56	1	FRT DASHBOARD ASSY	\$	3,940.00
57	1	FRT PASSENGER DASHBOARD AIR BAG	\$	2,959.00
58	1	FRT DRIVER STEERING AIR BAG	\$	2,959.00
59	1	FRT DRIVER STEERING CLOCK SPRING	\$	332.00
60	2	AIR BAG IMPART SENSOR	\$	496.00
61	1	AIR BAG CONTROL UNIT	\$	782.00
62	1	FRT DRIVER SEAT BELT	\$	922.00
63	1	FRT DRIVER SEAT BELT PRETENSIONER	\$	332.00
64	1	FRT PASSENGER SEAT BELT	\$	922.00
65	1	FRT PASSENGER SEAT BELT PRETENSIONER	\$	332.00
66	1	RR PASSENGER SEAT BELT RH	\$	898.00
67	1	RR PASSENGER SEAT BELT GARNISH RH	\$	254.00
68	1	RR PASSENGER SEAT BELT LH	\$	898.00
69	1	RR PASSENGER SEAT BELT GARNISH LH	\$	254.00
	1			
	1			

**Supplementary**

1	1	WATER PUMP	\$	512.00
2	1	HEADLAMP DAYLIGHT LED CONTROL UNIT	\$	746.00
3	1	TURBO SEAL	\$	173.00

Total: \$ 40,465.50  
Less 20%: \$ 8,093.10

Parts Total: \$ 32,372.40

Labour

No.		Price (SGD)
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	\$ 2,750.00
2	CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA.FRT BUMPER , FRT BONNET , FRT SUPPORT PANEL , FRT WHEELHOUSE PANEL RH , FRT FENDER RH , FRT DOOR RH , FRT FENDER LH , FRT WINDSCREEN PILLAR PANEL RH , FRT WINDSCREEN PILLAR PANEL LH	\$ 2,450.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$ 120.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR , VACUUM , REFILL AND CHECK AIR CON GAS SYSTEM	\$ 600.00
5	TO REMOVE AND REPLACE DASHBOARD SYSTEM , INTERIOR TRIMMING , SEAT CUSHION , ETC.	\$ 1,650.00
6	TO CONDUCT RESET OF ENGINE LIGHT ON	\$ 175.00
7	TO CONDUCT RESET OF AIR BAG LIGHT ON	\$ 175.00
8	REMOVE AND REFIT FRONT WINDSCREEN	\$ 150.00

Labour Total : \$ 8,070.00

Other

No.		Price (SGD)
1	1 FRT WINDSCREEN SEALANT	\$ 65.00
2	1 FRT WINDSCREEN INNER SEAL	\$ 40.00
3	1 FRT IU BRACKET	\$ 35.00
4	1 FRT WINDSCREEN SOLAR FILM	\$ 200.00

Other Total : \$ 340.00

Total : \$ 40,782.40  
 Amount As Agree: \$ 35,000.00  
 Excess: \$ 4,000.00  
 GST (7%): \$ 2,170.00  
 Grand Total : \$ 33,170.00

Yours Faithfully,

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Apr 2019 10:18 <a href="#">Edit Reg</a>		28 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$35,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$35,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by adjuster]							
Insured:	CHIN YEW WEN, ID: S1737239D, Email: LENNON_YWCHIN@SINGNET.COM.SG								
Vehicle Reg. No.:	SJE2266S	Date of Loss:	23/03/2019 11:00 - :59 [14 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / DMPC1900081H	Policy/Cover Note No.:	MPC18A00336201 (Comprehensive)						
		Excess:	S\$4,000.00						
Repairer:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Desmond Lee - 6303 0167]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/04/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>ECICS (05/04/2019): Alert - Adj Mandate Approved (S\$35000.00) - SJE2266S - Claim Handler: Desmond Le...</li> <li>ECICS (02/04/2019): Alert - Adj Mandate Maintained - SJE2266S - Claim Handler: Desmond Lee</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJE2266S (DMPC1900081H)

OD

Mar 23 2019 11:00AM

[CHIN YEW WEN]

1st Autoworks Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>		
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/04/19 11:05	<b>Adjuster Immediate Advice</b>		Load HTM	<input type="checkbox"/>
2	05/04/19 10:01	<b>Adjuster Immediate Advice</b>		Load HTM	<input type="checkbox"/>
3	05/04/19 16:22	<b>Adjuster Immediate Advice</b>		Load HTM	<input type="checkbox"/>
4	05/04/19 17:53	<b>Adjuster Immediate Advice</b>		Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
29	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
30	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
31	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
32	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
33	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
34	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
35	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
36	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
37	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
38	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
39	05/04/19 10:03	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
40	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
42	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
43	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
44	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
46	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
47	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
48	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
49	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
50	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
51	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
52	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
53	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
54	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
55	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
56	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
57	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
58	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
59	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
60	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
61	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
62	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
63	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
64	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
65	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
66	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
67	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
68	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
69	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
70	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
71	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
72	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
73	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
74	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
75	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
76	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
77	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
78	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
79	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
80	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
81	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
82	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
83	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
84	05/04/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
85	19/09/19 14:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	19/09/19 14:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	19/09/19 14:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	19/09/19 14:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	19/09/19 14:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	19/09/19 14:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	19/09/19 14:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	19/09/19 14:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	19/09/19 14:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	19/09/19 14:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
95	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
96	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
97	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
98	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
99	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
100	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
101	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
102	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
103	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
104	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
105	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
106	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
107	19/09/19 14:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/04/19 10:14	ESTIMATE		Load PDF	
2	05/04/19 10:18	UNDERTAKE AT 35K FROM FIRST AUTOWORKS		Load PDF	
3	25/09/19 15:07	Supplementary		Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited  
10 Eunos Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS19005511/AQD3E2

**Date:** 25/09/2019

#### REFERENCE

Insured/Claimant: CHIN YEW WEN Policy No: MPC18A00336201  
Date of Loss: 23/03/2019 Nature of Claim: OD Claim No: DMPC1900081H

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE2266S**  
Make & Model: OPEL ASTRA ST, 999cc (A) Engine No: B1171587HRXX0070  
Reg. Date: 27/12/2017 (Man. Year: 2017) Chassis No: W0VBE8EA6H8101850  
Colour: Black Odometer: 0 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$77,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,548.60	32,712.40	14,836.20	31.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,510.00	8,070.00	4,440.00	35.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>60,058.60</b>	<b>40,782.40</b>	<b>19,276.20</b>	<b>32.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>35,000.00</b>		
<b>- Excess (S\$)</b>	4,000.00	4,000.00	0.00	0.00
<b>(S\$)</b>	56,058.60	31,000.00	25,058.60	44.70
<b>+ GST 7.00/7.00% (S\$)</b>	3,924.10	2,170.00	1,754.10	44.70
<b>Nett Amount (S\$)</b>	<b>59,982.70</b>	<b>33,170.00</b>	<b>26,812.70</b>	<b>44.70</b>

#### INSPECTION

Date of Assignment: 28/03/2019  
Date Inspected: 29/03/2019 Inspected At: 1st Autoworks Pte Ltd (HQ)  
23 Kaki Bukit Ave 4, #04-01  
Singapore 415933  
Estimated Period of Repair: 12.0 days

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

Reference	
<b>Part Source:</b>	(Last Synchronised: 25 Sep 2019)
<b>Parts:</b>	N/A OPEL ASTRA ST 999cc (A) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJE2266S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Distorted	1,758.00 FL	*1,758.00 FL
2	1		*FRT BONNET LOCK	Damaged	312.00 FL	*312.00 FL
3	1		*FRT BONNET LOCK CABLE	Not Necessary	277.00 FL	*- FL
4	1		*FRT BONNET HINGE LH	Bent	186.00 FL	*186.00 FL
5	1		*FRT BONNET HINGE RH	Bent	186.00 FL	*186.00 FL
6	4		*FRT BONNET STOPED	Missing	40.00 FL	*40.00 FL
7	1		*FRT BUMPER	Distorted	1,994.00 FL	*1,994.00 FL
8	1		*FRT BUMPER TOW COVER	Missing	128.00 FL	*128.00 FL
9	1		*FRT BUMPER LOW LIP RH	Not Necessary	156.00 FL	*- FL
10	1		*FRT BUMPER LOW LIP LH	Not Necessary	156.00 FL	*- FL
11	15		*FRT BUMPER CLIP	Necessary	97.50 FL	*97.50 FL
12	1		*FRT BUMPER SIDE RETAINER LH - GUIDE	Necessary	136.00 FL	*136.00 FL
13	1		*FRT BUMPER SIDE RETAINER LH - UPP	Necessary	106.00 FL	*106.00 FL
14	1		*FRT BUMPER SIDE RETAINER RH - GUIDE	Necessary	136.00 FL	*136.00 FL
15	1		*FRT BUMPER SIDE RETAINER RH - UPP	Necessary	106.00 FL	*106.00 FL
16	1		*FRT BUMPER BRACKET LH	Distorted	192.00 FL	*192.00 FL
17	1		*FRT BUMPER BRACKET RH	Distorted	192.00 FL	*192.00 FL
18	1		*FRT BUMPER UNDER DUST COVER	Not Necessary	290.00 FL	*- FL
19	1		*FRT BUMPER BRACKET TOP CENTRE	Cracked	198.00 FL	*198.00 FL
20	1		*FRT BRACE BRACKET CENTRE	Distorted	229.00 FL	*229.00 FL
21	1		*FRT BRACE BRACKET RH	Distorted	118.00 FL	*118.00 FL
22	1		*FRT BRACE BRACKET LH	Distorted	118.00 FL	*118.00 FL
23	1		*FRT BUMPER SPONGE	Cracked	254.00 FL	*254.00 FL
24	1		*FRT BUMPER REINFORCEMENT UPP (METAL)	Bent	798.00 FL	*798.00 FL
25	1		*FRT BUMPER REINFORCEMENT LOW (FIBRE)	Not Necessary	374.00 FL	*- FL
26	1		*FRT BUMPER PARKING SENSOR (2PCS)	Damaged (1Pc only)	544.00 FL	*272.00 FL
27	1		*FRT BUMPER PARKING SENSOR SEAL (2PCS)	Necessary (1Pc only)	24.00 FL	*12.00 FL
28	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	394.00 FL	*- FL
29	1		*FRT GRILLE ASSY	Smashed	800.00 FL	*800.00 FL
30	1		*FRT GRILLE LOGO	Necessary	160.00 FL	*160.00 FL
31	1		*FRT LOW CENTRE GRILLE	Not Necessary	202.00 FL	*- FL
32	1		*RH HEADLAMP	Cracked	820.00 FL	*820.00 FL
33	1		*LH HEADLAMP	Cut	820.00 FL	*820.00 FL
34	1		*RH FOG LAMP	Not Necessary	434.00 FL	*- FL
35	1		*RH FOG LAMP COVER	Not Necessary	120.00 FL	*- FL
36	1		*FRT FENDER SIGNAL LAMP RH	Not Necessary	146.00 FL	*- FL
37	1		*FRT FENDER BRACKET RH	Bent	192.00 FL	*192.00 FL
38	10		*FENDER INNERSHIELD CLIP	Necessary	65.00 FL	*65.00 FL
39	1		*FRT FENDER RH	Distorted	682.00 FL	*682.00 FL
40	1		*FRT FENDER INNERSHIELD RH	Not Necessary	138.00 FL	*- FL
41	1		*FRT WHEELHOUSE PANEL RH	Repair	1,608.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*RADIATOR SUPORT PANEL TOP GARNISH RH	Cracked	152.00 FL	*152.00 FL
43	1		*RADIATOR SUPORT PANEL TOP GARNISH LH	Cracked	152.00 FL	*152.00 FL
44	1		*RADIATOR SUPORT PANEL TOP	Distorted	334.00 FL	*334.00 FL
45	1		*FRT HEADLAMP PANEL RH	Bent	160.00 FL	*160.00 FL
46	1		*FRT HEADLAMP PANEL LH	Bent	160.00 FL	*160.00 FL
47	1		*RADIATOR	Distorted	1,424.00 FL	*1,424.00 FL
48	1		*RADIATOR COOLANT	Necessary	164.00 FL	*164.00 FL
49	1		*RADIATOR FAN ASSY	Distorted	1,806.00 FL	*1,806.00 FL
50	1		*RADIATOR TOP BRACKET LH	Damaged	124.00 FL	*124.00 FL
51	1		*RADIATOR TOP BRACKET RH	Damaged	124.00 FL	*124.00 FL
52	1		*RADIATOR TOP MOUNTING	Necessary	18.00 FL	*18.00 FL
53	1		*RADIATOR BRACKET LOWER LH	Necessary	162.00 FL	*162.00 FL
54	1		*RADIATOR BRACKET LOWER RH	Necessary	162.00 FL	*162.00 FL
55	1		*A/C CONDENSER	Distorted	730.00 FL	*730.00 FL
56	1		*A/C CONDENSER TOP SEAL	Necessary	112.00 FL	*112.00 FL
57	1		*A/C CONDENSOR AIR GUIDE TOP CENTRE	Distorted	158.00 FL	*158.00 FL
58	1		*A/C CONDENSOR AIR GUIDE RH	Distorted	134.00 FL	*134.00 FL
59	1		*A/C CONDENSOR AIR GUIDE LH	Distorted	138.00 FL	*138.00 FL
60	1		*A/C PIPE (COMP TO COOLING COIL)	Not Necessary	934.00 FL	*- FL
61	1		*A/C PIPE (COOLING COIL TO CONDENSER)	Not Necessary	916.00 FL	*- FL
62	1		*A/C AMBIENT SENSOR	Not Necessary	317.00 FL	*- FL
63	1		*INTERCOOLER, TURBOCHARGER AIR GUIDE	Not Necessary	514.00 FL	*- FL
64	1		*INTERCOOLER, TURBOCHARGER	Dented	1,060.00 FL	*1,060.00 FL
65	1		*INTERCOOLER HOSE (TURBO TO INTERCOOLER), INLET	Not Necessary	302.00 FL	*- FL
66	1		*INTERCOOLER HOSE (INTERCOOLER TO THROTTLE BODY), OUTLET	Deformed	292.00 FL	*292.00 FL
67	1		*TURBO ASSY	Damaged	2,700.00 FL	*2,700.00 FL
68	1		*FRT WINDSCREEN WITH MLDG	Cracked	795.00 FL	*795.00 FL
69	1		*FRT WINDSCREEN MLDG RH	Necessary	160.00 FL	*160.00 FL
70	1		*FRT WINDSCREEN GARNISH	Cut	140.00 FL	*140.00 FL
71	1		*FRT WINDSCREEN PILLAR PANEL RH	Repair	856.00 FL	*- FL
72	1		*FRT WINDSCREEN PILLAR PANEL LH	Repair	856.00 FL	*- FL
73	1		*ENGINE AIR INTAKE DUCT	Cracked	166.00 FL	*166.00 FL
74	1		*ENGINE AIR INTAKE DUCT HOSE	Deformed	120.00 FL	*120.00 FL
75	1		*ENGINE AIR FILTER ASSY	Not Necessary	754.00 FL	*- FL
76	1		*FRT ARLARM SIREN RH	Not Necessary	420.00 FL	*- FL
77	1		*FRT ARLARM SIREN BRACKET RH	Not Necessary	60.00 FL	*- FL
78	1		*FRT DASHBOARD ASSY	Torn	3,940.00 FL	*3,940.00 FL
79	1		*FRT PASSENGER DASHBOARD AIR BAG	Activated	2,959.00 FL	*2,959.00 FL
80	1		*FRT DRIVER STEERING AIR BAG	Activated	2,959.00 FL	*2,959.00 FL
81	1		*FRT DRIVER STEERING CLOCK SPRING	Activated	332.00 FL	*332.00 FL
82	2		*AIR BAG IMPACT SENSOR	Activated	496.00 FL	*496.00 FL
83	1		*AIR BAG CONTROL UNIT	Activated	782.00 FL	*782.00 FL
84	1		*FRT DRIVER SEAT BELT	Activated	922.00 FL	*922.00 FL
85	1		*FRT DRIVER SEAT BELT BUCKLE	Not Necessary	238.00 FL	*- FL
86	1		*FRT DRIVER SEAT BELT PRETENSIONER	Activated	332.00 FL	*332.00 FL
87	1		*FRT PASSENGER SEAT BELT	Activated	922.00 FL	*922.00 FL
88	1		*FRT PASSENGER SEAT BELT BUCKLE	Not Necessary	238.00 FL	*- FL
89	1		*FRT PASSENGER SEAT BELT PRETENSIONER	Activated	332.00 FL	*332.00 FL
90	1		*RR PASSENGER SEAT BELT RH	Activated	898.00 FL	*898.00 FL
91	1		*RR PASSENGER SEAT BELT GARNISH RH	Deformed	254.00 FL	*254.00 FL
92	1		*RR FENDER INNER TRIM BOARD RH	Not Necessary	306.00 FL	*- FL
93	1		*RR PASSENGER SEAT BELT LH	Activated	898.00 FL	*898.00 FL
94	1		*RR PASSENGER SEAT BELT GARNISH LH	Deformed	254.00 FL	*254.00 FL
95	1		*RR FENDER INNER TRIM BOARD LH	Not Necessary	306.00 FL	*- FL
96	1		*FRT DRIVER SEAT CUSHION AIR BAG	Not Necessary	994.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
97	1		*FRT PASSENGER SEAT CUSHION AIR BAG	Not Necessary	944.00 FL	*- FL
98	1		*RH SIDE CURTAIN AIR BAG	Not Necessary	2,465.00 FL	*- FL
99	1		*LH SIDE CURTAIN AIR BAG	Not Necessary	2,465.00 FL	*- FL
100	1		*FRT NUMBER PLATE	Not Necessary	65.00 FS	*- FS
101	1		*FRT WINDSCREEN SEALANT	Necessary	65.00 FS	*65.00 FS
102	1		*FRT WINDSCREEN INNER SEAL	Necessary	40.00 FS	*40.00 FS
103	1		*FRT IU BRACKET	Necessary	35.00 FS	*35.00 FS
104	1		*FRT WINDSCREEN SOLAR FILM	Necessary	200.00 FS	*200.00 FS
105	1		*WATER PUMP	Damaged	512.00 FL	*512.00 FL
106	1		*DAY LIGHT LED CONTROL UNIT RH	Damaged	746.00 FL	*746.00 FL
107	1		*TURBO SEAL	Crumpled	173.00 FL	*173.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 59,334.50 40,805.50**  
**- List Item Discount on L Items 20.00/20.00% (\$\$) 11,785.90 8,093.10**

**Total Parts (\$\$) 47,548.60 32,712.40**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	4,400.00	2,750.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT SUPORT PANEL, FRT WHEELHOUSE PANEL RH, FRT FENDER RH, FRT DOOR RH, FRT FENDER LH, FRT WINDSCREEN PILLAR PANEL RH, FRT WINDSCREEN PILLAR PANEL LH	New	4,050.00	2,450.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	220.00	120.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	600.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	120.00	0.00
6	TO REMOVE AND REPLACE DASHBOARD SYSTEM, INTERIOR TRIMMING, SEAT CUSHION, E.T.C	New	2,200.00	1,650.00
7	TO CONDUCT RESET OF ENGINE LIGHT ON	New	350.00	175.00
8	TO CONDUCT RESET OF AIR BAG LIGHT ON	New	350.00	175.00
9	REMOVE AND REFIT FRONT WINDSCREEN	New	220.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>12,510.00</b>	<b>8,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >