

ASS. REC. BY:

REF: CS/FC119005513/K9D372

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Serene

of FC2

Date/Time: 27.3.2019

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC5542J

Insured: SHC3889Y

at Workshop m/s Trans Cab Auto

Tel: 62876666

of No 2 Ang Mokie Street 63

Policy No:

Claim No: D19002098 MP54

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23.3.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 28.3.2019

Person Contacted: Candy Kong

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 5542J - CC3/EA1 18012435/Kea3s2 DOA - 05/07/2018
	SHC 3889Y - CS/AG1130/6971/DX bn 2 DOA - 15/09/2018
28/3/19 @ 2:35pm	revised to Serene ler by email.

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Tans Cob

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: Site 3542J Yr Regn: 08.14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or \_\_\_\_\_

Make: Renault Latitude c.c. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 447393 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VFI ABL 15 AUC 278894

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modl: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Giti

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 23/3/19 D.O.I. 27/3/19

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to C1 Insp @ 4550h (Ref to 24160.15, 840/1)</u>

RECEIVED 9 APR 2019

Date/Time, File Pass to?  : Prel. Report  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trlp: 1

Report Format: TP  
Lump Sum / I.B.A. (\$) 4950

- Add Fee:
- : Site Insp (\$ )
  - : Interview (\$ )
  - : Tech Invs (\$ )
  - : Weekend (\$ )

Survey Fee:

Transportation: \_\_\_\_\_ \$ - RS. SI

Fuel: \_\_\_\_\_

Others: \_\_\_\_\_

350

TOTAL \_\_\_\_\_

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	27-03-2019	<b>Our Ref No.</b> D19002098MFSH
<b>Accident Date</b>	23-03-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC3889Y	<b>Third Party Vehicle.</b> SHC5542J
<b>Survey Location</b>	NO. 2 ANG MO KIO STREET 63	
<b>Contact Person.</b>	CANDY KONG	
<b>Contact No.</b>	62876666/ 0	<b>Fax No.</b> 62877764
<b>Survey Type</b>	WITHOUT PREJUDICE: EST. COR - \$28,710.15	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	TRANS-CAB AUTO SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Tuesday, 2 April 2019 1:49 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: TP VEHICLE SHC 5542J (DOA: 23/03/2019) -- AAD1903-180

Hi Shiau Chan

We confirmed COR amount \$ 4,550.00 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



### TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shiau Chan (LKKAuto) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Thursday, 28 March, 2019 2:37 PM  
**To:** 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>  
**Subject:** TP VEHICLE SHC 5542J (DOA: 23/03/2019)

Dear Wai Yin,

Based on our surveyor's marking estimate, the calculation repair cost will be at Lump Sum \$4,550.00 and 4 repair days.

Kindly check.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 28 March 2019 2:35 PM  
**To:** 'CWS Motor Claims'; assignments; SUR  
**Cc:** 'Serene Ler'  
**Subject:** RE: SURVEY ASSESSMENT - D19002098MFSH/1  
**Attachments:** CSFCI19005517Kqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SHC 5542J.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 27 March 2019 2:26 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'Serene Ler' <[Sereneler@msfirstcapital.com.sg](mailto:Sereneler@msfirstcapital.com.sg)>  
**Subject:** RE: SURVEY ASSESSMENT - D19002098MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

**Celine Fong**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 27 March 2019 2:20 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Serene Ler <[Sereneler@msfirstcapital.com.sg](mailto:Sereneler@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19002098MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX: (065) 62564315

Your Ref: D19002098MFSH

Date: 28 March 2019

Our Ref: CS/FCI19005517/Kqd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5542J**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/03/2019 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 28,710.15</u>
Revised Estimate Amount	: <u>S\$ 5,675.64</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

### Vehicle Details

Vehicle No.: SHC5542J

Vehicle to be Exported: Yes

Intended Deregistration Date: 25 Mar 2019

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C001870

Chassis No.: VF1ABL15AUC278894

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 15 Aug 2014

First Registration Date: 15 Aug 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Aug 2022

PARF Rebate Amount: \$9,373.00

### Intended COE Rebate Details

COE Expiry Date: 14 Aug 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$50,088.00

COE Rebate Amount: \$21,206.00

**Total Rebate Amount: \$30,579.00**

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Mar 2019

OK

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5542J**

**AAD1903-180**

*Not Authorised*  
*1/ Pay @ 45500*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHC 5542J**

VF1ABL15AUC278894

RENAULT

LATITUDE

23.3.2019

**FCIL**

15/8/2014

**PART**

**LIST**

1	1 BUMPER COVER REAR	\$	<i>Bulkm</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Red L</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	✓
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	✓
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	✓
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>my dir</i> 404.56	✓
15	1 BOOT REAR	\$	<i>R</i> 2,872.68	X
16	1 TAILLAMP RH	\$	<i>SL</i> 552.55	X
17	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	X
18	1 TAILLAMP LH	\$	<i>SL</i> 552.55	X
19	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	X
		\$	<b>11,496.85</b>	
		10% \$	<b>1,149.69</b>	
		\$	<b>10,347.17</b>	

**Special Nett**

1	1SET PARKING AID	\$	<i>SL</i> 700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	✓

**Trans-cab Auto Services Pte Ltd**

AAD1903-180

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	nn	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	nn	80.00	X
12	1 WINDSCREEN MOULDING	\$	nn	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
14	1 REAR BOOT STICKER 'Trans-cab'	\$	nn	80.00	X
15	1 REAR BOOT STICKER '6555-3333'	\$	nn	80.00	X
<b>TOTAL</b>		\$		<b>605.82</b>	
<b>TOTAL PARTS</b>		\$		<b>10,952.99</b>	

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00 X
To repair and realign rear exhaust pipe.	\$	nn	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601

**Trans-cab Auto Services Pte Ltd**

**AAD1903-180**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5542J**

To transfer of rear windscreen fittings and conduct water seepage test. \$ *nn* 170.00 X

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

**TOTAL \$ 7,410.00**

**Over All Total \$ 28,710.15**

*19161.98*

**(LUMP SUM)**

**Repair Days**

**~~10 DAYS~~**

*4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19005517/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-04-2019	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 3889Y	Veh. Inspected	SHC 5542J
Policy No.		Coverage (\$)	0.00
Claim No.	D19002098MFSH	Excess (\$)	0.00
Assign From	SERÉNE	Assign Date	27/03/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278894	Colour	METALLIC WHITE / RED
Odometer	447393	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	23/03/2019	Inspection Date	27/03/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5542J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BUMPER COVER REAR	BUCKLED / CRACKED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	CRACKED	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	BENT	225.95	225.95
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	MTG DISTORTED	404.56	404.56
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
	LESS 10% DISCOUNT		-1,149.68	-480.07
			10,347.16	4,320.64
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-

Report Ref No. CS/FCI19005517/Kqd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	REAR BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
			1,404.82	165.00
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BOOT REAR, TAILLAMP PANEL RH AND TAILLAMP PANEL LH.		3,000.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,410.00	1,190.00
	<b>GRAND TOTAL</b>		<b>19,161.98</b>	<b>5,675.64</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,550.00
---	--	--	----------

Report Ref No. CS/FCI19005517/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.